

T204/1003

ASS. REC. BY:

REF: CS3/MSG19004631 / RICD302

Special Instruction:

SURVEYOR

Menmen

Rasu

ASSIGNMENT (Office)

From (Person):

Jowyn Tay mei ling of MSG

Date/Time: 14. Mar. 2019 10:409.m

Estimated Cost:

Bill to:

OD / (TP) WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

PC7369K

Insured:

SMA 9741B

at Workshop m/s

ngee ngee motor

Tel:

6777 5382

of BK k, no. 22 Pandan Road, 128240 West Coast.

Policy No: 29115180APO

Claim No:

584325

Sum Insured:

Excess:

Make of Veh:

D.O.A. 4.2.2019 12.00p.m

(Client's Record)

CA / REV / REP. / REV 24 HRS

(wp)

H.O.D. Endorsement:

Date/Time:

14.3.2019 11:22a.m

Person Contacted:

Jessie

Vehicle (IN) OUT

Date/Time	Action/Instruction (X) Estimate
	PC 7369K - X
	SMA 9741B - X
	Dismantle: 15/3/2019
	After repair: 21/3/2019

Person

REF:

52844

ASSIGNMENT

From: Date: Estimated Cost: OD / ☒ WS / TP RES / QD RES / VA / INV / MV

To inspect Vehicle No: PC 7369K
at Workshop n/s: NGE NGE MOTOR
of: Blk 22, PIMMION RD
Insured: MS14

Policy No:

Claims No:

Sign Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Est. or Market Value:

HOAC Accident Report Consistent? Yes or No

GA / PR Scene Consistent? Yes or No

Est. Repairs days Rest: Yes or No

Est. Sum % B Val: Yes or No

CA / REV / REP / 24 HRS

Date: Person Contacted

Vehicle: IN / OUT

Vehicle No: PC 7369K at From: 2018 MAR

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: TOYOTA HAZE BX 3-0 LA cc: 2882

Colour: GREY A/C: Insured / Std / HI / NA

Sp/Boarding: 23810 E/Radio: Insured / Std / HI / NA

Eng/No:

Ch/No:

KDH2015029050

Gen. Cond: Good / ☒ Fair / Poor / Burnt

Steering: ☒ Border / Jammed / Leaked / Burnt or

Brake: ☒ Border / Jammed / Leaked / Burnt or

Mod: ☒ M / S/Rim / STD A/Rim or

Tyre Size: F:

195 R15

R:

BS / DUN / EXNOVA / GY / ES / LIZA / MIC / ☒ HITEC / PIR / SUMI /

TOYO / YOKO or

Front:

Rear:

R/Bal: 6 mm R/Bal: 6 mm

L/Bal: 6 mm L/Bal: 6 mm

D.O.A: 04/02/19 D.O.A: 14/03/19

Survey held at: NGE NGE

Des. of Damages: Frt / ☒ Rear / Q/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time: Action / Instruction

RANGE OF REPAIR - (5K - 6K) 6 days

Date/Time File Attached:

☐ Prelim. Report
☐ Final Report

Days Of Repair: 6

Resurvey No. of Trip: 2

Survey Fee:

Transportation:

Food/Drink:

Other:

Total:

Remarks:

Signature:

Report Format: PRS-

Temp Sum / U/C / Q/S

Add Fee: ☐ Site trip: 0%

☐ Interview: 0%

☐ Technical: 0%

☐ Work and: 0%

120

10

130

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	13 Mar 2019		14 Mar 2019 10:40 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS

[\[Created by insurer\]](#)

Insured:	ZHANG YUAN, ID: S8972805C, Tel: +6591851545		
Main Claimant:	EDMUND VEHICLE RENTAL PTE LTD, Co. Reg. No.: 201625244G		
Vehicle Reg. No.:	PC7369K	Date of Loss:	04/02/2019 12:00 - :59 [10 Months and 28 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 584325	Policy/Cover Note No.:	29115680APO (Comprehensive) Coverage: 31/01/2019 - 30/01/2020
Vehicle Reg. No. (Insured):	SMA9741B	Policy No. (Claimant):	
		Excess:	S\$500.00
Repairer:	Ngee Ngee Motor () Block K, No. 22 Pandan Road, 128240 West Coast - Tel: 67775382		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Jowyn Tay Mei Ling - 6643 1307]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 15/03/2019]		
Driver/Custodian (Insured):	ZHANG YUAN (29 / Female) , NRIC: S8972805C, Tel: +6591851545 Email:		
Adj Asg. Remarks:	on WP. SJE : DISAGREED / LIABILITY 100% Please appoint LKK AUTO t conduct the survey . Kindly contact MS JESSIE @ 6777 5382 to arrange for survey .		

ASSOCIATED MAIL RECEIVED

[View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

T: 1124
p: Jessie
v: in
eg. X

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	5244G
Vehicle Details	
Vehicle No.:	PC7369K
Vehicle to be Exported:	No
Intended Deregistration Date:	23 Apr 2019
Vehicle Make:	TOYOTA
Vehicle Model:	HIACE DX 3.0L AUTO
Primary Colour:	Silver
Manufacturing Year:	2017
Engine No.:	1KD2736745
Chassis No.:	KDH2015029050
Maximum Power Output:	-
Open Market Value:	\$34,074.00
Original Registration Date:	07 Mar 2018
First Registration Date:	07 Mar 2018
Transfer Count:	0
Actual ARF Paid:	\$1,704.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	06 Mar 2028
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$42,000.00
COE Rebate Amount:	\$37,240.00
Total Rebate Amount:	\$37,240.00

The information contained herein is correct as at 23 Apr 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	12/02/2019 12:02
Date Of Accident	04/02/2019 12:35
Exact Location Of Accident	ALONG MANDAI ROAD TOWARDS YISHUN AVE 1
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	PC7369K
Insured/Policyholder	
Name Of Registered Owner	EDMUND VEHICLE RENTAL PTE LTD
Co Reg No	201625244G
Email Address	EDMUNDEVIR@GMAIL.COM
Mobile Phone No	
Alternative Phone No	OFFICE-62503339
Vehicle Particulars	
Manufacturer	TOYOTA
Model	HIACE
Exact Purpose for which vehicle was being used at time of accident	WORK PURPOSE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE
Insurance Company	
Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5086597930-02
Cover Note Number	
Driver	
Name of Driver	TANG JIE
NRIC No	S6863493H
Date Of Birth	07/04/1968
Occupation	OUTDOOR
Date Of Driving Pass	29/11/2001
Driving Experience	17 YEARS AND 2 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-87143556
Fax Number	
Contact Number	
EMail Address	NOEMAIL

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Accident Report

On 4th February 2019 at approximately 12:35 hrs. I Tang Jie (S6863493H) was driving PC7369K along Mandai Road towards Yishun Avenue 1. I stop at the traffic light turned red when a BMW (SMA9741B) hit the back of my vehicle (PC7369K). My vehicle (PC7369K) was already at stop before the incident happened.



PC 7369K



SMA 9741B

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	13 Mar 2019		14 Mar 2019 10:40 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
-------------	------------------	----------------------	------------------	--------------------------

CLAIM SUBFOLDER DETAILS **[Created by insurer]**

Insured:	ZHANG YUAN, ID: S8972805C, Tel: +6591851545		
Main Claimant:	EDMUND VEHICLE RENTAL PTE LTD, Co. Reg. No.: 201625244G		
Vehicle Reg. No.:	PC7369K	Date of Loss:	04/02/2019 12:00 - :59 [10 Months and 28 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 584325	Policy/Cover Note No.:	29115680APO (Comprehensive) Coverage: 31/01/2019 - 30/01/2020
Vehicle Reg. No. (Insured):	SMA9741B	Policy No. (Claimant):	
		Excess:	S\$500.00
Repairer:	Ngee Ngee Motor () Block K, No. 22 Pandan Road, 128240 West Coast - Tel: 67775382		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Jowyn Tay Mei Ling - 6643 1307]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Imm.Advice due 15/03/2019]		
Driver/Custodian (Insured):	ZHANG YUAN (29 / Female) , NRIC: S8972805C, Tel: +6591851545 Email:		
Adj Asg. Remarks:	on WP. SJE : DISAGREED / LIABILITY 100% Please appoint LKK AUTO t conduct the survey . Kindly contact MS JESSIE @ 6777 5382 to arrange for survey .		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.














































ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*PC7369K (584325)
[SMA9741B]
TP
EDMUND VEHICLE RENTAL PTE LTD
Feb 4 2019 12:00PM
[ZHANG YUAN]
Ngee Ngee Motor

Upload Documents		Upload Photos		Compose New Letter		View		View in Browser	
Assessment Reports							1 per page		<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)					Thumbnail	Print	
1	13/03/19 15:17	Accident Statement From:OD - Reg. No: SMA9741B, Claimant: ZHANG YUAN						Load HTM	
Photos/Images							3 per page		<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)					Thumbnail	Print	
1	23/04/19 14:49	General View						Load JPG	<input checked="" type="checkbox"/>
2	23/04/19 14:49	General View						Load JPG	<input checked="" type="checkbox"/>
3	23/04/19 14:49	General View						Load JPG	<input checked="" type="checkbox"/>
4	23/04/19 14:49	General View						Load JPG	<input checked="" type="checkbox"/>
5	23/04/19 14:49	General View						Load JPG	<input checked="" type="checkbox"/>
6	23/04/19 14:49	General View						Load JPG	<input checked="" type="checkbox"/>
7	23/04/19 14:49	General View						Load JPG	<input checked="" type="checkbox"/>
8	23/04/19 14:49	General View						Load JPG	<input checked="" type="checkbox"/>
9	23/04/19 14:49	General View						Load JPG	<input checked="" type="checkbox"/>
10	23/04/19 14:49	General View						Load JPG	<input checked="" type="checkbox"/>
11	23/04/19 14:49	General View						Load JPG	<input checked="" type="checkbox"/>
12	23/04/19 14:49	General View						Load JPG	<input checked="" type="checkbox"/>
13	23/04/19 14:49	General View						Load JPG	<input checked="" type="checkbox"/>
14	23/04/19 14:49	General View						Load JPG	<input checked="" type="checkbox"/>
15	23/04/19 14:49	General View						Load JPG	<input checked="" type="checkbox"/>
16	23/04/19 14:49	General View						Load JPG	<input checked="" type="checkbox"/>
17	23/04/19 14:49	General View						Load JPG	<input checked="" type="checkbox"/>
18	23/04/19 14:49	General View						Load JPG	<input checked="" type="checkbox"/>
19	23/04/19 14:49	General View						Load JPG	<input checked="" type="checkbox"/>
20	23/04/19 14:49	General View						Load JPG	<input checked="" type="checkbox"/>
21	23/04/19 14:49	General View						Load JPG	<input checked="" type="checkbox"/>
22	23/04/19 14:49	General View						Load JPG	<input checked="" type="checkbox"/>
23	23/04/19 14:49	General View						Load JPG	<input checked="" type="checkbox"/>
24	23/04/19 14:49	General View						Load JPG	<input checked="" type="checkbox"/>
25	23/04/19 14:49	General View						Load JPG	<input checked="" type="checkbox"/>
26	23/04/19 14:49	General View						Load JPG	<input checked="" type="checkbox"/>
27	23/04/19 14:49	General View						Load JPG	<input checked="" type="checkbox"/>
28	23/04/19 14:49	General View						Load JPG	<input checked="" type="checkbox"/>
29	23/04/19 14:49	General View						Load JPG	<input checked="" type="checkbox"/>
30	23/04/19 14:49	General View						Load JPG	<input checked="" type="checkbox"/>
31	23/04/19 14:49	General View						Load JPG	<input checked="" type="checkbox"/>
32	23/04/19 15:24	Photographs of Damaged Parts						Load JPG	<input checked="" type="checkbox"/>
33	23/04/19 15:24	Photographs of Damaged Parts						Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
34	23/04/19 15:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
35	23/04/19 15:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
36	23/04/19 15:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
37	23/04/19 15:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
38	23/04/19 15:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
39	23/04/19 15:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
40	23/04/19 15:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
41	23/04/19 15:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
42	23/04/19 15:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
43	23/04/19 15:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
44	23/04/19 15:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
45	23/04/19 15:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
46	23/04/19 15:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
47	23/04/19 15:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
48	23/04/19 15:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
49	23/04/19 15:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
50	23/04/19 15:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
51	23/04/19 15:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
52	23/04/19 15:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
53	23/04/19 15:24	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
54	23/04/19 15:25	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
55	23/04/19 15:25	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
56	23/04/19 15:25	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
57	23/04/19 15:25	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
58	23/04/19 15:25	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
59	23/04/19 15:25	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
60	23/04/19 15:25	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
61	23/04/19 15:25	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
62	23/04/19 15:25	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
63	23/04/19 15:25	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
64	23/04/19 15:25	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
65	23/04/19 15:25	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
66	23/04/19 15:25	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
67	23/04/19 15:25	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
68	23/04/19 15:25	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
69	23/04/19 15:25	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
70	23/04/19 15:25	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
71	23/04/19 15:25	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	13/03/19 15:19	TPD PC7369K GIA REPORT	 Load PDF	
2	13/03/19 15:24	Reject email to TP Lawyer & appoint LKK AUTO	 Load PDF	
3	13/03/19 15:46	TPD PC7369K - PRI	 Load PDF	
4	23/04/19 10:10	Letter of Demand from Third Party - East Asia Law Corporation	 Load PDF	
5	23/04/19 10:10	Letter of Demand from Third Party - Survey Photographs 1	 Load PDF	
6	23/04/19 10:10	Letter of Demand from Third Party - Survey Photographs 2	 Load PDF	
7	23/04/19 10:10	Letter of Demand from Third Party - Survey Photographs 3	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

Reset

Save

Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**Show Remarks To:** ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG19004631/R1CD3E2

Date: 23/04/2019

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 29115680APO

Claimant Vehicle No : PC7369K

Insured Vehicle No : SMA9741B

Date of Loss: 04/02/2019

Nature of Claim: TP

Claim No: 584325

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: PC7369K

Make & Model: TOYOTA HIACE, 3.0 D DX (A)

Engine No: 1KD2736745

Reg. Date: 07/03/2018 (Man. Year: 2017)

Chassis No: KDH2015029050

Colour: Grey

Odometer: 23810 km

Engine Capacity: 2982 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195 R15	Rear Tyre Size:	195 R15
Front Left Side:	OHTSU 6 mm	Rear Left Side:	OHTSU 6 mm
Front Right Side:	OHTSU 6 mm	Rear Right Side:	OHTSU 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 14/03/2019

Date Inspected: 14/03/2019 Inspected At:

Ngee Ngee Motor
Block K, No. 22 Pandan Road
Singapore 128240

Estimated Period of Repair: 6.0 days

Adjuster: MOHD RASUL

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$5,000.00 -\$6,000.00

REPAIR DETAILS

Reference

Part Source: MRM-SG **Version:** 1.0 (Last Synchronised: 23 Apr 2019)

Parts: 213 TOYOTA HIACE 3.0 D DX (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for PC7369K)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.


Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

on 4th February 2019 at approximately 12:35 hrs
I (TANE TIE, S62634934) was driving PC7369K along
Manda Road towards Yishun Avenue 1. I stopped at
the traffic light which turned red. A BMW (SM1174113)
hit the back of my vehicle (PC7369K) my vehicle
PC7369K was already at stop before the
accident happened
(please see attached photos)

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Address	BLK 308C PUNGGOL WALK #12-326 SINGAPORE
Postcode	823308
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER ATTACHED

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SMA9741B
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	HELEN ZHANG YUAN
NRIC/Passport Number	S8972805C
Contact Number	91851545
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	