

ASS. REC. BY:

REF: CS 15m019004632/4vd3 | 02

Special Instruction:

Survivor:

Marcus

ASSIGNMENT (Office)

Meriman

From (Person): Chan Chu Hui Agnes of Somp0 (SMO)

Date/Time: 13.Mar.2019 15.01p.m

Estimated Cost:

Bill to:

OD (TP) WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SGD 5778 C

Insured: SCW 3314 T

at Workshop m/s: Are Autolubon Pte Ltd (HA)

Tel: 68441184

of 13 Kaki Bukit Road 4 # 03-22

Policy No: D18MTPV01005177

Claim No: CMTD 1901323

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 11.3.2019 15.00 PM

CA / REV / REP. / REV 24 HRS

"wp"

H.O.D. Endorsement:

Date/Time: 14.3.2019 11.01a.m

Person Contacted:

Anna

Vehicle: IN OUT

Date/Time	Action/Instruction (✓) Estimate
	SGD 5778 C - X
	SCW 3314 T - X
15/3/19	Informed Agnes pending workshop est via meriman
17/4/19	Send prel. revised via meriman

## ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour:

Sp. Reading

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

Rear

R/Bal.

mm

R/Bal.

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

D.O.I.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

1 yr 11m. L7A10321 not 4/73

16/4/19 confirmed m/s &amp; 4000 with Anna. (Red 8660-30, 689)

RECEIVED 17 APR 2019

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

17/4 - typist

Days Of Repair:

5

Resurvey No. of Trip:

2

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Report Format :

marimen

Lump Sum / I.B.I. (\$

4000/-

350

10

360

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: Somp Insurance Singapore Pte. Ltd.  
50 Raffles Place  
#05-01/06, Singapore Land Tower  
Singapore 048623

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: CHAN SHU HUI AGNES

Date: 17 Apr 2019

**Preliminary Advice**

Insured Vehicle No	: SCW3314T	Accident Date	: 11/03/2019
TP Vehicle No	: SGD5778C	Assignment Date	: 13/03/2019
Make	: RENAULT MEGANE	Est. Duration of Repair	: 5
Date of Inspection	: 14/3/2019		
Inspection At	: ACE AUTOLUTION PTE LTD		

**Point of Impact / General Description of Damages**

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	12,660.30
Revised Amount	:S\$	4,000.00 (LUMP SUM)
Check Items (Estimated)	:S\$	0.00
Total	:S\$	4,000.00

Lump Sum Repair	:S\$	
-----------------	------	--

**Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

**Remarks**

( ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.

( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

( X ) Other comments : The above survey was conducted on a 'Without Prejudice' basis.

## ...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	13 Mar 2019		13 Mar 2019 15:01 <a href="#">Assign</a>				<b>New Assignment</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	<a href="#">Show All</a>
------	-----------	---------------	-----------	--------------------------

**CLAIM SUBFOLDER DETAILS** [Created by insurer]

Insured: <b>SHEE SEE KUEN</b> , ID: S1730275B	
Main Claimant: <b>THAM YIN CHOON</b> , ID: S1261653H	
Vehicle Reg. No.: <b>SGD5778C</b>	Date of Loss: 11/03/2019 15:00 - :59
Claim Type: <b>TP / CMTD1901323</b>	Policy/Cover Note No.: D18MTPV01005177 (Comprehensive)
Vehicle Reg. No. (Insured): <b>SCW3314T</b>	Policy No. (Claimant):
	Excess:
Repairer: <b>Ace Autolution Pte Ltd (HQ)</b> 13 Kaki Bukit Road 4 #03-22, Bartley Biz Centre, 417807 Kaki Bukit - Tel: 68441184	
Handling Insurer: <b>Sompo Insurance Singapore Pte. Ltd. (HQ)</b> - Tel: 6461 6555 ... [Handled by <b>CHAN SHU HUI AGNES</b> - 6329 5327]	
Adjuster: <b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... <b>[Final Rpt due 22/03/2019]</b>	
Adj Asg. Remarks: -PLEASE BE INFORMED THAT OUR INSURED HAS NOT REPORTED THE ACCIDENT -NO TP SAS SUBMITTED	

**ASSOCIATED MAIL RECEIVED** [View All](#) [Compose Case Mail](#)

There are no mail for this case.

**ALL ASSOCIATED TASKS** [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Time: 11.01 a.m  
 person: Anna  
 -  
 v: in  
 est: X

**Veron Chen (LKKAuto)**

---

**From:** Ace Autolution <admin@aceauto.com.sg>  
**Sent:** Tuesday, 16 April 2019 4:06 PM  
**To:** Marcus Chua (LKKAuto)  
**Subject:** SGD5778C AFTER PAINT PHOTO  
**Attachments:** WhatsApp Image 2019-04-12 at 17.48.20.jpeg; WhatsApp Image 2019-04-12 at 17.48.21(1).jpeg; WhatsApp Image 2019-04-12 at 17.48.21(2).jpeg; WhatsApp Image 2019-04-12 at 17.48.21.jpeg; WhatsApp Image 2019-04-12 at 17.53.46(1).jpeg; WhatsApp Image 2019-04-12 at 17.53.46.jpeg; WhatsApp Image 2019-04-12 at 17.54.54(1).jpeg; WhatsApp Image 2019-04-12 at 17.54.54.jpeg

Hi,

My boss agree the amount for the COR = \$4000.00.  
Thank you.

Regards ,  
Anna / Shu Wen  
ACE AUTOLUTION PTE LTD  
13 KAKI BUKIT ROAD 4 ,  
#03-29 BARTLEY BIZ CENTRE  
SINGAPORE 417807  
Tel : 6844 1184 / 9657 2134

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Singapore NRIC
Owner ID:	1653H
<b>Vehicle Details</b>	
Vehicle No.:	SGD5778C
Vehicle to be Exported:	No
Intended Deregistration Date:	18 Mar 2019
Vehicle Make:	RENAULT
Vehicle Model:	MEGANE 1.6 M
Primary Colour:	Beige
Manufacturing Year:	2005
Engine No.:	K4MT760R075806
Chassis No.:	VF1LM0C0H34725879
Maximum Power Output:	83.0 kW (111 bhp)
Open Market Value:	\$18,007.00
Original Registration Date:	20 Feb 2006
First Registration Date:	20 Feb 2006
Transfer Count:	0
Actual ARF Paid:	\$19,808.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	19 Feb 2021
COE Category:	A - Car (1600cc & below)
COE Period(Years):	5
PQP Paid:	\$26,900.00
COE Rebate Amount:	\$10,327.00
<b>Total Rebate Amount:</b>	<b>\$10,327.00</b>
<b>Message</b>	
Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 15 Mar 2019

OK

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	12/03/2019 16:24
Date Of Accident	11/03/2019 15:40
Exact Location Of Accident	TAI SENG STREET
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SGD5778C
<b>Insured/Policyholder</b>	
Name Of Registered Owner	THAM YIN CHOON
NRIC No	S1261653H
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-96301504
Alternative Phone No	OFFICE-96301504

### Vehicle Particulars

Manufacturer	RENAULT
Model	MEGANE

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

### Insurance Company

Name of Insurance Company	AUTO & GENERAL INSURANCE (SINGAPORE) PTE. LIMITED.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	P10043381R01
Cover Note Number	

### Driver

Name of Driver	JIMMY TAN XIANG WEI
NRIC No	S9035349G
Date Of Birth	22/09/1990
Occupation	OUTDOOR
Date Of Driving Pass	19/09/2012
Driving Experience	6 YEARS AND 5 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-87677053
Fax Number	
Contact Number	
Email Address	NOEMAIL



Address	BLK 660 YISHUN AVE 4 #11-319
Postcode	760660
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - TOW TRUCK DRIVER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

### General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	YES
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : THAM YIN CHOON GENDER: : MALE

### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

### Circumstances of Accident

ON 11/03/2019 AT AROUND 3.40PM, I WAS TRAVELLING ALONG TAI SENG STREET TOWARDS AIRPORT ROAD. I SLOWED DOWN AND STOP AT THE STOP LINE TO CHECK FOR ONCOMING VEHICLE. SUDDENLY, VEHICLE B (SCW3314T) COLLIDED ONTO VEHICLE A (SGD5778C) WHICH WAS TOWED BY VEHICLE C (YM9148J)

### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SCW3314T
Vehicle Make/Model/Colour	
Details Of Properties	VEHICLE B
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	



Nature Of Damage

No. Of Passenger (Including Driver)

# **SKETCH PLAN**


## **IMPORTANT NOTICE**


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mall packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

  
Policyholder's Signature  
Date & Time:

  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

  
Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 11 March 2019 at around 3:40pm, I was travelling along  
 Tai Seng Street towards Airport Road. After that, I slow down and stop  
 to checking at the stop line to check for on-coming vehicle.  
 Suddenly, Vehicle B ~~collided to~~ (SW 3314 T) collided to vehicle A (SGD 5778 C)  
 which was tow by Vehicle C (YM 9148 J).

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature  
 Date & Time:

Driver's Signature  
 (If driver is not the policyholder)  
 Date & Time:

Reporting Centre Personnel's Signature  
 Name:  
 NRIC/FIN No.:

11/3/19 5.47pm



ACE AUTOLUTION PTE LTD

13 Kaki Bukit Road 4 Bartley Biz Centre #03-29

Singapore 417807

Tel: 6702 4282 Fax: 6702 4202

Page No. 1

Vehicle No. SGD5778C RENAULT MEGANE

QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE(\$S)	SURVEYOR ADJUSTMENT
<b>PARTS (LIST ITEMS)</b>				
1	BOOTLID	body	1890.00	—
1	BOOTLID LOGO	new	285.00	—
1	BOOTLID " MEGANE " EMBLEM	new	95.00	—
1	BOOTLID INNER LOCK	twi/shnd	285.00	—
1	BOOTLID SWITCH	11	280.00	X
1	BOOTLID OUTER HANDLE	11	240.00	X
1	REAR BUMPER	new	965.00	—
2	REAR BUMPER SIDE RETAINER @\$120.00	11	240.00	X
2	REAR BUMPER BRACKET @\$110.00	11	220.00	X
1	REAR BUMPER CARRIER	25	490.00	X
1	REAR BUMPER REINFORCEMENT	3rd	855.00	—
1	REAR BUMPER PROTECTOR	DE	630.00	—
1	REAR END PANEL	body	935.00	—
1	REAR END PANEL TOP GARNISH	8L	101.00	X
2	TAILLAMP LH & RH @\$388.00	11	776.00	X
1	SPARE TYRE PANEL	11	1680.00	X
			9967.00	
less 10%			996.70	10%
			8970.30	
<b>SPECIAL NETT ITEMS</b>				
1 SET	REVERSE SENSOR C/W CONTROL MODULE	shnd	300.00	200
1	REAR END SEALANT	11	100.00	X
1	SPARE TYRE PANEL SEALANT	11	80.00	X
1	REAR END PANEL TOP GARNISH CLIPS	11	80.00	X
1 SET	REAR BUMPER CLIPS	new	80.00	50
Total Parts			9610.30	

5973  
102  
4999.50

not allocated  
LH  
2/3 @ 4000  
5 shnd  
14/3/18  
take photo after repair.



## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/SMO19004632/UVD3N2  
Date: 24/04/2019

## REFERENCE

Handling Insurer:	Sompo Insurance Singapore Pte. Ltd.	Policy No:	D18MTPV01005177
Claimant Vehicle No :	SGD5778C	Insured Vehicle No :	SCW3314T
Date of Loss:	11/03/2019	Nature of Claim:	TP
		Claim No:	CMTD1901323

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No:	SGD5778C	Engine No:	K4MT760R075806
Make & Model:	RENAULT MEGANE, 1.5 D Sedan DCI AT EU6 (M)	Chassis No:	VF1LM0C0H34725879
Reg. Date:	20/02/2006 (Man. Year: 2005)	Odometer:	232221 km
Colour:	Grey		
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size:	195/65R15	Rear Tyre Size:	195/65R15
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

## COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	9,610.30	5,249.50	4,360.80	45.38
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,050.00	1,540.00	1,510.00	49.51
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>12,660.30</b>	<b>6,789.50</b>	<b>5,870.80</b>	<b>46.37</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>4,000.00</b>		
<b>Nett Amount (S\$)</b>	<b>12,660.30</b>	<b>4,000.00</b>	<b>8,660.30</b>	<b>68.41</b>

## INSPECTION

Date of Assignment:	13/03/2019	
Date Inspected:	14/03/2019 Inspected At:	Ace Autolution Pte Ltd (HQ) 13 Kaki Bukit Road 4 #03-22, Bartley Biz Centre Singapore 417807

Estimated Period of Repair: 5.0 days

Adjuster: MARCUS CHUA

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.





## REPAIR DETAILS

## Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 24 Apr 2019)  
 Parts: 143 RENAULT MEGANE 1.5 D Sedan DCI AT EU6 (M) (Catalogue:Merimen Singapore 1.0)  
 Labour: Repairer's (Price-denominated Standard List)  
 Print Code: (Unsubmitted, no print-code for SGD5778C)  
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page  
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

## Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*BOOTLID	Badly Dented	1,890.00 FL	*1,780.00 FL
2	1	*BOOTLID LOGO	Necessary	285.00 FL	*180.00 FL
3	1	*BOOTLID MEGANE EMBLEM	Necessary	95.00 FL	*95.00 FL
4	1	*BOOTLID INNER LOCK	Twisted/Shorted	285.00 FL	*285.00 FL
5	1	*BOOTLID SWITCH	Not Necessary	280.00 FL	*- FL
6	1	*BOOTLID OUTER HANDLE	Not Necessary	240.00 FL	*- FL
7	1	*REAR BUMPER	Dented/Deformed	965.00 FL	*965.00 FL
8	2	*REAR BUMPER SIDE RETAINER	Not Necessary	240.00 FL	*- FL
9	2	*REAR BUMPER BRACKET	Not Necessary	220.00 FL	*- FL
10	1	*REAR BUMPER CARRIER	No such part	490.00 FL	*- FL
11	1	*REAR BUMPER REINFORCEMENT	Bent	855.00 FL	*685.00 FL
12	1	*REAR BUMPER PROTECTOR	Deformed	630.00 FL	*630.00 FL
13	1	*REAR END PANEL	Badly Dented	935.00 FL	*935.00 FL
14	1	*REAR END PANEL TOP GARNISH	Serviceable	101.00 FL	*- FL
15	2	*TAILLAMP LH & RH	Not Necessary	776.00 FL	*- FL
16	1	*SPARE TYRE PANEL	Not Necessary	1,680.00 FL	*- FL
17	1	*SET REVERSE SENSOR C/W CONTROL MODULE	Shorted	300.00 FS	*200.00 FS
18	1	*REAR END SEALANT	Not Necessary	100.00 FS	*- FS
19	1	*SPARE TYRE PANEL SEALANT	Not Necessary	80.00 FS	*- FS
20	1	*REAR END PANEL TOP GARNISH CLIPS	Not Necessary	80.00 FS	*- FS
21	1	*SET REAR BUMPER CLIPS	Necessary	80.00 FS	*50.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	10,607.00	5,805.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	996.70	555.50
<b>Total Parts (\$\$)</b>	<b>9,610.30</b>	<b>5,249.50</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE THE AFFECTED PARTS & FITTINGS TO COMMENCE REPAIRS AND REPLACE DAMAGED PARTS	New	1,400.00	600.00
2	TO SUPPLY PAINT MATERIALS,EXPANDABLE ITEMS & PUTTY,RESPRAY PAINT ON PARTS REPLACED	New	1,200.00	800.00
3	TO REMOVE AND REFIX WIRING AT DAMAGED AREAS	New	80.00	30.00
4	TO PERFORM ANTI RUST TREATMENT ON AFFECTED AREAS	New	100.00	60.00
5	TO REMOVE AND REPLACE REVERSE SENSORS AND CHECK FOR PROPER FUNCTIONS	New	120.00	50.00
6	TO CLEAR FAULT CODE WITH DIAGNOSTIC COMPUTER AND RESET TO RENAULT SPECIFICATION	New	150.00	0.00
<b>Gross Labour Cost (\$\$)</b>			<b>3,050.00</b>	<b>1,540.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >