

2/03/2002

ASS. REC. BY:

REF: CS3/FWD/19004633/Gedser Special Instruction:

Surveyor  
Munim

GA

ASSIGNMENT (Office)

From (Person):

Lionel Tan

of

FWD

Date/Time:

14/3/19 @ 10:25am

Estimated Cost:

Bill to:

OD TP WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

FBH 3168P

Insured:

SJH 8412G

at Workshop m/s

Thienstal

Tel:

98615303

of

1 kaki Bkt Ave 6 #02-35

Policy No:

PNPV 2019-00000546

Claim No:

1201900005588

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

27/02/2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

12:44pm 14/3/19

Person Contacted:

Wilson

Vehicle IN / OUT

Date/Time

Action/Instruction (X) Estimate

FBH 3168P - X

SJH 8412G - NBA/VOI 11802196314

D.O.A - 06/12/2018

Dismantle: 15/3/2019.

Surveyor:

PRS  
GA

REF:

FWD

69168

## ASSIGNMENT

(2013)

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: \_\_\_\_\_

at Workshop m/s Trikristal

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt.: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: 3 days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: FBH3168P Yr Regn: 13 May 2013

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda CB400 C.C. 399Colour: white A/C: Insured / Std / NI / NASp. Reading: - T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: IH2NC4284BK300428Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 120 / 60 8R17R: 160 / 60 8R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 4 mmR/Bal. 4 mmL/Bal. 4 mmL/Bal. 4 mm

D.O.A. \_\_\_\_\_

D.O.I. 14-03-19Survey held at W/S323pmDes. of Damages: Frt / Rear / O/S N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

\$3000 - \$4000

Date/Time, File Pass to?

☐

Preli. Report

Days Of Repair: 3

1)

☐

Final Report

Resurvey No. of Trip: 1

Date/Time, File Return to?

2)

Add Fee:

☐

Site Insp (\$

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

Report Format: PRS

Lump Sum / I.B.I: (\$ \_\_\_\_\_)

8050130

## Nivitha (LKK Auto)

---

**From:** lionel.tan@fwd.com  
**Sent:** Thursday, 14 March 2019 10:25 AM  
**To:** assignments@lkkauto.com; sur@lkkauto.com  
**Cc:** motorclaims.sg@fwd.com  
**Subject:** FW: ACCIDENT ON 27.02.19 ALONG BKE TWDS WOODLANDS INVOLVING MOTOR VEHICLES FBH 3168P AND SJH 8412G

[Policy Number: PNPV2019-00000546]

Hi LKK Team,

Please arrange survey (SJE) with repairer as per email below.

No document is provided.

Regards,  
Lionel

---

**From:** Sal [mailto:sal@alc.com.sg]  
**Sent:** Thursday, March 14, 2019 9:03 AM  
**To:** Lionel Tan Tian Pei - SGUser  
**Cc:** Motor Claims SG - SG Common  
**Subject:** RE: ACCIDENT ON 27.02.19 ALONG BKE TWDS WOODLANDS INVOLVING MOTOR VEHICLES FBH 3168P AND SJH 8412G [FWD REF: 1201900005588-002/LT]

WITHOUT PREJUDICE

Dear Sirs

We refer to your email below.

Our client/ motor workshop is agreeable to LKK AUTO CONSULTANTS PTE LTD for the pre-repair survey.

Kindly arrange for the surveyors to the workshop.

Thank you.

Best Regards,  
Hana  
Legal Secretary

**Arasan Law Chambers**

151 Chin Swee Road | Manhattan House #06-08 | Singapore 169876

Tel: 6835 3350 | Fax: 6835 3352 | Email: [sal@alc.com.sg](mailto:sal@alc.com.sg)

This e-mail is from M/s Arasan Law Chambers, a firm of Advocates and Solicitors in Singapore, and is intended solely for the named addressee.

It contains confidential and/or legally privileged information. If the e-mail has reached you in error, please delete the e-mail immediately and inform us of the error.

Internet communications cannot be guaranteed to be secured or error-free as information could be intercepted, corrupted, lost, arrive late or contain viruses.

The sender therefore does not accept liability for any errors or omissions in the context of this message which arise as a result of Internet transmission.

---

**From:** [lionel.tan@fwd.com](mailto:lionel.tan@fwd.com) [<mailto:lionel.tan@fwd.com>]

**Sent:** Wednesday, March 13, 2019 3:04 PM

**To:** [sal@alc.com.sg](mailto:sal@alc.com.sg)

**Cc:** [motorclaims.sg@fwd.com](mailto:motorclaims.sg@fwd.com)

**Subject:** RE: ACCIDENT ON 27.02.19 ALONG BKE TWDS WOODLANDS INVOLVING MOTOR VEHICLES FBH 3168P AND SJH 8412G [FWD REF: 1201900005588-002/LT]

Without Prejudice

Dear Sir/Madam,

Please select one of our surveyors as follows: -

1. LKK AUTO CONSULTANTS PTE LTD
2. INFINITI APPRAISAL SERVICE
3. AJAX INSPECTION SERVICES PTE LTD
4. APPRAISALS ASSOCIATES PTE LTD
5. VICOM LTD

If you are not agreeable to any of the above, we would proceed to appoint a surveyor to conduct a pre repair survey & post repair inspection within the timeline stipulated under the NIMA protocol.

We look forward to your reply.

Thank you.

Lionel

---

**From:** Sal [<mailto:sal@alc.com.sg>]

**Sent:** Tuesday, 12 March, 2019 4:27 PM

**To:** SG Corporate Contact

**Subject:** ACCIDENT ON 27.02.19 ALONG BKE TWDS WOODLANDS INVOLVING MOTOR VEHICLES FBH 3168P AND SJH 8412G

WITHOUT PREJUDICE

Your ref: SJH 8412G

Our ref: ALC.2019.168.MGS.nf

ATTN: Motor Claims Department

RE: NOTICE TO INSURANCE TO CONDUCT PRE-REPAIR SURVEY WITHIN 2 WORKING DAYS PURSUANT TO PARAGRAPH 6.2 OF PRE-ACTION  
PROTOCOL FOR NIMA CASE

We refer to the above matter.

We act for **Mr. Muhyiddeen Ghani Bin N Syed Pulavar**, the rider of motor vehicle **FBH 3168P** who has appointed us to act on his behalf to claim against your insured's vehicle no. **SJH 8412G** in regards to the road traffic accident on 27.02.19.

Please be informed that the said motor vehicle can be inspected at:-

**Trikristal Aerospace Pte Ltd**

1 Kaki Bukit Ave 6

#02-35 Autobay@Kaki Bukit  
Singapore 417883

Kindly contact **Mr Wilson** at Tel: (+65) 9861 5303 or 6909 3080

If you fail to conduct the pre-repair inspection within the next 2 working days excluding any intervening Saturday, Sunday or Public Holiday, the said workshop will commence repairs thereafter without further reference to you.

Thank you.

Best Regards,  
Hana  
Legal Secretary

**Arasan Law Chambers**

151 Chin Swee Road | Manhattan House #06-08 | Singapore 169876

Tel: 6835 3350 | Fax: 6835 3352 | Email: [sal@alc.com.sg](mailto:sal@alc.com.sg)

This e-mail is from M/s Arasan Law Chambers, a firm of Advocates and Solicitors in Singapore, and is intended solely for the named addressee.

It contains confidential and/or legally privileged information. If the e-mail has reached you in error, please delete the e-mail immediately and inform us of the error.

Internet communications cannot be guaranteed to be secured or error-free as information could be intercepted, corrupted, lost, arrive late or contain viruses.

The sender therefore does not accept liability for any errors or omissions in the context of this message which arise as a result of Internet transmission.

**ATTENTION:**

The email and any attachments transmitted with it are private and confidential and intended solely for the use of the individual or entity to whom they are addressed. If you have received this email in error, please notify the sender immediately and delete this email and any attachments from your system. You should not use, disclose, copy or store this email and any attachments.

Messages and attachments are scanned for all viruses known. However, you are advised that you open any attachments at your own risk. If this message contains password-protected attachments, the files have NOT been scanned for viruses by our mail domain. Please always scan for viruses before opening any attachments.

**ATTENTION:**

The email and any attachments transmitted with it are private and confidential and intended solely for the use of the individual or entity to whom they are addressed. If you have received this email in error, please notify the sender immediately and delete this email and any attachments from your system. You should not use, disclose, copy or store this email and any attachments.

Messages and attachments are scanned for all viruses known. However, you are advised that you open any attachments at your own risk. If this message contains password-protected attachments, the files have NOT been scanned for viruses by our mail domain. Please always scan for viruses before opening any attachments.

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	5916Z
Vehicle Details	
Vehicle No.:	FBH3168P
Vehicle to be Exported:	No
Intended Deregistration Date:	14 Mar 2019
Vehicle Make:	HONDA
Vehicle Model:	CB400
Primary Colour:	White
Manufacturing Year:	2013
Engine No.:	NC42E1124249
Chassis No.:	JH2NC4294BK300428
Maximum Power Output:	-
Open Market Value:	\$6,904.00
Original Registration Date:	13 May 2013
First Registration Date:	13 May 2013
Transfer Count:	4
Actual ARF Paid:	\$1,036.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	12 May 2023
COE Category:	D - Motorcycle
COE Period(Years):	10
QP Paid:	\$1,700.00
COE Rebate Amount:	\$852.00
<b>Total Rebate Amount:</b>	<b>\$852.00</b>

The information contained herein is correct as at 14 Mar 2019

OK

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	28/02/2019 20:41
Date Of Accident	27/02/2019 21:00
Exact Location Of Accident	BKE TOWARDS WOODLANDS CHECKPOINT
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SJH8412G
Insured/Policyholder	
Name Of Registered Owner	JASON
NRIC No	S7923054E
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-96653769
Alternative Phone No	OFFICE-96653769
Vehicle Particulars	
Manufacturer	TOYOTA
Model	VIOS 1.5E A
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	REPORTING ONLY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	FWD SINGAPORE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	PNPV2019-00000546
Cover Note Number	
Driver	
Name of Driver	HENG KIA HWEE FLORENCE
NRIC No	S8223528J
Date Of Birth	23/07/1982
Occupation	INDOOR
Date Of Driving Pass	08/01/2009
Driving Experience	10 YEARS AND 1 MONTH
Gender	FEMALE
Mobile Number	(LOCAL) +65-87152294
Fax Number	
Contact Number	
Email Address	HENG_FLORENCE@HOTMAIL.COM



Address	NIL
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	SIBLING
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	YES
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
POLICE STATION NAME [OTHER]	WOODLANDS EAST NPC
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

REFER TO THE POLICE REPORT NO : T/20190227/2190 LODGED AT WOODLANDS EAST NPC. ON 27/02/2019 AT ABOUT 2100HRS, I WAS DRIVING VEHICLE SJH8412G ALONG LANE 1 OF BKE TOWARDS WOODLANDS CHECKPOINT. AS I WANTED TO FILTER TO LANE 2 I MADE A CHECK ON MY SIDE MIRROR WHERE I SAW A MOTORIST HAD KNOCK ONTO MY LEFT SIDE MIRROR OF THE VEHICLE. THE MOTORIST LOST HIS BALANCE OF HIS MOTORBIKE AND FELL ONTO THE ROAD. I QUICKLY STOP MY VEHICLE ALONG LANE 1 AND QUICKLY MAKE A CHECK ON THE MOTORIST. TWO MOTORIST THEN ALIGHTED AND ASSIST THE MOTORIST WHILE I CALL FOR AMBULANCE. SHORTLY AFTER AMBULANCE AND TRAFFIC POLICE ARRIVED. BEFORE THE MOTORIST WAS CONVEYED TO THE HOSPITAL, I MANAGE TO GET HIS CONTACT NUMBER : 81125871 HOWEVER WAS NOT ABLE TO GET MORE DETAILS. THE TRAFFIC POLICE THEN ASKED FOR MY IN VEHICLE CAMERA AND I PROVIDED THE SD CARD TO THE TRAFFIC POLICE. I WAS ADVICE TO LODGE A TRAFFIC POLICE REPORT. I WISH TO INFORM THE ONLY DAMAGE TO MY VEHICLE WAS LEFT SIDE MIRRORS.

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	PENDING FROM INSURED
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	UNKNOWN
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	MOTORCYCLE
Name of Driver	UNKNOWN
NRIC/Passport Number	



Contact Number	81125871
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF INJURED PERSON 1	
-----------------------------	--

Name	UNKNOWN
Approximate Age	
Injuries Sustain	
Injured person in which vehicle?	UNKNOWN
Were seat belts worn?	
Was this injured conveyed to hospital by ambulance?	YES
Address	
Postcode	

### SINGAPORE ACCIDENT STATEMENT

#### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

#### ACCIDENT STATEMENT

Date Of Report	08/03/2019 16:18
Date Of Accident	27/02/2019 21:15
Exact Location Of Accident	BKE TWDS WOODLANDS AT EXIT 8 FLYOVER
Country/State of Loss	SINGAPORE

#### DETAILS OF OWN VEHICLE

Vehicle Registration Number	FBH3168P
<b>Insured/Policyholder</b>	
Name Of Registered Owner	MUHYIDDEEN GHANI BIN N SYED PULAVAR
NRIC No	S9335916Z
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-81125871
Alternative Phone No	OFFICE-81125871

#### Vehicle Particulars

Manufacturer	HONDA
Model	CB400
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	MOTORCYCLE

#### Insurance Company

Name of Insurance Company	EQ INSURANCE COMPANY LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	NO
Policy Number	DMMPHQ18-000969
Cover Note Number	

#### Driver

Name of Driver	MUHYIDDEEN GHANI BIN N SYED PULAVAR
NRIC No	S9335916Z
Date Of Birth	24/09/1993
Occupation	INDOOR
Date Of Driving Pass	22/09/2017
Driving Experience	1 YEAR AND 5 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-81125871
Fax Number	
Contact Number	OFFICE-81125871
EMail Address	NOEMAIL

Address	BLK 731 CLEMENTI WEST ST 2 #09-316
Postcode	120731
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - CHANGE/CROSS LANE
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	TRAFFIC POLICE DIVISION HQ
Police Station Address	ROAD: 10 UBI AVENUE 3 , POSTCODE: 408865 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 65470000 - FAX NO:
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

REFER TO POLICE REPORT: T/20190301/2052.

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJH8412G
Vehicle Make/Model/Colour	
Details Of Properties	VEHICLE B
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

No. Of Passenger (Including Driver)

**DETAILS OF INJURED PERSON 1**

Name	MUHYIDDEEN GHANI BIN N SYED PULAVAR
Approximate Age	
Injuries Sustain	
Injured person in which vehicle?	FBH3168P
Were seat belts worn?	
Was this injured conveyed to hospital by ambulance?	
Address	
Postcode	

Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.


**8. Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

  
Policyholder's Signature

Date & Time: 6/3/2019  
1.05pm

  
Driver's Signature  
(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

### SKETCH PLAN

SKETCH PLAN

EXIT  
8

BKE TWDS WOODLANDS

B A

A: FBH3168P  
B: SJH8412G

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

AS PER POLICE REPORT

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time: 6/3/2019 1:05pm

GLAUCOMA Screening Form, 5/3

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:



**SINGAPORE  
POLICE FORCE**



T/20190301/2052

Police Station Of Origin:  
Traffic Police  
10 Ubi Avenue 3 SINGAPORE 408865  
Tel No: 65470000

1 of 3

Report No. T/20190301/2052

**REPORT OF A TRAFFIC ACCIDENT**

Date/Time Report Made: 01/03/2019 12:43	Vide Report No.:	Station Diary No.:
--	------------------	--------------------

**Informant's Particulars**

Name of Informant: MUHYIDDEEN GHANI BIN N SYED PULAVAR			Address: APT BLK 731 CLEMENTI WEST STREET 2 #09-316 SINGAPORE 120731		
ID Type / ID No.: NRIC NO / S9335916Z			Contact No.: Home/Office: Mobile: 81125871		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 25	Date of Birth: 24/09/1993	Type of Informant: Rider		
Race: Indian			Language:		Institution / School Name:
Occupation: ICA OFFICER			Driving Licence Information: Class: 2B,2A Date of Expiry:		

**General Information of the Accident**

General Information of the Accident				
Type of Accident:	Injury Attended by Police	Drink Drive: No	Date/Time of Accident: 27/02/2019 21:15	Type of Location: Straight Road
Location: Along Road 1 BUKIT TIMAH EXPRESSWAY  BKE TOWARDS WOODLANDS AT EXIT 8 FLYOVER				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow: One Way		Traffic Control: Not Controlled		Traffic Volume: Light
Type of Collision: Between Moving Vehicles - Head To Side				Anyone conveyed by ambulance: Yes

**Details of Vehicle Involved**

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
FBH3168P	Motorcycle				Slightly Damaged	0
SJH8412G	Car				Slightly Damaged	0

**Details of Person Involved**

Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA



## Sketch Plan #4 Pg. 1



**SINGAPORE  
POLICE FORCE**



T/20190301/2052

Police Station Of Origin:  
Traffic Police  
10 Ubi Avenue 3 SINGAPORE 408865  
Tel No: 65470000

2 of 3

Report No. T/20190301/2052

## CONTINUATION OF REPORT

Rider			
Name	MUHYIDDEEN GHANI BIN N SYED PULAVAR	ID No.	S9335916Z
Related Vehicle	NIL	Contact No.	81125871
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 2B/2A Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

**Brief Details.**

On the above mentioned date time and location

I was travelling along the said BKE going towards Woodlands exit 8 flyover. This is a 3 lane straight road. I was on the 1st lane riding. The vehicle which was from the 2nd lane, cut over to my lane. This resulted in head to side collision. I was then admitted to Khoo Teck Puat Hospital and was given 4 days mc from 27 February to 2 March 2019.



**SINGAPORE  
POLICE FORCE**



T/20190301/2052

Police Station Of Origin:  
Traffic Police  
10 Ubi Avenue 3 SINGAPORE 408865  
Tel No: 65470000

3 of 3

Report No. T/20190301/2052

**CONTINUATION OF REPORT**

**Sketch Plan**

Informant is not able to provide sketch plan

**IMPORTANT:** Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report: TP / NG JIN SHENG	Signature Of Informant:
Signature Of Interpreter: Not applicable	Date/Time: 01/03/2019 12:43
Officer In Charge Of Case: TP / GIT / Staff Sgt MOHAMED HUSNUL TAUFIQ BIN MD YUSOF Contact No.: 65476358	Classification Of Case:
Authentication Stamp NP168	

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	28 Feb 2019 <a href="#">Edit Reg</a>		14 Mar 2019 00:00 <a href="#">Edit Adj Rpt</a>	<b>S\$0.00</b> <a href="#">Edit Estimates</a>	<b>S\$0.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by adjuster]</span>									
Insured: <b>Jason Heng</b> , ID: S7923054E									
Main Claimant: <b>MUHYIDDEEN GHANI BIN N SYED PULAVAR</b> , ID: S9335916Z									
Vehicle Reg. No.: <b>FBH3168P</b>		Date of Loss: 27/02/2019 21:00 - :59 [69 Months and 14 Days From LTA Reg Date (Man Yr)]							
Claim Type: <b>TP / 1201900005588</b>		Policy/Cover Note No.: PNPV2019-00000546							
Vehicle Reg. No. (Insured): <b>SJH8412G</b>		Policy No. (Claimant):							
		Excess:							
Repairer: <b>Trikrystal Aerospace (HQ)</b> 259 Macpherson Road, 348584 Macpherson - Tel: 98615303									
Handling Insurer: <b>FWD Singapore Pte. Ltd. (HQ)</b> - Tel: 6727 5700 ... [Handled by <b>Lionel Tan</b> ]									
Adjuster: <b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>XING GUO QIANG</b> ] ... [Final Rpt due 26/03/2019]									
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

\*FBH3168P (1201900005588)

[SJH8412G]

TP




















MUHYIDDEEN GHANI BIN N SYED PULAVAR

Feb 27 2019 9:00PM

[Jason Heng]

Trikristal Aerospace

Upload Documents			Upload Photos		Compose New Letter		View		View in Browser	
Photos/Images								3 per page		<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print					
1	18/03/19 10:00	General View		Load JPG	<input checked="" type="checkbox"/>					
2	18/03/19 10:00	General View		Load JPG	<input checked="" type="checkbox"/>					
3	18/03/19 10:00	General View		Load JPG	<input checked="" type="checkbox"/>					
4	18/03/19 10:00	General View		Load JPG	<input checked="" type="checkbox"/>					
5	18/03/19 10:00	General View		Load JPG	<input checked="" type="checkbox"/>					
6	18/03/19 10:00	General View		Load JPG	<input checked="" type="checkbox"/>					
7	18/03/19 10:00	General View		Load JPG	<input checked="" type="checkbox"/>					
8	18/03/19 10:00	General View		Load JPG	<input checked="" type="checkbox"/>					
9	18/03/19 10:00	General View		Load JPG	<input checked="" type="checkbox"/>					
10	18/03/19 10:00	General View		Load JPG	<input checked="" type="checkbox"/>					
11	18/03/19 10:00	General View		Load JPG	<input checked="" type="checkbox"/>					
12	18/03/19 10:00	General View		Load JPG	<input checked="" type="checkbox"/>					
13	18/03/19 10:00	General View		Load JPG	<input checked="" type="checkbox"/>					
14	18/03/19 10:00	General View		Load JPG	<input checked="" type="checkbox"/>					
15	18/03/19 10:00	General View		Load JPG	<input checked="" type="checkbox"/>					
16	18/03/19 10:00	General View		Load JPG	<input checked="" type="checkbox"/>					
17	18/03/19 10:00	General View		Load JPG	<input checked="" type="checkbox"/>					
18	18/03/19 10:00	General View		Load JPG	<input checked="" type="checkbox"/>					
19	18/03/19 10:00	General View		Load JPG	<input checked="" type="checkbox"/>					
20	18/03/19 10:00	General View		Load JPG	<input checked="" type="checkbox"/>					
21	18/03/19 10:00	General View		Load JPG	<input checked="" type="checkbox"/>					
22	18/03/19 10:00	General View		Load JPG	<input checked="" type="checkbox"/>					
23	18/03/19 10:00	General View		Load JPG	<input checked="" type="checkbox"/>					
24	18/03/19 10:00	General View		Load JPG	<input checked="" type="checkbox"/>					
25	18/03/19 10:00	General View		Load JPG	<input checked="" type="checkbox"/>					
26	18/03/19 10:00	General View		Load JPG	<input checked="" type="checkbox"/>					
27	18/03/19 10:00	General View		Load JPG	<input checked="" type="checkbox"/>					
28	18/03/19 10:00	General View		Load JPG	<input checked="" type="checkbox"/>					
29	18/03/19 10:00	General View		Load JPG	<input checked="" type="checkbox"/>					
30	18/03/19 10:00	General View		Load JPG	<input checked="" type="checkbox"/>					
31	18/03/19 10:00	General View		Load JPG	<input checked="" type="checkbox"/>					
32	18/03/19 10:00	General View		Load JPG	<input checked="" type="checkbox"/>					
33	18/03/19 10:00	General View		Load JPG	<input checked="" type="checkbox"/>					
34	18/03/19 10:00	General View		Load JPG	<input checked="" type="checkbox"/>					
35	18/03/19 10:00	General View		Load JPG	<input checked="" type="checkbox"/>					
36	18/03/19 10:00	General View		Load JPG	<input checked="" type="checkbox"/>					
37	18/03/19 10:00	General View		Load JPG	<input checked="" type="checkbox"/>					

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	18/03/19 10:00	General View	 Load JPG	<input checked="" type="checkbox"/>
39	18/03/19 10:00	General View	 Load JPG	<input checked="" type="checkbox"/>
40	18/03/19 10:00	General View	 Load JPG	<input checked="" type="checkbox"/>
41	18/03/19 10:00	General View	 Load JPG	<input checked="" type="checkbox"/>
42	18/03/19 10:00	General View	 Load JPG	<input checked="" type="checkbox"/>
43	18/03/19 10:01	Chassis Number	 Load JPG	<input checked="" type="checkbox"/>
44	18/03/19 10:01	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
45	18/03/19 10:01	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
46	18/03/19 10:01	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
47	18/03/19 10:01	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
48	18/03/19 10:01	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
49	18/03/19 10:01	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
50	18/03/19 10:01	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
51	18/03/19 10:01	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
52	18/03/19 10:01	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
53	18/03/19 10:01	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
54	18/03/19 10:01	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
55	18/03/19 10:01	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
56	18/03/19 10:01	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>

## Documents Checklist

<b>DOCUMENTS CHECKLIST</b>	Reset	Save	Print
There are no document checklists configured.			

<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/FWD19004633/GCD3E2

Date: 21/03/2019

## REFERENCE

Handling Insurer: FWD Singapore Pte. Ltd. Policy No: PNPV2019-00000546

Claimant Vehicle No: FBH3168P Insured Vehicle No: SJH8412G

Date of Loss: 27/02/2019 Nature of Claim: TP Claim No: 1201900005588

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: **FBH3168P**  
 Make & Model: HONDA CB 400 F3WYB, 399cc (M) Engine No: NC42E1124249  
 Reg. Date: 13/05/2013 (Man. Year: 2013) Chassis No: JH2NC4294BK300428  
 Colour: White Odometer: 0 km  
 Engine Capacity: 399 cc  
 Market Value/New Car Price: N/A  
 Sum Insured (S\$): **Market Value/New Car Price**

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size: 120/60Z R17 Rear Tyre Size: 160/60Z R17  
 Front Left Side: Pirelli 4 mm Rear Left Side: Pirelli 4 mm  
 Front Right Side: 0 mm Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

## INSPECTION

Date of Assignment: 14/03/2019

Date Inspected: 14/03/2019 Inspected At:

1 KAKI BUKIT AVE 6 # 02-35

Repairer : Trikristal Aerospace (HQ)

Estimated Period of Repair: 3.0 days

Adjuster: XING GUO QIANG

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.  
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,000.00 -\$4,000.00



## REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 21 Mar 2019)	
Parts:	N/A	HONDA CB 400 F3WYB 399cc (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for FBH3168P)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.
---

< END OF ESTIMATES >