



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
80 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 05/04/2019

User ID : CatherineLee

Vic Finalized - HJ

Section A - Accident Details

Registration Number	SMB227Z
Case Reference Number	BUS/03/19/1028
Registration Date	14/12/2011
Company Type	SMRT Buses Ltd
Make	MAN
Model	A22
Name of Driver	Tan Kok Chye
Type of Accident	Open Door Case
Accident Date and Time	10/3/2019 3:28 PM
Accident Reported Date and Time	12/3/2019 10:54 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle Issued?	No
Job Card Number	24100577
Special Instruction to ARC, if any	SMB227Z - REAR DOOR SHA1161L (TP) - COMFORT TAXI. INSURED WITH III. RIGHT PORTION
Prepared Date and Time	12/3/2019 1:28 PM
Chassis Number	WMAA22Z1B7001201
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$2,120.00	\$1,325.00
Total Spray Cost	\$786.00	\$446.00
Total Spare Part Cost	\$14,904.00	\$14,904.00
Total Other Cost	\$0.00	\$0.00
TOTAL COST	\$17,810.00	\$16,675.00
Lump Sum Total	\$17,800.00	\$16,700.00
Number of Repair Days	5.0	4.0
Prepared / Adjusted By	Kok Khoon Goh	Hwee Jie
ARC / Surveyor Sign Off Date	13/03/2019 11:12 AM	13/03/2019 4:02 PM
Signature		LKK
Remarks		

Section C - Quotation and Accident Invoice Details

Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 05/04/2019

User ID : CatherineLee

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS	\$2,120.00	\$1,325.00
Total Labour	\$2,120.00	\$1,325.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS	\$786.00	\$446.00
Total Spray Painting & Panel Beating	\$786.00	\$446.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Other Costs		

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
6010001	BODY LH	A01001-CW557	PANEL, SIDE L7, FOR MAN A22 BUS	1.00	\$330.70	100.00	\$0.00	Repair	Repair
6010003	BODY LH	A01001-CW558	PANEL, SIDE L9, FOR MAN A22 BUS	1.00	\$248.20	100.00	\$0.00	Repair	Repair
6010005	BODY LH	A01001-CW562	PANEL, SIDE L12, FOR MAN A22 BUS	1.00	\$247.30	100.00	\$0.00	Repair	Repair
6010060	Body	F01001-CW271	COVER, REAR TAIL LAMP, LH, FOR MAN A22 BUS	1.00	\$974.70	100.00	\$0.00	Repair	Repair
6010457	DOOR		LEAF ASSY, REAR DOOR, FOR MAN A22 BUS	1.00	\$20,700.00	10.00	\$18,630.00	Replace	Replace
Total					\$22,500.90		\$18,630.00		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

L/S \$16,700/- 4 days.