



Your Ref: AEMD/105/009/2016/007

Date: 15<sup>th</sup> March 2019

Our Ref: CS1/SPF19004656/Dvd3s2

**M/s Automotive Engineering & MGT Division**

Accident Claim Section (Singapore Police Force)

1 Mount Pleasant Road

Blk 8 Old Police Academy

Singapore 298333

Attn: Hafizul Farhan

Dear Sir / Madam,

**EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: SJA 4068E  
INSURED VEHICLE: QX 587X ACCIDENT DATE: 18/01/2016**

We thank you for your instruction on 13/03/2019.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SJA 4068E from M/s Motor Image Enterprises Pte Ltd.
- b) Final Repair Bill of SJA 4068E from M/s Motor Image Enterprises Pte Ltd.
- c) Singapore Accident Statement of Vehicles SJA 4068E.
- d) Colour damaged vehicle photographs of SJA 4068E.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number	: SJA 4068E
Make & Model	: Subaru 2.5 WRX
Year of Registration	: 2007
Chassis Number	: JF1GDGKD37G071906
Engine Capacity	: 2457 cc

2. We recommend that the repairs of the entire damage require about 4 (Four) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.