

ASS. REC. BY:

REF: CS31SM019004660/T1cd302 Special Instruction:

Surveyor Tau Fik
Mu Min

ASSIGNMENT (Office)

From (Person): Hwang Shiang Yi of Smo (Somp)Date/Time: 14-MAR-2019 12:14 PM

Estimated Cost: _____ Bill to: _____

OD / ☒ TP / WS / TP RES / OD RES / EVA / INV / MY / CSTo Inspect Vehicle No: GBE 7793ZInsured: YP8040Bat Workshop m/s Lys Engineering (Jurong)

Tel: _____

of JTA Jurong Port Road 619101Policy No: D18MTHCVC 003071Claim No: CMTD1901329

Sum Insured: _____

Excess: _____

Make of Veh:
(Client's Record)D.O.A. 13.3.2019

CA / REV / REP. / REV 24 HRS

1/rwp)

H.O.D. Endorsement: _____

Date/Time: 14-3-2019 2.17 PM Person Contacted: STEVENVehicle ☒ IN ☐ OUT

Date/Time	Action/Instruction (✓) Estimate
	<u>GBE 7793Z - X</u>
	<u>YP 8040B - X</u>
	<u>Re-survey: 2/4/2019 (disassemble)</u>


J

Taufik

SMO

REGISTRATION

Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To inspect Vehicle No: _____
 at Workshop no: _____
 of: _____
 Incident: _____
 Policy No: _____
 Claim No: _____
 Sum Insured: _____
 Excess: _____
 (Claim's Record)
 Make of Veh: _____



(Policy Condition)
 Remark: The veh had commenced its repair at the time of inspection.

Est. or Market Value: _____
 IDAC Accident Report Consistent? - Yes or No
 GIA / DR Seen Consistent? - Yes or No
 Est. Repairs days Res.: Yes or No
 Lump sum % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: **GRE 77932** to Regd: **Mar 16**
 Type: M/Car / B/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: **Nissan NV 350** CC: **2488**
 Color: **Blue** A/C: _____ Insured / Std / Nil / NA
 Sp Reading: **169416** Btadde Insured / Std / Nil / NA
 Engine No: **JN1MC2E26Z 0005718**
 Chassis No: _____
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Inoper / Jammed / Leaked / Burnt or
 Brake: Inoper / Jammed / Leaked / Burnt or
 Mod: **Nil / SRim / STD ARim or**
 Tyre Size F: **195/RC17**
 R: _____

BS / DUN / EXNOVA / GY / ES / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or **Linam.**

Front Rear
 R/Bal: **6** mm R/Bal: **6** mm
 L/Bal: **6** mm L/Bal: **6** mm
 D.O.A. D.O.I.
 Survey held at **lys** **14/3/19c 320pm**
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time: _____ Action / Instruction: **No GIA - \$4000 \$5000, 5 days**

Date/Time File Pass to: ☐ : Proh. Report
 Date/Time File Return to: ☐ : Final Report

Days Of Repair: **5**
 Resurvey No. of Trip: **1**

Add Fee: ☐ Site Insp. (\$) ☐
☐ Interview (\$) ☐
☐ Team Insp. (\$) ☐
☐ Weekend (\$) ☐

Survey Fee: _____
 Transportation: _____
 Hotel: _____
 Meals: _____
 Total: _____

100
60
10
170

Report Format: **PRS**
 Lump Sum / LBT: **0**

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	13 Mar 2019		14 Mar 2019 12:14 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	CHC EXPRESS PTE LTD, Co. Reg. No.: 199003360M		
Main Claimant:	SG SAGAWA AMEROID PTE. LTD., Co. Reg. No.: 199100423D		
Vehicle Reg. No.:	GBE7793Z	Date of Loss:	13/03/2019 09:00 - :59
Claim Type:	TP / CMTD1901329	Policy/Cover Note No.:	D18MTHCVE003071 (Comprehensive)
Vehicle Reg. No. (Insured):	YP8040B	Policy No. (Claimant):	
		Excess:	
Repairer:	Lys Engineering (JURONG) 27A JURONG PORT ROAD, 619101 Jurong East - Tel:		
Handling Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by Hwang Shiang YI - 6329 5205]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 25/03/2019]		
Adj Asg. Remarks:	WS: STEVEN LOO 97308695 -PLEASE BE INFORMED THAT OUR INSURED HAS NOT REPORTED THE ACCIDENT -NO TP SAS SUBMITTED		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

2-17pm
 Veh: ✓
 Steven
 finished
 est: ✓

[> Back to OneMotoring](#)

Enquire Transfer Fee

Vehicle Details			
Vehicle No. :	GBE7793Z		
Vehicle Type :	A50 - Goods (Closed) Van/Van Panel (Delivery)		
Vehicle Attachment 1 :	No Attachment		
Vehicle Scheme :	Normal		
Vehicle Make :	NISSAN		
Vehicle Model :	NV350 PANEL VAN 2.5 5AT 5DR EURO V		
Chassis No. :	JN1MC2E26Z0005768		
Propellant :	Diesel		
Engine No. :	YD25387539A		
Engine Capacity :	2488 cc		
Maximum Power Output :	-		
Maximum Laden Weight :	3300 kg		
Unladen Weight :	1800 kg		
Year Of Manufacture :	2015		
Original Registration Date :	28 Mar 2016		
Lifespan Expiry Date :	27 Mar 2036		
COE Category :	C - Goods Vehicle & Bus		
Quota Premium :	\$45,001.00		
COE Expiry Date :	27 Mar 2026		
Road Tax Expiry Date :	27 Mar 2020		
Inspection Due Date :	27 Mar 2020		
Intended Transfer Date :	22 Mar 2019		
CO2 Emission :	219.00 (g/km)		
CEV/VES Rebate Utilised Amount :	-		
CO Emission :	-		
HC Emission :	-		
NOx Emission :	-		
PM Emission :	-		
Late renewal fee(s) will be imposed if road tax / lay up has expired. Please use Enquire Road Tax Payable for fee(s) payable.			
Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.			
Amount Payable			
	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee :	25.00	-	25.00
Total Amount Payable :			25.00

You may print this page for reference.

OK

Print

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	0423D
Vehicle Details	
Vehicle No.:	GBE7793Z
Vehicle to be Exported:	No
Intended Deregistration Date:	22 Mar 2019
Vehicle Make:	NISSAN
Vehicle Model:	NV350 PANEL VAN 2.5 5AT 5DR EURO V
Primary Colour:	White
Manufacturing Year:	2015
Engine No.:	YD25387539A
Chassis No.:	JN1MC2E26Z0005768
Maximum Power Output:	-
Open Market Value:	\$23,098.00
Original Registration Date:	28 Mar 2016
First Registration Date:	28 Mar 2016
Transfer Count:	0
Actual ARF Paid:	\$1,155.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	27 Mar 2026
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$45,001.00
COE Rebate Amount:	\$31,561.00
Total Rebate Amount:	\$31,561.00

The information contained herein is correct as at 22 Mar 2019

OK

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	13 Mar 2019		14 Mar 2019 12:14 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	CHC EXPRESS PTE LTD, Co. Reg. No.: 199003360M								
Main Claimant:	SG SAGAWA AMEROID PTE. LTD., Co. Reg. No.: 199100423D								
Vehicle Reg. No.:	GBE7793Z	Date of Loss:	13/03/2019 09:00 - :59 [35 Months and 13 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / CMTD1901329	Policy/Cover Note No.:	D18MTHCVE003071 (Comprehensive)						
Vehicle Reg. No. (Insured):	YP8040B	Policy No. (Claimant):							
		Excess:							
Repairer:	Lys Engineering (JURONG) 27A JURONG PORT ROAD, 619101 Jurong East - Tel:								
Handling Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by Hwang Shiang Yi - 6329 5205]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 25/03/2019]								
Adj Asg. Remarks:	WS: STEVEN LOO 97308695 -PLEASE BE INFORMED THAT OUR INSURED HAS NOT REPORTED THE ACCIDENT -NO TP SAS SUBMITTED								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*GBE7793Z (CMTD1901329)
 [YP8040B]
 TP
 SG SAGAWA AMEROID PTE. LTD.
 Mar 13 2019 9:00AM
 [CHC EXPRESS PTE LTD]
 Lys Engineering

Upload Documents			Upload Photos		Compose New Letter		View		View in Browser	
Photos/Images							3 per page		<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print	
1	22/03/19 16:57	General View						Load JPG	<input checked="" type="checkbox"/>	
2	22/03/19 16:57	General View						Load JPG	<input checked="" type="checkbox"/>	
3	22/03/19 16:57	General View						Load JPG	<input checked="" type="checkbox"/>	
4	22/03/19 16:57	General View						Load JPG	<input checked="" type="checkbox"/>	
5	22/03/19 16:57	General View						Load JPG	<input checked="" type="checkbox"/>	
6	22/03/19 16:57	General View						Load JPG	<input checked="" type="checkbox"/>	
7	22/03/19 16:57	General View						Load JPG	<input checked="" type="checkbox"/>	
8	22/03/19 16:57	General View						Load JPG	<input checked="" type="checkbox"/>	
9	22/03/19 16:57	General View						Load JPG	<input checked="" type="checkbox"/>	
10	22/03/19 16:57	General View						Load JPG	<input checked="" type="checkbox"/>	
11	22/03/19 16:57	General View						Load JPG	<input checked="" type="checkbox"/>	
12	22/03/19 16:57	General View						Load JPG	<input checked="" type="checkbox"/>	
13	22/03/19 16:57	General View						Load JPG	<input checked="" type="checkbox"/>	
14	22/03/19 16:57	General View						Load JPG	<input checked="" type="checkbox"/>	
15	22/03/19 16:57	General View						Load JPG	<input checked="" type="checkbox"/>	
16	22/03/19 16:57	General View						Load JPG	<input checked="" type="checkbox"/>	
17	22/03/19 16:57	General View						Load JPG	<input checked="" type="checkbox"/>	
18	22/03/19 16:57	General View						Load JPG	<input checked="" type="checkbox"/>	
19	22/03/19 16:57	General View						Load JPG	<input checked="" type="checkbox"/>	
20	22/03/19 16:57	General View						Load JPG	<input checked="" type="checkbox"/>	
21	22/03/19 16:57	General View						Load JPG	<input checked="" type="checkbox"/>	
22	22/03/19 16:57	General View						Load JPG	<input checked="" type="checkbox"/>	
23	22/03/19 16:57	General View						Load JPG	<input checked="" type="checkbox"/>	
24	22/03/19 16:57	General View						Load JPG	<input checked="" type="checkbox"/>	
25	05/04/19 12:33	Reinspection Photo						Load JPG	<input checked="" type="checkbox"/>	
26	05/04/19 12:33	Reinspection Photo						Load JPG	<input checked="" type="checkbox"/>	
27	05/04/19 12:33	Reinspection Photo						Load JPG	<input checked="" type="checkbox"/>	
28	05/04/19 12:33	Reinspection Photo						Load JPG	<input checked="" type="checkbox"/>	
29	05/04/19 12:33	Reinspection Photo						Load JPG	<input checked="" type="checkbox"/>	
30	05/04/19 12:33	Reinspection Photo						Load JPG	<input checked="" type="checkbox"/>	
31	05/04/19 12:33	Reinspection Photo						Load JPG	<input checked="" type="checkbox"/>	
Documentation							1 per page		<input checked="" type="checkbox"/>	
No	Finalized On	Sompo Insurance Singapore Pte. Ltd. (HQ)						Thumbnail	Print	
1	13/03/19 16:31	PRI FR LYS ENGINEERING - GBE7793Z						Load PDF		
2	14/03/19 12:15	Pre-Repair Survey/ BONNIE KWOK LLC - ASSIGN LKK						Load PDF		

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)
<div></div>
Show Remarks To: <input type="checkbox"/> Handling Insurer
<small>Note: Remarks are private unless you show it to other parties.</small>

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/SMO19004660/T1CD3E2

Date: 02/05/2019

REFERENCE

Handling Insurer:	Sompo Insurance Singapore Pte. Ltd.	Policy No:	D18MTHCVE003071
Claimant Vehicle No :	GBE7793Z	Insured Vehicle No :	YP8040B
Date of Loss:	13/03/2019	Nature of Claim:	TP
		Claim No:	CMTD1901329

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBE7793Z	Engine No:	YD25387539A
Make & Model:	NISSAN NV350, 2.5 5AT 5DR EURO V (A)	Chassis No:	JN1MC2E26Z0005768
Reg. Date:	28/03/2016 (Man. Year: 2015)	Odometer:	169416 km
Colour:	Blue		
Engine Capacity:	2488 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195 R15	Rear Tyre Size:	195 R15
Front Left Side:	LINAM 6 mm	Rear Left Side:	LINAM 6 mm
Front Right Side:	LINAM 6 mm	Rear Right Side:	LINAM 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:	14/03/2019		
Date Inspected:	14/03/2019	Inspected At:	Lys Engineering (JURONG) 27A JURONG PORT ROAD Singapore 619101
Estimated Period of Repair:	5.0 days		

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$4,000.00 -\$5,000.00

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 02 May 2019)

Parts: N/A NISSAN NV350 2.5 5AT 5DR EURO V (A) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for GBE7793Z)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >