

ASS. REC. BY:

REF: CS/FWD19004661/Evd 302

Special Instruction:

SUNVAJOY

Steve

ASSIGNMENT (Office)

merimen

From (Person): Lionel Tan

of FWD

Date/Time: 13-Mar-2019 14:12 p.m.

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SEA 4999G

Insured:

at Workshop m/s Vin's Motor Pte Ltd (Sin ming)

Tel: 64532121

of 160 Sin ming Drive, # 03-03

Policy No: PNPV2018-00011243

Claim No: 1201900006518

Sum Insured:

Excess: \$500.00

Make of Veh:

(Client's Record)

D.O.A. 12.3.2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 14.3.2019 10:11am

Person Contacted:

Raymond

Vehicle IN / OUT

Date/Time

Action/Instruction (✓) Estimate

SEA 4999G - X

15/3/19

@ 1009am Informed Raymond hold back authorise

15/3/19

Revert via merimen

15/3/19

Recd approved \$ 6290 from Lionel by merimen

15/3/19

Informed Raymond c/A ex \$500 by email

Steve

REF: FWP

ASSIGNMENT

From: Date: 14/3/19

Estimated Cost:

☒ OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SKA 4999G

at Workshop m/s Vin's Motor of 160 Sin Ming Drive # 03-03

Insured:

Policy No.

Claims No

Sum Insured: Excess: \$ 500.00

(Client's Record)

Make of Veh:

Morning Raymond

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res: Yes or No

Lump Sum: % 3 Val: Yes or No

CA / ☒ REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SKA 4999G Yr Regn: 28/03/2013

Type: ☒ Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: BMW 116 C.C. 1598

Colour: Black A/C: Insured / Std / NI / NA

Sp. Reading: 70479 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: WBA 1A12070 VV 24623

Gen. Cond: ☒ Good / Fair / Poor / Burnt

Steering: ☒ Inorder / Jammed / Leaked / Burnt or

Brake: ☒ Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 225/45R17

R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Firelli

Front

R/Bal. 7 mm R/Bal. 7 mm

L/Bal. 7 mm L/Bal. 7 mm

D.O.A. 12/3/19 D.O.I. 14/3/19

Survey held at

Des. of Damages: Frt / Rear ☒ O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

MV- 52,000
PV- 45,989
NV- 6918

RECEIVED 26 APR 2019

25/4/19 Final \$7530, 5 days (Red 600, 790)

26/4/2019

Date/Time: File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time: File Return to?

2) 26/4 - typist

Report Format: merimen

Lump Sum / I.B.I: (\$ 7530)

Days Of Repair: 5

Resurvey No. of Trip: 1

Add Fee: ☐ : Site Insp (\$

☐ : Interview (\$

☐ : Tech. Invs (\$

☐ : Weekend (\$

Survey Fee:

Transportation

\$ + RS. \$

Photos

Others

TOTAL

200

50

50

10

310

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rat	Adj Submitted	Ins Auth'd	Status
Main	13 Mar 2019 Sendback Est	13 Mar 2019 14:12 S\$7,510.00	13 Mar 2019 15:14 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS

Insured:	TAY SWEE MENG, DAVID, ID: S8231557H, Tel: +6590068299, Email: davidtay007@gmail.com		
Vehicle Reg. No.:	SKA4999G	Date of Loss:	12/03/2019 09:00 - :59 [71 Months and 12 Days From LTA Reg Date (Man Yr)]
Claim Type:	OD / 1201900006518	Policy/Cover Note No.:	PNPV2018-00011243 (Comprehensive)
		Excess:	S\$500.00
Repairer:	Vin's Motor Pte Ltd (Sin Ming) 160 Sin Ming Drive, #03-03, Sin Ming AutoCity, 575722 Sin Ming - Tel: 64532121		
Handling Insurer:	FWD Singapore Pte. Ltd. (HQ) - Tel: 6727 5700 ... [Handled by Lionel Tan]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 22/03/2019]		
Driver/Custodian:	TAY SWEE MENG, DAVID (36 / Male), NRIC: S8231557H, Tel: +6590068299 Email: davidtay007@gmail.com		

ASSOCIATED MAIL RECEIVED

[View All](#)
[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

vph ✓
 Raymond
 10-11am
 SUR Steve

View Received Message

This mail is associated with :

SKA4999G (1201900006518)

OD

Mar 12 2019 9:00AM

[TAY SWEE MENG, DAVID]

Vin's Motor Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From FWD Singapore Pte. Ltd. (HQ) (FWD_SG), sent on 25/04/2019 13:13 PM.

To LKK_HQ

Subject Alert - Adj Mandate Approved (S\$7530.00) - SKA4999G - Claim Handler: Lionel Tan

Approved:7530.00.

DOCUMENTS SUMMARY

There are no documents.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To:	FWD Singapore Pte. Ltd. 6 Temasek Boulevard #18-01 Suntec Tower 4 Singapore 038986	From:	LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933
Attn:	Lionel Tan	Date:	25 Apr 2019

Preliminary Advice

Vehicle No	: SKA4999G	Accident Date	: 12/03/2019
Make	: BMW 116I	Policy No.	: PNPV2018-00011243
Assignment Date	: 13/03/2019	Excess	: S\$500.00
Date of Inspection	: 14/03/2019	Est. Duration of Repair	: 5.00
Inspection At	VIN'S MOTOR PTE LTD (SIN MING) 160 SIN MING DRIVE, #03-03, SIN MING AUTOCITY SINGAPORE 575722		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages o/s body and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	8,130.00 (incl.supplementary \$620.00)
Revised Amount	:S\$	7,530.00 (incl.supplementary \$620.00)
Total	:S\$	7,530.00
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	52,000.00
COE / PARF Rebate	:S\$	45,082.00
Salvage Value	:S\$	
Margin for Repair	:S\$	6,918.00

Remarks

() The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.

() The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

() Other comments :

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Friday, 15 March 2019 3:42 PM
To: admin; SUR
Subject: SKA 4999G-DOA: 12/3/2019 (FWD OD)

Dear Raymond,

As instructed by our client , please proceed to repair the **insured vehicle SKA 4999G (Excess \$500/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

View Received Message

This mail is associated with :

SKA4999G (1201900006518)

OD

Mar 12 2019 9:00AM

[TAY SWEE MENG, DAVID]

Vin's Motor Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From FWD Singapore Pte. Ltd. (HQ) (FWD_SG), sent on 15/03/2019 13:02 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$6290.00) - SKA4999G - Claim Handler: Lionel Tan

Approved:6290.00.

DOCUMENTS SUMMARY

There are no documents.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: FWD Singapore Pte. Ltd.
6 Temasek Boulevard
#18-01 Suntec Tower 4
Singapore 038986From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Lionel Tan

Date: 15 Mar 2019

Preliminary Advice

Vehicle No	: SKA4999G	Accident Date	: 12/03/2019
Make	: BMW 116I	Policy No.	: PNPV2018-00011243
Assignment Date	: 13/03/2019	Excess	: S\$500.00
Date of Inspection	: 14/03/2019	Est. Duration of Repair	: 5.00
Inspection At	: VIN'S MOTOR PTE LTD (SIN MING) 160 SIN MING DRIVE, #03-03, SIN MING AUTOCITY SINGAPORE 575722		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages o/s body and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	7,510.00
Revised Amount	:S\$	5,380.00
Check Items (Estimated)	:S\$	910.00
Total	:S\$	6,290.00

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	52,000.00
COE / PARF Rebate	:S\$	45,082.00
Salvage Value	:S\$	
Margin for Repair	:S\$	6,918.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :

Nivitha (LKK Auto)

From: lionel.tan@fwd.com
Sent: Thursday, 14 March 2019 1:59 PM
To: assignments@lkkauto.com; sur@lkkauto.com
Cc: motorclaims.sg@fwd.com
Subject: FW: Notice of PRI of vehicle SDQ 9779 R // FWD - SJS2927U
Attachments: FW: Notice of PRI of vehicle SDQ 9779 R (26.9 KB)

[Policy Number: PNPV2018-00003175-01]

Hi LKK Team,

Please arrange PRI with repairer.

Refer to attached workshop details.

Regards,
Lionel

From: Lionel Tan Tian Pei - SGUser
Sent: Thursday, March 14, 2019 1:01 PM
To: 'Mdm Ling'
Cc: Motor Claims SG - SG Common; 'Ling Leong Hui'
Subject: RE: Notice of PRI of vehicle SDQ 9779 R // FWD - SJS2927U

WITHOUT PREJUDICE

Dear Sir/ Madam,

Please advise your clients contact and workshop location.

Thank you.

Regards,
Lionel

From: Mdm Ling [<mailto:mdmling@tcmg.com.sg>]
Sent: Thursday, March 14, 2019 11:02 AM
To: Lionel Tan Tian Pei - SGUser
Cc: Motor Claims SG - SG Common; Ling Leong Hui
Subject: RE: Notice of PRI of vehicle SDQ 9779 R // FWD - SJS2927U

WITHOUT PREJUDICE

Dear Sir,

We refer to the above matter and to your e-mail of even date.

Our client is not agreeable to any of your appointed panel of surveyors as the Single Joint Expert.

Our client's panel of surveyors nominated as the Single Joint Expert is as attached.

2:17pm
veh -
Mdm Ling
SJS2927U
est: X

Yours faithfully,

Mdm Ling
TOMMY CHOO MARK GO LLC

From: lionel.tan@fwd.com [mailto:lionel.tan@fwd.com]
Sent: Thursday, March 14, 2019 10:45 AM
To: mdmling@tcmg.com.sg
Cc: motorclaims.sg@fwd.com
Subject: [Spam-pop3] RE: Notice of PRI of vehicle SDQ 9779 R // FWD - SJS2927U

Without Prejudice

Dear Sir/Madam,

Please select one of our surveyors as follows: -

1. LKK AUTO CONSULTANTS PTE LTD
2. INFINITI APPRAISAL SERVICE
3. AJAX INSPECTION SERVICES PTE LTD
4. APPRAISALS ASSOCIATES PTE LTD
5. VICOM LTD

If you are not agreeable to any of the above, we would proceed to appoint a surveyor to conduct a pre repair survey & post repair inspection within the timeline stipulated under the NIMA protocol.

We look forward to your reply.

Thank you.

Lionel

From: Mdm Ling [mailto:mdmling@tcmg.com.sg]
Sent: Thursday, 14 March, 2019 8:58 AM
To: Motor Claims SG - SG Common
Subject: Notice of PRI of vehicle SDQ 9779 R

Dear Sir,

We refer to the above matter.

Attach herewith the notice of PRI of vehicle SDQ 9779 R for your attention.

Yours faithfully,

Mdm Ling
Tommy Choo Mark Go LLC

ATTENTION:

The email and any attachments transmitted with it are private and confidential and intended solely for the use of the individual or entity to whom they are addressed. If you have received this email in error, please notify the sender immediately and delete this email and any attachments from your system. You should not use, disclose, copy or store this email and any attachments.

Messages and attachments are scanned for all viruses known. However, you are advised that you open any attachments at your own risk. If this message contains password-protected attachments, the files have NOT been scanned for viruses by our mail domain. Please always scan for viruses before opening any attachments.

ATTENTION:

The email and any attachments transmitted with it are private and confidential and intended solely for the use of the individual or entity to whom they are addressed. If you have received this email in error, please notify the sender immediately and delete this email and any attachments from your system. You should not use, disclose, copy or store this email and any attachments.

Messages and attachments are scanned for all viruses known. However, you are advised that you open any attachments at your own risk. If this message contains password-protected attachments, the files have NOT been scanned for viruses by our mail domain. Please always scan for viruses before opening any attachments.

TOMMY CHOO, MARK GO LLC

Advocates & Solicitors

UEN NO : 201523418E

(a law corporation with limited liability)

151 CHIN SWEE ROAD #14-15/16

MANHATTAN HOUSE

SINGAPORE 169876

TEL : (65) 6532 2455

FAX : (65) 6538 9850 (Services of Court Documents By Fax Not Accepted)

EMAIL: lhling@tcmg.com.sg;mdmling@tcmg.com.sg

Our Ref: TCMG/SDQ9779R/0319/SLM

Your Ref: SJS 2927 U

14 March 2019

M/S FWD SINGAPORE PTE LTD

6 Temasek Boulevard

#18-01

Suntec Tower 4

Singapore 038986

BY E-MAIL ONLY
(motorclaims.sg@fwd.com)

Attn: Motor Claims Department

Dear Sirs,

PRE-REPAIR INSPECTION NOTICE

We act for **Cheng Gim Seng**, the owner and/or driver of motor vehicle no. **SDQ 9779 R**, which was involved in an accident along ECP towards City on 11 March 2019 at 07:10 hrs.

We hereby give you **NOTICE** that we are claiming against your Insured motor vehicle no. **SJS 2927 U** for damages and/or injuries, costs and disbursements as a result of your Insured's negligence.

Kindly let us know if you wish to conduct a pre-repair inspection on our client's motor vehicle at M/s S L Motor Repair, (c/o 1 Kaki Bukit Avenue 6 #01-107, Singapore 417883 - Ah Heng @ 91079182).

If we do not hear from you within the next **two (2) working days**, we shall deem that you have waived the requirement for the pre-repair inspection.

Yours faithfully,

MR LING LEONG HUI

cc. M/s SL Motor Repair
(Yref:SDQ9779R)

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	1557H
Vehicle Details	
Vehicle No.:	SKA4999G
Vehicle to be Exported:	No
Intended Deregistration Date:	14 Mar 2019
Vehicle Make:	B.M.W.
Vehicle Model:	116I AT ABS D/AIRBAG 2WD HID 5DR
Primary Colour:	Black
Manufacturing Year:	2013
Engine No.:	B184J430N13B16A
Chassis No.:	WBA1A12070VV24623
Maximum Power Output:	100.0 kW (134 bhp)
Open Market Value:	\$29,269.00
Original Registration Date:	28 Mar 2013
First Registration Date:	28 Mar 2013
Transfer Count:	2
Actual ARF Paid:	\$19,269.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	27 Mar 2023
PARF Rebate Amount:	\$13,488.00
Intended COE Rebate Details	
COE Expiry Date:	27 Mar 2023
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$78,301.00
COE Rebate Amount:	\$31,594.00
Total Rebate Amount:	\$45,082.00

The information contained herein is correct as at 14 Mar 2019

OK



ANNOUNCING Cosmo Automobiles

as sgCarMart Premium Dealer for the 4th Consecutive Year

COSMO
AUTOMOBILES

Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

[Post an Ad](#)
[Advertiser Login](#)
[Ways of Selling](#)

New 5 Years Coe Renewal Honda Stream 1.8A



2.88% P.A. Low Interest @ GY
Finance, 2 Years Warranty.
\$2500 Down Monthly From \$63
GV Credit Pte Ltd Started



VALUE FOR MONEY
VALUE FOR TIME
A PEACE OF MIND

HOTLINE: 6741 9997

[View our cars](#)
[Browse by Category](#)
[Sort by Date Posted](#)
[20 results/page](#)

4 vehicles

BMW 1

[Advanced Search](#)


	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	BMW 1		Any	Any	2013	Any	Any	Any	Available
	BMW 1 Series 116i Urban		\$51,800	\$10,890 /yr	27-Feb-2013	1,598 cc	69,000 km	Hatchback	Available
Asking Near To Export/Scrap Value! Well Maintained By Previous Lady Owner. Clean And Beautiful Interior And Exterior. Free Servicing Provided. Please Feel Free To Call Our Friendly Sales Consultants N... Car Lingual Posted: 14-Mar-2019 Tags: 2013 BMW 116i, 2013 bmw 116i, BMW 116i, bmw 116i, BMW, 116i, Used BMW									
	BMW 1 Series 116i		\$54,500	\$10,190 /yr	23-Aug-2013	1,598 cc	71,714 km	Hatchback	Available
Rare Pearl White BMW 116i At Amazing Low Depreciation Yet Price Negotiable! Low Mileage Clocked Of 13000km Annually. Superb Condition. 1 Lady Owner. Road Tax Till Aug 19. 100% Accident Free. Call Now! Lake View Credit Pte Ltd Posted: 09-Mar-2019 Tags: 2013 BMW 116i, 2013 bmw 116i, BMW 116i, bmw 116i, BMW, 116i, Used BMW									
	BMW 1 Series 116i		\$58,800	\$10,890 /yr	30-Aug-2013	1,598 cc	51,715 km	Hatchback	Available
Easy And Flexible In-House Loan And Balloon Scheme Available, No Gimmicks! High COE At \$77989, Auto Xenon Lights With LEDs DRL, Keyless Entry/Start, Cruise Control, Brown In Colour, Serviced And Maint... Posted: 01-Mar-2019 Tags: 2013 BMW 116i, 2013 bmw 116i, BMW 116i, bmw 116i, BMW, 116i, Used BMW									
	BMW 1 Series 116i		\$72,900	\$14,330 /yr	30-Aug-2013	1,598 cc	33,000 km	Hatchback	Available
Posted: 10-Feb-2019 Tags: 2013 BMW 116i, 2013 bmw 116i, BMW 116i, bmw 116i, BMW, 116i, Used BMW									

Save this search criteria, to get email alerts whenever a match is found.

Make Model Price Depreciation Reg Date Eng Cap Mileage Veh Type Status

For old advertisements, view [Expired ads](#)

20 results/page

[Home](#) | [New Cars](#) | [Used Cars](#) | [Sell My Car](#) | [Directory](#) | [Products](#) | [Insurance](#) | [Article](#) | [Forum](#) | [Resources](#)

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sedan cars, luxury cars, cars or stationwagons, SUV, MPV, hatchback, to COE cars & OPC cars. You can also buy from a car auction, look up car loans, financial services, low mileage cars, car brands, carpark rate insurance. Find buy used BMW 1, BMW 1 Singapore, used BMW 1 Singapore, used BMW 1, used vehicles Singapore or even buy used BMW 1 Singapore. We have new car dealers compare parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sites for job openings in Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

Compare

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	13/03/2019 09:30
Date Of Accident	12/03/2019 09:35
Exact Location Of Accident	ALONG IRWELL BANK ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKA4999G
Insured/Policyholder	
Name Of Registered Owner	TAY SWEE MENG, DAVID
NRIC No	S8231557H
Email Address	DAVIDTAY007@GMAIL.COM
Mobile Phone No	(LOCAL) +65-90068299
Alternative Phone No	OFFICE-90068299

Vehicle Particulars

Manufacturer	BMW
Model	116i AT ABS D/AIRBAG 2WD HID 5DR
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	FWD SINGAPORE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	PNPV2018-00011243
Cover Note Number	

Driver

Name of Driver	TAY SWEE MENG, DAVID
NRIC No	S8231557H
Date Of Birth	14/10/1982
Occupation	INDOOR
Date Of Driving Pass	23/12/2002
Driving Experience	16 YEARS AND 2 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-90068299
Fax Number	
Contact Number	OFFICE-90068299
Email Address	DAVIDTAY007@GMAIL.COM

Address 2 HILLVIEW RISE #25-07 S'667978

Postcode

Was driver an employee of the Insured's Company NO
If No, Relationship of the Driver with the Insured OWNER
Vehicle Registration Number of Driver's Own Vehicle -
-
-
Insurance Company of Driver's Own Vehicle -
-
-

General Information of the Accident

Type Of Accident COLLISION - CHANGE/CROSS LANE
Weather Conditions CLEAR
Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? YES
Foreign Vehicle Registration Number JQK6387 (PRIVATE CAR)
Number of vehicles (including own vehicle) involved in the accident 2
Was any body injured in the Accident? NO
Was any injured conveyed to hospital by ambulance? NO
Was any other material or property damaged? YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? NO
If Yes, Please state which Police Station
Was notice of intended Prosecution given? NO
If Yes, against whom?

Circumstances of Accident

REFER TO SKETCH PLAN

Attachment(s)

Are accident photos available for attachment? YES
Was there any video captured by Car Camera? YES
Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number JQK6387
Vehicle Make/Model/Colour
Details Of Properties
Vehicle Category PRIVATE CAR
Name of Driver IBRAHIM BIN MUDAH
NRIC/Passport Number
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.




Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 12/3/2019 at and 9:35 hrs, I was driving along Irwell Bank Road

I was driving at the second left lane. All of sudden, the vehicle JSK 6387

squaze into my lane and hit on my right

DECLARATION

I/We declare the foregoing particulars are true in every respect.

[Signature]

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:



Reporting Centre Personnel's Signature
Name:
NRIC/FIN No:

**SINGAPORE
POLICE FORCE**

Police Station Of Origin:
Bukit Timah N.P.C
1 Duke's Road SINGAPORE 268914
Tel No: 1800-4629999



T/20190312/2161

1 of 3

Report No: T/20190312/2161

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made:
12/03/2019 18:10

Vide Report No.

Station Diary No.:
98

Informant's Particulars

Name of Informant: TAY SWEE MENG, DAVID			Address: 2 HILLVIEW RISE #25-07 SINGAPORE 667978		
ID Type / ID No.: NRIC NO / S8231557H			Contact No.: Home/Office: Mobile: 90068299		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 36	Date of Birth: 14/10/1982	Type of Informant: Driver		
Race: Chinese			Language: English		Institution / School Name:
Occupation: ASSISTANT DIRECTOR			Driving Licence Information: Class: 2B.3 Date of Expiry:		

General Information of the Accident

Type of Accident:	Non-Injury Foreign Vehicle	Drink Drive: No	Date/Time of Accident: 12/03/2019 09:35	Type of Location: Straight Road
Location: Along Road 1 Traveling Toward Road 2 IRWELL BANK ROAD KIM SENG ROAD				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow: One Way		Traffic Control: Traffic Light - Working		Traffic Volume: Moderate
Type of Collision: Between Moving Vehicles - Side Swipe - Same Direction				Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
JQK6387	Car				Slightly Damaged	1
SKA4999G	Car	BMW	116I AT ABS D/AIRBAG 2WD HID 5DR	Black	Seriously Damaged	0

Details of Vehicle Insurance

Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
-------------	-------------------	--------------	-----------	-------------

**SINGAPORE
POLICE FORCE**

Police Station Of Origin:
Bukit Timah N.P.C
1 Duke's Road SINGAPORE 268914
Tel No: 1800-4629999



T/20190312/2161

2 of 3

Report No: T/20190312/2161

CONTINUATION OF REPORT**Details of Vehicle Insurance**

Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
SKA4999G	FWD Singapore Pte. Ltd	PNPV2018-00011243	28/09/2018	27/09/2019

Details of Person Involved

Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL			
Driver Name		TAY SWEE MENG, DAVID	
Related Vehicle		NIL	
Hospital/Clinic		NIL	
Date Treatment		NIL	
No. of Days granted Medical Leave		NIL	
ID No.		S8231557H	
Contact No.		90068299	
Class of Driving Licence & Expiry Date		Class: 2B,3 Date of Expiry: NIL	
Date Discharge		NIL	
Degree of Injury		NIL	

Brief Details.

On the above mentioned date, time and place. I was travelling with my vehicle, SKA4999G, along Irwell Bank Road towards Kim Seng Road. I was driving at the second left lane. All of sudden, the vehicle JQK6387 squeeze into my lane and collided on my right side of vehicle. Both of us alighted the vehicle and make an exchange of particulars. At 0430pm, I went down to Sin Ming @ IDAC to make an accident report and I was told to make a police report as it is involving with a foreign vehicle. The other party also make a police report and send me a photo of his version of report, I wished to state that some facts he gave was wrong. I have a in-car camera and I have save the video footage that captured the accident and I wish to provide this footage to the Traffic Police investigation officer.

The other party driver's particular:

Name: Ibrahim Bin Mudah

IC No.: 650128015063

Contact No.: +60197705231



Sin Ming Autocity,
160 Sin Ming Drive #03-03
Singapore 575722

6453 2121 (4 lines) / 6458 1111 (24 hrs)

6459 9795 / 6459 0433

admin@vinsautogroup.com.sg

www.vinsautogroup.com.sg

INSURER: **FWD Singapore Pte. Ltd. (HQ)**

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	OD/032019/3807
Policy No:	PNPV2018-00011243	Date of Loss:	12/03/2019
Vehicle Reg. No.:	SKA4999G	Driveable?	
Driver Age/Info:	36 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	TAY SWEE MENG, DAVID	Contact No:	+6590068299
Driver:	TAY SWEE MENG, DAVID		
Make/Model:	BMW 116i, 1.6 (A)	Vehicle Reg. Date:	28/03/2013
Vehicle Colour:	BLACK		
Engine No:	B184J430N13B16A	Chassis No:	WBA1A12070VV24623
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	8		
Description of Accident/Loss	REFER TO SKETCH PLAN		
Present Location:	VIN'S MOTOR PTE LTD (SIN MING)		

COST OF CLAIMS

	Amount
Parts	5,370.00
Miscellaneous Items	0.00
Labour	1,160.00
Paintwork Labour	980.00
Towing	0.00
	8130
Gross Total (\$\$)	7,510.00
+ GST 7.00% (\$\$)	525.70
Nett Amount (\$\$)	8,035.70

This claim is handled by: **TAN YIN LEI**

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 13 Mar 2019)
 Parts: 144 BMW 116i 1.6 (A) (Catalogue: Merimen Singapore 1.0)
 Labour: Repairer's (Price-denominated Standard List)

Print Code: Vin's Motor Pte Ltd/SKA4999G/13/03/2019 14:12

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1	①	*Front RH sport rim / CUT DM	0.00	0.00	*880.00 F ✓
2	1	②	*Front RH wheel bearing *? / DM	0.00	0.00	*340.00 F ✓
3	1	③	*Front RH fender / OD	0.00	0.00	*410.00 F ✓
4	1	④	*Front RH fender inner fiber X NA	0.00	0.00	*90.00 F ✓
5	10	⑤	*Front RH fender inner fiber clips @ \$3.00 X NA	0.00	0.00	*30.00 F ✓
6	1	⑥	*Front RH fender Sport name plate / CUT	0.00	0.00	*40.00 F ✓
7	1	⑦	*Front RH door / OD	0.00	0.00	*890.00 F ✓
8	1	⑧	*Front RH door rubber (lower) / NEC	0.00	0.00	*40.00 F ✓
9	1	⑨	*Front RH door outer moulding ? / BT	0.00	0.00	*60.00 F ✓
10	1	⑩	*Front RH door side mirror housing / DR	0.00	0.00	*680.00 F ✓
11	1	⑪	*Front RH door handle X R ? / BT	0.00	0.00	*410.00 F ✓
12	1	⑫	*Front RH door regulator X NA ? / BT	0.00	0.00	*210.00 F ✓
13	1	⑬	*Front RH door regulator motor X NA / Shift	0.00	0.00	*270.00 F ✓
14	1	⑭	*Rear RH sport rim / CUT	0.00	0.00	*880.00 F ✓
15	1	⑮	*Rear RH wheel bearing X NA ? / DM	0.00	0.00	*140.00 F ✓

F=Franchise part.

Total Parts (\$\$)

5,370.00

Vin's Motor Pte Ltd/SKA4999G/13/03/2019 14:12. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

[Signature]
 15/3/19

Stew (LKK) OD Authn
 8372 8813 EXPRIS - \$500

14/3/19 1.00pm 5 days

Repairing before spray and damage parts

5250 ✓

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Paintwork Labour</u>			
1	To spray painting	New	980.00
<u>Labour Items</u>			
2	To check wheel alignment	New	120.00
3	To remove and replace front bearing	New	80.00
4	To remove and replace rear bearing	New	80.00
5	To repair damages	New	880.00
Gross Labour Cost (S\$)			2,140.00

Vin's Motor Pte Ltd/SKA4999G/13/03/2019 14:12. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

1660

Vin's

AUTOMOTIVE GROUP

Our Ref : OD/032019/3807

Accident date: 12/03/2019

Your Ref : SKA4999G

A Sin Ming Autocity,
160 Sin Ming Drive #03-03
Singapore 575722

T 6453 2121 (4 lines) / 6458 1111 (24 hrs)

F 6459 9795 / 6459 0433

E admin@vinsautogroup.com.sg

W www.vinsautogroup.com.sg

Tax Invoice:

Date : 18/03/2019

MOTOR CLAIM DEPARTMENT

FWD Singapore Pte Ltd

6 Temasek Boulevard, #18-01

Suntec Tower 4

Singapore 038986

(Supp)

SUPPLEMENTARY COST OF REPAIRS TO BMW 116I SKA4999G

13	1	pc	Front RH door mirror cover	✓	OR	\$	90.00	✓
14	1	pc	Front RH door mirror glass	✓	OLF	\$	530.00	✓

VIN'S MOTOR PTE LTD

\$ 620.00

620

Enno Ang.
UKK
19/3/19.

INSURER:

FWD Singapore Pte. Ltd. (HQ)

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	OD/032019/3807
Policy No:	PNPV2018-00011243	Date of Loss:	12/03/2019
Vehicle Reg. No.:	SKA4999G	Driveable?	
Driver Age/Info:	36 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	TAY SWEE MENG, DAVID	Contact No:	+6590068299
Driver:	TAY SWEE MENG, DAVID		
Make/Model:	BMW 116I, 1.6 (A)	Vehicle Reg. Date:	28/03/2013
Vehicle Colour:	BLACK	Chassis No:	WBA1A12070VV24623
Engine No:	B184J430N13B16A		
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	8		
Description of Accident/Loss	REFER TO SKETCH PLAN		
Present Location:	VIN'S MOTOR PTE LTD (SIN MING)		

COST OF CLAIMS

Parts	Amou
Miscellaneous Items	5,370.
Labour	0.
Paintwork Labour	1,160.
Towing	980.
	0.
Gross Total (S\$)	7,510.
+ GST 7.00% (S\$)	525
Nett Amount (S\$)	8,035

This claim is handled by: TAN YIN LEI

Generated using Merimen e-Claims Internet Estimation & Adjusting Sy

REPAIR DETAILS

Reference

Part Source: MRM-SG

Version: 1.0 (Last Synchronised: 13 Mar 2019)

Parts: 144

BMW 116i 1.6 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's

(Price-denominated Standard List)

Print Code: Vin's Motor Pte Ltd/SKA4999G/13/03/2019 14:12

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*Front RH sport rim <i>CNT</i>	0.00	0.00	/ *880.00 F
2	1		*Front RH wheel bearing <i>MC ? DM</i>	0.00	0.00	/ *340.00 F
3	1		*Front RH fender <i>DD</i>	0.00	0.00	/ *410.00 F
4	1		*Front RH fender inner fiber <i>MC NN</i>	0.00	0.00	X *90.00 F
5	10		*Front RH fender inner fiber clips @ \$3.00 <i>MC NN</i>	0.00	0.00	X *30.00 F
6	1		*Front RH fender Sport name plate <i>CNT</i>	0.00	0.00	/ *40.00 F
7	1		*Front RH door <i>DD</i>	0.00	0.00	/ *890.00 F
8	1		*Front RH door rubber (lower) <i>MC</i>	0.00	0.00	/ *40.00 F
9	1		*Front RH door outer moulding <i>MC ? DT</i>	0.00	0.00	/ *60.00 F
10	1		*Front RH door side mirror housing	0.00	0.00	/ *680.00 F
11	1		*Front RH door handle <i>MC ? RR</i>	0.00	0.00	/ *410.00 F
12	1		*Front RH door regulator <i>MC ? CRU</i>	0.00	0.00	/ *210.00 F
13	1		*Front RH door regulator motor <i>MC NN</i>	0.00	0.00	/ *270.00 F
14	1		*Rear RH sport rim <i>CNT</i>	0.00	0.00	/ *880.00 F
15	1		*Rear RH wheel bearing <i>MC ? DM</i>	0.00	0.00	/ *140.00 F

F=Franchise part.

Total Parts (S\$)

5,370.00

Vin's Motor Pte Ltd/SKA4999G/13/03/2019 14:12. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

Steve (LKK) OD Authorize 5250
 8322 8813 EXCESS - \$500
 14/3/19 1.00pm 5 days
 Repairing before spray and damage parts

Eric Ong
 15/3/19

A - 5250
 Supp - 620
 L - 1660
 7530

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Paintwork Labour</u>			
1	To spray painting	New	900 980.00
<u>Labour Items</u>			
2	To check wheel alignment	New	69 120.00
3	To remove and replace front bearing	New	80 80.00
4	To remove and replace rear bearing	New	80 80.00
5	To repair damages	New	800 880.00
Gross Labour Cost (\$)			2,140.00

Vin's Motor Pte Ltd/SKA4999G/13/03/2019 14:12. Not valid without Reference section.

Generated using Merlman e-Claims IEAS

< END OF ESTIMATES >

1660



友興汽車零件私人有限公司 YEW HENG AUTO PARTS PTE LTD

BLK 3017 UBI ROAD 1 #04-129 SINGAPORE 408708
TEL: 6743 9858 A/C: 6392 0830 FAX: 6749 0858
Email: yewheng@yewhengauto.sg
Co. Reg. No.: 201130046W GST Reg. No.: 201130046W

TAX INVOICE

M/S: VIN'S MOTOR PTE LTD

160 SIN MING DRIVE #03-03 SIN MING AUTOCITY
SINGAPORE 575722
WORKSHOP: 160 #08-09 SIN MING AUTOCITY

NO: YLI1220295
PAGE: 1
DATE: 23/03/2019
A/C CODE: LYVIN001
TERMS: 30 DAYS

Part No	Description	Location	Qty	Unit Price	Amount
				SIN	SIN
1 3611 6 850 151	ALLOY RIM 7.5JX17 STAR SPOKE 379 FRT & RR	YDS	2	880.00	1,760.00 (1)
2 3120 6 857 230	FRT RHS WHEEL BEARING	YDS	1	340.00	340.00 (2)
3 4100 7 284 646	FRONT SIDE PANEL/M RH	YDS	1	410.00	410.00 (3)
4 5114 7 327 750	FRT FENDER EMBLEM SPORT	1N-43D1	1	40.00	40.00 (4)
5 4100 7 284 512	DOOR FRONT RIGHT	1N-5A	1	890.00	890.00 (5)
5 5133 7 240 850	DR SEAL FRT LOWER F20	1N-11B	1	40.00	40.00 (6)
7 5133 7 240 862	SEALING	1N-17B2	1	60.00	60.00 (7)
8 5116 7 242 748	HEATED OUTSIDE MIRROR RH	YDS	1	680.00	680.00 (8)
9 5121 7 326 918	FRT DOOR HANDLE RH	YDS	1	410.00	410.00 (9)
10 5133 7 281 882	FRT RH DOOR REGULATOR	YDS	1	210.00	210.00 (10)
11 6762 7 406 624	FRT DOOR REGULATOR MOTOR RH	YDS	1	270.00	270.00 (11)
12 3341 6 792 356	ANGULAR BALL BEARING	1N-43D6	1	140.00	140.00 (12)
TOTAL QUANTITY:			13	TOTAL	SIN 5,250.00
				ADD GST @ 7%	367.50
				GRAND TOTAL	SIN 5,617.50

SALESMAN: KXM

This document is computer generated. No signature required.

GOODS SOLD ARE NOT RETURNABLE



友興汽車零件私人有限公司
YEW HENG AUTO PARTS PTE LTD

BLK 3017 UBI ROAD 1 #04-129 SINGAPORE 408708
TEL: 6743 9858 A/C: 6392 0830 FAX: 6749 0858
Email: yewheng@yewhengauto.sg
Co. Reg. No.: 201130046W GST Reg. No.: 201130046W

TAX INVOICE

I/S: VIN'S MOTOR PTE LTD

160 SIN MING DRIVE #03-03 SIN MING AUTOCITY
SINGAPORE 575722
WORKSHOP: 160 #08-09 SIN MING AUTOCITY

NO: YLI1221225
PAGE: 1
DATE: 11/04/2019
A/C CODE: LYVIN001
TERMS: 30 DAYS

Part No	Description	Location	Qty	Unit Price	Amount
				SIN	SIN
5116 7 292 746	SIDE MIRROR COVER	YDS	1	90.00	90.00
5116 7 285 006	SIDE MIRROR GLASS	YDS	1	530.00	530.00
TOTAL QUANTITY:			2	TOTAL	SIN 620.00
				ADD GST @ 7%	43.40
				GRAND TOTAL	<u>SIN 663.40</u>

SKA4999G

int / KXM / 11/04/2019 1:25:59 PM

LES MAN: KXM

This document is computer generated. No signature required.

GOODS SOLD ARE NOT RETURNABLE

Steve Chen (LKK Auto)

From: Admin @ VAuG <admin@vinsautogroup.com.sg>
Sent: Thursday, April 25, 2019 5:47 PM
To: Steve Chen (LKK Auto)
Cc: Veron Chen (LKKAuto)
Subject: Re: SKA4999G Finalize

Good afternoon,
We confirm the amount @ \$7530/-
Please offer through Merimen
Thanks!
Best Regards
Raymond Teo

On Thu, Apr 25, 2019 at 5:45 PM Steve Chen (LKK Auto) <SteveChen@lkkauto.com> wrote:

Attn to Raymond,

Hi Raymond as spoken a while. The above vehicle finalize \$7,530.00 (P/P. before GST). 5 days.

Kindly confirm.

Thanks

Best Regards,

Steve Chen | Assistant Automotive Assessor

LKK Auto Consultants

Phone: 6256 3561 | Email: SteveChen@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	13 Mar 2019	13 Mar 2019	13 Mar 2019	S\$7,530.00	S\$7,530.00		Pending for Survey Report
	Send Back Est	14:12 S\$7,510.00	15:14 Edit Adj Rpt	Edit Estimates	View Rpt		Cancel Case
Supp #1	18 Mar 2019 13:39	18 Mar 2019 13:40 S\$620.00	18 Mar 2019 13:40			(Combined)	Combined with Main Uncombine Suppl.

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS

Insured: **TAY SWEE MENG, DAVID**, ID: S8231557H, Tel: +6590068299, Email: davidtay007@gmail.com

Vehicle Reg. No.: **SKA4999G** Date of Loss: 12/03/2019 09:00 - :59
[71 Months and 12 Days From LTA Reg Date (Man Yr)]

Claim Type: **OD / 1201900006518** Policy/Cover Note No.: PNPV2018-00011243 (Comprehensive)

Excess: S\$500.00

Repairer: **Vin's Motor Pte Ltd (Sin Ming)** 160 Sin Ming Drive, #03-03, Sin Ming AutoCity, 575722 Sin Ming - Tel: 64532121

Handling Insurer: **FWD Singapore Pte. Ltd. (HQ)** - Tel: 6727 5700 ... [Handled by **Lionel Tan**]

Adjuster: **LKK Auto Consultants Pte Ltd (HQ)** - Tel: 6256-3561 ... [Handled by **CHEN TSUE YEE**] ... [Final Rpt due 22/03/2019]

Driver/Custodian: TAY SWEE MENG, DAVID (36 / Male), NRIC: S8231557H, Tel: +6590068299 Email: davidtay007@gmail.com

ASSOCIATED MAIL RECEIVED
[View All](#)
[Compose Case Mail](#)

- FWD_SG (25/04/2019): Alert - Adj Mandate Approved (S\$7530.00) - SKA4999G - Claim Handler: Lionel Tan
- FWD_SG (15/03/2019): Alert - Adj Mandate Approved (S\$6290.00) - SKA4999G - Claim Handler: Lionel Tan

ALL ASSOCIATED TASKS
[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

SKA4999G (1201900006518)
OD

Mar 12 2019 9:00AM
[TAY SWEE MENG, DAVID]
Vin's Motor Pte Ltd

[Upload Documents](#) |
 [Upload Photos](#) |
 [Compose New Letter](#)

View [View in Browser](#)

Video				1 per page	☒
No	Finalized On	Vin's Motor Pte Ltd (Sin Ming)	Thumbnail	Print	
1	13/03/19 09:47	Video - Accident [Linked Accident Report Documents]	Load MOV		
Assessment Reports				1 per page	☒
No	Finalized On	Vin's Motor Pte Ltd (Sin Ming)	Thumbnail	Print	
1	13/03/19 14:12	Repairer Estimates	Load HTM		
2	18/03/19 13:40	Repairer Estimates Suppl. #1	Load HTM		
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print	
1	15/03/19 11:32	Adjuster Immediate Advice	Load HTM		
2	25/04/19 09:58	Adjuster Immediate Advice	Load HTM		
Photos/Images				3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print	
1	14/03/19 19:25	General View	Load JPG	☒	
2	14/03/19 19:25	General View	Load JPG	☒	
3	14/03/19 19:25	General View	Load JPG	☒	
4	14/03/19 19:25	General View	Load JPG	☒	
5	14/03/19 19:25	General View	Load JPG	☒	
6	14/03/19 19:25	General View	Load JPG	☒	
7	14/03/19 19:25	General View	Load JPG	☒	
8	14/03/19 19:25	General View	Load JPG	☒	
9	14/03/19 19:25	General View	Load JPG	☒	
10	14/03/19 19:25	General View	Load JPG	☒	
11	14/03/19 19:25	General View	Load JPG	☒	
12	14/03/19 19:25	General View	Load JPG	☒	
13	14/03/19 19:25	General View	Load JPG	☒	
14	14/03/19 19:25	General View	Load JPG	☒	
15	14/03/19 19:25	General View	Load JPG	☒	
16	14/03/19 19:25	General View	Load JPG	☒	
17	14/03/19 19:25	General View	Load JPG	☒	
18	14/03/19 19:25	General View	Load JPG	☒	
19	14/03/19 19:25	General View	Load JPG	☒	
20	14/03/19 19:25	General View	Load JPG	☒	
21	14/03/19 19:25	General View	Load JPG	☒	
22	14/03/19 19:25	General View	Load JPG	☒	
23	14/03/19 19:25	General View	Load JPG	☒	
24	14/03/19 19:25	General View	Load JPG	☒	
25	14/03/19 19:25	General View	Load JPG	☒	
26	14/03/19 19:25	General View	Load JPG	☒	
27	14/03/19 19:25	General View	Load JPG	☒	
28	14/03/19 19:25	General View	Load JPG	☒	

Video			1 per page	☒
No	Finalized On	Vin's Motor Pte Ltd (Sin Ming)	Thumbnail	Print
29	14/03/19 19:25	General View		☒
30	14/03/19 19:25	General View		☒
31	14/03/19 19:25	Odometer Reading		☒
32	14/03/19 19:25	Chassis Number		☒
33	14/03/19 19:25	General View		☒
34	14/03/19 19:25	General View		☒
35	14/03/19 19:25	General View		☒
36	14/03/19 19:25	General View		☒
37	14/03/19 19:25	General View		☒
38	14/03/19 19:25	General View		☒
39	14/03/19 19:25	General View		☒
40	14/03/19 19:25	General View		☒
41	14/03/19 19:25	General View		☒
42	14/03/19 19:25	General View		☒
43	14/03/19 19:25	General View		☒
44	14/03/19 19:25	General View		☒
45	14/03/19 19:25	General View		☒
46	14/03/19 19:25	General View		☒
47	23/03/19 13:15	Reinspection Photo		☒
48	23/03/19 13:15	Reinspection Photo		☒
49	23/03/19 13:15	Reinspection Photo		☒
50	23/03/19 13:15	Reinspection Photo		☒
51	23/03/19 13:15	Reinspection Photo		☒
52	23/03/19 13:15	Reinspection Photo		☒
53	23/03/19 13:15	Reinspection Photo		☒
54	23/03/19 13:15	Reinspection Photo		☒
55	23/03/19 13:15	Reinspection Photo		☒
56	23/03/19 13:15	Reinspection Photo		☒
57	23/03/19 13:15	Reinspection Photo		☒
58	23/03/19 13:15	Reinspection Photo		☒
59	23/03/19 13:15	Reinspection Photo		☒
60	23/03/19 13:15	Reinspection Photo		☒
61	23/03/19 13:15	Reinspection Photo		☒
62	23/03/19 13:15	Reinspection Photo		☒
63	23/03/19 13:15	Reinspection Photo		☒
64	23/03/19 13:15	Reinspection Photo		☒
65	23/03/19 13:15	Reinspection Photo		☒
66	23/03/19 13:15	Reinspection Photo		☒
67	23/03/19 13:15	Reinspection Photo		☒
68	23/03/19 13:15	Reinspection Photo		☒
69	23/03/19 13:15	Reinspection Photo		☒
70	23/03/19 13:15	Reinspection Photo		☒
71	23/03/19 13:15	Reinspection Photo		☒
72	23/03/19 13:15	Reinspection Photo		☒
73	23/03/19 13:15	Reinspection Photo		☒
74	23/03/19 13:15	Reinspection Photo		☒
75	23/03/19 13:15	Reinspection Photo		☒
76	23/03/19 13:15	Reinspection Photo		☒
77	23/03/19 13:15	Reinspection Photo		☒
78	23/03/19 13:15	Reinspection Photo		☒

Video			1 per page	☒
No	Finalized On	Vin's Motor Pte Ltd (Sin Ming)	Thumbnail	Print
79	23/03/19 13:15	Reinspection Photo	 Load JPG	☒
80	23/03/19 13:15	Reinspection Photo	 Load JPG	☒
81	23/03/19 13:15	Reinspection Photo	 Load JPG	☒
82	23/03/19 13:15	Reinspection Photo	 Load JPG	☒
83	23/03/19 13:15	Reinspection Photo	 Load JPG	☒
84	23/03/19 13:15	Reinspection Photo	 Load JPG	☒
85	23/03/19 13:15	Reinspection Photo	 Load JPG	☒
86	23/03/19 13:15	Reinspection Photo	 Load JPG	☒
87	23/03/19 13:15	Reinspection Photo	 Load JPG	☒
88	23/03/19 13:15	Reinspection Photo	 Load JPG	☒
89	23/03/19 13:15	Reinspection Photo	 Load JPG	☒
90	23/03/19 13:15	Reinspection Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	15/03/19 11:34	MARK ESTIMATE	 Load PDF	
2	23/03/19 13:20	SUPPLEMENTARY	 Load PDF	
3	25/04/19 09:53	SUPPLEMENTARY MARKING	 Load PDF	
4	07/05/19 09:50	Parts Invoice	 Load PDF	

Linked Accident Report Documents

Video			View	View in Browser
No	Finalized On	Vin's Motor Pte Ltd (Sin Ming)	Thumbnail	Print
1	13/03/19 09:47	Video - Accident	 Load MOV	
Assessment Reports			1 per page	☒
No	Finalized On	Vin's Motor Pte Ltd (Sin Ming)	Thumbnail	Print
1	13/03/19 13:36	Accident Statement	 Load HTM	
2	13/03/19 13:55	Addendum Sheet	 Load TIF	
3	13/03/19 13:57	Accident Statement Addm. #1	 Load HTM	
Photos/Images			3 per page	☒
No	Finalized On	Vin's Motor Pte Ltd (Sin Ming)	Thumbnail	Print
1	13/03/19 09:47	Accident Photo	 Load JPG	☒
2	13/03/19 09:47	Accident Photo	 Load JPG	☒
3	13/03/19 09:47	Accident Photo	 Load JPG	☒
4	13/03/19 09:47	Accident Photo	 Load JPG	☒
5	13/03/19 09:47	Accident Photo	 Load JPG	☒
6	13/03/19 09:47	Accident Photo	 Load JPG	☒
7	13/03/19 09:47	Accident Photo	 Load JPG	☒
8	13/03/19 09:47	Accident Photo	 Load JPG	☒
9	13/03/19 09:47	Accident Photo	 Load JPG	☒
10	13/03/19 09:47	Accident Photo	 Load JPG	☒
11	13/03/19 09:47	Accident Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	Vin's Motor Pte Ltd (Sin Ming)	Thumbnail	Print
1	13/03/19 09:50	Sketch Plan	 Load TIF	
2	13/03/19 13:56	Police Report	 Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST[Reset](#)[Save](#)[Print](#)

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Repairer ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

FWD Singapore Pte. Ltd.
6 Temasek Boulevard, #18-01 Suntec Tower 4
Singapore 038986

Our File No: CS/FWD19004661/EVD3E2

Date: 07/05/2019

REFERENCE

Insured/Claimant: TAY SWEE MENG, DAVID Policy No: PNPV2018-00011243
Date of Loss: 12/03/2019 Nature of Claim: OD Claim No: 1201900006518

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SKA4999G
Make & Model: BMW 116i, 1.6 (A) Engine No: B184J430N13B16A
Reg. Date: 28/03/2013 (Man. Year: 2013) Chassis No: WBA1A12070VV24623
Colour: Black Odometer: 70479 km
Engine Capacity: 1598 cc
Market Value/New Car Price: S\$52,000.00
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/45 R17 Rear Tyre Size: 225/45 R17
Front Left Side: Pirelli 7 mm Rear Left Side: Pirelli 7 mm
Front Right Side: Pirelli 7 mm Rear Right Side: Pirelli 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,990.00	5,870.00	120.00	2.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,160.00	760.00	400.00	34.48
Paintwork Labour	980.00	900.00	80.00	8.16
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,130.00	7,530.00	600.00	7.38
- Excess (S\$)	0.00	500.00	-500.00	
(S\$)	8,130.00	7,030.00	1,100.00	13.53
+ GST 7.00/7.00% (S\$)	569.10	492.10	77.00	13.53
Nett Amount (S\$)	8,699.10	7,522.10	1,177.00	13.53

INSPECTION

Date of Assignment: 13/03/2019 Present Location: Vin's Motor Pte Ltd (Sin Ming)
Date Inspected: 14/03/2019 Inspected At: Vin's Motor Pte Ltd (Sin Ming)
160 Sin Ming Drive, #03-03, Sin Ming
AutoCity
Singapore 575722
Estimated Period of Repair: 5.0 days

Adjuster: CHEN TSUE YEE

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 07 May 2019)
Parts: 144	BMW 116I 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SKA4999G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*Front RH sport rim	Cut	880.00 F	*880.00 F
2	1		*Front RH wheel bearing	Damaged	340.00 F	*340.00 F
3	1		*Front RH fender	Dented	410.00 F	*410.00 F
4	1		*Front RH fender inner fiber	Not Necessary	90.00 F	*- F
5	10		*Front RH fender inner fiber clips @ \$3.00	Not Necessary	30.00 F	*- F
6	1		*Front RH fender Sport name plate	Cut	40.00 F	*40.00 F
7	1		*Front RH door	Dented	890.00 F	*890.00 F
8	1		*Front RH door rubber (lower)	Necessary	40.00 F	*40.00 F
9	1		*Front RH door outer moulding	Bent	60.00 F	*60.00 F
10	1		*Front RH door side mirror housing	Broken	680.00 F	*680.00 F
11	1		*Front RH door handle	Broken	410.00 F	*410.00 F
12	1		*Front RH door regulator	Bent	210.00 F	*210.00 F
13	1		*Front RH door regulator motor	Shorted	270.00 F	*270.00 F
14	1		*Rear RH sport rim	Cut	880.00 F	*880.00 F
15	1		*Rear RH wheel bearing	Damaged	140.00 F	*140.00 F
Supplementary #1						
16	1		*Front RH door mirror cover	Broken	90.00 F	*90.00 F
17	1		*Front RH door mirror glass	Deformed	530.00 F	*530.00 F
Total Parts (S\$)					5,990.00	5,870.00

F=Franchise part

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Paintwork Labour</u>				
1	To spray painting	New	980.00	900.00
<u>Labour Items</u>				
2	To check wheel alignment	New	120.00	60.00
3	To remove and replace front bearing	New	80.00	50.00
4	To remove and replace rear bearing	New	80.00	50.00
5	To repair damages	New	880.00	600.00
Gross Labour Cost (S\$)			2,140.00	1,660.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >