

ASS. REC. BY:

REF:

CS/CT#19004683/4 v d3

n2

Special Instruction:

Supervisor:

GQ

ASSIGNMENT (Office)

From (Person):

Chong Boon Sen

of

CTI

Date/Time:

14/3/19 @ 3:49pm

Estimated Cost:

Bill to:

OD (TP) WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SL 6338G

Insured:

GBE 8202G

at Workshop m/s

Jack Cars

Tel:

67488824

of

Blk 3007 Ubi Rd 1 #01-450

Policy No:

Claim No:

SNM19D201155C02

Sum Insured:

Excess:

Make of Veh:

D.O.A.

12/3/19

(Client's Record)

18/3/19 @ 4:10pm.

H.O.D. Endorsement:

CA / REV / REP. / REV 24 HRS

Date/Time:

4:40pm @ 14/3/19

Person Contacted:

Thana

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SL 6338G - NA / LIP17022254 / 1

D.O.A. - 22/11/2017

11/6/19

Final fig \$ 4216.40 confirmed by email (Red 5857.60, 5819)

REF:

CTI

B5718J

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

4 days

Res.: Yes or No

Lump Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

Type: M/Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour

Sp. Reading

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD / Rim or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

RECEIVED 1 JUN 2019

Date/Time, File Pass to?

1)

Date/Time, File Return to?

2)

Report Format:

Lump Sum / I.B.I. (\$

☐ : Preli. Report☐ : Final Report

Days Of Repair: 4

Resurvey No. of Trip: 1

Add Fee:

☐ : Site Insp (\$☐ : Interview (\$☐ : Tech. Invs (\$☐ : Weekend (\$

Survey Fee:

Transportation:

) \$ + R.S. \$

) Photos

) Others

TOTAL

220

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Tuesday, 11 June 2019 12:38 PM
To: Thanaletchumi Santerashigaram
Cc: SUR
Subject: RE: FW: SLL 6338G-DOA: 12/3/2019

Dear Thana,

Noted with thanks.

Kindly send Final invoice and all supporting documents directly to CHINA TAIPING

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Thanaletchumi Santerashigaram <thana@jackcars.com.sg>
Sent: Tuesday, 11 June 2019 12:31 PM
To: Veron Chen (LKKAUTO) <veronchen@lkkauto.com>
Cc: SUR <sur@lkkauto.com>
Subject: Re: FW: SLL 6338G-DOA: 12/3/2019

Greetings MS. Veron ,

For an amicable settlement would agree with \$4216.40 @ 4 working days.

Kindly revert.

Thank You.

*Best Regards ,
S.Thanaletchumi (Ms)
JACK CARS ENTERPRISE PTE LTD
Office : 67488824
Mobile : 91701900
Fax : 67488834
Email : thana@jackcars.com.sg*

On Tue, Jun 11, 2019 at 8:02 AM Veron Chen (LKKAUTO) <veronchen@lkkauto.com> wrote:

Dear Thana,

WITHOUT PREJUDICE

Offer part by part \$4216.40 @ 4 working days.

Please check and confirm urgent please.

Best Regards,
Veron Chen | Case Handler
LKK Auto Consultants Pte Ltd
Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Veron Chen (LKKAuto)
Sent: Thursday, 30 May 2019 5:08 PM
To: thana (thana@jackcars.com.sg) <thana@jackcars.com.sg>; SUR <sur@lkkauto.com>
Subject: SLL 6338G-DOA: 12/3/2019

Dear Thana,

WITHOUT PREJUDICE

Offer part by part \$4216.40 @ 4 working days.

Please check and confirm

Best Regards,
Veron Chen | Case Handler
LKK Auto Consultants Pte Ltd
Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Veron Chen (LKKAUTO)

From: Bokhari Makrob <bokhari@aaplpro.com>
Sent: Monday, 10 June 2019 11:22 AM
To: Chee So Chow
Cc: Alfred Toh; SUR; Information aapl
Subject: RE: OUR REF : SNM19D201155C02

URGENT

Dear So Chow,

Our driver has attended at CAD interview.

ASP Choo Kwang Meng is asking for the survey report as well as the TPPD LOD urgently.

Thank you and regards.

BOKHARI BIN MAKROB



2 Sims Close #06-14 Gemini @ Sims || Singapore 387298 || D: 67472822 || M: 81384347

APPRAISALS ASSOCIATES PTE. LTD. Company registration 201707686W

The information contained in this message and any attachment(s) may be privileged and confidential and is intended for the exclusive use of the addressee designated. If you are not the addressee any disclosure, reproduction, distribution, on-transmission, dissemination or use of the communication is strictly prohibited. Whilst any attachments may have been checked for viruses you should rely on your own virus checking programmes and procedures. To facilitate our communications we will store on our database your e-mail name and address together with any other contact details you have provided. Any views expressed in this message are those of the individual sender, except where the sender specifically states them to be the views of Appraisals Associates Pte. Ltd.

From: Chee So Chow
Sent: Friday, 10 May 2019 4:32 PM
To: SUR
Cc: Bokhari Makrob; Alfred Toh
Subject: OUR REF : SNM19D201155C02

Dear Veron

Please expedite on the survey report as this is a police case.

Chee So Chow (Ms)

Deputy Manager
Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #16-00 Springleaf Tower Singapore 079909
Direct (65) 6389 6176
Fax (65) 6224 7175 / 6224 7478
Email : claimsdept@sg.cntaiping.com



Disclaimer :

This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

Veron Chen (LKKAUTO)

From: Chee So Chow <sochow.chee@sg.cntaiping.com>
Sent: Friday, 10 May 2019 4:32 PM
To: SUR
Cc: Bokhari Makrob; Alfred Toh
Subject: OUR REF : SNM19D201155C02
Attachments: SNM19D201155C02 - PRI OF SLL6338G.pdf

Dear Veron

Please expedite on the survey report as this is a police case.

Chee So Chow (Ms)

Deputy Manager
Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower Singapore 079909

Direct (65) 6389 6176

Fax (65) 6224 7175 / 6224 7478

Email : claimsdept@sg.cntaiping.com

sochow.chee@sg.cntaiping.com

Website: www.sg.cntaiping.com



Disclaimer :

This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

Angie Foo

From: Claims Dept of CTI
Sent: Tuesday, March 19, 2019 10:49 AM
To: Angie Foo
Subject: FW: PRI of SLL6338G (ANR)
Attachments: PRI FORM.pdf

From: Thanaletchumi Santerashigaram [mailto:thana@jackcars.com.sg]
Sent: Wednesday, 13 March 2019 12:14 PM
To: Claims Dept of CTI <claimsdept@sg.cntaiping.com>
Subject: PRI of SLL6338G

Greetings ,

Attached would be the PRI of SLL6338G for your kind perusal.

Kindly revert.

Thank You.

*Best Regards ,
S.Thanaletchumi (Ms)
JACK CARS ENTERPRISE PTE LTD
Office : 67488824
Mobile : 91701900
Fax : 67488834
Email : thana@jackcars.com.sg*

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>



Our ref : 2019.JC.SLL6338G
Your ref : GBE8202G

13TH MARCH 2019

PLEASE REPLY VIA EMAIL(thana@jackcars.com.sg)

CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD
3 Anson Road
#16-00
Springleaf Tower
Singapore 079909
Attn: Motor Claims Dept
2 DAY'S PRE-REPAIR NOTICE

Surveyor from CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD
Vehicle **SLL6338G** inspected as follows by Name:

Signature

Date/Time:

Signature

Date/Time:

Signature

Date/Time:

Dear Sir/Madam,

NOTICE TO THIRD PARTY INSURER FOR PRE-REPAIR NOTICE

CLAIMANT: POON TECK JIN (JOJO TRANSPORT)

ACCIDENT INVOLVING SLL6338G & GBE8202G ON 12TH MARCH 2019 ALONG CLEMENCEAU AVE TO NEWTON CIRCUS

We refer to the above matter wherein we are instructed to act for **POON TECK JIN (JOJO TRANSPORT)**, the owner of vehicle no. **SLL6338G**.

Our Client's vehicle **SLL6338G** is available as follows; **please call prior appointment** for the pre-repair inspection:

Jack Cars Enterprise Pte Ltd
Blk 3007 Ubi Road 1,
#01-450,
Singapore 408701
Tel: 67488824 (Ms S.Thanaletchumi)

Please arrange for the pre-repair inspection on the damaged vehicle within 2 working days from the time of notification, excluding Saturdays, Sundays and public holidays.

Regards,
S.Thanaletchumi
Claims Manager
Jack Cars Enterprise Pte Ltd

A:3007 Ubi Road 1 #01-450 S(480701) T:67488824 F:67488834 W:www.jackcars.com.sg

Nivitha (LKK Auto)

From: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>
Sent: Thursday, 14 March 2019 3:49 PM
To: Thanaletchumi Santerashigaram
Cc: 'assignments'
Subject: RE: PRI of SLL6338G

Without Prejudice

Dear Sir,

We will appoint LKK.

Dear LKK,

Pls pri.

Regards,
Chong Boon Sen
Claims Executive
Claims

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower
Singapore 079909
Co. Reg. No. 200208384E
DID: 63896171
Fax: 62247175
Email: boonsen.chong@sg.cntaiping.com
Website: www.sg.cntaiping.com

Disclaimer :

This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

From: Thanaletchumi Santerashigaram [mailto:thana@jackcars.com.sg]
Sent: Thursday, 14 March, 2019 3:43 PM
To: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>
Subject: Re: PRI of SLL6338G

Greetings Mr. Boon Sen ,

Would agree with Mr. Marcus as our SJE.

Kindly revert.

Thank You.

Best Regards ,
S.Thanaletchumi (Ms)
JACK CARS ENTERPRISE PTE LTD
Office : 67488824
Mobile : 91701900
Fax : 67488834

Time: 5.13 p.m

Person: Thana

In: Out

Estimate: ✓

18.3.2019 After 2.00 p.m

Email : thana@jackcars.com.sg

On Thu, Mar 14, 2019 at 3:42 PM Chong Boon Sen <boonsen.chong@sg.cntaiping.com> wrote:

Without Prejudice

Dear Sirs

We intend to conduct a pre-repair survey of the damage to your client's vehicle jointly with your client/your motor workshop. We propose to use one of the following motor surveyors to conduct the joint pre-repair survey as a single joint expert.

ADRIAN LING
Kelvin Ang
SEE CHEW SENG
MOHD FADHILAH BIN OSMAN
XING QUO QIANG
KENNETH KONG
SIMON HO
CHUA WEIJIE
MARCUS CHUA
HENRY NG

Please let us know within two(2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.

You may select one of the listed motor surveyors and we will bear the cost of the pre-repair survey carried out by the single joint expert.

Regards,

Chong Boon Sen

Claims Executive

Claims

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower

Singapore 079909

Co. Reg. No. 200208384E

DID: 63896171

Fax: 62247175

Email: boonsen.chong@sg.cntaiping.com

Website: www.sg.cntaiping.com

Disclaimer :

This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

From: Thanaletchumi Santerashigaram [mailto:thana@jackcars.com.sg]
Sent: Thursday, 14 March, 2019 3:35 PM
To: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>
Subject: PRI of SLL6338G

Greetings Mr.Boon Sen ,

As spoken , attached would be the PRI of SLL6338G for your kind perusal.

Kindly revert.

Thank You.

Best Regards ,

S.Thanaletchumi (Ms)

JACK CARS ENTERPRISE PTE LTD

Office : 67488824

Mobile : 91701900

Fax : 67488834

Email : thana@jackcars.com.sg

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Business
Owner ID:	5718J
Vehicle Details	
Vehicle No.:	SLL6338G
Vehicle to be Exported:	No
Intended Deregistration Date:	19 Mar 2019
Vehicle Make:	HONDA
Vehicle Model:	VEZEL 1.5X CVT
Primary Colour:	Brown
Manufacturing Year:	2016
Engine No.:	L15B4409270
Chassis No.:	RU11209271
Maximum Power Output:	96.0 kW (128 bhp)
Open Market Value:	\$19,816.00
Original Registration Date:	03 Mar 2017
First Registration Date:	03 Mar 2017
Transfer Count:	0
Actual ARF Paid:	\$9,816.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	02 Mar 2027
PARF Rebate Amount:	\$7,362.00
Intended COE Rebate Details	
COE Expiry Date:	02 Mar 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$49,430.00
COE Rebate Amount:	\$39,291.00
Total Rebate Amount:	\$46,653.00

The information contained herein is correct as at 19 Mar 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	12/03/2019 15:46
Date Of Accident	12/03/2019 14:30
Exact Location Of Accident	CLEMENCEAU AVE TO NEWTON CIRCUS
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLL6338G
Insured/Policyholder	
Name Of Registered Owner	JOJO TRANSPORT
Co Reg No	53355718J
Email Address	JOJOCHENPL@GMAIL.COM
Mobile Phone No	
Alternative Phone No	OFFICE-81281765

Vehicle Particulars

Manufacturer	HONDA
Model	VEZEL
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

Insurance Company

Name of Insurance Company	FWD SINGAPORE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	PNCV2019-00000209
Cover Note Number	

Driver

Name of Driver	POON TECK JIN
NRIC No	S1621271G
Date Of Birth	21/11/1963
Occupation	OUTDOOR
Date Of Driving Pass	27/07/1981
Driving Experience	37 YEARS AND 7 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96179380
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	BLK 475D UPP SERANGOON CRESCENT #16-563 PARKLAND RESIDENCES
Postcode	537475
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : RYNA YVETTE GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO ATTACHED STATEMENT RECORDED BY LILY - PROGRESSIVE CAR CARE PTE LTD 67415336

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	REQUEST FROM OWNER
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBE8202G
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	TAN KHENG HONG
NRIC/Passport Number	S1200206H
Contact Number	96649898
Address	
Postcode	
Insurance Company Name	

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name POON TECK JIN

Approximate Age

Injuries Sustain

Injured person in which vehicle? SLL6338G

Were seat belts worn?

Was this injured conveyed to hospital by ambulance?

Address

Postcode

DETAILS OF INJURED PERSON 2

Name RYNA YVETTE

Approximate Age

Injuries Sustain

Injured person in which vehicle? SLL6338G

Were seat belts worn?

Was this injured conveyed to hospital by ambulance?

Address

Postcode

Sketch Plan

SKETCH PLAN


IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers to the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon applications by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claim and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (a) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time:




Driver's Signature
(if driver is not the policyholder)
Date & Time:



Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Sketch Plan #2

SKETCH PLAN

Vehicle
A - GLL 63386
B - GBE 82026

Legend
 Vehicle
 Shockwave



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

At 2:30pm I was driving from Clemence Ave toward Newton Circus. Suddenly the back Van GBE 82026 hit my car back as I was waiting for my turn to turn out of Newton Circus. As I'm a Grab driver, I have a rider seating behind my car Miss Brito Ryna Yvette has just board my car from Ngce Ann city shopping mall. I was understand that she has just finished her back surgical. I myself also have a stiff neck and going for medical check.

DECLARATION

I/We declare the foregoing particulars are true in every respect.
Please be advised that your insurance may have a 24 hours (24) days (date when the claim against our policy must be made within the stipulated time frame) from the day of the accident. Kindly check your policy for more details.

Policyholder's Signature
Date & Time:



Driver's Signature
(if driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/ID No:



ESTIMATE

DATE OF ACCIDENT : 12/03/2019
VEHICLE : SLL6338G
MAKE & MODEL : HONDA VEZEL
INSURANCE : CHINA TAIPING INSURANCE
SURVEYOR : LKK AUTO

PARTS		CONDITION	AMOUNT
1.	REAR BOOT / Bmc.	972.4	\$ 1540
2.	REAR BOOT INNER COVER / Cut.	153.4	\$ 520
3.	REAR BOOT GARNISH / NN	X	\$ 270
4.	REAR BUMPER / Re.	463.7	\$ 730
5.	REAR BUMPER LOWER COVER / NN	X	\$ 450
6.	REAR END PANEL X repair	X	\$ 730
7.	REAR END PANEL TOP COVER / Re.	92.3	\$ 210
8.	TAILGATE LAMP - INNER / 1 CPA	529.2	\$ 750
9.	TAILGATE LAMP - OUTER / 1 CPA	857.4	\$ 920
10.	LOCK / BT.	157.1	\$ 380
11.	REAR RIGHT SIDE PAD / Re.	195	\$ 480
			3420.5
SPECIAL NETT			20% = 2736.4
1.	REVERSE SENSOR / NN	X	\$ 200
2.	RELAY SENSOR / NN	X	\$ 180
3.	WINDSCREEN MOULDING /		\$ 150
4.	SILICON SEALANT / Mc.		\$ 100
5.	CLIPS /		\$ 80
6.	"HONDA" EMBLEM / NN		\$ 95
7.	"VEZEL" EMBLEM / Mc.	30	\$ 75



LABOUR			
1.	TO PUTTY & SPRAY PAINT OF AFFECTED AREA	700	\$ 1200
2.	TO PANEL BEAT & RENEWAL OF ALL NECESSARY DAMAGED BODY PARTS	400	\$ 1500
3.	TO CHECK WIRING & REWIRE	30	\$ 80
4.	TO REMOVE AND REINSTALL TAILGATE COMPONENTS	60	\$ 120
5.	TO REMOVE AND REINSTALL REAR BOOT UPHOLSTERY		\$ 120
6.	TO REMOVE AND REINSTALL REAR WINDSCREEN	100	\$ 200
7.	TO REMOVE & REINSTALL REVERSE & RELAY SENSOR	40	\$ 150
8.	TO CHECK LIGHTING SYSTEM	mg x	\$ 120
9.	ANTI RUST TREATMENT	mg x	\$ 120
			1330
	PARTS - 20% :	\$ 5,584	
	SPECIAL NETT :	\$ 880	
	LABOUR :	\$ 3,610	
	TOTAL :	\$ 10,074	
	7% GST :	\$ 705.18	
	GRAND TOTAL :	\$ 10,779.18	

19/3/19

4 Days.

part my part.

before paint photo's.

Gino Ong - 8288 028 2

18/3/19.

4216.4

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

LKK Auto Consultants Pte Ltd (Co.Reg.No.199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI19004683/GVD3N2

Date: 11/06/2019

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	
Claimant	SLL6338G	Insured Vehicle No :	GBE8202G
Vehicle No :		Nature of Claim:	TP
Date of Loss:	12/03/2019	Claim No:	N/A

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLL6338G	Engine No:	L15B4409270
Make & Model:	HONDA VEZEL, 1.5 (A)	Chassis No:	RU11209271
Reg. Date:	03/03/2017 (Man. Year: 2016)	Odometer:	144924 km
Colour:	Brown		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60R16	Rear Tyre Size:	215/60R16
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	Dunlop 6 mm	Rear Right Side:	Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	6,464.00	2,886.40	3,577.60	55.35
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,610.00	1,330.00	2,280.00	63.16
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	10,074.00	4,216.40	5,857.60	58.15
+ GST 7.00/7.00% (S\$)	705.18	295.15	410.03	58.15
Nett Amount (S\$)	10,779.18	4,511.55	6,267.63	58.15

INSPECTION

Date of Assignment:	25/03/2019	
Date Inspected:	18/03/2019	Inspected At:
		Jack Cars Enterprise Pte Ltd - Ubi (HQ)
		BLK 3007 UBI ROAD 1 #01-450
		Singapore 408701

Estimated Period of Repair: 4.0 days

Adjuster: XING GUO QIANG

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 11 Jun 2019)
Parts: M1-SUV	HONDA VEZEL 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SLL6338G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT	Buckled	1,540.00 FL	*972.40 FL
2	1		*REAR BOOT INNER COVER	Cut	520.00 FL	*153.40 FL
3	1		*REAR BOOT GARNISH	Not Necessary	270.00 FL	*- FL
4	1		*REAR BUMPER	Deformed	730.00 FL	*463.70 FL
5	1		*REAR BUMPER LOWER COVER	Not Necessary	450.00 FL	*- FL
6	1		*REAR END PANEL	Repair	730.00 FL	*- FL
7	1		*REAR END PANEL TOP COVER	Deformed	210.00 FL	*92.30 FL
8	1		*TAILGATE LAMP-INNER	Cracked	750.00 FL	*529.20 FL
9	1		*TAILGATE LAMP-OUTER	Cracked	920.00 FL	*857.40 FL
10	1		*LOCK	Bent	380.00 FL	*157.10 FL
11	1		*REAR RIGHT SIDE PAD	Deformed	480.00 FL	*195.00 FL
12	1		*REVERSE SENSOR	Not Necessary	200.00 FS	*- FS
13	1		*RELAY SENSOR	Not Necessary	180.00 FS	*- FS
14	1		*WINDSCREEN MOULDING	Necessary	150.00 FS	*50.00 FS
15	1		*SILICON SEALANT	Necessary	100.00 FS	*40.00 FS
16	1		*CLIPS	Necessary	80.00 FS	*30.00 FS
17	1		*HONDA EMBLEM	Not Necessary	95.00 FS	*- FS
18	1		*VEZEL EMBLEM	Necessary	75.00 FS	*30.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	7,860.00	3,570.50
- List Item Discount on L Items 20.00/20.00% (S\$)	1,396.00	684.10
Total Parts (S\$)	6,464.00	2,886.40

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO PUTTY & SPRAY PAINT OF AFFECTED AREA	New	1,200.00	700.00
2	TO PANEL BEAT & RENEWAL OF ALL NECESSARY DAMAGED BODY PARTS	New	1,500.00	400.00
3	TO CHECK WIRING & REWIRE	New	80.00	30.00
4	TO REMOVE AND REINSTALL TAILGATE COMPONENTS }	New	120.00	60.00
5	TO REMOVE AND REINSTALL REAR BOOT UPHOLSTERY }	New	120.00	0.00
6	TO REMOVE AND REINSTALL REAR WINDSCREEN	New	200.00	100.00
7	TO REMOVE & REINSTALL REVERSE & RELAY SENSOR	New	150.00	40.00
8	TO CHECK LIGHTING SYSTEM	New	120.00	0.00
9	ANTI RUST TREATMENT	New	120.00	0.00
Gross Labour Cost (\$\$)			3,610.00	1,330.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >