

ASS. REC. BY:

REF: CS31/FWD19004699/Gcd35<sup>2</sup>

Special Instruction:

Surveyor: Cuo Cieny  
From (Person): Minmen Lionel Tan

ASSIGNMENT (Office)

of PWD

Date/Time: 14/3/19 @ 1:54pm

Estimated Cost: \_\_\_\_\_ Bill to: \_\_\_\_\_

OD  TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SDQ 9779R

Insured: SJS 29274

at Workshop m/s: S.L. Motor

Tel: 9107 9182

of 1 Kaki Bkt Ave 6# 01107

Policy No: PNP V 2018-00503175-01

Claim No: 1201900006311

Sum Insured: \_\_\_\_\_

Excess: \_\_\_\_\_

Make of Veh: \_\_\_\_\_  
(Client's Record)

D.O.A. 11/3/19

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement: \_\_\_\_\_

Date/Time: 2:41pm 15/3/19

Person Contacted: Ah Hong

Vehicle:  IN  OUT

Date/Time	Action/Instruction (X) Estimate
	SDQ 9779R - NA/CTI/91004320/ha DUA: 11/3/19
	SJS 29274 - NA/CTI/91004320/ha DUA: 11/3/19
	Dismantle: 15/3/2019
	After repair: 26/3/2019

PPRS  
GA


REF: FWD

46086 (-2028)

ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
 OD  TP / WS / TP RES / OD RES / EVA / INV / MV  
 To Inspect Vehicle No: \_\_\_\_\_  
 at Workshop m/s: S.L. Motor  
 of \_\_\_\_\_  
 Insured: \_\_\_\_\_  
 Policy No. \_\_\_\_\_  
 Claims No. \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_

Veh No: SDQ9779R Yr Regn: 24 Sep 2008  
 Type:  M.C. / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
 Truck / Trailer or \_\_\_\_\_  
 Make: Merce C200 C.C. 1796  
 Colour: Black A/C: Insured / Std / NI / NA  
 Sp. Reading: 185585 T/Radio: Insured / Std / NI / NA  
 Eng/No: \_\_\_\_\_  
 C/No: WDD2040412A191563  
 Gen. Cond:  Good / Fair / Poor / Burnt  
 Steering:  In order / Jammed / Leaked / Burnt or \_\_\_\_\_  
 Brake:  In order / Jammed / Leaked / Burnt or \_\_\_\_\_  
 Modi: Nil / S/Rim / STD  A/Rim or \_\_\_\_\_  
 Tyre Size: F: 225 / 45 R17  
 R: 17  
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
 TOYO / YOKO or ling long  
 Front R/Bal. 5 mm Rear R/Bal. 5 mm  
 L/Bal. 5 mm L/Bal. 5 mm  
 D.O.A. \_\_\_\_\_ D.O.I. 14-03-19  
 Survey held at w/s  
 Des. of Damages  Frt /  Rear / O/S / N/S / U/C / Rooftop or  
 The U/C / Chassis frame / Body Structure affected due to collision.



(Policy Condition)  
 Remark: The veh had commenced its repair at the time of inspection.  
 Bal. or Market Value: \$60k  
 IDAC Accident Rport. Consistent? : Yes or No  
 GIA / PR Seen: Consistent? : Yes or No  
 Est. Repairs: 10 days Res.: Yes or No  
 Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No  
 CA / REV / REP. / 24 HRS  
 Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

Date / Time	Action / Instruction
	\$8000 - \$10k

Date/Time, File Pass to?  : Preli. Report  
 : Final Report  
 1) \_\_\_\_\_  
 Date/Time, File Return to? \_\_\_\_\_  
 2) \_\_\_\_\_

Days Of Repair: 10  
 Resurvey No. of Trip: 2

Report Format: PRS  
 Lump Sum / I.B.I: (\$ \_\_\_\_\_)

Add Fee:  : Site Insp (\$ \_\_\_\_\_)  
 : Interview (\$ \_\_\_\_\_)  
 : Tech. Invs (\$ \_\_\_\_\_)  
 : Weekend (\$ \_\_\_\_\_)

Survey Fee: \_\_\_\_\_  
 Transportation: \_\_\_\_\_  
 S + RS, SI \_\_\_\_\_  
 Photos \_\_\_\_\_  
 Others \_\_\_\_\_  
 TOTAL \_\_\_\_\_

## Nivitha (LKK Auto)

---

**From:** lionel.tan@fwd.com  
**Sent:** Thursday, 14 March 2019 1:59 PM  
**To:** assignments@lkkauto.com; sur@lkkauto.com  
**Cc:** motorclaims.sg@fwd.com  
**Subject:** FW: Notice of PRI of vehicle SDQ 9779 R // FWD - SJS2927U  
**Attachments:** FW: Notice of PRI of vehicle SDQ 9779 R (26.9 KB)

[Policy Number: PNPV2018-00003175-01]

Hi LKK Team,

Please arrange PRI with repairer.

Refer to attached workshop details.

Regards,  
Lionel

---

**From:** Lionel Tan Tian Pei - SGUser  
**Sent:** Thursday, March 14, 2019 1:01 PM  
**To:** 'Mdm Ling'  
**Cc:** Motor Claims SG - SG Common; 'Ling Leong Hui'  
**Subject:** RE: Notice of PRI of vehicle SDQ 9779 R // FWD - SJS2927U

### WITHOUT PREJUDICE

Dear Sir/ Madam,

Please advise your clients contact and workshop location.

Thank you.

Regards,  
Lionel

---

**From:** Mdm Ling [<mailto:mdmling@tcmg.com.sg>]  
**Sent:** Thursday, March 14, 2019 11:02 AM  
**To:** Lionel Tan Tian Pei - SGUser  
**Cc:** Motor Claims SG - SG Common; Ling Leong Hui  
**Subject:** RE: Notice of PRI of vehicle SDQ 9779 R // FWD - SJS2927U

### WITHOUT PREJUDICE

Dear Sir,

We refer to the above matter and to your e-mail of even date.

Our client is not agreeable to any of your appointed panel of surveyors as the Single Joint Expert.

Our client's panel of surveyors nominated as the Single Joint Expert is as attached.

Yours faithfully,

Mdm Ling  
TOMMY CHOO MARK GO LLC

---

**From:** [lionel.tan@fwd.com](mailto:lionel.tan@fwd.com) [mailto:[lionel.tan@fwd.com](mailto:lionel.tan@fwd.com)]  
**Sent:** Thursday, March 14, 2019 10:45 AM  
**To:** [mdmling@tcmg.com.sg](mailto:mdmling@tcmg.com.sg)  
**Cc:** [motorclaims.sg@fwd.com](mailto:motorclaims.sg@fwd.com)  
**Subject:** [Spam-pop3] RE: Notice of PRI of vehicle SDQ 9779 R // FWD - SJS2927U

**Without Prejudice**

Dear Sir/Madam,

Please select one of our surveyors as follows: -

1. LKK AUTO CONSULTANTS PTE LTD
2. INFINITI APPRAISAL SERVICE
3. AJAX INSPECTION SERVICES PTE LTD
4. APPRAISALS ASSOCIATES PTE LTD
5. VICOM LTD

If you are not agreeable to any of the above, we would proceed to appoint a surveyor to conduct a pre repair survey & post repair inspection within the timeline stipulated under the NIMA protocol.

We look forward to your reply.

Thank you.

Lionel

---

**From:** Mdm Ling [mailto:[mdmling@tcmg.com.sg](mailto:mdmling@tcmg.com.sg)]  
**Sent:** Thursday, 14 March, 2019 8:58 AM  
**To:** Motor Claims SG - SG Common  
**Subject:** Notice of PRI of vehicle SDQ 9779 R

Dear Sir,

We refer to the above matter.

Attach herewith the notice of PRI of vehicle SDQ 9779 R for your attention.

Yours faithfully,

Mdm Ling  
Tommy Choo Mark Go LLC

ATTENTION:

The email and any attachments transmitted with it are private and confidential and intended solely for the use of the individual or entity to whom they are addressed. If you have received this email in error, please notify the sender immediately and delete this email and any attachments from your system. You should not use, disclose, copy or store this email and any attachments.

Messages and attachments are scanned for all viruses known. However, you are advised that you open any attachments at your own risk. If this message contains password-protected attachments, the files have NOT been scanned for viruses by our mail domain. Please always scan for viruses before opening any attachments.

**ATTENTION:**

The email and any attachments transmitted with it are private and confidential and intended solely for the use of the individual or entity to whom they are addressed. If you have received this email in error, please notify the sender immediately and delete this email and any attachments from your system. You should not use, disclose, copy or store this email and any attachments.

Messages and attachments are scanned for all viruses known. However, you are advised that you open any attachments at your own risk. If this message contains password-protected attachments, the files have NOT been scanned for viruses by our mail domain. Please always scan for viruses before opening any attachments.

# TOMMY CHOO, MARK GO LLC

Advocates & Solicitors

UEN NO : 201523418E

(a law corporation with limited liability)

151 CHIN SWEE ROAD #14-15/16  
MANHATTAN HOUSE  
SINGAPORE 169876  
TEL : (65) 6532 2455  
FAX : (65) 6538 9850 (Services of Court Documents By Fax Not Accepted)

EMAIL: lhling@tcmg.com.sg;mdmling@tcmg.com.sg

Our Ref: TCMG/SDQ9779R/0319/SLM

Your Ref: SJS 2927 U

14 March 2019

**BY E-MAIL ONLY**  
(motorclaims.sg@fwd.com)

**M/S FWD SINGAPORE PTE LTD**

6 Temasek Boulevard  
#18-01  
Suntec Tower 4  
Singapore 038986

Attn: Motor Claims Department

Dear Sirs,

## PRE-REPAIR INSPECTION NOTICE

We act for **Cheng Gim Seng**, the owner and/or driver of motor vehicle no. **SDQ 9779 R**, which was involved in an accident along ECP towards City on 11 March 2019 at 07:10 hrs.

We hereby give you **NOTICE** that we are claiming against your insured motor vehicle no. **SJS 2927 U** for damages and/or injuries, costs and disbursements as a result of your insured's negligence.

Kindly let us know if you wish to conduct a pre-repair inspection on our client's motor vehicle at M/s S L Motor Repair, (c/o 1 Kaki Bukit Avenue 6 #01-107, Singapore 417883 - Ah Heng @ 91079182).

If we do not hear from you within the next **two (2) working days**, we shall deem that you have waived the requirement for the pre-repair inspection.

Yours faithfully,



**MR LING LEONG HUI**

cc. M/s SL Motor Repair  
(Yref:SDQ9779R)

---

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	4608G
Vehicle Details	
Vehicle No.:	SDQ9779R
Vehicle to be Exported:	No
Intended Deregistration Date:	14 Mar 2019
Vehicle Make:	MERCEDES BENZ
Vehicle Model:	C 200 KOMPRESSOR
Primary Colour:	Black
Manufacturing Year:	2008
Engine No.:	27195031106024
Chassis No.:	WDD2040412A191563
Maximum Power Output:	135.0 kW (181 bhp)
Open Market Value:	\$43,084.00
Original Registration Date:	24 Sep 2008
First Registration Date:	24 Sep 2008
Transfer Count:	1
Actual ARF Paid:	\$43,084.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	23 Sep 2028
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
PQP Paid:	\$33,377.00
COE Rebate Amount:	\$31,791.00
<b>Total Rebate Amount:</b>	<b>\$31,791.00</b>

The information contained herein is correct as at 14 Mar 2019

OK

## ▶ Mercedes-Benz c200 Used Vehicle List (11 vehicles)

Car Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Company	Availabi
<b>Mercedes-Benz C-Class C200 (COE till 04/2021)</b>	<b>\$14,800</b>	\$6,950 /yr	25-Apr-1997	1,998 cc	-	Auto Zoom Enterprise Pte Ltd	Availal
Good Running Condition. Selling As It Is. Silver Paintwork With Beige Interior. Own A Piece Of Classic Now. Office No. - 63421000 Jeffrey - 90041167   Stanley Chua - 96813489   Robin - 97603335							
<b>Mercedes-Benz C-Class C200 (New 10-yr COE)</b>	<b>\$48,800</b>	\$4,880 /yr	20-Jul-2000	1,998 cc	-	Motorone Pte Ltd	Availal
Only One Owner. Selling With New 10 Years COE. Very Well Maintained. New Paint Will Be Given. Smooth Engine And Automatic Transmissic No Repair Needed. Very Reliable Model. Trade In Welcome. Office No. - - Lawrence - 94551331							
<b>Mercedes-Benz C-Class C200K (New 10-yr COE)</b>	<b>\$62,888</b>	\$6,280 /yr	22-Dec-2008	1,796 cc	-	Mandai Motor Trading	Availal
Office No. - 67775585 Heng Heng - 90058812   Darren - 82233251   Ms Li Jin - 97548093   Mr Chong - 93513956							
<b>Mercedes-Benz C-Class C200K (New 5-yr COE)</b>	<b>\$45,800</b>	\$9,150 /yr	23-Dec-2008	1,796 cc	113,216 km	United Motoring Pte Ltd	Availal
High Loan With 3.98% - 4.25% Lowest Interest Guaranteed. Extremely Well Maintained By Owner! Sporty Yet Fuel Efficient! Quiet And Smo Engine And Gearbox! 1 To 1 Exchange With High Trade In Value Av... Office No. - 64635355 Alan - 93483386   Zack - 87672182   Jasper - 88188897   Calvin - 88008820							
<b>Mercedes-Benz C-Class C200K (COE till 01/2024)</b>	<b>\$45,800</b>	\$9,500 /yr	08-Jan-2009	1,796 cc	122,741 km	United Motoring Pte Ltd	Availal
Panoramic Roof Unit! Full View Of The Sky From Rear To Front! High Loan Available With The Lowest Interest Guaranteed For A COE Unit, B Surprised. Extremely Well Maintained By Owner! Sporty Yet Fuel ... Office No. - 64635355 Jasper - 88188897   Zac - 87672182   Calvin - 88008820							
<b>Mercedes-Benz C-Class C200K (COE till 01/2029)</b>	<b>\$64,800</b>	\$6,590 /yr	12-Jan-2009	1,796 cc	168,889 km		Availal
New 10 Years COE, Well Maintain, Accident Free, No Repair Needed, View To Appreciate. Office No. - - Chin - 97266885							
<b>Mercedes-Benz C-Class C200K (COE till 01/2029)</b>	<b>\$68,888</b>	\$6,990 /yr	19-Jan-2009	1,796 cc	122,000 km	JDM Cars	Availal
4 New Tyres And Sports Rims! Free 1 Servicing Upon Purchase! Up To 2 Years Warranty Engine And Gearbox! 100% Loan Approval! Bank Ai In House Loan Available! No Gimmicks! Trade In Welcome! Priced Lowe... Office No. - 62994111 Yang - 92981269   William Chew - 96463854   John - 90105163   Patrick Wong - 93865066							
<b>Mercedes-Benz C-Class C200K (New 10-yr COE)</b>	<b>\$71,800</b>	\$7,170 /yr	22-Jan-2009	1,796 cc	111,000 km	AA Trust Automotive	Availal
AA Trust Certified Quality 1 Owner Vehicle! Well Maintained By Previous Owner! The Perfect Executive Sedan That Suits Every And Any Occasion! Unit Comes With Diamond Grille Facelift! Powerful Engine A... Office No. - 63450381 Willey - 91692071   Clement - 93365036   Dave - 98500051   Joanna - 81895495							
<b>Mercedes-Benz C-Class C200K Avantgarde (COE till 01/2029)</b>	<b>\$62,800</b>	\$6,370 /yr	23-Jan-2009	1,796 cc	-	First Auto Car Pte Ltd	Availal

### ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	11 Mar 2019 <a href="#">Edit Reg</a>		14 Mar 2019 00:00 <a href="#">Edit Adj Rpt</a>	<b>S\$0.00</b> <a href="#">Edit Estimates</a>	<b>S\$0.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

[Main](#)
[Reference](#)
[Claim Details](#)
[Documents](#)
[Show All](#)

CLAIM SUBFOLDER DETAILS		[Created by adjuster]	
Insured:	Amos Tan Peng Lam, ID: S7012765B		
Main Claimant:	-		
Vehicle Reg. No.:	SDQ9779R	Date of Loss:	11/03/2019 00:00 - :59 [125 Months and 15 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 1201900006311	Policy/Cover Note No.:	PNPV2018-00003175-01 (Comprehensive)
Vehicle Reg. No. (Insured):	SJS2927U	Policy No. (Claimant):	
		Excess:	
Repairer:	- Not Applicable - (-)		
Handling Insurer:	FWD Singapore Pte. Ltd. (HQ) - Tel: 6727 5700 ... [Handled by Lionel Tan]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 26/03/2019]		
<b>ASSOCIATED MAIL RECEIVED</b>		<a href="#">View All</a>	<a href="#">Compose Case Mail</a>
There are no mail for this case.			
<b>ALL ASSOCIATED TASKS</b>		<a href="#">View All</a>	<a href="#">Search Tasks</a>
		<a href="#">Create New Task</a>	<a href="#">Complete</a>
Due Date	Priority	Type	Task Group
			Subject
			Handler
			Assigned By
			Completed On
			Created On
			Done?
No results.			



## Claim Documents

**\*SDQ9779R (1201900006311)**  
**[SJS2927U]**  
**TP**

-  
**Mar 11 2019 12:00AM**  
**[Amos Tan Peng Lam]**

**View**

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	18/03/19 10:14	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
2	18/03/19 10:14	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
3	18/03/19 10:14	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
4	18/03/19 10:14	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
5	18/03/19 10:14	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
6	18/03/19 10:14	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
7	18/03/19 10:14	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
8	18/03/19 10:14	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
9	18/03/19 10:14	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
10	18/03/19 10:14	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
11	18/03/19 10:14	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
12	18/03/19 10:14	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
13	18/03/19 10:14	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
14	18/03/19 10:14	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
15	18/03/19 10:14	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
16	18/03/19 10:14	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
17	18/03/19 10:14	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
18	18/03/19 10:14	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
19	18/03/19 10:14	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
20	18/03/19 10:14	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
21	18/03/19 10:14	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
22	18/03/19 10:14	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
23	18/03/19 10:14	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
24	18/03/19 10:14	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
25	18/03/19 10:14	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
26	18/03/19 10:14	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
27	18/03/19 10:14	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
28	18/03/19 10:14	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
29	18/03/19 10:14	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
30	18/03/19 10:14	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
31	18/03/19 10:14	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
32	18/03/19 10:14	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
33	18/03/19 10:14	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
34	18/03/19 10:14	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
35	18/03/19 10:14	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
36	18/03/19 10:14	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
37	18/03/19 10:14	General View	 Load JPG	<input checked="" type="checkbox"/>
38	18/03/19 10:14	General View	 Load JPG	<input checked="" type="checkbox"/>
39	18/03/19 10:14	General View	 Load JPG	<input checked="" type="checkbox"/>
40	18/03/19 10:14	General View	 Load JPG	<input checked="" type="checkbox"/>
41	18/03/19 10:14	General View	 Load JPG	<input checked="" type="checkbox"/>
42	18/03/19 10:14	General View	 Load JPG	<input checked="" type="checkbox"/>
43	18/03/19 10:14	General View	 Load JPG	<input checked="" type="checkbox"/>
44	18/03/19 10:14	General View	 Load JPG	<input checked="" type="checkbox"/>
45	18/03/19 10:14	General View	 Load JPG	<input checked="" type="checkbox"/>
46	18/03/19 10:14	General View	 Load JPG	<input checked="" type="checkbox"/>
47	18/03/19 10:14	General View	 Load JPG	<input checked="" type="checkbox"/>
48	18/03/19 10:14	General View	 Load JPG	<input checked="" type="checkbox"/>
49	18/03/19 10:14	General View	 Load JPG	<input checked="" type="checkbox"/>
50	18/03/19 10:14	General View	 Load JPG	<input checked="" type="checkbox"/>
51	18/03/19 10:14	General View	 Load JPG	<input checked="" type="checkbox"/>
52	18/03/19 10:14	General View	 Load JPG	<input checked="" type="checkbox"/>
53	18/03/19 10:14	Odometer Reading	 Load JPG	<input checked="" type="checkbox"/>
54	18/03/19 10:14	Chassis Number	 Load JPG	<input checked="" type="checkbox"/>
55	18/03/19 10:15	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
56	18/03/19 10:15	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
57	18/03/19 10:15	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
58	18/03/19 10:15	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
59	18/03/19 10:15	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
60	18/03/19 10:15	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
61	18/03/19 10:15	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
62	18/03/19 10:15	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
63	18/03/19 10:15	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
64	18/03/19 10:15	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
65	18/03/19 10:15	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
66	18/03/19 10:15	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
67	18/03/19 10:15	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
68	18/03/19 10:15	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
69	18/03/19 10:15	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
70	18/03/19 10:15	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
71	18/03/19 10:15	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
72	18/03/19 10:15	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
73	18/03/19 10:15	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
74	18/03/19 10:15	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
75	18/03/19 10:15	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
76	18/03/19 10:15	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
77	18/03/19 10:15	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
78	18/03/19 10:15	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
79	18/03/19 10:15	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
80	18/03/19 10:15	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
81	18/03/19 10:15	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
82	18/03/19 10:15	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
83	18/03/19 10:15	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
84	18/03/19 10:15	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
85	18/03/19 10:15	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
86	18/03/19 10:15	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
87	18/03/19 10:15	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
88	18/03/19 10:15	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
89	18/03/19 10:15	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
90	18/03/19 10:15	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
91	18/03/19 10:15	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
92	18/03/19 10:15	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
93	18/03/19 10:15	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
94	18/03/19 10:15	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
95	18/03/19 10:15	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
96	18/03/19 10:15	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
97	18/03/19 10:15	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
98	18/03/19 10:15	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
99	18/03/19 10:15	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
100	18/03/19 10:15	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
101	18/03/19 10:15	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
102	18/03/19 10:15	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
103	18/03/19 10:15	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
104	18/03/19 10:15	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
105	18/03/19 10:15	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
106	28/03/19 17:39	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
107	28/03/19 17:39	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
108	28/03/19 17:39	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
109	28/03/19 17:39	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
110	28/03/19 17:39	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
111	28/03/19 17:39	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
112	28/03/19 17:39	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
113	28/03/19 17:39	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
114	28/03/19 17:39	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
115	28/03/19 17:39	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
116	28/03/19 17:39	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
117	28/03/19 17:39	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
118	28/03/19 17:39	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
119	28/03/19 17:39	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
120	28/03/19 17:39	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
121	28/03/19 17:39	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
122	28/03/19 17:39	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
123	28/03/19 17:39	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
124	28/03/19 17:39	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
125	28/03/19 17:39	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
126	28/03/19 17:41	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
127	28/03/19 17:41	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	FWD Singapore Pte. Ltd. (HQ)	Thumbnail	Print
1	22/03/19 18:27	E-filed GIA report	 Load PDF	

# Documents Checklist

## DOCUMENTS CHECKLIST

[Reset](#) [Save](#) [Print](#)

There are no document checklists configured.

### Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To:  Handling Insurer

Note: Remarks are private unless you show it to other parties.

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS3/FWD19004699/GCD3S2  
**Date:** 01/04/2019

### REFERENCE

Handling Insurer: FWD Singapore Pte. Ltd. Policy No: PNPV2018-00003175-01  
**Claimant Vehicle No :** SDQ9779R **Insured Vehicle No :** SJS2927U  
 Date of Loss: 11/03/2019 Nature of Claim: TP Claim No: 1201900006311

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SDQ9779R**  
 Make & Model: MERCEDES-BENZ C200, 1.8 Kompressor (A) Engine No: 27195031106024  
 Reg. Date: 24/09/2008 (Man. Year: 2008) Chassis No: WDD2040412A191563  
 Colour: Black Odometer: 185585 km  
 Engine Capacity: 1796 cc  
 Market Value/New Car Price: N/A  
 Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 225/45R17 Rear Tyre Size: 225/45R17  
 Front Left Side: Linglong 5 mm Rear Left Side: Linglong 5 mm  
 Front Right Side: Linglong 5 mm Rear Right Side: Linglong 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

### INSPECTION

Date of Assignment: 14/03/2019  
 Date Inspected: 14/03/2019 Inspected At: 1 KAKI BUKIT AVE 6 #01-107  
 Estimated Period of Repair: 10.0 days Repairer: S.L. MOTOR SERVICES

**Adjuster:** XING GUO QIANG

**Manager:** CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.  
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$8,000.00 - \$10,000.00

## REPAIR DETAILS

### Reference

**Part Source:** MRM-SG      Version: 1.0 (Last Synchronised: 01 Apr 2019)

**Parts:**            143            MERCEDES-BENZ C200 1.8 Kompressor (A) (Catalogue:Merimen Singapore 1.0)

**Labour:**          Repairer's      (Price-denominated Standard List)

**Print Code:** (Unsubmitted, no print-code for SDQ9779R)

**Validity:**        These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.

### Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >