

ASS. REC. BY:

REF:

CS/CTI19004701/E-10302

Est. Instruction:

SURVEYOR

Steve

ASSIGNMENT (Office)

Meimen

From (Person):

Chong Sun Sen

of

CTI

Date/Time: 14/3/2019 @ 9:56am

Estimated Cost:

Bill to:

OD (TP) WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SGX 7180R

Insured:

GBA 5655Z

at Workshop m/s:

Leit Huat (Meng Kee)

Tel:

64538110

of

160 Sin Ming Drive #04-01

Policy No:

DMCVSN/8254618000

Claim No:

SNM19D20113402

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

12/3/2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

10:30am on 15/3/19

Person Contacted:

jenny

Vehicle IN OUT

Date/Time

Action/Instruction (✓) Estimate

SGX 7180R - CCE/AIG/13001742/7/16/19 392

DUA: 22/1/13

GBA 5655Z - CCA/EAI/SUIS439/Ming 352

DUA: 8/9/15

Part by Part \$2310.44 confirm.

5days

(Red: 63% 27%)

Steve

REF:

ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
OO / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop no: _____

of _____

Insured _____

Policy No _____

Claims No _____

Sum Insured _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S
X	X

Bal. or Market Value _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lump Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: **SGX 7980 R** Yt Regn: **7/09/2007**

Type: **M.Car** / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: **Toyota Rush** CC: **1.5**

Colour: **Black** A/C: Insured / Std / NI / NA

Sp. Reading: **160796** T/Radin: Insured / Std / NI / NA

Eng/No: _____

C/No: **J200E0016799**

Gen. Cond: **Good** / Fair / Poor / Burnt

Steering: **in order** / Jammed / Leaked / Burnt or

Brake: **in order** / Jammed / Leaked / Burnt or

Modif: Nil / S/Rim / STD A/Rim or

Tyre Size: F: **215/60R16**

R: **11**

BS / **DUN** / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal: **6** mm R/Bal: **6** mm

L/Bal: **6** mm L/Bal: **6** mm

D.O.A: **12/3/19** D.O.I: **14/3/19**

Survey held at: **Lai Huat**

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time: _____ Action / Instruction

MV - 21,000

PL - 15,719

NI - 7281

RECEIVED 09 APR 2019

[Signature]
8/4/2019

Date/Time: File Pass to?

914 Typist

Date/Time: File Return to?

: Prel. Report

: Final Report

Days Of Repair: **5**

Resurvey No. of Trip: **2**

Survey Fee:

220

Transportation

3 + R5 2

Private

Notes

100

100

Add Fee: : Site Insp (\$

: Interview (\$

: Tech Invs (\$

: Weekend (\$

Report Format: **TP**

Lump Sum / (B) : **2310.44**

220

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Revised	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Inv Auth'd	Status
Main	13 Mar 2019 Sendback Est	13 Mar 2019 17:56 \$2,273.44	14 Mar 2019 09:56 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS

Insured:	He Fengyang, ID: S2650662Z		
Main Claimant:	LIN PEISHAN AGNES, ID: S8523641E		
Vehicle Reg. No.:	SGX7980R	Date of Loss:	12/03/2019 08:00 - :59 [138 Months and 5 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / SNM19D201134C02	Policy/Cover Note No.:	DMCVSN18254618000
Vehicle Reg. No. (Insured):	GBA5655Z	Policy No. (Claimant):	1700032612-01
		Excess:	\$50.00
Repairer:	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming) 160 Sin Ming Drive #04-01, Sin Ming AutoCity, 575722 Sin Ming - Tel: 64538110		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]		
Claimant's Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 25/03/2019]		
Driver/Custodian (Insured):	He Fengyang (/ Male) , NRIC: S2650662Z Email:		

ASSOCIATED MAIL RECEIVED

[View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Denise Tay (LKKAuto)

From: Denise Tay (LKKAuto)
Sent: Monday, 8 April 2019 11:09 AM
To: Jenny Lim; Steve Chen (LKK Auto)
Cc: SUR
Subject: RE: Finalisation - SGX 7980R / Toyota Rush
Attachments: SGX 7980R REPORT.pdf

Dear Jenny,

As spoken with Steve, Confirm \$2310.44, 5days

Please submit your documents to China Taiping directly.

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Jenny Lim <jenny.lim@laihuat.com.sg>
Sent: Saturday, 6 April 2019 11:33 AM
To: Steve Chen (LKK Auto) <SteveChen@lkkauto.com>
Cc: SUR <sur@lkkauto.com>
Subject: Finalisation - SGX 7980R / Toyota Rush

Dear Sir

For your confirmation, please:

- Parts: \$1,465.00
- Sundry: \$ 100.00
- L&P: \$ 745.44
- Total: \$2,310.44 / 8 days**

Supporting documents and photographs are enclosed for your reference.

Thank you.

Kind regards.

Jenny Lim
for LAI HUAT (MENG KEE) MOTOR PTE LTD
160 Sin Ming Drive
#04-01, #04-02 & #07-03
Sin Ming Autocity
Singapore 575722
Tel: 64538110
Fax: 64596267

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	12/03/2019 09:49
Date Of Accident	12/03/2019 08:15
Exact Location Of Accident	SELETAR NORTHLINK
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SGX7980R
Insured/Policyholder	
Name Of Registered Owner	LIN PEISHAN AGNES
NRIC No	S8523641E
Email Address	AGNESLIN85@GMAIL.COM
Mobile Phone No	(LOCAL) +65-81004533
Alternative Phone No	OTHERS-81004533
Vehicle Particulars	
Manufacturer	TOYOTA
Model	RUSH
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	1700032612-01
Cover Note Number	
Driver	
Name of Driver	TAN WEI GUANG BENSON
NRIC No	S8529881Z
Date Of Birth	16/09/1985
Occupation	INDOOR
Date Of Driving Pass	17/05/2016
Driving Experience	2 YEARS AND 9 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-81000341
Fax Number	
Contact Number	
Email Address	BENSONTANWG@GMAIL.COM

Address	414 SEMBAWANG DRIVE #04-726
Postcode	750414
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	SPOUSE
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	YES
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO SKETCH PLAN.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBA5655Z
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	HE FENGYANG
NRIC/Passport Number	S2650662Z
Contact Number	90085928
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation**.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature

Date & Time:

12 MAR 2019




Driver's Signature

(If driver is not the policyholder)

Date & Time:

12/3/19
9:43 AM



Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

Jenny Lim
S8927273H

2019 MAR 12

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S8529881Z



Name

TAN WEI GUANG, BENSON

陈伟光

Race

CHINESE

Date of birth

16-09-1985

Sex

M

Country of birth

SINGAPORE

S8529881Z



S852190



NRIC No. S8529881Z

Date of issue

26-03-2012

Address

APT BLK 414 SEMBAWANG DRIVE
#04-725
SINGAPORE 750414

REPUBLIC OF SINGAPORE DRIVING LICENCE


 Licence Number: **S8529881Z**
 Name: **TAN WEI GUANG, BENSON**
 Birth Date: **16 Sep 1985**
 Issue Date: **04 Dec 2014**

002372437E



YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

		EFFECTIVE DATE
Class 2B	MOTORCYCLES NOT EXCEEDING 200 CC	04 Dec 2014
Class 3A	MOTOR CARS AND MOTOR TRACTORS WITHOUT CLUTCH PEDALS THE WEIGHT OF WHICH UNLOADED DOES NOT EXCEED 2000 KILOGRAMS	07 May 2014

MODEL: _____ S / No. 9000247847

Licence No: S8529881Z


HP 428A



CERTIFICATE OF INSURANCE

AUTOPLUS PRIVATE VEHICLE

Name of Policyholder : LIN PEISHAN, AGNES
Period of Insurance : 07 Sep 2018 To 06 Sep 2019
Engine No. : 3SZ1922403
Chassis No. : J200E0016799

Vehicle No. : SGX7980R
Policy No. : 1700032612-01
Endorsement No. :
Issued Date : 16 Aug 2018

ABOUT THE COVER

Make/Model : TOYOTA RUSH 1.5
Engine Capacity/Tonnage : 1,495.00 CC
Driver Restriction : NA
Person or Classes of Persons Entitled to Drive* :

Sum Insured : Market Value
Off Peak Car : No
First Year of Registration : 2007
Insuring with COE/PARF : Yes

a) The Policyholder
 b) Any other person who is driving on the Policyholder's order or with his/her permission.
 This Policy will indemnify the Policyholder or any authorized driver only if he/she meets the specified age condition.

You have to pay an additional sum of \$3,000 as "Young and/or Inexperienced Driver Excess" ("YIDR") if You are or Your Authorized Driver (named or unnamed) is under the age of 23 and/or has less than 3 years' driving experience.

Age Condition : All Age Condition
Limitation as to use* :

Use only for social, domestic and pleasure purposes and for the Policyholder's business.
 This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

Loss of Use 1500cc - 1600cc Optional

* Limitations rendered imperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 186) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS

Section 1
 Fire - \$0 Own Damage - \$600 Theft - \$0 Flood Cover - \$0

Section 2
 Property Damage - \$0

Windscreen : \$100

Named Driver and Excess (where applicable)

LIN PEISHAN, AGNES - \$600 (Own Damage)

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

Approved Reporting Centres/ AIG Authorised Repairers (For claims related repairs)
 Any accident repairs to the Vehicle must be carried out by one of our Authorised Repairers. Within the first 3 years of the first registration of the Vehicle in Singapore. You have the option of having the accident repairs carried out at the Sole Agent's workshop.
 For other Approved Reporting Centres/AIG Authorised Repairers, please contact our 24-hour accidents emergency hotline at +65 6308 6200. Alternatively, You may refer to AIG website www.aig.com.sg or AIG SG Mobile App. Simply search and download "AIG SG" from iTunes or Google Play.

IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: KENSO LEASING PTE LTD

I/We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap. 186), Part IV of the Road Transport Act, 1987 (Malaysia) and Motor Vehicles (Third Party Risks) Rules, 1989 (Malaysia).

0501295000

INSURE LINK PTE LTD
 2 KALLANG AVE #08-16 CT HUB
 SINGAPORE 339407

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

Manile

AIG Asia Pacific Insurance Pte. Ltd.
 AUTHORISED REPRESENTATIVE

Yeh Ying Lin

> **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 3641E

Vehicle Details

Vehicle No.: SGX7980R
Vehicle to be Exported: Yes
Intended Deregistration Date: 12 Mar 2019
Vehicle Make: TOYOTA
Vehicle Model: RUSH 1.5 A
Primary Colour: Black
Manufacturing Year: 2007
Engine No.: 3SZ1922403
Chassis No.: J200E0016799
Maximum Power Output: 80.0 kW (107 bhp)
Open Market Value: \$13,046.00
Original Registration Date: 07 Sep 2007
First Registration Date: 07 Sep 2007
Transfer Count: 2
Actual ARF Paid: \$14,351.00

Intended PARF Rebate Details

PARF Eligibility: Forfeited
PARF Eligibility Expiry Date: -
PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 31 Aug 2022
COE Category: A - Car (1600cc & below)
COE Period(Years): 5
PQP Paid: \$22,700.00
COE Rebate Amount: \$15,743.00
Total Rebate Amount: \$15,743.00

Message

Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 12 Mar 2019

OK

Enquire Vehicle Insurer

Vehicle No.	Incident Date/Time	Search Status	Insurance Company Code	Insurance Company Name
GBA5655Z	12 Mar 2019 / 08:14:00	Successful	C01	CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD

Previous

OK



Thank you

Lai Mei Ling Deborah has successfully logged out.

Your last login date and time was 12 Mar 2019, 09:48:02.

To return to ONE.MOTORING, please click [here](#)

For security reasons, please **CLEAR YOUR CACHE** after each session.

Session Transaction History


S/No.	Asset Type	Asset ID	Asset Owner ID	Transaction Type
1	Vehicle	GBA5655Z	-	18.32 Insurance Enquiry (GIRO Payment)
• Log Date/Time 12 Mar 2019 / 09:48:19				

500+ dealers
competed to
buy my car!



Sell ur Car for More Cash
Highest Price or Get \$100 Free
Get Paid Now, Handover Later

SELL YOUR CAR



Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

One-Demon, Cycle And Carriage Unit, Stock Car...



Well Maintained, Super
Clean, New Tyres,
Direct Owner

HIN LUNG AUTO
The One Group
One Stop Car Hub
Finance, Insurance, Workshop
New and Used Cars

30 years
of car care

[Post an Ad](#) [Advertiser Login](#) [View of Selling](#)

Browse by Category

« Back (1 2) Next »

Sort by Date Posted 20 results/page

28 vehicles

Toyota Rush

Advanced Search

Model	Price	Depreciation	Reg Date	Eng Cap	Milage	Veh Type	Status
Search Selection Toyota Rush	Any	Any	> 10 year(s) old	Any	Any	Any	Available
Toyota Rush 1.5A X (COE till 12/2023)	\$35,800	\$7,580 /yr	04-Dec-2008	1,495 cc	-	SUV	Available
Smooth Engine, Easy To Maintain Unit, Immaculate Condition, Depreciation Is Even Cheaper, Do Not Miss. Bank And In House Loan Available! Trade In Welcome. Call For Appointment For A Test Drive Now Bef...							
Posted: 14-Mar-2019 Tags: 2008 Toyota Rush, 2008 toyota rush, Toyota Rush, toyota rush, Toyota, Rush, rush, Used Toyota							
Toyota Rush 1.5A X (COE till 01/2024)	\$33,800	\$6,990 /yr	12-Jan-2009	1,495 cc	87,000 km	SUV	Available
Well Maintained, Super Low Genuine Mileage Done, Well Groomed Inside Out, No Repairs Needed. Comes With 6 Months Warranty By Our In House Workshop. Free Island Wide Towing In Event Of Emergency, We Pr...							
Posted: 14-Mar-2019 Tags: 2009 Toyota Rush, 2009 toyota rush, Toyota Rush, toyota rush, Toyota, Rush, rush, Used Toyota							
Toyota Rush 1.5A X (New 5-yr COE)	\$29,800	\$5,950 /yr	05-Mar-2009	1,495 cc	120,012 km	SUV	Available
\$29.8K! New 5 Yrs COE Loan Available, One Of The Best Toyota Rush 1.5A x For COE Renewal Unit For Either 5 Or 10yrs! One Of The Lowest Price Quantum And Depreciation For This Make In Japan Toyota SUV...							
Posted: 13-Mar-2019 Tags: 2009 Toyota Rush, 2009 toyota rush, Toyota Rush, toyota rush, Toyota, Rush, rush, Used Toyota							
Toyota Rush 1.5A (COE till 04/2022)	\$21,800	\$4,990 /yr	26-Apr-2007	1,495 cc	-	SUV	Available
Loan Available, Lowest Genuine Pricing! Lowest Depreciation! Best Point A To Point B In A Stylish Toyota 1.5A SUV! No Extra Or Hidden Charges! 37 More Months To Drive! Japanese Manufactured Toyota Rush...							
Posted: 13-Mar-2019 Tags: 2007 Toyota Rush, 2007 toyota rush, Toyota Rush, toyota rush, Toyota, Rush, rush, Used Toyota							
GET YOUR COE RENEWAL LOAN	Is your COE expiring? Let us help you renew it! Getting your COE renewed is easy, fast and affordable. We'll help you renew your COE and get a loan for it. Get the cheapest loan in town and an approval in 2 days without effort! Enquire today.						
Toyota Rush 1.5A X (New 5-yr COE)	\$29,800	\$5,950 /yr	29-Dec-2008	1,495 cc	136,000 km	SUV	Available
Well Maintained By Previous Owner, Smooth Engine, Easy To Maintain, Bank And In House Loan Available! Trade In Welcome. Call For Appointment For A Test Drive.							
Posted: 13-Mar-2019 Tags: 2008 Toyota Rush, 2008 toyota rush, Toyota Rush, toyota rush, Toyota, Rush, rush, Used Toyota							
Toyota Rush 1.5A X (COE till 02/2024)	\$29,800	\$6,080 /yr	06-Feb-2009	1,495 cc	97,000 km	SUV	Available
\$2200 To Driveaway, Monthly \$700 Only, Spacious And Reliable SUV, Insurance Can Pay By 12 Months GIRD, A Car With Low Fuel Consumption And Fun To Drive.							
Posted: 12-Mar-2019 Tags: 2009 Toyota Rush, 2009 toyota rush, Toyota Rush, toyota rush, Toyota, Rush, rush, Used Toyota							
Toyota Rush 1.5A X (New 10-yr COE)	\$48,888	\$4,980 /yr	22-Jan-2009	1,495 cc	122,500 km	SUV	Available
New Paint Spray, 4 New Tyres, 6 Mths Warranty Cover All Parts Or 30,000KM Whichever Come First, Covered By Kinlay Workshop, Free 4 Servicing, 100% Wear And Tear Settled, No Repair Needed, Trade In Wel...							
Posted: 12-Mar-2019 Tags: 2009 Toyota Rush, 2009 toyota rush, Toyota Rush, toyota rush, Toyota, Rush, rush, Used Toyota							
Toyota Rush 1.5A (COE till 05/2021)	\$17,700	\$8,010 /yr	30-May-2006	1,495 cc	-	SUV	Available
Very Good Condition Maintained By Previous Lady Owner, Most Sought After SUV, Lowest Price And Lowest Depreciation, Call Now To Enquire More.							
Posted: 12-Mar-2019 Tags: 2006 Toyota Rush, 2006 toyota rush, Toyota Rush, toyota rush, Toyota, Rush, rush, Used Toyota							
Compare	Toyota Rush 1.5A X (COE till	\$20,800	\$7,710 /yr	24-Nov-2006	1,495 cc	-	SUV Available

Lai Huat (Meng Kee) Motor Pte Ltd

160 Sin Ming Drive, #04-01,
#04-02 & #07-03, Sin Ming
Autocity
575722

Claim Reference: TP-GBA 5655Z
Assessment number: 70314
Version: 1810
Date calculated: 03/13/2019 05:39 PM

Full Report
Registration: SGX 7980R
Printed: 13/03/2019 5:39 PM

Summary Information

Claim

Location:	Singapore (SG)	Work Provider:	China Taiping Insurance (Singapore) Pte Ltd
Printed by:	Jenny Lim	Currency:	SGD
Claim Reference:	TP-GBA 5655Z	Date of Incident:	2019-03-12
Estimated Repair Time:		Hire Car Start:	
Actual Repair Days:		Hire Car End:	

Vehicle Details

Vehicle

Manufacturer: TOYOTA
Model: RUSH (F700)
Sub Model: BASE MODEL
Model Sheet Number: 70 R1 01
Registration: SGX 7980R
VIN number:
Odometer:

Model Specs

FROM 08/2007 AIR CONDITIONING FOG LAMPS 1.5 LTR 80KW
TWO COAT METALLIC PREPARE OFF VEHICLE

Labour

Code	Description	Time Base 10 WU/h	Price = 42.00 SGD/h	
			WU	Price SGD
642091)	R + R REAR DOOR INCLUDES: REAR DOOR TRIM AND REQUIRED ATTACHED REMOVE AND REFIT		5.0	21.00
642091)	RENEW REAR DOOR (REMOVED)		27.0	113.40
743111	R + R L/UPPER C-PILLAR TRIM		6.0	25.20
743111	R + R R/UPPER C-PILLAR TRIM		6.0	25.20
645011)	R + R LEFT REAR SIDE WINDOW GLASS		9.0	37.80
645011)	R + R RIGHT REAR SIDE WINDOW GLASS		9.0	37.80
520051)	R + R REAR BUMPER		5.0	21.00
520051)	RENEW REAR BUMPER (REMOVED)		1.0	4.20
2711	INCLUDES: R + R NECESSARY ATTACHED PARTS REAR PANEL REPAIR		15 WU 30.0* 63	126.00

Lai Huat (Meng Kee) Motor Pte Ltd
160 Sin Ming Drive, #04-01,
#04-02 & #07-03, Sin Ming
Autocity
575722

Claim Reference: TP-GBA 5655Z

Assessment number: 70314

Version: 1810

Date calculated: 13/03/2019 05:39 PM

Full Report

Registration: SGX 7980F

Printed: 13/03/2019 5:39 PM

	Hrs	WU	Price SGI
Panel / Mechanical Labour	9.80	98.0	411.61
Total of Labour			411.61

Paint

Paint Work	SYSTEM AZT	Time Basis 10WU/h	WU	Price SGI
Code	Description - TWO COAT METALLIC			
	TAILGATE NEW PART PAINTING		17.0	
	REAR BUMPER NEW PART PAINT K1R		8.0	
	REAR PANEL REPAIR PAINTING <50%		9.0	

Paint Material Per Part

Code	Description	Price SGI
2931	TAILGATE NEW PART PAINTING	49.5
2583	REAR BUMPER NEW PART PAINT K1R	34.4
2711	REAR PANEL REPAIR PAINTING <50%	6.4

Labour Cost - Paint

	Factor	42.00 SGD/h	Hrs	WU	Price SGI
	Time Paint			34.0	
	Preparation Main Work Metal		2.50	25.0	105.0
	Preparation Comp. Work Plastic		0.50	5.0	21.0
Total			10 WU/h	64.0	268.8

Material Cost - Paint

	Price SGI
New Part Painting	49.5
New Part Painting - Plastic K1R	34.4
Repair Painting	6.4
Material-constant Metal Preparation	28.6
Material-constant Plastic	9.0
Total	128.0

Spare Parts

Code	Description	Part Number	Supplier	prices as at 2015-06-01/0	Price SGI
2583	REAR BUMPER	52159 BZ450 ✓	DD		190.0
2931	TAILGATE	67005 BZ220 ✓	DD		380.0

Lai Huat (Meng Kee) Motor Pte Ltd
160 Sin Ming Drive, #04-01,
#04-02 & #07-03, Sin Ming
Autocity
575722

Claim Reference: TP-GBA 5655Z
 Assessment number: 70314
 Version: 1810

Full Report
 Registration: SGX 7980F
 Printed: 13/03/2019 05:39 PM

Date calculated:	Part Number	Supplier	Price SGD
13/03/2019 05:39 PM	3013 BADGE MODEL 75441 BZ130 ✓	NEC	65.00
	3151 REAR SCREEN 68105 BZ070 ✓	BR	350.00
	3162 REAR SCREEN BOND KIT PZ49I 00C1131 ✓	NEC	0.00
	3163 REAR SCREEN FIX SET USE SINGLE PARTS ✓	NEC	0.00
	3164 SPACER 62785 BZ030 X		0.00
	3165 CHECK 64828 BZ010 X		0.00
	3166 SPACER 64827 BZ010 X		0.00
	3839 L/S-WINDOW MOULDING 75642 BZ010 ✓	NEC	50.00
	3840 R/S-WINDOW MOULDING 75641 BZ010 ✓	NEC	50.00
	9692 SPARE WHEEL COVER 64771 BZ060A0 ✓	BR 1465 ✓	380.00
f: OEM Parts	Savings		0.00
n: Non-OEM Parts	Subtotal		1,465.00
u: Used parts	Total		1,465.00

Final Calculation

	SGD	SGD
Parts	1,465.00	
Total Parts		1,465.00
Labour Time Base 10 WU/h		
Total 98.0 WU X 42.00 SGD/h	348.00	
Total of Labour		411.60
Paint Work Time Base 10 WU/h		
Labour Cost 64.0 WU X 42.00 SGD/h	268.80	
Material Cost	128.04	
Total Paint Including Material		396.84
Repair Cost Excludes GST		2,273.44
GST (+7.0%)		159.14
Repair Cost Included GST		2,432.58

Handwritten notes:
 20/3/19
 with PIP ✓
 5 & chys
 Resurvey before spray

Handwritten notes:
 Steve CLKK)
 8322 8813

LKK Auto Consultants hence notify the Repairer of the following:
 • To resurvey before/after spray painting
 • To display damaged part(s) during resurvey
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modification(s) is allowed
 • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Audatex System Using Manufacturer Times
 Signature:
 Date:

**Lai Huat (Meng Kee) Motor Pte
Ltd
160 Sin Ming Drive, #04-01,
#04-02 & #07-03, Sin Ming
Autocity
575722**

Claim Reference: TP-GBA 5655Z

Assessment number: 70314

Version: 1810

Date calculated: 03/13/2019 05:39 PM

**Full Report
Registration: SGX 7980F
Printed: 13/03/2019 5:39 PM**

Comments

* - USER SUPPLIED DATA

NN - NO MANUFACTURERS CODE EXISTS

) - WU PARTIAL INCL IN OTHER POSITIONS

LKK Auto Consultants
#01-25 Paya Ubi Industrial Park,
51 Ubi Avenue 1
408933

Claim Reference: TP-GBA 5655Z
Assessment number: 70314
Version: 1810
Date calculated: 04/08/2019 10:39 AM

Full Report
Registration: SGX 7980R
Printed: 08/04/2019 10:39 AM

Summary Information

Claim

Location:	Singapore (SG)	Work Provider:	China Taiping Insurance (Singapore) Pte Ltd
Printed by:	KK LAU	Currency:	SGD
Claim Reference:	TP-GBA 5655Z	Date of Incident:	2019-03-12
Estimated Repair Time:		Hire Car Start:	
Actual Repair Days:		Hire Car End:	

Vehicle Details

Vehicle

Manufacturer:	TOYOTA		
Model:	RUSH (F700)		
Sub Model:	BASE MODEL		
Model Sheet Number:	70 R1 01		
Registration:	SGX 7980R		
VIN number:			
Odometer:			
Model Specs			
FROM 08/2007	AIR CONDITIONING	FOG LAMPS	1.5 LTR 80KW
TWO COAT METALLIC	PREPARE OFF VEHICLE		

LKK Auto Consultants
#01-25 Paya Ubi Industrial Park,
51 Ubi Avenue 1
408933

Claim Reference: TP-GBA 5655Z
 Assessment number: 70314
 Version: 1810
 Date calculated: 04/08/2019 10:39 AM

Full Report
 Registration: SGX 7980R
 Printed: 08/04/2019 10:39 AM


Vehicle Condition

Vehicle Status

Pre-Accident Damage:
 Date of Inspection:

Damage Areas

All
 Underbody



Labour

Code	Description	Time Base 10 WU/h	Price = 42.00 SGD/h	
			WU	Price SGD
642091)	R + R REAR DOOR INCLUDES: REAR DOOR TRIM AND REQUIRED ATTACHED REMOVE AND REFIT		5.0	21.00
642091)	RENEW REAR DOOR (REMOVED)		27.0	113.40
743111	R + R L/UPPER C-PILLAR TRIM		6.0	25.20
743111	R + R R/UPPER C-PILLAR TRIM		6.0	25.20
645011)	R + R LEFT REAR SIDE WINDOW GLASS		9.0	37.80
645011)	R + R RIGHT REAR SIDE WINDOW GLASS		9.0	37.80
520051)	R + R REAR BUMPER		5.0	21.00
520051)	RENEW REAR BUMPER (REMOVED)		1.0	4.20
2711	INCLUDES: R + R NECESSARY ATTACHED PARTS REAR PANEL REPAIR		15.0*	63.00

LKK Auto Consultants
#01-25 Paya Ubi Industrial Park,
51 Ubi Avenue 1
408933

Claim Reference: TP-GBA 5655Z
 Assessment number: 70314
 Version: 1810
 Date calculated: 04/08/2019 10:39 AM

Full Report
 Registration: SGX 7980R
 Printed: 08/04/2019 10:39 AM

Labour Cost	Hrs	WU	
Panel / Mechanical Labour	8.30	83.0	348.60
Total of Labour			348.60

Paint

Paint Work	SYSTEM AZT	Time Basis 10WU/h
Code	Description - TWO COAT METALLIC	WU Price SGD
	TAILGATE NEW PART PAINTING	17.0
	REAR BUMPER NEW PART PAINT K1R	8.0
	REAR PANEL REPAIR PAINTING <50%	9.0

Paint Material Per Part

Code	Description	Price SGD
2931	TAILGATE NEW PART PAINTING	49.54
2583	REAR BUMPER NEW PART PAINT K1R	34.44
2711	REAR PANEL REPAIR PAINTING <50%	6.46

Labour Cost - Paint	Hrs	WU	Price SGD
Factor	42.00 SGD/h		
Time Paint		34.0	
Preparation Main Work Metal	2.50	25.0	105.00
Preparation Comp. Work Plastic	0.50	5.0	21.00
Total	10 WU/h	64.0	268.80

Material Cost - Paint	Price SGD
New Part Painting	49.54
New Part Painting - Plastic K1R	34.44
Repair Painting	6.46
Material-constant Metal Preparation	28.60
Material-constant Plastic	9.00
Total	128.04

Spare Parts

Code	Description	Part Number	Supplier	prices as at 2015-06-01/01	Price SGD
2583	REAR BUMPER	52159 BZ450			190.00
2931	TAILGATE	67005 BZ220			380.00

LKK Auto Consultants
#01-25 Paya Ubi Industrial Park,
51 Ubi Avenue 1
408933

Claim Reference: TP-GBA 5655Z
 Assessment number: 70314
 Version: 1810
 Date calculated: 04/08/2019 10:39 AM

Full Report
 Registration: SGX 7980R
 Printed: 08/04/2019 10:39 AM

Code	Description	Part Number	Supplier	Price SGD
3013	BADGE MODEL	75441 BZ130		65.00
3151	REAR SCREEN	68105 BZ070		350.00
3162	REAR SCREEN BOND KIT	PZ49I 00C1131		0.00
3163	REAR SCREEN FIX SET	USE SINGLE PARTS		
3164	SPACER	62785 BZ030		0.00
3165	CHECK	64828 BZ010		0.00
3166	SPACER	64827 BZ010		0.00
3839	L/S-WINDOW MOULDING	75642 BZ010		50.00
3840	R/S-WINDOW MOULDING	75641 BZ010		50.00
9692	SPARE WHEEL COVER	64771 BZ060A0		380.00
				0.00
				1,465.00
				1,465.00

f: OEM Parts
 n: Non-OEM Parts
 u: Used parts

Savings
Subtotal
Total

Extras

Code	Description	Price SGD
1000	SUNDRY (1)	100.00*
	Total Extras	100.00

LKK Auto Consultants
#01-25 Paya Ubi Industrial Park,
51 Ubi Avenue 1
408933

Claim Reference: TP-GBA 5655Z
Assessment number: 70314
Version: 1810
Date calculated: 04/08/2019 10:39 AM

Full Report
Registration: SGX 7980R
Printed: 08/04/2019 10:39 AM

Final Calculation

	SGD	SGD
Parts	1,465.00	
Total Parts		1,465.00
Labour Time Base 10 WU/h		
Total 83.0 WU X 42.00 SGD/h	348.60	
Total of Labour		348.60
Total Of Extras		100.00
Paint Work Time Base 10 WU/h		
Labour Cost 64.0 WU X 42.00 SGD/h	268.80	
Material Cost	128.04	
Total Paint Including Material		396.84
Repair Cost Excludes GST		2,310.44
GST (+7.0%)		161.73
Repair Cost Included GST		2,472.17

Comments

* - USER SUPPLIED DATA
NN - NO MANUFACTURERS CODE EXISTS
) - WU PARTIAL INCL IN OTHER POSITIONS

**Lai Huat (Meng Kee) Motor Pte
Ltd**
**160 Sin Ming Drive, #04-01,
#04-02 & #07-03, Sin Ming
Autocity**
575722

Claim Reference: TP-GBA 5655Z
 Assessment number: 70314
 Version: 1810
 Date calculated: 04/05/2019 04:22 PM

Full Report
 Registration: SGX 7980R
 Printed: 05/04/2019 4:28 PM

Summary Information

Claim			
Location:	Singapore (SG)	Work Provider:	China Taiping Insurance (Singapore) Pte Ltd
Printed by:	Jenny Lim	Currency:	SGD
Claim Reference:	TP-GBA 5655Z	Date of Incident:	2019-03-12
Estimated Repair Time:		Hire Car Start:	
Actual Repair Days:		Hire Car End:	

Vehicle Details

Vehicle			
Manufacturer:	TOYOTA		
Model:	RUSH (F700)		
Sub Model:	BASE MODEL		
Model Sheet Number:	70 R1 01		
Registration:	SGX 7980R		
VIN number:			
Odometer:			
Model Specs			
FROM 08/2007	AIR CONDITIONING	FOG LAMPS	1.5 LTR 80KW
TWO COAT METALLIC	PREPARE OFF VEHICLE		

Labour

Code	Description	Time Base 10 WU/h	Price = 42.00 SGD/h	
			WU	Price SGD
642091)	R + R REAR DOOR INCLUDES: REAR DOOR TRIM AND REQUIRED ATTACHED REMOVE AND REFIT		5.0	21.00
642091)	RENEW REAR DOOR (REMOVED)		27.0	113.40
743111	R + R L/UPPER C-PILLAR TRIM		6.0	25.20
743111	R + R R/UPPER C-PILLAR TRIM		6.0	25.20
645011)	R + R LEFT REAR SIDE WINDOW GLASS		9.0	37.80
645011)	R + R RIGHT REAR SIDE WINDOW GLASS		9.0	37.80
520051)	R + R REAR BUMPER		5.0	21.00
520051)	RENEW REAR BUMPER (REMOVED)		1.0	4.20
2711	INCLUDES: R + R NECESSARY ATTACHED PARTS REAR PANEL REPAIR		15.0*	63.00

Lai Huat (Meng Kee) Motor Pte Ltd
160 Sin Ming Drive, #04-01,
#04-02 & #07-03, Sin Ming
Autocity
575722

Claim Reference: TP-GBA 5655Z
 Assessment number: 70314
 Version: 1810
 Date calculated: 04/05/2019 04:22 PM

Full Report
 Registration: SGX 7980F
 Printed: 05/04/2019 4:28 PM

	Hrs	WU	
Panel / Mechanical Labour	8.30	83.0	348.60
Total of Labour			348.60

Paint

Paint Work	SYSTEM AZT	Time Basis 10WU/h	
Code	Description - TWO COAT METALLIC	WU	Price SGD
	TAILGATE NEW PART PAINTING	17.0	
	REAR BUMPER NEW PART PAINT K1R	8.0	
	REAR PANEL REPAIR PAINTING <50%	9.0	

Paint Material Per Part

Code	Description	Price SGD
2931	TAILGATE NEW PART PAINTING	49.54
2583	REAR BUMPER NEW PART PAINT K1R	34.44
2711	REAR PANEL REPAIR PAINTING <50%	6.46

Labour Cost - Paint

Factor	42.00 SGD/h	Hrs	WU	Price SGD
Time Paint			34.0	
Preparation Main Work Metal		2.50	25.0	105.00
Preparation Comp. Work Plastic		0.50	5.0	21.00
Total	10 WU/h	6.40	64.0	268.80

Material Cost - Paint

	Price SGD
New Part Painting	49.54
New Part Painting - Plastic K1R	34.44
Repair Painting	6.46
Material-constant Metal Preparation	28.60
Material-constant Plastic	9.00
Total	128.04

Spare Parts

Code	Description	Part Number	Supplier	prices as at 2015-06-01/01	Price SGD
2583	REAR BUMPER	52159 BZ450			190.00
2931	TAILGATE	67005 BZ220			380.00

**Lai Huat (Meng Kee) Motor Pte
Ltd
160 Sin Ming Drive, #04-01,
#04-02 & #07-03, Sin Ming
Autocity
575722**

Claim Reference: TP-GBA 5655Z
Assessment number: 70314
Version: 1810

Full Report
Registration: SGX 7980F
Printed: 05/04/2019 4:28 PM

Date calculated:	Part Number	Supplier	Price SGD
04/05/2019 04:22 PM	3013 BADGE MODEL 75441 BZ130		65.00
	3151 REAR SCREEN 68105 BZ070		350.00
	3162 REAR SCREEN BOND KIT PZ49I 00C1131		0.00
	3163 REAR SCREEN FIX SET USE SINGLE PARTS		
	3164 SPACER 62785 BZ030		0.00
	3165 CHECK 64828 BZ010		0.00
	3166 SPACER 64827 BZ010		0.00
	3839 L/S-WINDOW MOULDING 75642 BZ010		50.00
	3840 R/S-WINDOW MOULDING 75641 BZ010		50.00
	9692 SPARE WHEEL COVER 64771 BZ060A0		380.00
			0.00
	Savings		
	Subtotal		1,465.00
	Total		1,465.00

Final Calculation

	SGD	SGD
Parts	1,465.00	
Total Parts		1,465.00
Labour Time Base 10 WU/h		
Total 83.0 WU X 42.00 SGD/h	348.60	
Total of Labour		348.60
Paint Work Time Base 10 WU/h		
Labour Cost 64.0 WU X 42.00 SGD/h	268.80	
Material Cost	128.04	
Total Paint Including Material		396.84
Repair Cost Excludes GST		2,210.44
GST (+7.0%)		154.73
Repair Cost Included GST		2,365.17

**Lai Huat (Meng Kee) Motor Pte
Ltd
160 Sin Ming Drive, #04-01,
#04-02 & #07-03, Sin Ming
Autocity
575722**

Claim Reference: TP-GBA 5655Z

Assessment number: 70314

Version: 1810

Date calculated: 04/05/2019 04:22 PM

**Full Report
Registration: SGX 7980F
Printed: 05/04/2019 4:28 PM**

Comments

* - USER SUPPLIED DATA

NN - NO MANUFACTURERS CODE EXISTS

) - WU PARTIAL INCL IN OTHER POSITIONS

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	13 Mar 2019 Sendback Est	13 Mar 2019 17:56 S\$2,273.44	14 Mar 2019 09:56 Edit Adj Rpt	S\$2,310.44 Edit Estimates	S\$2,310.44 View Rpt		Pending for Survey Report Cancel Case
Supp #1	05 Apr 2019 16:36	05 Apr 2019 16:36 S\$100.00	05 Apr 2019 16:36			(Combined)	Combined with Main Uncombine Suppl.

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS									
Insured:	He Fengyang , ID: S2650662Z								
Main Claimant:	LIN PEISHAN AGNES , ID: S8523641E								
Vehicle Reg. No.:	SGX7980R	Date of Loss:	12/03/2019 08:00 - :59 [138 Months and 5 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / SNM19D201134C02	Policy/Cover Note No.:	DMCVSN18254618000						
Vehicle Reg. No. (Insured):	GBA5655Z	Policy No. (Claimant):	1700032612-01						
		Excess:	S\$0.00						
Repairer:	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming) 160 Sin Ming Drive #04-01, Sin Ming AutoCity, 575722 Sin Ming - Tel: 64538110								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]								
Claimant's Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by CHEN TSUE YEE] ... [Final Rpt due 25/03/2019]								
Driver/Custodian (Insured):	He Fengyang (/ Male) , NRIC: S2650662Z Email:								
ASSOCIATED MAIL RECEIVED				View All	Compose Case Mail				
There are no mail for this case.									
ALL ASSOCIATED TASKS				View All	Search Tasks	Create New Task	Complete		
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

**SGX7980R (SNM19D201134C02)
[GBA5655Z]**

TP

LIN PEISHAN AGNES

Mar 12 2019 8:00AM

[He Fengyang]

Lai Huat (Meng Kee) Motor Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			View View in Browser	
Video									1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)		Thumbnail	Print					
1	13/03/19 14:31	Video - Accident [Linked Accident Report Documents]		Load MOV						
Assessment Reports									1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)		Thumbnail	Print					
1	13/03/19 15:30	Accident Statement		Load HTM						
2	13/03/19 17:56	Repairer Estimates		Load HTM						
3	05/04/19 16:36	Repairer Estimates Suppl. #1		Load HTM						
Photos/Images									3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)		Thumbnail	Print					
1	13/03/19 15:30	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>					
2	13/03/19 15:30	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>					
3	13/03/19 15:30	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>					
4	13/03/19 15:30	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>					
5	13/03/19 15:30	Chassis Number [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>					
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print					
1	18/03/19 18:28	General View		Load JPG	<input checked="" type="checkbox"/>					
2	18/03/19 18:28	General View		Load JPG	<input checked="" type="checkbox"/>					
3	18/03/19 18:28	General View		Load JPG	<input checked="" type="checkbox"/>					
4	18/03/19 18:28	General View		Load JPG	<input checked="" type="checkbox"/>					
5	18/03/19 18:28	General View		Load JPG	<input checked="" type="checkbox"/>					
6	18/03/19 18:28	General View		Load JPG	<input checked="" type="checkbox"/>					
7	18/03/19 18:28	General View		Load JPG	<input checked="" type="checkbox"/>					
8	18/03/19 18:28	General View		Load JPG	<input checked="" type="checkbox"/>					
9	18/03/19 18:28	General View		Load JPG	<input checked="" type="checkbox"/>					
10	18/03/19 18:28	General View		Load JPG	<input checked="" type="checkbox"/>					
11	18/03/19 18:28	General View		Load JPG	<input checked="" type="checkbox"/>					
12	18/03/19 18:28	General View		Load JPG	<input checked="" type="checkbox"/>					
13	18/03/19 18:28	General View		Load JPG	<input checked="" type="checkbox"/>					
14	18/03/19 18:28	General View		Load JPG	<input checked="" type="checkbox"/>					
15	18/03/19 18:28	General View		Load JPG	<input checked="" type="checkbox"/>					
16	18/03/19 18:28	General View		Load JPG	<input checked="" type="checkbox"/>					
17	18/03/19 18:28	General View		Load JPG	<input checked="" type="checkbox"/>					
18	18/03/19 18:28	General View		Load JPG	<input checked="" type="checkbox"/>					
19	18/03/19 18:28	General View		Load JPG	<input checked="" type="checkbox"/>					
20	18/03/19 18:28	General View		Load JPG	<input checked="" type="checkbox"/>					
21	18/03/19 18:28	General View		Load JPG						

Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)	Thumbnail	Print
				<input checked="" type="checkbox"/>
22	18/03/19 18:28	General View	 Load JPG	<input checked="" type="checkbox"/>
23	18/03/19 18:28	General View	 Load JPG	<input checked="" type="checkbox"/>
24	18/03/19 18:28	General View	 Load JPG	<input checked="" type="checkbox"/>
25	18/03/19 18:28	General View	 Load JPG	<input checked="" type="checkbox"/>
26	18/03/19 18:28	General View	 Load JPG	<input checked="" type="checkbox"/>
27	18/03/19 18:28	General View	 Load JPG	<input checked="" type="checkbox"/>
28	18/03/19 18:28	General View	 Load JPG	<input checked="" type="checkbox"/>
29	18/03/19 18:28	General View	 Load JPG	<input checked="" type="checkbox"/>
30	18/03/19 18:28	General View	 Load JPG	<input checked="" type="checkbox"/>
31	18/03/19 18:28	General View	 Load JPG	<input checked="" type="checkbox"/>
32	18/03/19 18:28	Odometer Reading	 Load JPG	<input checked="" type="checkbox"/>
33	18/03/19 18:28	General View	 Load JPG	<input checked="" type="checkbox"/>
34	18/03/19 18:28	General View	 Load JPG	<input checked="" type="checkbox"/>
35	18/03/19 18:28	General View	 Load JPG	<input checked="" type="checkbox"/>
36	18/03/19 18:28	General View	 Load JPG	<input checked="" type="checkbox"/>
37	18/03/19 18:28	Chassis Number	 Load JPG	<input checked="" type="checkbox"/>
38	18/03/19 18:28	General View	 Load JPG	<input checked="" type="checkbox"/>
39	18/03/19 18:28	General View	 Load JPG	<input checked="" type="checkbox"/>
40	18/03/19 18:29	General View	 Load JPG	<input checked="" type="checkbox"/>
41	18/03/19 18:29	General View	 Load JPG	<input checked="" type="checkbox"/>
42	18/03/19 18:29	General View	 Load JPG	<input checked="" type="checkbox"/>
43	18/03/19 18:29	General View	 Load JPG	<input checked="" type="checkbox"/>
44	18/03/19 18:29	General View	 Load JPG	<input checked="" type="checkbox"/>
45	18/03/19 18:29	General View	 Load JPG	<input checked="" type="checkbox"/>
46	18/03/19 18:29	General View	 Load JPG	<input checked="" type="checkbox"/>
47	18/03/19 18:29	General View	 Load JPG	<input checked="" type="checkbox"/>
48	18/03/19 18:29	General View	 Load JPG	<input checked="" type="checkbox"/>
49	18/03/19 18:29	General View	 Load JPG	<input checked="" type="checkbox"/>
50	18/03/19 18:29	General View	 Load JPG	<input checked="" type="checkbox"/>
51	09/04/19 11:41	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
52	09/04/19 11:41	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
53	09/04/19 11:41	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
54	09/04/19 11:41	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
55	09/04/19 11:41	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
56	09/04/19 11:41	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
57	09/04/19 11:41	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
58	09/04/19 11:41	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
59	09/04/19 11:41	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
60	09/04/19 11:41	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
61	09/04/19 11:41	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
62	09/04/19 11:41	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
63	09/04/19 11:41	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
64	09/04/19 11:41	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
65	09/04/19 11:41	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
66	09/04/19 11:41	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
67	09/04/19 11:41	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
68	09/04/19 11:41	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
69	09/04/19 11:41	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
70	09/04/19 11:41	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>

Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)	Thumbnail	Print
71	09/04/19 11:41	Photo After Spray		Load JPG <input checked="" type="checkbox"/>
72	09/04/19 11:41	Photo After Spray		Load JPG <input checked="" type="checkbox"/>
73	09/04/19 11:41	Photo After Spray		Load JPG <input checked="" type="checkbox"/>
74	09/04/19 11:41	Photo After Spray		Load JPG <input checked="" type="checkbox"/>
75	09/04/19 11:41	Photo After Spray		Load JPG <input checked="" type="checkbox"/>
76	09/04/19 11:41	Photo After Spray		Load JPG <input checked="" type="checkbox"/>
77	09/04/19 11:41	Photo After Spray		Load JPG <input checked="" type="checkbox"/>
78	09/04/19 11:41	Photo After Spray		Load JPG <input checked="" type="checkbox"/>
79	09/04/19 11:41	Photo After Spray		Load JPG <input checked="" type="checkbox"/>
80	09/04/19 11:41	Photo After Spray		Load JPG <input checked="" type="checkbox"/>
81	09/04/19 11:41	Photo After Spray		Load JPG <input checked="" type="checkbox"/>
82	09/04/19 11:41	Photo After Spray		Load JPG <input checked="" type="checkbox"/>
83	09/04/19 11:41	Photo After Spray		Load JPG <input checked="" type="checkbox"/>
84	09/04/19 11:41	Photo After Spray		Load JPG <input checked="" type="checkbox"/>
85	09/04/19 11:41	Photo After Spray		Load JPG <input checked="" type="checkbox"/>
86	09/04/19 11:41	Photo After Spray		Load JPG <input checked="" type="checkbox"/>
87	09/04/19 11:41	Photo After Spray		Load JPG <input checked="" type="checkbox"/>
88	09/04/19 11:41	Photo After Spray		Load JPG <input checked="" type="checkbox"/>
89	09/04/19 11:41	Photo After Spray		Load JPG <input checked="" type="checkbox"/>

Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)	Thumbnail	Print
1	13/03/19 15:29	Sketch Plan <small>[Linked Accident Report Documents]</small>		Load TIF
2	13/03/19 15:29	Driver NRIC & Driving Licence <small>[Linked Accident Report Documents]</small>		Load TIF
3	13/03/19 15:29	Certificate of Insurance <small>[Linked Accident Report Documents]</small>		Load TIF
4	13/03/19 17:56	E-filed GIA report		Load PDF
5	13/03/19 17:56	Driver NRIC & Driving Licence		Load PDF
6	13/03/19 17:56	Certificate of Insurance		Load PDF
7	13/03/19 17:56	Enquire PARF / COE Rebate for Registered Vehicle		Load PDF
8	13/03/19 17:56	LTA Search		Load PDF
9	13/03/19 17:56	Audatex Report		Load PDF

Linked Accident Report Documents

Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)	Thumbnail	Print
1	13/03/19 14:31	Video - Accident		Load MOV

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)	Thumbnail	Print
1	13/03/19 15:30	Accident Statement		Load HTM

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)	Thumbnail	Print
1	13/03/19 15:30	Accident Photo		Load JPG <input checked="" type="checkbox"/>
2	13/03/19 15:30	Accident Photo		Load JPG <input checked="" type="checkbox"/>
3	13/03/19 15:30	Accident Photo		Load JPG <input checked="" type="checkbox"/>
4	13/03/19 15:30	Accident Photo		Load JPG <input checked="" type="checkbox"/>
5	13/03/19 15:30	Chassis Number		Load JPG <input checked="" type="checkbox"/>

Documentation			1 per page	<input checked="" type="checkbox"/>
---------------	--	--	------------	-------------------------------------

Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)		Thumbnail Print
No	Finalized On	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)		Thumbnail Print
1	13/03/19 15:29	Sketch Plan Sketch Plan	1	Load TIF
2	13/03/19 15:29	Driver NRIC & Driving Licence	1	Load TIF
3	13/03/19 15:29	Certificate of Insurance	1	Load TIF

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
<div style="border: 1px solid black; height: 40px; width: 100%;"></div>			
Show Remarks To: <input type="checkbox"/> Repairer <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co Reg No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT119004701/ETD3E2
Date: 18/04/2019

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd.	Policy No: DMCVSN18254618000	
Claimant Vehicle No: SGX7980R	Insured Vehicle No: GBA5655Z	
Date of Loss: 12/03/2019	Nature of Claim: TP	Claim No: SNM19D201134C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SGX7980R		Engine No: 3SZ1922403	
Make & Model: TOYOTA RUSH, 1.5 (A)		Chassis No: J200E0016799	
Reg. Date: 07/09/2007 (Man. Year: 2007)		Odometer: 160796 km	
Colour: Black			
Engine Capacity: 1495 cc			
Market Value/New Car Price: N/A			
Sum Insured (S\$): Market Value/New Car Price			

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	Dunlop 6 mm	Rear Right Side:	Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,465.00	1,465.00	0.00	0.00
Miscellaneous Items	100.00	100.00	0.00	0.00
Labour	411.60	348.60	63.00	15.31
Paintwork Labour	396.84	396.84	0.00	0.00
Towing	0.00	0.00	0.00	
Gross Total (S\$)	2,373.44	2,310.44	63.00	2.65
+ GST 7.00/7.00% (S\$)	166.14	161.73	4.41	2.65
Nett Amount (S\$)	2,539.58	2,472.17	67.41	2.65

INSPECTION

Date of Assignment:	14/03/2019 Present Location:	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)
Date Inspected:	14/03/2019 Inspected At:	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming) 160 Sin Ming Drive #04-01, Sin Ming AutoCity Singapore 575722
Estimated Period of Repair:	5.0 days	

Adjuster: CHEN TSUE YEE

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 18 Apr 2019)
Parts: M1-SUV	TOYOTA RUSH 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SGX7980R)	
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*Spare Parts		1,465.00 F	*1,465.00 F
					Total Parts (S\$)	1,465.00

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Supplementary #1				
1	1	SUNDRY PARTS (NECESSARY)	100.00	100.00
Sub Total (S\$)			100.00	100.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Paintwork Labour				
1	Total Paint including Material	New	396.84	396.84
Labour Items				
2	Total of Labour	New	411.60	348.60
Gross Labour Cost (S\$)			808.44	745.44

Report was unsubmitted during this print-out.

< END OF ESTIMATES >