

ASS. REC. BY:

REF: Cs/MSG19004706/0vd3

Special Instruction:

SUPERVISOR: Meirys ASSIGNMENT (Office)

From (Person):

Pauline Thom

of

MSIG

Date/Time:

15/3/19 @ 10:07am

Estimated Cost:

Bill to:

OD /  IP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLK 5094X

Insured:

PC 4536P

at Workshop no/s

Euro Success

Tel:

9828 9277

of

1 Kaki Bkt Ave 6 #02-03

Policy No:

28675693

Claim No:

587501

Sum Insured:

Excess:

Make of Veh:

D.O.A.

12/03/2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

10:37am 15/3/19

Person Contacted:

An YungVehicle  IN  OUT

Date/Time

Action/Instruction (✓) Estimate

SLK 5094X - XPC 4536P - CCF/AA 17023389/Aha39\*2/03/19@ 09:21 revised IO to Pauline Thom via meirys.

(08/11/13) wef  
ASS. REC. BY: MGR/CS

REF:

MSIC/

**ASSIGNMENT**

From: \_\_\_\_\_ Date: \_\_\_\_\_  
Estimated Cost: \_\_\_\_\_  
OD / TP / WS / TP RES / OD RES / EVA / INV / MV  
To Inspect Vehicle No: SLK5094X  
at Workshop m/s Euro Success  
of \_\_\_\_\_  
Insured: \_\_\_\_\_  
Policy No. \_\_\_\_\_  
Claims No. \_\_\_\_\_  
Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
(Client's Record)  
Make of Veh: \_\_\_\_\_

(Policy Condition)  
Remark: **The veh had commenced its repair at the time of inspection.**

N/S	O/S

Bal. or Market Value: \_\_\_\_\_  
IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No  
GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No  
Est. Repairs: 3 days Res.: Yes or No  
Lum Sum: 20 % 3 Val.: Yes or No  
CA / REV / REP. / 24 HRS  
Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

Veh No: SLK5094X Yr Regn: 1, 17  
Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
Truck / Trailer or 91  
Make: Mercedes Prins Hybrid cc 1797  
Colour: Black A/C: Insured / Std / NI / NA  
Sp. Reading: 202890 T/Radio: Insured / Std / NI / NA  
Eng/No: \_\_\_\_\_  
C/No: ZUV506042591  
Gen. Cond: Good / Fair / Poor / Burnt  
Steering: Inorder / Jammed / Leaked / Burnt or  
Brake: Inorder / Jammed / Leaked / Burnt or  
Modi: Nil / S/Rim / STD A/Rim or  
Tyre Size: F: 195/05R15  
R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
TOYO / YOKO or Davanti  
Front 6 mm Rear 6 mm  
R/Bal. 6 mm R/Bal. 6 mm  
L/Bal. 6 mm L/Bal. 6 mm  
D.O.A. 12/3/19 D.O.I. 14/3/19  
Survey held at \_\_\_\_\_  
Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or  
MSIC  
The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>phly At folder lone Dnye on rear o/s bayer area.</u> <u>headup 202890</u>
<u>15/3/19</u>	<u>1/5 @ 3250 confirmed with AH heat.</u> <u>( \$ 5,982.54 Red - 65% )</u>

[Signature]  
21/3/2019

RECEIVED 25 MAR 2019

Date/Time, File Pass to?  : Preli. Report  : Final Report  
1) \_\_\_\_\_  
Date/Time, File Return to?  
2) 25/3 - typist

Days Of Repair: 3  
Resurvey No. of Trip: 1

Report Format: merimen  
Lump Sum / I.B.I.: (\$ 3,250/- 1/5)

Add Fee:  : Site Insp (\$ )  
 : Interview (\$ )  
 : Tech. Invs (\$ )  
 : Weekend (\$ )

Survey Fee: \_\_\_\_\_  
Transportation: \_\_\_\_\_  
Photos \_\_\_\_\_  
Others \_\_\_\_\_  
TOTAL \_\_\_\_\_

## ...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	13 Mar 2019		15 Mar 2019 10:07 <a href="#">Assign</a>				<b>New Assignment</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	<a href="#">Show All</a>
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS		[Created by insurer]
Insured:	Mariteam Transport Services Pte. Ltd, Co. Reg. No.: 200402055D	
Main Claimant:	AMV PTE. LTD., Co. Reg. No.: 201505825Z	
Vehicle Reg. No.:	SLK5094X	Date of Loss: 12/03/2019 08:00 - :59 [25 Months and 22 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 587501	Policy/Cover Note No.: 28675693 (Comprehensive) Coverage: 22/01/2019 - 21/01/2020
Vehicle Reg. No. (Insured):	PC4536P	Policy No. (Claimant):
		Excess:
Repairer:	Euro Success Services Pte Ltd (HQ) 1 KAKI BUKIT AVENUE 6 #02-03 AUTOBAY, 417883 Kaki Bukit - Tel:	
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Pauline Tham - 6594 2545]	
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 16/03/2019]	
Driver/Custodian (Insured):	TOONG NGAI JUAY (), NRIC: S1544713C Email:	
Adj. Remarks:	on WP> LIABILITY NOT CLEAR. TP AGREE SJE - ASSIGN LKK AUTO CONSULTANTS PTE LTD CONTACT: Ah Huat (Tel. 9828 9277 / 6742 6231)	

ASSOCIATED MAIL RECEIVED	<a href="#">View All</a> <a href="#">Compose Case Mail</a>
There are no mail for this case.	

ALL ASSOCIATED TASKS	<a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a>								
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

> **Back to OneMotoring**

## Enquire PARF/COE Rebate for Registered Vehicle

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Company
Owner ID:	5825Z
<b>Vehicle Details</b>	
Vehicle No.:	SLK5094X
Vehicle to be Exported:	No
Intended Deregistration Date:	14 Mar 2019
Vehicle Make:	TOYOTA
Vehicle Model:	PRIUS HYBRID 1.8S AT ABS D/AIRBAG 2WD
Primary Colour:	Black
Manufacturing Year:	2016
Engine No.:	2ZR6824794
Chassis No.:	ZVW506040591
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$26,089.00
Original Registration Date:	18 Jan 2017
First Registration Date:	18 Jan 2017
Transfer Count:	0
Actual ARF Paid:	\$5,000.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	17 Jan 2027
PARF Rebate Amount:	\$3,750.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	17 Jan 2027
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$53,001.00
COE Rebate Amount:	\$41,560.00
<b>Total Rebate Amount:</b>	<b>\$45,310.00</b>

The information contained herein is correct as at 14 Mar 2019

OK

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.  
4 Shenton Way  
#21-01 SGX Centre 2  
Singapore 068807

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Pauline Tham

Date: 21 Mar 2019

**Preliminary Advice**

Insured Vehicle No	: PC4536P	Accident Date	: 12/03/2019
TP Vehicle No	: SLK5094X	Assignment Date	: 15/03/2019
Make	: TOYOTA PRIUS	Est. Duration of Repair	: 3 days
Date of Inspection	: 14/03/2019		
Inspection At	: Euro Success Services Pte Ltd (HQ) 1 KAKI BUKIT AVENUE 6 #02-03 AUTOBAY Singapore 417883		

**Point of Impact / General Description of Damages**

The vehicle sustained impact / damages n/s front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	9,232.54
Revised Amount	:S\$	4,072.66
Check Items (Estimated)	:S\$	0.00
Total	:S\$	4,072.66

Lump Sum Repair :S\$

**Total Loss Consideration**

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

**Remarks**

- ( ) The vehicle is economical/not economical for repair.
- ( X ) The above survey was conducted on a 'without prejudice' basis.

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the judgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	13/03/2019 12:50
Date Of Accident	12/03/2019 08:40
Exact Location Of Accident	AIRPORT BOULEVARD (BEFORE T2 AIRPORT)
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLK5094X
<b>Insured/Policyholder</b>	
Name Of Registered Owner	AMV PTE. LTD.
Co Reg No	201505825Z
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-98583956

### Vehicle Particulars

Manufacturer	TOYOTA
Model	PRIUS HYBRID 1.8S AT ABS D/AIRBAG 2WD
Exact Purpose for which vehicle was being used at time of accident	

Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

### Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5087569065-02 CLASSIC
Cover Note Number	

### Driver

Name of Driver	LIM POH SAN (LIN BAOSHAN)
NRIC No	S7603500H
Date Of Birth	09/02/1976
Occupation	OUTDOOR
Date Of Driving Pass	04/12/1995
Driving Experience	23 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91958688
Fax Number	
Contact Number	
EMail Address	LINBAOSHANLPS@GMAIL.COM

Address BLK 34 BEDOK SOUTH AVENUE 2 #16-387  
 Postcode 460034  
 Was driver an employee of the Insured's Company YES  
 If No, Relationship of the Driver with the Insured  
 Vehicle Registration Number of Driver's Own Vehicle -  
 -  
 -  
 Insurance Company of Driver's Own Vehicle -  
 -  
 -

**General Information of the Accident**

Type Of Accident SIDE SWIPE  
 Weather Conditions CLEAR  
 Road Surface DRY

**Other Information**

Was any foreign vehicle involved in this accident? NO  
 Number of vehicles (including own vehicle) Involved in the accident 2  
 Was any body injured in the Accident? NO  
 Was any injured conveyed to hospital by ambulance? NO  
 Was any other material or property damaged? YES  
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO  
 Number of Passengers (Including Driver) 1

**Details of Police Action**

Was the accident reported to the police? NO  
 If Yes, Please state which Police Station  
 Was notice of intended Prosecution given? NO  
 If Yes, against whom?

**Circumstances of Accident**

REFER TO SKETCH PLAN ATTACHED

**Attachment(s)**

Are accident photos available for attachment? YES  
 Was there any video captured by Car Camera? NO  
 Was there any audio recorded? NO

**DETAILS OF OTHER VEHICLE PROPERTY 1**

Vehicle Registration Number PC4536P  
 Vehicle Make/Model/Colour NISSAN NV350 HR MICROBUS 2.5 4DR 5AT ABS D/AB  
 Details Of Properties  
 Vehicle Category COMMERCIAL VEHICLE  
 Name of Driver STEVEN  
 NRIC/Passport Number  
 Contact Number 92305520  
 Address  
 Postcode  
 Insurance Company Name  
 Nature Of Damage  
 No. Of Passenger (Including Driver)

**IMPORTANT NOTICE**

- 1. Please report **correctly** the details of the accident to speed up the claims process.
- 2. This Form must be **completed by the Policyholder and/or the Authorized Driver**.
- 3. Information provided must be as **truthful and accurate as possible**. Any willful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. **Any false reporting may be referred to the Police for investigation.**
- 6. The report will be forwarded by the insurers of the IDA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workmate and the General Insurance Association of Singapore ("GIA") may be permitted to collect, use, disclose and/or process my personal data/personal information set out in this Form and any other personal information provided by me or possessed by my insurer collectively the "Personal Information" and disclose and transfer such Personal Information to all Insurers who have insured vehicles involved in this accident (all Insurers who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers") and Insurers' lawyers/law firms, the Analytics Authority of Singapore and other relevant government agencies/subsidiaries such as the Central for the Protection of Personal Data ("CPD").
- (b) Processing involving or in connection with my claims involving a settlement of the claim involving the Insurers' investigations relating to the claims.
- (c) Investigating the accident and/or the claim.
- (d) Determining and/or dealing with my claim/submitting a response to my insurer's claim.
- (e) Administering my claim (including the handling of contact overseas statements, invoices, receipts, notices from, which could involve disclosure of certain personal data should such information be a disclosure of the claim as well as the external level of employees' self assessment) and/or
- (f) Complying with applicable law in administering, processing, handling and/or dealing with my claim collectively the "Purposes".
- (g) All Insurers who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes, and
- (h) My Personal Information may also be disclosed by any of the Insurers and/or GIA to their third party service providers or agents including their Insurers/law firms, which may be able outside of Singapore, for one or more of the above Purposes.
- (i) My Personal Information will also be provided and used to enable the Insurers to manage the processing of their insurance/claims and management processes and all other matters.
- (j) The information collected shall be stored in a secure and protected manner.
- (k) I have agreed to allow my Personal Information to be used in analyzing, investigating, processing, or handling of the claims that regulatory and enforcement and government agencies as reasonably required for the purposes stated.
- (l) Not complying with requirements under any regulations, laws and/or standards.

**IDAC KAKI BUKIT (VAC)**  
 23 Kaki Bukit Ave 4  
 Singapore 415933  
 Tel: 67416697 Fax: 67492305  
 Email: [yackb@singnet.com.sg](mailto:yackb@singnet.com.sg)



Policyholder's Signature  
 Date & Time:

*[Handwritten Signature]*


Driver's Signature  
 (if driver is not the policyholder)  
 Date & Time:

Reporting Centre Personnel's Signature  
 Name:  
 NRIC/PRN No.:

13 MAR 2019

General Insurance Association of Singapore

Sketch Plan #2 Pg. 1



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On the above stated date and time I was travelling towards terminal 2 at airport and I was going straight when suddenly car B swerve into my lane and swing on to my front left portion. When I got hit and went to check I notice my car front left portion was damage.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

  
 Policyholder's Signature  
 Date & Time:

SA 01AC (Revised) Form 1/2

  
 Driver's Signature  
 (if driver is not the policyholder)  
 Date & Time: 13 MAR 2019

**IDAC KAKI BUKIT (VAC)**  
 23 Kaki Bukit Ave 4  
 Singapore 415933  
 Tel: 67416697 Fax: 67492305  
 Email: [vackb@singnet.com.sg](mailto:vackb@singnet.com.sg)  
Reporting Centre's Representative Signature  
 Name:  
 NRIC/PN No.:

EURO SUCCESS SERV PTE. LTD  
Blk 1 Kaki Bukit 6, #02-03 Singapore 417883

TEL: 67426231 FAX: 67411019 H/P: 98289277 (AH HUAT)

Vehicle No: SLK5094X Model: Toyota Prius

*not Authorized  
here  
2/5 → 3250/  
3 ty.  
the photo attached*

QTY	List Items	Price S
1	Front bumper <i>745-10</i>	<i>De/wegub</i> 1394.40
2	Front L-R bumper retainer @104.2	<i>17</i> 208.40 X
1	Front bumper L/H spotlight cover	<i>SCR</i> 130.20
1	Front L/H head lamp	<i>SCR</i> 2531.35
1	Front L/H fender	<i>70</i> 556.90
1	Front L/H fender inner shield	<i>17</i> 139.80 X
1	Front L/H door mirror	<i>2</i> 986.40 X
1	Front L/H shock absorber	<i>17</i> 298.60 X
1	Front L/H lower arm	<i>17</i> 339.30 X
1	Front L/H knuckle arm	<i>17</i> 576.20 X
1	Front L/H wheel bearing	<i>17</i> 488.50 X

Total **\$7,650.05**  
Less 25% **\$1,912.51**  
Total **\$5,737.54**

**Special Nett Items**

1	Front bumper clip	<i>RU</i> 60.00 <i>50</i>
1	Front fender shield clip	<i>17</i> 45.00 X
1	Front L/H door board clip	<i>17</i> 60.00 X
1	Front L/H tyre	<i>RU</i> 250.00 X
1	Front L/H tyre hup cage	<i>R</i> 160.00 X

**\$575.00**

**Labour Charge**

To apply undercoating on accident parts	200.00 <i>30</i>
To remove refix front undercarriage	<i>RU</i> 250.00 X
To conduct wheel alignment	<i>17</i> 150.00 X
To remove, refix headlamp, mirror and check electrical wiring	120.00 <i>20</i>
To respray painting	1000.00 <i>600</i>
Panel beating, workmanship, remove, knowing front door and replacting above parts	1200.00 <i>400</i>

**\$2,920.00**

**ESTIMATED PARTS AND LABOUR GRAND TOTAL**

**\$9,232.54**

*R-3963-55  
297266  
407266  
325813*

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	13 Mar 2019		15 Mar 2019 10:07 <a href="#">Edit Adj Rpt</a>	<b>S\$3,250.00</b> <a href="#">Edit Estimates</a>	<b>S\$3,250.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by insurer]</span>									
Insured:	<b>Maritime Transport Services Pte. Ltd.</b> , Co. Reg. No.: 200402055D								
Main Claimant:	<b>AMV PTE. LTD.</b> , Co. Reg. No.: 201505825Z								
Vehicle Reg. No.:	<b>SLK5094X</b>	Date of Loss:	12/03/2019 08:00 - :59 [25 Months and 22 Days From LTA Reg Date (Man Yr)]						
Claim Type:	<b>TP / 587501</b>	Policy/Cover Note No.:	28675693 (Comprehensive) Coverage: 22/01/2019 - 21/01/2020						
Vehicle Reg. No. (Insured):	<b>PC4536P</b>	Policy No. (Claimant):							
		Excess:							
Repairer:	<b>Euro Success Services Pte Ltd (HQ)</b> 1 KAKI BUKIT AVENUE 6 #02-03 AUTOBAY, 417883 Kaki Bukit - Tel:								
Handling Insurer:	<b>MSIG Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: +65 6827 7888 ... [Handled by <b>Pauline Tham</b> - 6594 2545]								
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>MARCUS CHUA</b> ] ... [Final Rpt due 14/04/2019]								
Driver/Custodian (Insured):	TOONG NGAI JUAY ( ) . NRIC: S1544713C Email:								
Adj Asg. Remarks:	on WP> LIABILITY NOT CLEAR. TP AGREE SJE - ASSIGN LKK AUTO CONSULTANTS PTE LTD CONTACT: Ah Huat (Tel. 9828 9277 / 6742 6231)								
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
<b>Due Date</b>	<b>Priority</b>	<b>Type</b>	<b>Task Group</b>	<b>Subject</b>	<b>Handler</b>	<b>Assigned By</b>	<b>Completed On</b>	<b>Created On</b>	<b>Done?</b>
No results.									

## Claim Documents

\*SLK5094X (587501)  
[PC4536P]  
TP  
AMV PTE. LTD.  
Mar 12 2019 8:00AM  
[Mariteam Transport Services Pte. Ltd]  
Euro Success Services Pte Ltd

Upload Documents			Upload Photos		Compose New Letter		View <input type="button" value="View in Browser"/>	
<b>Video</b>							1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)			Thumbnail	Print		
1	03/04/19 08:49	TP Video - Accident				Load MP4		
<b>Assessment Reports</b>							1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)			Thumbnail	Print		
1	21/03/19 09:21	Adjuster Immediate Advice				Load HTM		
<b>Photos/Images</b>							3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)			Thumbnail	Print		
1	15/03/19 17:18	Chassis Number				Load JPG	<input checked="" type="checkbox"/>	
2	15/03/19 17:18	Odometer Reading				Load JPG	<input checked="" type="checkbox"/>	
3	15/03/19 17:18	General View				Load JPG	<input checked="" type="checkbox"/>	
4	15/03/19 17:18	General View				Load JPG	<input checked="" type="checkbox"/>	
5	15/03/19 17:18	General View				Load JPG	<input checked="" type="checkbox"/>	
6	15/03/19 17:18	General View				Load JPG	<input checked="" type="checkbox"/>	
7	15/03/19 17:18	General View				Load JPG	<input checked="" type="checkbox"/>	
8	15/03/19 17:18	General View				Load JPG	<input checked="" type="checkbox"/>	
9	15/03/19 17:18	General View				Load JPG	<input checked="" type="checkbox"/>	
10	15/03/19 17:18	General View				Load JPG	<input checked="" type="checkbox"/>	
11	15/03/19 17:18	General View				Load JPG	<input checked="" type="checkbox"/>	
12	15/03/19 17:18	General View				Load JPG	<input checked="" type="checkbox"/>	
13	15/03/19 17:18	General View				Load JPG	<input checked="" type="checkbox"/>	
14	15/03/19 17:18	General View				Load JPG	<input checked="" type="checkbox"/>	
15	15/03/19 17:18	General View				Load JPG	<input checked="" type="checkbox"/>	
16	15/03/19 17:18	General View				Load JPG	<input checked="" type="checkbox"/>	
17	15/03/19 17:18	General View				Load JPG	<input checked="" type="checkbox"/>	
18	15/03/19 17:18	General View				Load JPG	<input checked="" type="checkbox"/>	
19	15/03/19 17:18	General View				Load JPG	<input checked="" type="checkbox"/>	
20	15/03/19 17:18	General View				Load JPG	<input checked="" type="checkbox"/>	
21	15/03/19 17:18	General View				Load JPG	<input checked="" type="checkbox"/>	
22	15/03/19 17:18	General View				Load JPG	<input checked="" type="checkbox"/>	
23	15/03/19 17:18	General View				Load JPG	<input checked="" type="checkbox"/>	
24	15/03/19 17:18	General View				Load JPG	<input checked="" type="checkbox"/>	
25	15/03/19 17:18	General View				Load JPG	<input checked="" type="checkbox"/>	
26	15/03/19 17:18	General View				Load JPG	<input checked="" type="checkbox"/>	
27	15/03/19 17:18	General View				Load JPG	<input checked="" type="checkbox"/>	
28	15/03/19 17:18	General View				Load JPG	<input checked="" type="checkbox"/>	
29	15/03/19 17:18	General View				Load JPG	<input checked="" type="checkbox"/>	
30	15/03/19 17:18	General View				Load JPG	<input checked="" type="checkbox"/>	

Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
31	15/03/19 17:18	General View		<input checked="" type="checkbox"/>
32	15/03/19 17:18	General View		<input checked="" type="checkbox"/>
33	15/03/19 17:18	General View		<input checked="" type="checkbox"/>
34	15/03/19 17:18	General View		<input checked="" type="checkbox"/>
35	15/03/19 17:18	General View		<input checked="" type="checkbox"/>
36	15/03/19 17:18	General View		<input checked="" type="checkbox"/>
37	15/03/19 17:18	General View		<input checked="" type="checkbox"/>
38	15/03/19 17:18	General View		<input checked="" type="checkbox"/>
39	15/03/19 17:18	General View		<input checked="" type="checkbox"/>
40	15/03/19 17:18	General View		<input checked="" type="checkbox"/>
41	15/03/19 17:18	General View		<input checked="" type="checkbox"/>
42	15/03/19 17:18	General View		<input checked="" type="checkbox"/>
43	15/03/19 17:18	General View		<input checked="" type="checkbox"/>
44	15/03/19 17:18	General View		<input checked="" type="checkbox"/>
45	15/03/19 17:18	General View		<input checked="" type="checkbox"/>
46	15/03/19 17:18	General View		<input checked="" type="checkbox"/>
47	15/03/19 17:18	General View		<input checked="" type="checkbox"/>
48	15/03/19 17:18	General View		<input checked="" type="checkbox"/>
49	15/03/19 17:18	General View		<input checked="" type="checkbox"/>
50	15/03/19 17:18	General View		<input checked="" type="checkbox"/>
51	15/03/19 17:18	General View		<input checked="" type="checkbox"/>
52	21/03/19 09:17	Reinspection Photo		<input checked="" type="checkbox"/>
53	21/03/19 09:17	Reinspection Photo		<input checked="" type="checkbox"/>
54	21/03/19 09:17	Reinspection Photo		<input checked="" type="checkbox"/>
55	21/03/19 09:17	Reinspection Photo		<input checked="" type="checkbox"/>
56	21/03/19 09:17	Reinspection Photo		<input checked="" type="checkbox"/>
57	21/03/19 09:17	Reinspection Photo		<input checked="" type="checkbox"/>
58	21/03/19 09:17	Reinspection Photo		<input checked="" type="checkbox"/>
59	21/03/19 09:17	Reinspection Photo		<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	14/03/19 09:53	TP PRI REQUEST EMAIL		<input type="checkbox"/>
2	14/03/19 09:54	SLK5094X e-file report		<input type="checkbox"/>
3	14/03/19 09:54	OI PC4536P e-file report		<input type="checkbox"/>
4	14/03/19 15:17	tp agree sje - assign LKK		<input type="checkbox"/>

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b>			
<div style="border: 1px solid black; width: 100%; height: 100%;"></div>			
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

### VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS/MSG19004706/UVD3Q2

**Date:** 04/04/2019

#### REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 28675693

**Claimant Vehicle No :** SLK5094X

**Insured Vehicle No :** PC4536P

Date of Loss: 12/03/2019

Nature of Claim: TP

Claim No: 587501

#### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLK5094X**

Make & Model: TOYOTA PRIUS, 1.8 HYBRID CVT (A)

Engine No: 2ZR6824794

Reg. Date: 18/01/2017 (Man. Year: 2016)

Chassis No: ZVW506040591

Colour: Black

Odometer: 202890 km

Engine Capacity: 1797 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

#### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

#### CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Davanti 6 mm	Rear Left Side:	Davanti 6 mm
Front Right Side:	Davanti 6 mm	Rear Right Side:	Davanti 6 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,312.54	3,022.66	3,289.88	52.12
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,920.00	1,050.00	1,870.00	64.04
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>9,232.54</b>	<b>4,072.66</b>	<b>5,159.88</b>	<b>55.89</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>3,250.00</b>		
<b>Nett Amount (S\$)</b>	<b>9,232.54</b>	<b>3,250.00</b>	<b>5,982.54</b>	<b>64.80</b>

#### INSPECTION

Date of Assignment: 15/03/2019

Date Inspected: 14/03/2019 Inspected At:

Euro Success Services Pte Ltd (HQ)  
1 KAKI BUKIT AVENUE 6 #02-03  
AUTOBAY  
Singapore 417883

Estimated Period of Repair: 3.0 days

**Adjuster:** MARCUS CHUA

**Manager:** VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

Reference	
<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 03 Apr 2019)
<b>Parts:</b> 144	TOYOTA PRIUS 1.8 HYBRID CVT (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SLK5094X)
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b> Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed/ Warped	1,394.40 FL	*745.10 FL
2	2		*FRONT L-R BUMPER RETAINER	Not Necessary	208.40 FL	*- FL
3	1		*FRONT BUMPER L/H SPORTLIGHT COVER	Scratched	130.20 FL	*130.20 FL
4	1		*FRONT L/H HEAD LAMP	Scratched	2,531.35 FL	*2,531.35 FL
5	1		*FRONT L/H FENDER	Dented	556.90 FL	*556.90 FL
6	1		*FRONT L/H FENDER INNER SHIELD	Not Necessary	139.80 FL	*- FL
7	1		*FRONT L/H DOOR MIRROR	Repair	986.40 FL	*- FL
8	1		*FRONT L/H SHOCK ABSORBER	Not Necessary	298.60 FL	*- FL
9	1		*FRONT L/H LOWER ARM	Not Necessary	339.30 FL	*- FL
10	1		*FRONT L/H KNUCKLE ARM	Not Necessary	576.20 FL	*- FL
11	1		*FRONT L/H WHEEL BEARING	Not Necessary	488.50 FL	*- FL
12	1		*FRONT BUMPER CLIP	Necessary	60.00 FS	*50.00 FS
13	1		*FRONT FENDER SHIELD CLIP	Not Necessary	45.00 FS	*- FS
14	1		*FRONT L/H DOOR BOARD CLIP	Not Necessary	60.00 FS	*- FS
15	1		*FRONT L/H TYRE	Not Necessary	250.00 FS	*- FS
16	1		*FRONT L/H TYRE HUP CAGE	Repair	160.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>8,225.05</b>	<b>4,013.55</b>
<b>- List Item Discount on L Items 25.00/25.00% (\$\$)</b>	1,912.51	990.89
<b>Total Parts (\$\$)</b>	<b>6,312.54</b>	<b>3,022.66</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO APPLY UNDERCOATING ON ACCIDENT PARTS	New	200.00	30.00
2	TO REMOVE REFIX FRONT UNDERCARRIAGE	New	250.00	0.00
3	TO CONDUCT WHEEL ALIGNMENT	New	150.00	0.00
4	TO REMOVE,REFIX HEADLAMP ,MIRROR AND CHECK ELECTRICAL WIRING	New	120.00	20.00
5	TO RESPRAY PAINTING	New	1,000.00	600.00
6	PANEL BEATING ,WORKMANSHIP ,REMOVE,KNOWING FRONT DOOR AND REPLACTING ABOVE PARTS	New	1,200.00	400.00
<b>Gross Labour Cost (S\$)</b>			<b>2,920.00</b>	<b>1,050.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >