

ASS. REC. BY:

REF:

CS3/MSG/19004707 / Bcd3d

Special Instruction:

SURVAILOR  
Menmen

Mr. Jim

## ASSIGNMENT (Office)

From (Person):

Monica chung

of

M81G

Date/Time:

14/3/19 @ 4:15pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SDS 8989 Y

Insured:

SFR 3408Y

at Workshop m/s

A.T. performance

Tel:

96866219

of

160 Sin Ming Drive #07-18/19

Policy No:

71514546

Claim No:

587382

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

12/3/2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

15/3/19 @ 10:03am

Person Contacted:

Alvin

Vehicle IN / OUT

Date/Time

Action/Instruction

(✓)

Estimate

SDS 8989Y - CC5/A1907000141/KDS

D.O.A - 4/7/2007

NA/TMI 15001492/14

D.O.A - 26/11/2015

19/03/19

@ 16:50 p.m. rec'd reply estimate from repairer to Monica &amp; v.a. memo.

27/3/19

@ 11 Ham Alvin said no est provided, engaged independent dismantle: 18/3/2019

REF: MSG

## ASSIGNMENT

From:

Date:

15/3/19

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SDS 89894

at Workshop m/s

AT Performance

of

160 Sio Ming Drive #07-18/19

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

4

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SDS 89894

Yr Regn:

12/5/2011

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

BMW 523i

c.c 2497

Colour

SILVER

A/C: Insured / Std / NI / NA

Sp. Reading

133474

T/Radio: Insured / Std / NI / NA

Eng/No:

04937583N52B25AF

C/No:

WBAFP32672 C546603

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F: 245/40/17 (MIC)

R: 275/35/17 (GY)

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

7

mm

R/Bal.

7

mm

L/Bal.

7

mm

L/Bal.

7

mm

D.O.A.

12/3/19

D.O.I.

15/3/19

Survey held at

AT Performance

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Range 3000/2 - 4000/2

*[Signature]*  
2/4/2019

M.V

57,000/2

P.V

58,554/2

N.V

18,446/2

T.C. Gen

1/4 - 18/1

Date/Time, File Pass to?

☐

: Preli. Report

☐

: Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair:

4

Resurvey No. of Trip:

1

Survey Fee:

120

Transportation:

Add Fee:

☐

: Site Insp (\$

) \$ + R.S. \$ SI

☐

: Interview (\$

) Photos

☐

: Tech. Invs (\$

) Others

☐

: Weekend (\$

)

Report Format:

PRE

Lump Sum / I.B.I. (\$

TOTAL

130

## ...CLAIM SUBFOLDER...(New Assignment)

### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	13 Mar 2019		14 Mar 2019 16:15 <a href="#">Assign</a>				<b>New Assignment</b> <a href="#">Cancel Case</a>

[Main](#)
[Reference](#)
[Claim Details](#)
[Documents](#)
[Show All](#)

### CLAIM SUBFOLDER DETAILS

[\[Created by insurer\]](#)

[Created by Insur]

Insured:	JEYA LETCHUMI JEYA LETCHUMI D/O BALA SUBRAMA, ID: S1447710A, Tel: +6590262649		
Main Claimant:	CHONG KIM TECK, ID: S1764334G		
Vehicle Reg. No.:	SDS8989Y	Date of Loss:	12/03/2019 07:00 - :59 [94 Months From LTA Reg Date (Man Yr)]
Claim Type:	TP / 587382	Policy/Cover Note No.:	71514546 (Comprehensive) Coverage: 10/04/2018 - 09/04/2019
Vehicle Reg. No. (Insured):	SFR3408Y	Policy No. (Claimant):	
		Excess:	
Repairer:	A T Performance (SIN MING) 160 SIN MING DRIVE, #07-18/19 SIN MING AUTOCITY, 575722 Sin Ming - Tel: 96866219		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Monica Chung Pei Zhen - 6594 2552]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 15/03/2019]		
Driver/Custodian (Insured):	C SAKTIVEL (), NRIC: S9041109H, Tel: +6591836190 Email:		
Adj Asg. Remarks:	on WP. LIAB 100% SJE DISAGREE APPOINT LKK. PLS CONTACT Mr Alvin Tng (H/P : 9686 6219)		

### ASSOCIATED MAIL RECEIVED

[View All](#)
[Compose Case Mail](#)

There are no mail for this case.

### ALL ASSOCIATED TASKS

[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

### Vehicle Owner Particulars

Owner ID Type: Singapore NRIC  
Owner ID: 4334G

### Vehicle Details

Vehicle No.: SDS8989Y  
Vehicle to be Exported: No  
Intended Deregistration Date: 18 Mar 2019  
Vehicle Make: B.M.W.  
Vehicle Model: 523I A  
Primary Colour: Silver  
Manufacturing Year: 2010  
Engine No.: 04937583N52B25AF  
Chassis No.: WBAFP32070C546603  
Maximum Power Output: 150.0 kW (201 bhp)  
Open Market Value: \$44,225.00  
Original Registration Date: 12 May 2011  
First Registration Date: 12 May 2011  
Transfer Count: 1  
Actual ARF Paid: \$44,225.00

### Intended PARF Rebate Details

PARF Eligibility: Yes  
PARF Eligibility Expiry Date: 11 May 2021  
PARF Rebate Amount: \$26,535.00

### Intended COE Rebate Details

COE Expiry Date: 11 May 2021  
COE Category: E - Open Category  
COE Period(Years): 10  
QP Paid: \$56,001.00  
COE Rebate Amount: \$12,019.00  
Total Rebate Amount: \$38,554.00

The information contained herein is correct as at 18 Mar 2019

OK

COE left 2 yrs 3 mths

avg dep 14,000/yr

MV 57,000/-  
PV 38,554/2  
NV 18,446/2

18/3/19



## ANNOUNCING AA Trust Automotive as sgCarMart Premium Dealer 2019



**Post an Advertisement**  
Sell it yourself! Advertise it at just  
**\$58 until it's SOLD!**

Post an Ad

Advertiser Login

Ways of Selling

Jaguar XF 2.0 Luxury.



Inline 4 Turbo Engine,  
Immaculate Condition, View To  
Believe. Best In Class.  
Direct Owner **StarArt**

**Lake View  
Credit Pte Ltd**

[view our cars](#)  
 > Low prices guaranteed  
 > Specialist in Japanese cars  
 > Easy loan approval  
 > All terms are negotiable

Browse by Category ▾

« Back ( 1 2 3 4 ) Next »

Sort by Date Posted ▾

20 results/page ▾

76 vehicles

BMW 523i

Advanced Search

	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
<b>Search Selection</b>	BMW 523i	Any	Any	2011	Any	Any	Any	All
	<b>BMW 5 Series 523i</b>	<b>\$54,500</b>	<b>\$14,170 /yr</b>	<b>27-Jun-2011</b>	<b>2,497 cc</b>	<b>-</b>	<b>Luxury</b>	<b>Available</b>
Flexible Loan, Tenure, Flexible Down Payment Available! 2011 Bmw 523 F10 2.5A On Sale Now! Beautiful Condition! Black Exterior! Best Time And Chances For You To Own This F10 Lowest Pricing Quantum! Lo...								
Posted: 17-Mar-2019 Tags: 2011 BMW 523i, 2011 bmw 523i, BMW 523i, bmw 523i, BMW, 523i, Used BMW								
	<b>BMW 5 Series 523i Sunroof</b>	<b>\$58,000</b>	<b>\$16,300 /yr</b>	<b>15-Apr-2011</b>	<b>2,497 cc</b>	<b>96,000 km</b>	<b>Luxury</b>	<b>Available</b>
Price Reduced! Unless You Are A Sincere Buyer, Please Do Us Both A Favor And Don't Waste Each Others Time, Thank You. Fully Done Up F10 With M5 Bodykit, Dressed Up Beautifully With Carbon Fiber Both I...								
Posted: 15-Mar-2019 Tags: 2011 BMW 523i, 2011 bmw 523i, BMW 523i, bmw 523i, BMW, 523i, Used BMW								
	<b>BMW 5 Series 523i Highline</b>	<b>\$60,888</b>	<b>\$13,980 /yr</b>	<b>01-Nov-2011</b>	<b>2,497 cc</b>	<b>100,000 km</b>	<b>Luxury</b>	<b>Available</b>
1 Owner, High Spec BMW 523i Highline Model. PML Unit With Regular Serviced By Previous Owner. Come With Free 6 Month Warranty. Low Mileage Done. Car Still In Original Paintwork And Condition. High ARF ...								
Posted: 15-Mar-2019 Tags: 2011 BMW 523i, 2011 bmw 523i, BMW 523i, bmw 523i, BMW, 523i, Used BMW								
	<b>BMW 5 Series 523i</b>	<b>\$50,800</b>	<b>\$13,160 /yr</b>	<b>31-May-2011</b>	<b>2,497 cc</b>	<b>131,000 km</b>	<b>Luxury</b>	<b>Available</b>
Elegant White BMW. Regular Servicing, Well Maintain, Superb Condition, View To Believe. Please Call Before Viewing.								
Posted: 15-Mar-2019 Tags: 2011 BMW 523i, 2011 bmw 523i, BMW 523i, bmw 523i, BMW, 523i, Used BMW								
	<b>BMW 5 Series 523i</b>	<b>\$55,000</b>	<b>\$14,070 /yr</b>	<b>28-Jul-2011</b>	<b>2,497 cc</b>	<b>82,000 km</b>	<b>Luxury</b>	<b>Available</b>
Luxurious And Spacious. Low Mileage Done! Beautiful On Brown Dakota Leather. Very Well Maintained! Superb Condition! 100% Accident-Free. Owner Rebuilt A Lot Of Accessories For Next Buyer. Owner Loss I...								
Posted: 15-Mar-2019 Tags: 2011 BMW 523i, 2011 bmw 523i, BMW 523i, bmw 523i, BMW, 523i, Used BMW								
	<b>BMW 5 Series 523i Sunroof</b>	<b>\$53,800</b>	<b>\$12,250 /yr</b>	<b>05-Aug-2011</b>	<b>2,497 cc</b>	<b>128,000 km</b>	<b>Luxury</b>	<b>Available</b>
This Is A PI Model With Suction Doors Which Is A Rare Gem For 5 Series, Full Service Record Under Workshop, Road Tax Just Paid, Home And Office With Sheltered Parking, Higher OMV At \$49K+, Slight Nego...								
Posted: 14-Mar-2019 Tags: 2011 BMW 523i, 2011 bmw 523i, BMW 523i, bmw 523i, BMW, 523i, Used BMW								
	<b>BMW 5 Series 523i</b>	<b>\$47,500</b>	<b>\$12,890 /yr</b>	<b>04-Apr-2011</b>	<b>2,497 cc</b>	<b>160,000 km</b>	<b>Luxury</b>	<b>Available</b>
PML UNIT Comes With 20" Inch Rim!								
Posted: 14-Mar-2019 Tags: 2011 BMW 523i, 2011 bmw 523i, BMW 523i, bmw 523i, BMW, 523i, Used BMW								

Complete

IW 5 Series 523i Highline

\$48,666

\$13,950 /yr

10-Feb-2011

2,497 cc

-

Luxury

Available

ided Car Number. 100% Loan Available. Well Kept Pristine Condition, High Coe And Omv. 100% Loan! Accident Free, High Trade In, Cheapest

## View Sent Message

This mail is associated with :

**\*SDS8989Y (587382)**  
**[SFR3408Y]**

TP

CHONG KIM TECK

Mar 12 2019 7:00AM

[JEYA LETCHUMI JEYA LETCHUMI D/O BALA SUBRAMA]

A T Performance

[Resend](#)[View Recipients](#)[Print Message](#)[Delete Message](#)[Forward](#)

**From** LKK Auto Consultants Pte Ltd (LKK\_HQ), sent on 19/03/2019 16:50 PM.

**To** monica\_chung@sg.msg-asia.com

**CC** sur@lkkauto.com

**Subject** SDS8989Y (587382) [SFR3408Y] TP

Dear Monica,

Please be informed that we have inspected the vehicle SDS 8989Y on 15/03/2019.

We are pending estimate from repairer.

Thank you.

Best Regards,

Shirley Hiew | Case Handler (On Behalf Veron)

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

### DOCUMENTS SUMMARY

There are no documents.

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	12/03/2019 15:01
Date Of Accident	12/03/2019 07:35
Exact Location Of Accident	YIO CHU KANG RD TWDS SLE OPP S'PORE TECHNOLOGY
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SDS8989Y
<b>Insured/Policyholder</b>	
Name Of Registered Owner	CHONG KIM TECK
NRIC No	S1764334G
Email Address	DICKSONCHONG@GMAIL.COM
Mobile Phone No	(LOCAL) +65-98370262
Alternative Phone No	OFFICE-NOPHONE

### Vehicle Particulars

Manufacturer	BMW
Model	523I
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

### Insurance Company

Name of Insurance Company	FWD SINGAPORE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	PNPV2017-00008194-01
Cover Note Number	12/11/2018 TO 11/11/2019

### Driver

Name of Driver	CHONG KIM TECK
NRIC No	S1764334G
Date Of Birth	11/03/1966
Occupation	INDOOR
Date Of Driving Pass	06/03/1992
Driving Experience	27 YEARS AND 0 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98370262
Fax Number	
Contact Number	OFFICE-NOPHONE
Email Address	DICKSONCHONG@GMAIL.COM

Address	16 CACTUS DRIVE #03-02
Postcode	809690
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	DRIZZLING
Road Surface	WET

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

REFER TO SKETCH PLAN

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SFR3408Y
Vehicle Make/Model/Colour	HYUNDAI AVANTE
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	C SAKTIVEL
NRIC/Passport Number	S9041109H
Contact Number	91836190
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	



SKETCH PLAN

FWD


Vehicle: - SDS  
89894

IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow Insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by Insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My Insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all Insurer(s) who have insured vehicle(s) involved in this accident (all Insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all Insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

  
Policyholder's Signature  
Date & Time: 12 Mar 2019


Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

  
Reporting Centre Person's Signature  
Name:   
NRIC/FIN No.: 12/03/19

Sketch Plan Pg. 2

SKETCH PLAN

Date: 12-3-2019 Time: 0737 HRS Location: YIO CHU KANG ROAD TOWARDS SLE OPPOSITE  
 My Vehicle A: SDS8989Y Vehicle B: SFR3408Y Vehicle C/Others: SINGAPORE TECHNOLOGY



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I stopped my vehicle A SDS8989Y as the traffic light in front was RED. AS I was STATIONARY WAITING vehicle B SFR3408Y came from behind and collided into the rear section of my vehicle. I would like to state that my vehicle SDS8989Y was stationary at the point of impact.

( ) Claim OD / TP at Ah Lim Motor (✓) Claim OD / TP at other workshop ( ) Reporting Only

Remarks: Please forward a copy of my efile accident report to

My workshop: ALVIN TAN 800YAHOO.COM.SG

Email Address

& Myself

Email Address: DICKSONCHONG12@gmail.com

Note: Please take note that your insurer have 14 days timeframe for you to submit own damage claim under your own policy. Kindly check with your own insurer for more information.

DECLARATION

I/We declare the foregoing particulars are true in every respect. Vehicle: SDS8989Y

Policyholder's Signature  
Date & Time:

Driver's Signature (If driver is not the policyholder)  
Date & Time

Witnessed by Reporting Centre  
Personnel



12/3/19

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	13 Mar 2019		14 Mar 2019 16:15 <a href="#">Edit Adj Rpt</a>	<b>S\$0.00</b> <a href="#">Edit Estimates</a>	<b>S\$0.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b>		<b>[Created by insurer]</b>							
Insured: <b>JEYA LETCHUMI JEYA LETCHUMI D/O BALA SUBRAMA</b> , ID: S1447710A, Tel: +6590262649									
Main Claimant: <b>CHONG KIM TECK</b> , ID: S1764334G									
Vehicle Reg. No.: <b>SDS8989Y</b>		Date of Loss: 12/03/2019 07:00 - :59 <b>[94 Months From LTA Reg Date (Man Yr)]</b>							
Claim Type: <b>TP / 587382</b>		Policy/Cover Note No.: 71514546 (Comprehensive) Coverage: 10/04/2018 - 09/04/2019							
Vehicle Reg. No. (Insured): <b>SFR3408Y</b>		Policy No. (Claimant):							
		Excess:							
Repairer: <b>A T Performance (SIN MING)</b> 160 SIN MING DRIVE, #07-18/19 SIN MING AUTOCITY, 575722 Sin Ming - Tel: 96866219									
Handling Insurer: <b>MSIG Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: +65 6827 7888 ... [Handled by <b>Monica Chung Pei Zhen</b> - 6594 2552]									
Adjuster: <b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>Lim Teow Guan</b> ] ... <b>[Imm.Advice due 15/03/2019]</b>									
Driver/Custodian (Insured): C SAKTIVEL (), NRIC: S9041109H, Tel: +6591836190 Email:									
Adj Asg. Remarks: on WP, LIAB 100% SJE DISAGREE APPOINT LKK. PLS CONTACT Mr Alvin Tng (H/P : 9686 6219)									
<b>ASSOCIATED MAIL RECEIVED</b> <a href="#">View All</a> <a href="#">Compose Case Mail</a>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a>									
<b>Due Date</b>	<b>Priority</b>	<b>Type</b>	<b>Task Group</b>	<b>Subject</b>	<b>Handler</b>	<b>Assigned By</b>	<b>Completed On</b>	<b>Created On</b>	<b>Done?</b>
No results.									

## Claim Documents

**\*SDS8989Y (587382)**

**[SFR3408Y]**



































**TP**






























**CHONG KIM TECK**

**Mar 12 2019 7:00AM**

**[JEYA LETCHUMI JEYA LETCHUMI D/O BALA SUBRAMA]**

**A T Performance**

<a href="#">Upload Documents</a>		<a href="#">Upload Photos</a>	<a href="#">Compose New Letter</a>	<b>View</b> <a href="#">View in Browser</a>	
<b>Assessment Reports</b>				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print	
1	14/03/19 09:22	<b>Accident Statement</b> From: SC - Reg. No: SFR3408Y, Claimant: JEYA LETCHUMI JEYA LETCHUMI D/O BALA SUBRAMA	 Load HTM		
<b>Photos/Images</b>				3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print	
1	02/04/19 17:04	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>	
2	02/04/19 17:04	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>	
3	02/04/19 17:04	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>	
4	02/04/19 17:04	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>	
5	02/04/19 17:04	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>	
6	02/04/19 17:04	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>	
7	02/04/19 17:04	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>	
8	02/04/19 17:04	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>	
9	02/04/19 17:04	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>	
10	02/04/19 17:04	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>	
11	02/04/19 17:04	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>	
12	02/04/19 17:04	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>	
13	02/04/19 17:04	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>	
14	02/04/19 17:04	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>	
15	02/04/19 17:04	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>	
16	02/04/19 17:04	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>	
17	02/04/19 17:04	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>	
18	02/04/19 17:04	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>	
19	02/04/19 17:04	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>	
20	02/04/19 17:04	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>	
21	02/04/19 17:04	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>	
22	02/04/19 17:04	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>	
23	02/04/19 17:04	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>	
24	02/04/19 17:04	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>	
25	02/04/19 17:04	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>	
26	02/04/19 17:04	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>	
27	02/04/19 17:04	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>	
28	02/04/19 17:04	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>	
29	02/04/19 17:04	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>	
30	02/04/19 17:04	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>	
31	02/04/19 17:04	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>	
32	02/04/19 17:04	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>	
33	02/04/19 17:04	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>	

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
34	02/04/19 17:04	General View	 Load JPG	<input checked="" type="checkbox"/>
35	02/04/19 17:04	General View	 Load JPG	<input checked="" type="checkbox"/>
36	02/04/19 17:04	General View	 Load JPG	<input checked="" type="checkbox"/>
37	02/04/19 17:04	General View	 Load JPG	<input checked="" type="checkbox"/>
38	02/04/19 17:04	General View	 Load JPG	<input checked="" type="checkbox"/>
39	02/04/19 17:04	General View	 Load JPG	<input checked="" type="checkbox"/>
40	02/04/19 17:04	General View	 Load JPG	<input checked="" type="checkbox"/>
41	02/04/19 17:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
42	02/04/19 17:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
43	02/04/19 17:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
44	02/04/19 17:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
45	02/04/19 17:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
46	02/04/19 17:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
47	02/04/19 17:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
48	02/04/19 17:05	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
49	02/04/19 17:05	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
50	02/04/19 17:05	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
51	02/04/19 17:05	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
52	02/04/19 17:05	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
53	02/04/19 17:05	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
54	02/04/19 17:05	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
55	02/04/19 17:05	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
56	02/04/19 17:05	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
57	02/04/19 17:05	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
58	02/04/19 17:05	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
59	02/04/19 17:05	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
60	02/04/19 17:05	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	14/03/19 09:23	TP SDS8989Y E-REPORT	 Load PDF	
2	14/03/19 09:43	SJE DISAGREE APPOINT LKK	 Load PDF	

## Documents Checklist

### DOCUMENTS CHECKLIST

Reset

Save

Print

There are no document checklists configured.

### Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG19004707/BCD3E2

Date: 04/04/2019

## REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 71514546

Claimant Vehicle No : SDS8989Y

Insured Vehicle No : SFR3408Y

Date of Loss: 12/03/2019

Nature of Claim: TP

Claim No: 587382

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: SDS8989Y

Make &amp; Model: BMW 523I, 2.5 (A)

Engine No: 04937583N52B25AF

Reg. Date: 12/05/2011 (Man. Year: 2010)

Chassis No: WBAFP32070C546603

Colour: Silver

Odometer: 133474 km

Engine Capacity: 2497 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size: 245/40 R19

Rear Tyre Size: 275/35 R19

Front Left Side: Michelin 7 mm

Rear Left Side: Goodyear 7 mm

Front Right Side: Michelin 7 mm

Rear Right Side: Goodyear 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

## INSPECTION

Date of Assignment: 14/03/2019

Date Inspected: 15/03/2019 Inspected At:

A T Performance (SIN MING)

160 SIN MING DRIVE, #07-18/19 SIN

MING AUTOCITY

Singapore 575722

Estimated Period of Repair: 4.0 days

Adjuster: Lim Teow Guan

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.  
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,000.00 -\$4,000.00

## REPAIR DETAILS

<b>Reference</b>	
<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 03 Apr 2019)
<b>Parts:</b> 143	BMW 523I 2.5 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SDS8989Y)
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b> Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.



## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.
---

< END OF ESTIMATES >