

ASS. REC. BY:

REF: CSZ

CT119004728/71cd3ek

Special Instruction:

Surveyor:

Tang Hui

ASSIGNMENT (Office)

From (Person):

Cheng Ben &

of

CTI

Date/Time:

15/3/19 1:04pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJD 5212H

Insured:

XD 7423L

at Workshop m/s

Hup Hup Motor

Tel:

62651966

of

27A Junyong Port Road

Policy No:

DMCSN17085818022

Claim No:

SNM19D200946C02

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

23/2/19

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

2:19pm 15/3/19

Person Contacted:

Ms. Wong

Vehicle IN/OUT

Date/Time

Action/Instruction

(✓)

Estimate

SJD 5212H - NA/INC 19003421/r3

D.O.A: 23/2/19

XD 7423L - NA/INC 19003421/r3

D.O.A: 23/2/19

After repair: 20/3/2019

Tanaka

91

05 2023 March
2008 March

Vehicle No. Date

Type

Make

Color

Sp. No.

Eng. No.

Chassis No.

Year of Manufacture

Insured

Policy No.

Make of Motor

(Policy Conditions)

Remarks: The veh had commenced its repair at the time of inspection.

INS	OK
-----	----

Est. or Motor Value

How recent report Consistent? Yes or No

Est. or Motor Value Consistent? Yes or No

Est. or Motor Value days Rest Yes or No

Est. or Motor Value % 3rd Val. Yes or No

CA / TRV / REP / 24 HRS

Date Person Contacted Vehicle IN / OUT

Date / Time Action / Instruction

Vehicle No. 5JD5212H

Type

Make Honda Stream

Color White

Sp. No. 170357

Eng. No.

Chassis No. 5HMRN6840SS201748

Year of Manufacture 2008

Insured

Policy No.

Make of Motor

(Policy Conditions)

Remarks: The veh had commenced its repair at the time of inspection.

INS	OK
-----	----

Est. or Motor Value

How recent report Consistent? Yes or No

Est. or Motor Value Consistent? Yes or No

Est. or Motor Value days Rest Yes or No

Est. or Motor Value % 3rd Val. Yes or No

CA / TRV / REP / 24 HRS

Date Person Contacted Vehicle IN / OUT

Date / Time Action / Instruction

\$4000 - \$5000 6 days

Reference File Path

Reference File Path

Days of Repair: 6

Resurvey No. of Trip: 1

Add Fee:

Add Fee:

Add Fee:

Add Fee:

Survey Fee

Transportation

Food

Accommodation

Other

Total

PRS

150

150

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	13 May 2019		13 May 2019 10:10 Edit Adj Rpt				Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [\[Created by insurer\]](#)

Insured:				
Main Claimant:	A-STAR TESTING & INSPECTION (S) PTE. LTD., Co. Reg. No.: 200806168D			
Vehicle Reg. No.:	SJD5212H	Date of Loss:	23/02/2019 09:00 - :59	
Claim Type:	TP / SNM19D200946C02	Policy/Cover Note No.:	DMCVSN17085818022	
Vehicle Reg. No. (Insured):	XD7423L	Policy No. (Claimant):	5098644211	
		Excess:	S\$0.00	
Repairer:	Hup Hup Workshop Pte Ltd (HQ) 27-A Jurong Port Rd, #01-29, 619101 Boon Lay - Tel: 62651966			
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]			
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:			
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 23/05/2019]			

[View All](#) [Compose Case Mail](#)

ASSOCIATED MAIL RECEIVED

There are no mail for this case.

ALL ASSOCIATED TASKS
[View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Nivitha (LKK Auto)

From: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>
Sent: Friday, 15 March 2019 1:04 PM
To: Accident@kscgp.com
Cc: assignments
Subject: RE: 2nd Notice to conduct Pre-Repair Survey: Your ref: XD7423L Ourref: SJD5212H/HUP/ms/mt - SNM19D200946
Attachments: Template 2nd PRS (reject).pdf

WITHOUT PREJUDICE
SAVE AS TO COSTS

Dear Sir,

We refer to your email.

We regret to inform that we are not agreeable to your list of proposed surveyors and will be assigning our panel surveyor, M/s LKK Auto Consultants to conduct the Pre-repair survey.

Please contact our surveyor to conduct the post repair inspection before returning the repaired vehicle to the claimant.

Aside to LKK,

Please refer to the email below and liaise with third party workshop accordingly.

Thank you.

Regards,
Chong Boon Sen
Claims Executive
Claims

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower
Singapore 079909
Co. Reg. No. 200208384E
DID: 63896171
Fax: 62247175
Email: boonsen.chong@sg.cntaiping.com
Website: www.sg.cntaiping.com

Disclaimer :

This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

From: Accident@kscgp.com [mailto:Accident@kscgp.com]
Sent: Tuesday, 12 March, 2019 10:54 AM
To: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>
Subject: RE: 2nd Notice to conduct Pre-Repair Survey: Your ref: XD7423L Ourref: SJD5212H/HUP/ms/mt - SNM19D200946

Dear Sir/Mdm

We refer to your below email of even date.

Please see enclosed our 2nd Notice to conduct Pre-Repair Survey. Our client is not agreeable to appointing your proposed surveyor as a Single Joint Expert.

The workshop details are as follows :

Hup Hup Workshop Pte Ltd

27-A Jurong Port Road

#01-29

Contact Person : Ms Wong (tel: 6265 1966 / 6265 5270 / 6265 3407)

Singapore 619101

Thank you.

Regards,
May Teo
for and on behalf of Mr Gurdeep Singh Sekhon
KSCGP Juris LLP
10 Hoe Chiang Road
#13-03A Keppel Towers
Singapore 089315
Tel: 6538 3611 / DID: 3152 0989 / Fax: 6538 3708
Email: accident@kscgp.com

KSCGP Juris LLP (UEN/Registration No: T10LL1855L) is registered in Singapore under the Limited Liability Partnerships Act (Chapter 163A) with limited liability. This message is intended only for the use of the individual or entity to whom it is addressed (including any attachments) and is confidential and may be protected by legal privilege. If you are not the intended recipient, please notify the sender immediately by return email, delete this message and you should not disseminate, distribute or copy any information contained herein. Please note that e-mails are susceptible to change and we shall not be liable for the improper or incomplete transmission of the information contained in this communication nor for any delay in its receipt or damage to your system. We do not guarantee that the integrity of this communication has been maintained nor that this communication is free of viruses, interceptions or interference.

----- Original Message -----

From: Chong Boon Sen [<mailto:boonsen.chong@sg.cntaiping.com>]

To: Accident@kscgp.com

Sent: Tue, 12 Mar 2019 00:40:53 +0000

Subject:

WITHOUT PREJUDICE

Dear Sir,

We refer to your email below.

We intend to conduct a pre-repair survey of the damage to your client's vehicle jointly with your client/your motor workshop. We propose to use one of the following motor surveyors to conduct the joint pre-repair survey as a single joint expert.

ADRIAN LING
Kelvin Ang
SEE CHEW SENG

MOHD FADHILAH BIN OSMAN
XING QUO QIANG
KENNETH KONG
SIMON HO
CHUA WEIJIE
MARCUS CHUA
HENRY NG

Please let us know within two(2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.

You may select one of the listed motor surveyors and we will bear the cost of the pre-repair survey carried out by the single joint expert

Regards,
Chong Boon Sen
 Claims Executive
 Claims

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower
 Singapore 079909
 Co. Reg. No. 200208384E
 DID: 63896171
 Fax: 62247175
 Email: boonsen.chong@sg.cntaiping.com
 Website: www.sg.cntaiping.com

Disclaimer :

This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

From: Claims Dept of CTI
Sent: Monday, 11 March, 2019 7:06 PM
To: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>
Subject: FW: 1st Notice to conduct Pre-Repair Survey: Your ref: XD7423L Our ref: SJD5212H/HUP/ms/mt - SNM19D200946

From: Accident@kscgp.com [<mailto:Accident@kscgp.com>]
Sent: Monday, March 11, 2019 10:22 AM
To: Catherine Thia <catherine.thia@sg.cntaiping.com>; Claims Dept of CTI <claimsdept@sg.cntaiping.com>
Subject: 1st Notice to conduct Pre-Repair Survey: Your ref: XD7423L Our ref: SJD5212H/HUP/ms/mt

Dear Sirs,

We refer to the above matter.

Please find enclosed herein the 1st Notice to conduct Pre-Repair Survey, for your immediate attention and necessary action.

Thank you.

Regards,
May Teo
for and on behalf of Mr Gurdeep Singh Sekhon
KSCGP Juris LLP
10 Hoe Chiang Road
#13-03A Keppel Towers
Singapore 089315
Tel: 6538 3611 / DID: 3152 0989 / Fax: 6538 3708
Email: accident@kscgp.com

KSCGP Juris LLP (UEN/Registration No: T10LL1855L) is registered in Singapore under the Limited Liability Partnerships Act (Chapter 163A) with limited liability. This message is intended only for the use of the individual or entity to whom it is addressed (including any attachments) and is confidential and may be protected by legal privilege. If you are not the intended recipient, please notify the sender immediately by return email, delete this message and you should not disseminate, distribute or copy any information contained herein. Please note that e-mails are susceptible to change and we shall not be liable for the improper or incomplete transmission of the information contained in this communication nor for any delay in its receipt or damage to your system. We do not guarantee that the integrity of this communication has been maintained nor that this communication is free of viruses, interceptions or interference.

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	6168D
Vehicle Details	
Vehicle No.:	SJD5212H
Vehicle to be Exported:	No
Intended Deregistration Date:	01 Apr 2019
Vehicle Make:	HONDA
Vehicle Model:	STREAM 1.8L A
Primary Colour:	White
Manufacturing Year:	2007
Engine No.:	R18A12801745
Chassis No.:	JHMRN68408S201748
Maximum Power Output:	103.0 kW (138 bhp)
Open Market Value:	\$20,815.00
Original Registration Date:	26 Mar 2008
First Registration Date:	26 Mar 2008
Transfer Count:	3
Actual ARF Paid:	\$20,815.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	25 Mar 2023
COE Category:	B - Car (1601cc & above)
COE Period(Years):	5
PQP Paid:	\$22,499.00
COE Rebate Amount:	\$17,914.00
Total Rebate Amount:	\$17,914.00
Message	
Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 01 Apr 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	23/02/2019 15:17
Date Of Accident	23/02/2019 09:20
Exact Location Of Accident	JURONG PIER RD TWDS JURONG ISLAND B4 CHECKPOINT
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJD5212H
Insured/Policyholder	
Name Of Registered Owner	A-STAR TESTING & INSPECTION (S) PTE. LTD.
Co Reg No	200806168D
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-91835902

Vehicle Particulars

Manufacturer	HONDA
Model	STREAM
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5098644211
Cover Note Number	

Driver

Name of Driver	SUGUMARAN THIRUVENKADAM
Passport No/FIN	G7982691Q
Date Of Birth	15/02/1978
Occupation	OUTDOOR
Date Of Driving Pass	28/06/2017
Driving Experience	1 YEAR AND 7 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91835902
Fax Number	
Contact Number	
E-Mail Address	NOEMAIL

Address	BLK 333 BUKIT BATOK ST 32 #10-255
Postcode	650333
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - CHANGE/CROSS LANE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLS REFER TO THE ATTACHED STATEMENT.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	XD7423L
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	MIAH MOHAMMED RIPON
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Accident Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to rescind policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be used outside of Singapore, for one or more of the above Purposes
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any regulations, laws or court orders


Policyholder's Signature
Date & Time:

Driver's Signature
(if driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name
NRIC/FIN No:

Individual Statement

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 23/02/19 at 09:20 hrs, I was travelling in my vehicle (530 52124) along Jury Pier Road after the junction of Jury Pier Way before Jury Checkpoint on the second lane from the left within my lane. Suddenly, a tripper truck on my right, put into my path and collided onto the front right portion of my vehicle.

DECLARATION

I/We declare the foregoing particulars are true in every respect

[Signature]
Policyholder's Signature
Date & Time

[Signature]
Driver's Signature
(if driver is not the policyholder)
Date & Time

[Signature] 28/02/19
Reporting Officer's Signature
Name
NR/CI/PL/NO

...CLAIM SUBFOLDER...(Pending for Survey Report)









































CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	13 May 2019		13 May 2019 10:10 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	-, Co. Reg. No.: -								
Main Claimant:	A-STAR TESTING & INSPECTION (S) PTE. LTD., Co. Reg. No.: 200806168D								
Vehicle Reg. No.:	SJD5212H	Date of Loss:	23/02/2019 09:00 - :59 [130 Months and 28 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / SNM19D200946C02	Policy/Cover Note No.:	DMCVSN17085818022						
Vehicle Reg. No. (Insured):	XD7423L	Policy No. (Claimant):	5098644211						
		Excess:	S\$0.00						
Repairer:	Hup Hup Workshop Pte Ltd (HQ) 27-A Jurong Port Rd, #01-29, 619101 Boon Lay - Tel: 62651966								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]								
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 23/05/2019]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SJD5212H (SNM19D200946C02)
[XD7423L]
TP
A-STAR TESTING & INSPECTION (S) PTE. LTD.
Feb 23 2019 9:00AM
[-]
Hup Hup Workshop Pte Ltd












Upload Documents			Upload Photos			Compose New Letter			View			View in Browser		
Assessment Reports									1 per page			<input checked="" type="checkbox"/>		
No	Finalized On	National Assessment Centre Services (Ubi)								Thumbnail	Print			
1	23/02/19 15:39	Accident Statement								Load HTM				
Photos/Images									3 per page			<input checked="" type="checkbox"/>		
No	Finalized On	National Assessment Centre Services (Ubi)								Thumbnail	Print			
1	23/02/19 15:34	Accident Photo [Linked Accident Report Documents]								Load JPG		<input checked="" type="checkbox"/>		
2	23/02/19 15:34	Accident Photo [Linked Accident Report Documents]								Load JPG		<input checked="" type="checkbox"/>		
3	23/02/19 15:34	Accident Photo [Linked Accident Report Documents]								Load JPG		<input checked="" type="checkbox"/>		
4	23/02/19 15:34	Accident Photo [Linked Accident Report Documents]								Load JPG		<input checked="" type="checkbox"/>		
5	23/02/19 15:34	Accident Photo [Linked Accident Report Documents]								Load JPG		<input checked="" type="checkbox"/>		
6	23/02/19 15:34	Accident Photo [Linked Accident Report Documents]								Load JPG		<input checked="" type="checkbox"/>		
7	23/02/19 15:34	Accident Photo [Linked Accident Report Documents]								Load JPG		<input checked="" type="checkbox"/>		
8	23/02/19 15:34	Accident Photo [Linked Accident Report Documents]								Load JPG		<input checked="" type="checkbox"/>		
9	23/02/19 15:34	Accident Photo [Linked Accident Report Documents]								Load JPG		<input checked="" type="checkbox"/>		
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)								Thumbnail	Print			
1	16/05/19 16:42	General View								Load JPG		<input checked="" type="checkbox"/>		
2	16/05/19 16:42	General View								Load JPG		<input checked="" type="checkbox"/>		
3	16/05/19 16:42	General View								Load JPG		<input checked="" type="checkbox"/>		
4	16/05/19 16:42	General View								Load JPG		<input checked="" type="checkbox"/>		
5	16/05/19 16:42	General View								Load JPG		<input checked="" type="checkbox"/>		
6	16/05/19 16:42	General View								Load JPG		<input checked="" type="checkbox"/>		
7	16/05/19 16:42	General View								Load JPG		<input checked="" type="checkbox"/>		
8	16/05/19 16:42	General View								Load JPG		<input checked="" type="checkbox"/>		
9	16/05/19 16:42	General View								Load JPG		<input checked="" type="checkbox"/>		
10	16/05/19 16:42	General View								Load JPG		<input checked="" type="checkbox"/>		
11	16/05/19 16:42	General View								Load JPG		<input checked="" type="checkbox"/>		
12	16/05/19 16:42	General View								Load JPG		<input checked="" type="checkbox"/>		
13	16/05/19 16:42	General View								Load JPG		<input checked="" type="checkbox"/>		
14	16/05/19 16:42	General View								Load JPG		<input checked="" type="checkbox"/>		
15	16/05/19 16:42	General View								Load JPG		<input checked="" type="checkbox"/>		
16	16/05/19 16:42	General View								Load JPG		<input checked="" type="checkbox"/>		
17	16/05/19 16:42	General View								Load JPG		<input checked="" type="checkbox"/>		
18	16/05/19 16:42	General View								Load JPG		<input checked="" type="checkbox"/>		
19	16/05/19 16:42	General View								Load JPG		<input checked="" type="checkbox"/>		
20	16/05/19 16:42	General View								Load JPG		<input checked="" type="checkbox"/>		
21	16/05/19 16:42	General View								Load JPG		<input checked="" type="checkbox"/>		

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	National Assessment Centre Services (Ubi)	Thumbnail	Print
22	16/05/19 16:42	General View	 Load JPG	<input checked="" type="checkbox"/>
23	16/05/19 16:43	General View	 Load JPG	<input checked="" type="checkbox"/>
24	16/05/19 16:43	General View	 Load JPG	<input checked="" type="checkbox"/>
25	16/05/19 16:43	General View	 Load JPG	<input checked="" type="checkbox"/>
26	16/05/19 16:43	General View	 Load JPG	<input checked="" type="checkbox"/>
27	16/05/19 16:43	General View	 Load JPG	<input checked="" type="checkbox"/>
28	16/05/19 16:43	General View	 Load JPG	<input checked="" type="checkbox"/>
29	16/05/19 16:59	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
30	16/05/19 16:59	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
31	16/05/19 16:59	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
32	16/05/19 16:59	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
33	16/05/19 16:59	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
34	16/05/19 16:59	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
35	16/05/19 16:59	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
36	16/05/19 16:59	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
37	16/05/19 16:59	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
38	16/05/19 16:59	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
39	16/05/19 16:59	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
40	16/05/19 16:59	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
41	16/05/19 16:59	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
42	16/05/19 16:59	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
43	16/05/19 16:59	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
44	16/05/19 16:59	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
45	16/05/19 16:59	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
46	16/05/19 16:59	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
47	16/05/19 16:59	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
48	16/05/19 16:59	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
49	16/05/19 16:59	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
50	16/05/19 16:59	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
51	16/05/19 16:59	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
52	16/05/19 16:59	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
53	16/05/19 16:59	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
54	16/05/19 16:59	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
55	16/05/19 16:59	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
56	16/05/19 16:59	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
57	16/05/19 16:59	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
58	16/05/19 16:59	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	13/05/19 10:12	PRI CONTACT	 Load PDF	
No	Finalized On	National Assessment Centre Services (Ubi)	Thumbnail	Print
1	23/02/19 15:35	Accident Sketch Plan [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
2	23/02/19 15:35	Individual Statement [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>

Linked Accident Report Documents

View

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	National Assessment Centre Services (Ubi)	Thumbnail	Print

Assessment Reports				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	National Assessment Centre Services (Ubi)		Thumbnail	Print
1	23/02/19 15:39	Accident Statement		Load HTM	
Photos/Images				3 per page	<input checked="" type="checkbox"/>
No	Finalized On	National Assessment Centre Services (Ubi)		Thumbnail	Print
1	23/02/19 15:34	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
2	23/02/19 15:34	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
3	23/02/19 15:34	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
4	23/02/19 15:34	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
5	23/02/19 15:34	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
6	23/02/19 15:34	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
7	23/02/19 15:34	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
8	23/02/19 15:34	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
9	23/02/19 15:34	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
Documentation				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	National Assessment Centre Services (Ubi)		Thumbnail	Print
1	23/02/19 15:35	Accident Sketch Plan		Load JPG	<input checked="" type="checkbox"/>
2	23/02/19 15:35	Individual Statement		Load JPG	<input checked="" type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/CTI19004728/T1CD3E2

Date: 24/05/2019

REFERENCE

Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMCVSN17085818022

Claimant Vehicle
No: SJD5212HInsured Vehicle
No: XD7423L

Date of Loss: 23/02/2019

Nature of Claim: TP

Claim
No: SNM19D200946C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SJD5212H

Make & Model: HONDA STREAM, 1.8 L (A)

Engine No: R18A12801745

Reg. Date: 26/03/2008 (Man. Year: 2007)

Chassis No: JHMRN68408S201748

Colour: White

Odometer: 170357 km

Engine Capacity: 1799 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/65 R15

Rear Tyre Size: 205/65 R15

Front Left Side: Continental 6 mm

Rear Left Side: Continental 6 mm

Front Right Side: Continental 6 mm

Rear Right Side: Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 13/05/2019

Date Inspected: 15/03/2019 Inspected At:

Hup Hup Workshop Pte Ltd (HQ)
27-A Jurong Port Rd, #01-29
Singapore 619101

Estimated Period of Repair: 6.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$4,000.00 - \$5,000.00

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 24 May 2019)

Parts: M1-MPV HONDA STREAM 1.8 L (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SJD5212H)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >