

ASS. REC. BY.

REF: CS3/smo/9004846/Gcd302

Special Instructions

Surveyor

62

ASSIGNMENT (Office)

From (Person):

Gnoli Pau Loong

kdl

Sompo (sno)

Date/Time: 15.3.2019 17:58

Estimated Cost:

Table 10.

OD / (TP) WS / TP RES / OD RES / EVA / INV / MV / CS

To inspect Vehicle No:

SJW 7530B

Insured:

PA FL70A

at Workshop m/s A- Tec Automotive Pte Ltd

Tel: 90 626929 / 7103383

of 8 kaki Bukit Aram 4# 05-27 Premix ✓

Policy No: D18m7SCBU000295

Claim No: CMTD1901377

Sum insured:

Excess

Make of Veh:

D.O.A. 143.2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

 r_{wp}''

H.O.D. Endorsement:

Date/Time: 18.3.19 10.02 a.m

Person Contacted:

James

Vehicle (IN)OUT

Date/Time	Action/Instruction (X) Estimate
	SJW 7530B-X
	PA 7670 A-X
	After repair: 26/3/2019.

PRS
000

REF:

500

20513

ASSIGNMENT

(-2020)

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

STW 7530B

at Workshop m/s

A-Tea Automotive

of

8 Kato Bulat Ave 4 #05-27

Insured:

dt-20

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

<input checked="" type="checkbox"/>	<input type="checkbox"/>
N/S	O/S
<input type="checkbox"/>	<input type="checkbox"/>

Bal. or Market Value:

\$20K

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

5

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

PRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

STW 7530B

Yr Regn:

15 Apr 2016

Type: M.Cat / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toyota Altis

C.C

1598

Colour:

Silver

A/C: Insured / Std / NI / NA

Sp. Reading

114402

T/Radio: Insured / Std / NI / NA

Eng/No:

MR0532EE 106169989

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD / R/Rim or

Tyre Size:

F:

195/65 R15

R:

11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

5

mm

R/Bal.

5

mm

L/Bal.

5

mm

L/Bal.

5

mm

D.O.A.

D.O.I.

18-03-19

Survey held at

W/S

Ph: 4090

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S RA

The U/C Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

\$3000 - \$4000

RECEIVED 29 MAR 2019

Date/Time. File Pass to?

☐

: Preli. Report

☐

: Final Report

1)

Date/Time. File Return to?

2)

Days Of Repair:

5

Resurvey No. of Trip:

1

Survey Fee:

100

Transportation:

60

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

) S + RS. SI

) Photos

) Others

10

TOTAL

170

Report Format:

PRS

Lump Sum / I.B.I: (\$

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	15 Mar 2019		15 Mar 2019 17:58 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	BEDOK TRANSPORT PTE LTD, Co. Reg. No.: 200311654W			
Main Claimant:	LEONG JIARONG, KEVIN LIANG JIARONG			
Vehicle Reg. No.:	SJW7530B	Date of Loss:	14/03/2019 00:00 - :59	
Claim Type:	TP / CMTD1901377	Policy/Cover Note No.:	D18MTSCBU000295 (Comprehensive)	
Vehicle Reg. No. (Insured):	PA7670A	Policy No. (Claimant):		
		Excess:		
Repairer:	A-Tec Automotive Pte Ltd (Kaki Bukit) 8 Kaki Bukit Avenue 4 # 05-27 Premier, 415875 Kaki Bukit - Tel: (1) 90626929 , (2) 97103383			
Handling Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by GNOH PAU LOONG - 63295217]			
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 26/03/2019]			
Adj Asg. Remarks:	WS: #04-20 PREMIER / PEGGIE 63845206 -PLEASE BE INFORMED THAT OUR INSURED HAS NOT REPORTED THE ACCIDENT -NO TP SAS SUBMITTED			

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

T.m: 10.02
 in: in
 P: Jaws.
 co X

XGD

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	2051B
Vehicle Details	
Vehicle No.:	SJW7530B
Vehicle to be Exported:	No
Intended Deregistration Date:	18 Mar 2019
Vehicle Make:	TOYOTA
Vehicle Model:	COROLLA ALTIS 1.6 AUTO
Primary Colour:	Silver
Manufacturing Year:	2010
Engine No.:	3ZZ4983694
Chassis No.:	MR053ZEE106169989
Maximum Power Output:	80.0 kW (107 bhp)
Open Market Value:	\$16,716.00
Original Registration Date:	15 Apr 2010
First Registration Date:	15 Apr 2010
Transfer Count:	1
Actual ARF Paid:	\$16,716.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	14 Apr 2020
PARF Rebate Amount:	\$9,193.00
Intended COE Rebate Details	
COE Expiry Date:	14 Apr 2020
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$34,001.00
COE Rebate Amount:	\$3,651.00
Total Rebate Amount:	\$12,844.00

The information contained herein is correct as at 18 Mar 2019

OK

Altis Used Vehicle List (3 vehicles)

Car Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Company	Availability
Toyota Corolla Altis 1.6A	\$21,800	\$13,940 /yr	19-Feb-2010	1,598 cc	120,000 km		Available

Excellent And Original Condition, Low Mileage Done, Well Maintained Interior And Exterior, Call Now For Viewing. Price Stated Above Excluding Road Tax.

Office No. --

Aaron - 81812085

Toyota Corolla Altis 1.6A	\$20,800	\$10,840 /yr	11-May-2010	1,598 cc	-	Car Empire Automobiles Pte Ltd	Available
----------------------------------	-----------------	--------------	-------------	----------	---	--------------------------------	------------------

One Owner Only. Practical And Good Fuel Efficiency Ideal For Daily Drives. High Loan And Trade In Available! Car In Good Condition, View To Believe! Guarantee Buyback At \$10,500.

Office No. - 69097310

Lucas - 87506761 | Sean - 90120468 | Samuel - 97222822 | Soon - 97379527

Toyota Corolla Altis 1.6A	\$22,988	\$12,710 /yr	12-May-2010	1,598 cc	142,000 km	Car Buddy Pte Ltd	Available
----------------------------------	-----------------	--------------	-------------	----------	------------	-------------------	------------------

Well Maintained With Zero Mishap. Great Fuel Consumption, Easy Maintenance & Most Importantly Reliable. Most Popular Family Sedan. Call Our Sales Person Now To Arrange For An Appointment For Viewing. ...

Office No. --

Kelvin - 84488668 | Eric - 98358585

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, even for COE cars, OPC cars, vans, trucks, hybrid cars, sports cars or stationwagons. You can also buy from a car auction, look up car loans, financial services, low mileage cars, car brands, carpark rates & car insurance. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions, and also motoring advice, car reviews & car news on the latest models. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

© 2004-2019 sgCarMart. All rights reserved.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	15/03/2019 16:52
Date Of Accident	14/03/2019 13:15
Exact Location Of Accident	HEMSLEY AVENUE
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SJW7530B
Insured/Policyholder	
Name Of Registered Owner	LEONG JIARONG KEVIN
NRIC No	S8622051B
Email Address	LEONG_KEVIN@HOTMAIL.COM
Mobile Phone No	(LOCAL) +65-91546685
Alternative Phone No	OTHERS-91546685
Vehicle Particulars	
Manufacturer	TOYOTA
Model	COROLLA ALTIS 1.6 AUTO
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	AVIVA LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	10850609
Cover Note Number	
Driver	
Name of Driver	LEONG JIARONG KEVIN
NRIC No	S8622051B
Date Of Birth	18/08/1986
Occupation	OUTDOOR
Date Of Driving Pass	18/06/2015
Driving Experience	3 YEARS AND 8 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91546685
Fax Number	
Contact Number	OTHERS-91546685
EMail Address	LEONG_KEVIN@HOTMAIL.COM

Address NA
 Postcode
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured OWNER
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident HIT AND RUN / VANDALISM / DAMAGED WHILST PARKED
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles (including own vehicle) involved in the accident 2
 Was any body injured in the Accident? NO
 Was any injured conveyed to hospital by ambulance? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? YES
 If Yes, Please state which Police Station
 POLICE STATION NAME [OTHER] TRAFFIC POLICE DIVISION HQ
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

REFER TO POLICE REPORT NO: T/20190315/2065 LODGED AT TRAFFIC POLICE-UBI. On the above mentioned date and location, I parked my car (SJW7530B) at the roadside in front of my apartment, I was away and reached back to the location where I parked my vehicle about 20 mins. Later I realised that my car was damaged. There was a note left behind on my car's windscreen. The note was from a witness who saw the accident. The witness stated that a bus (PA7670A) knocked into my car when reversing. The driver of the mentioned bus reversed in a "NO ENTRY" road and the driver went against the flow of traffic. There is not much information on the note, that is all.

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? NO
 Was there any audio recorded? NO

Details of Witness 1

Name UNKNOWN
 Phone Number
 Email Address

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number PA7670A
 Vehicle Make/Model/Colour YUTONG / ZK6100H
 Details Of Properties NA
 Vehicle Category BUS
 Name of Driver NA
 NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GI Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available application by interested parties.
7. By the lodgement of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)
 - (i) I understand, acknowledge, agree and consent that:
 - (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes").
 - (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
 - (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

VERIFIED BY AJAX MARS
REPORTING OFFICER


Mohamed Salfullah S/O Syed
Masood

Witnessed by Reporting Centre
Personnel

Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Sketch Plan



POLICE REPORT



**SINGAPORE
POLICE FORCE**



T/20190315/2065

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

1 of 3

Report No. T/20190315/2065

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 15/03/2019 12:57	Vide Report No.:	Station Diary No.:
--	------------------	--------------------

Informant's Particulars

Name of Informant: LEONG JIARONG, KEVIN LIANG JIARONG		Address: APT BLK 1 HEMSLEY AVENUE SERANGOON GARDEN ESTATE SINGAPORE 557668	
ID Type / ID No.: NRIC NO / S8622051B		Contact No.: Home/Office: Mobile: 91546685	
Nationality: SINGAPORE CITIZEN		Email:	
Sex: Male	Age: 32	Date of Birth: 18/09/1986	Type of Informant: Driver
Race: Chinese		Language:	Institution / School Name:
Occupation: OTHERS		Driving Licence Information: Class: 3A Date of Expiry:	

General Information of the Accident

Type of Accident:	Non-Injury Hit and Run	Drink Drive: No	Date/Time of Accident: 14/03/2019 13:15	Type of Location: Straight Road
Location: Along Road 1 HEMSLEY AVENUE SERANGOON GARDEN ESTATE				
Weather:	Road Surface:	Road Speed Limit:		
Traffic Flow:	Traffic Control: Not Controlled	Traffic Volume:		
Type of Collision:	Anyone conveyed by ambulance: No			

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
PA7670A	Bus/Coach/Minibus					0
SJW7530B	Car	TOYOTA	COROLLA ALTIS 1.6 AUTO	Silver	Slightly Damaged	0

Details of Vehicle Insurance

Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
-------------	-------------------	--------------	-----------	-------------

POLICE REPORT



**SINGAPORE
POLICE FORCE**



T/20190315/2065

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

Report No. T/20190315/2065

CONTINUATION OF REPORT

Details of Vehicle Insurance				
Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
SJW7530B	AVIVA LTD	10850809	07/07/2018	14/10/2019

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Driver			
Name	LEONG JIARONG, KEVIN LIANG JIARONG	ID No.	S8622051B
Related Vehicle	NIL	Contact No.	91546685
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 3A Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

ON THE ABOVE MENTIONED DATE & LOCATION,

I PARKED MY CAR (SJW7530B) AT THE ROADSIDE INFRONT OF MY APARTMENT. I WAS AWAY AND REACHED BACK TO THE LOCATION WHERE I PARKED MY VEHICLE ABOUT 20 MINS LATER. I REALISED THAT MY CAR WAS DAMAGED. THERE WAS A NOTE LEFT BEHIND ON MY CAR'S WINDSCREEN.

THE NOTE WAS FROM A WITNESS WHO SAW THE ACCIDENT.
THE WITNESS STATED THAT A BUS (PA7670A) KNOCKED INTO MY CAR WHEN REVERSING..

THE DRIVER OF THE MENTIONED BUS REVERSED IN A "NO ENTRY" ROAD AND THE DRIVER WENT AGAINST THE FLOW OF TRAFFIC.

THERE ISNT MUCH INFORMATION OMN THE NOTE.

THATS ALL

POLICE REPORT



SINGAPORE
POLICE FORCE



T/20190315/2065

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

3 of 3

Report No. T/20190315/2065

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:
TP /
YOGENDRAN S/O RAJASAKARAN

Signature Of Informant:

Signature Of Interpreter:
Not applicable

Date/Time:
15/03/2019 12:57

Officer In Charge Of Case:
TP / HRT /
SI KALESWARI PALANI
Contact No.: 65476902

Classification Of Case:




SINGAPORE
POLICE FORCE

Authentication Stamp
NP168

Signature

Accident Photo



Accident Photo



Accident Photo



...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	15 Mar 2019		15 Mar 2019 17:58 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main		Reference	Claim Details	Documents	Show All
-------------	--	------------------	----------------------	------------------	-----------------

CLAIM SUBFOLDER DETAILS				[Created by insurer]	
Insured:	BEDOK TRANSPORT PTE LTD, Co. Reg. No.: 200311654W				
Main Claimant:	LEONG JIARONG, KEVIN LIANG JIARONG				
Vehicle Reg. No.:	SJW7530B	Date of Loss:	14/03/2019 00:00 - :59 [106 Months and 27 Days From LTA Reg Date (Man Yr)]		
Claim Type:	TP / CMTD1901377	Policy/Cover Note No.:	D18MTSCBU000295 (Comprehensive)		
Vehicle Reg. No. (Insured):	PA7670A	Policy No. (Claimant):			
		Excess:			
Repairer:	A-Tec Automotive Pte Ltd (Kaki Bukit) 8 Kaki Bukit Avenue 4 # 05-27 Premier, 415875 Kaki Bukit - Tel: (1) 90626929 , (2) 97103383				
Handling Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by GNOH PAU LOONG - 63295217]				
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 26/03/2019]				
Adj Asg. Remarks:	WS: #04-20 PREMIER / PEGGIE 63845206 -PLEASE BE INFORMED THAT OUR INSURED HAS NOT REPORTED THE ACCIDENT -NO TP SAS SUBMITTED				

ASSOCIATED MAIL RECEIVED		View All	Compose Case Mail
There are no mail for this case.			

ALL ASSOCIATED TASKS										View All	Search Tasks	Create New Task	Complete
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?				
No results.													

Claim Documents

*SJW7530B (CMTD1901377)
[PA7670A]




































TP

LEONG JIARONG, KEVIN LIANG JIARONG

Mar 14 2019 12:00AM

[BEDOK TRANSPORT PTE LTD]

A-Tec Automotive Pte Ltd

Upload Documents			Upload Photos		Compose New Letter		View		View in Browser	
Photos/Images							3 per page		<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print	
1	25/03/19 15:26	General View						Load JPG	<input checked="" type="checkbox"/>	
2	25/03/19 15:26	General View						Load JPG	<input checked="" type="checkbox"/>	
3	25/03/19 15:26	General View						Load JPG	<input checked="" type="checkbox"/>	
4	25/03/19 15:26	General View						Load JPG	<input checked="" type="checkbox"/>	
5	25/03/19 15:26	General View						Load JPG	<input checked="" type="checkbox"/>	
6	25/03/19 15:26	General View						Load JPG	<input checked="" type="checkbox"/>	
7	25/03/19 15:26	General View						Load JPG	<input checked="" type="checkbox"/>	
8	25/03/19 15:26	General View						Load JPG	<input checked="" type="checkbox"/>	
9	25/03/19 15:26	General View						Load JPG	<input checked="" type="checkbox"/>	
10	25/03/19 15:26	General View						Load JPG	<input checked="" type="checkbox"/>	
11	25/03/19 15:26	General View						Load JPG	<input checked="" type="checkbox"/>	
12	25/03/19 15:26	General View						Load JPG	<input checked="" type="checkbox"/>	
13	25/03/19 15:26	General View						Load JPG	<input checked="" type="checkbox"/>	
14	25/03/19 15:26	General View						Load JPG	<input checked="" type="checkbox"/>	
15	25/03/19 15:26	General View						Load JPG	<input checked="" type="checkbox"/>	
16	25/03/19 15:26	General View						Load JPG	<input checked="" type="checkbox"/>	
17	25/03/19 15:26	General View						Load JPG	<input checked="" type="checkbox"/>	
18	25/03/19 15:26	General View						Load JPG	<input checked="" type="checkbox"/>	
19	25/03/19 15:26	General View						Load JPG	<input checked="" type="checkbox"/>	
20	25/03/19 15:26	General View						Load JPG	<input checked="" type="checkbox"/>	
21	25/03/19 15:26	General View						Load JPG	<input checked="" type="checkbox"/>	
22	25/03/19 15:26	General View						Load JPG	<input checked="" type="checkbox"/>	
23	25/03/19 15:26	General View						Load JPG	<input checked="" type="checkbox"/>	
24	25/03/19 15:26	General View						Load JPG	<input checked="" type="checkbox"/>	
25	25/03/19 15:26	General View						Load JPG	<input checked="" type="checkbox"/>	
26	25/03/19 15:26	General View						Load JPG	<input checked="" type="checkbox"/>	
27	29/03/19 13:45	Photo After Spray						Load JPG	<input checked="" type="checkbox"/>	
28	29/03/19 13:45	Photo After Spray						Load JPG	<input checked="" type="checkbox"/>	
29	29/03/19 13:45	Photo After Spray						Load JPG	<input checked="" type="checkbox"/>	
30	29/03/19 13:45	Photo After Spray						Load JPG	<input checked="" type="checkbox"/>	
31	29/03/19 13:45	Photo After Spray						Load JPG	<input checked="" type="checkbox"/>	
32	29/03/19 13:45	Photo After Spray						Load JPG	<input checked="" type="checkbox"/>	
33	29/03/19 13:45	Photo After Spray						Load JPG	<input checked="" type="checkbox"/>	
34	29/03/19 13:45	Photo After Spray						Load JPG	<input checked="" type="checkbox"/>	
35	29/03/19 13:45	Photo After Spray						Load JPG	<input checked="" type="checkbox"/>	
36	29/03/19 13:45	Photo After Spray						Load JPG	<input checked="" type="checkbox"/>	
37	29/03/19 13:45	Photo After Spray						Load JPG	<input checked="" type="checkbox"/>	

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	29/03/19 13:45	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
39	29/03/19 13:45	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
40	29/03/19 13:45	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Sompo Insurance Singapore Pte. Ltd. (HQ)	Thumbnail	Print
1	15/03/19 17:22	Pre-Repair Survey	 Load PDF	
2	15/03/19 17:56	Pre-Repair Survey - ASSIGN LKK	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/SMO19004846/GCD3E2

Date: 04/04/2019

REFERENCE

Handling Insurer:	Sompo Insurance Singapore Pte. Ltd.	Policy No:	D18MTSCBU000295
Claimant Vehicle No :	SJW7530B	Insured Vehicle No :	PA7670A
Date of Loss:	14/03/2019	Nature of Claim:	TP
		Claim No:	CMTD1901377

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJW7530B	Engine No:	3ZZ4983694
Make & Model:	TOYOTA COROLLA ALTIS, 1.6 (A)	Chassis No:	MR053ZEE106169989
Reg. Date:	15/04/2010 (Man. Year: 2010)	Odometer:	114402 km
Colour:	Silver		
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Yokohama 5 mm	Rear Left Side:	Yokohama 5 mm
Front Right Side:	Yokohama 5 mm	Rear Right Side:	Yokohama 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:	15/03/2019	
Date Inspected:	18/03/2019	Inspected At: A-Tec Automotive Pte Ltd (Kaki Bukit) 8 Kaki Bukit Avenue 4 # 05-27 Premier Singapore 415875
Estimated Period of Repair:	5.0 days	

Adjuster: XING GUO QIANG

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,000.00 - \$4,000.00

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 04 Apr 2019)
Parts:	143	TOYOTA COROLLA ALTIS 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJW7530B)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >