



REF: MSG

**ASSIGNMENT**

From: \_\_\_\_\_ Date: 18/3/19  
 Estimated Cost: \_\_\_\_\_  
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV  
 To Inspect Vehicle No: SMA 7057 G  
 at Workshop m/s Xin Yun Auto  
 of 8 Caki Bukit Ave 4 #05-23  
 Insured: \_\_\_\_\_  
 Policy No. \_\_\_\_\_  
 Claims No. \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_  
 (Policy Condition)  
 Remark: **The veh had commenced its repair at the time of inspection.**  
 Bal. or Market Value: \_\_\_\_\_  
 IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No  
 GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No  
 Est. Repairs: 4 days Res.: Yes or No  
 Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No  
 CA / REV / REP. / 24 HRS  
 Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_  
 Vehicle: IN / OUT

Veh No: SMA 7057G Yr Regn: 18/6/2018  
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
 Truck / Trailer or  
 Make: HONDA VEZEL C.C 1496  
 Colour: WHITE A/C: Insured / Std / NI / NA  
 Sp. Reading: 014517 T/Radio: Insured / Std / NI / NA  
 Eng/No: L15B5552117  
 C/No: RU11302110  
 Gen. Cond: Good / Fair / Poor / Burnt  
 Steering: Inorder / Jammed / Leaked / Burnt or  
 Brake: Inorder / Jammed / Leaked / Burnt or  
 Modi: Nil / S/Rim / STD A/Rim or  
 Tyre Size: F: 215/60/16  
 R: 215/60/16  
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
 TOYO / YOKO or  
 Front 6 mm R/Bal. 6 mm  
 L/Bal. 6 mm Rear 6 mm  
 D.O.A. 13/3/19 D.O.I. 18/3/19  
 Survey held at Xin Yun Auto  
 Des. of Damages: FR / Rear / O/S / N/S / U/C / Rooftop or  
 The U/C / Chassis frame / Body Structure affected due to collision.

N/S	O/S

Date / Time	Action / Instruction
	Range 3,000/2 - 4,000/2
	M.V. 84,000/2
	P.V. 43,606/2
	IN V 4039A/2

*[Signature]*  
 2/24/2019

TORUM WA  
 25/3/19

Date/Time, File Pass to?  : Preli. Report  
 : Final Report  
 1) \_\_\_\_\_  
 Date/Time, File Return to?  
 2) \_\_\_\_\_

Days Of Repair: 4  
 Resurvey No. of Trip: -  
 Survey Fee: 120  
 Transportation: \_\_\_\_\_  
 Add Fee:  : Site Insp (\$ )  
 : Interview (\$ )  
 : Tech. Invs (\$ )  
 : Weekend (\$ )  
 Photos \_\_\_\_\_  
 Others \_\_\_\_\_  
 TOTAL 130

Report Format: PRE  
 Lump Sum / I.B.I: (\$ )

## ...CLAIM SUBFOLDER...(New Assignment)

### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	(Not Notified)		18 Mar 2019 09:13 <a href="#">Assign</a>				<b>New Assignment</b> <a href="#">Cancel Case</a>

<a href="#">Main</a>	<a href="#">Reference</a>	<a href="#">Claim Details</a>	<a href="#">Documents</a>	<a href="#">Show All</a>
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

### CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	Ong Buck Cheng, ID: S0377012E		
Main Claimant:	NEO CHI KIAH, ID: S1480509E		
Vehicle Reg. No.:	SMA7057G	Date of Loss:	13/03/2019 00:00 - :59 [8 Months and 23 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP	Policy/Cover Note No.:	28821881QMX (TP, Fire & Theft) Coverage: 22/09/2016 - 22/09/2019
Vehicle Reg. No. (Insured):	SGL6128E	Policy No. (Claimant):	
		Excess:	
Repairer:	Xin Yun Auto Private Limited (HQ) 1 Kaki Bukit Avenue 6, #01-59 Autobay @ Kaki Bukit, 417883 Kaki Bukit - Tel: 8226 5945 / 9136 8884		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Monica Chung Pei Zhen - 6594 2552]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 19/03/2019]		
Adj Asg. Remarks:	on WP, LIAB 100% SJE DISAGREE APPOINT LKK. Arrange @ Block 8 Kaki Bukit Avenue 4 #05-23 Premier @ Kaki Bukit Singapore 415875 and contact 9839 1555 (Yi Xin).		

### ASSOCIATED MAIL RECEIVED

[View All](#) [Compose Case Mail](#)

There are no mail for this case.

### ALL ASSOCIATED TASKS

[View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Time: 10.03 a.m

In: ✓

Person: Ah Hua

ex: X

XGA

> Back to OneMotoring

### Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	0509E
Vehicle Details	
Vehicle No.:	SMA7057G
Vehicle to be Exported:	No
Intended Deregistration Date:	25 Mar 2019
Vehicle Make:	HONDA
Vehicle Model:	VEZEL 1.5X CVT
Primary Colour:	White
Manufacturing Year:	2018
Engine No.:	L15B5552117
Chassis No.:	RU11302110
Maximum Power Output:	96.0 kW (128 bhp)
Open Market Value:	\$22,367.00
Original Registration Date:	18 Jun 2018
First Registration Date:	18 Jun 2018
Transfer Count:	0
Actual ARF Paid:	\$13,314.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	17 Jun 2028
PARF Rebate Amount:	\$9,985.00
Intended COE Rebate Details	
COE Expiry Date:	17 Jun 2028
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$36,426.00
COE Rebate Amount:	\$33,621.00
<b>Total Rebate Amount:</b>	<b>\$43,606.00</b>

The information contained herein is correct as at 25 Mar 2019

OK

avg dep. 8,500/yr

MV 83K - 84,000/2  
 PV 43606/2  
 NV 40394/2



**Honda Vezel 1.5A X Honda Sensing**      **\$86,500**      **\$8,700 /yr**      **14-Jun-2018**      **1,496 cc**      **650 km**      **SUV**      **Available**

Condition Like New, 3 Years Hitachi Warranty.

Posted: 18-Mar-2019    Tags: 2018 Honda Vezel, 2018 honda vezel, Honda Vezel, honda vezel, Honda, Vezel, vezel, Used Honda



**Honda Vezel 1.5A X**      **\$85,988**      **\$8,630 /yr**      **23-Jun-2018**      **1,496 cc**      **70 km**      **SUV**      **Available**

3 Years Warranty Provided. Loan/High Loan Available, Flawless And Pristine Condition, Perfect Paintwork, View To Believe. Hurry Up, Arrange An Appointment With Us Now.

Posted: 24-Feb-2019    Tags: 2018 Honda Vezel, 2018 honda vezel, Honda Vezel, honda vezel, Honda, Vezel, vezel, Used Honda



**Honda Vezel Hybrid 1.5A RS Honda Sensing (OPC)**      **\$86,000**      **\$8,020 /yr**      **25-Jun-2018**      **1,496 cc**      **42 km**      **SUV**      **Available**

**Fuel Type:** Petrol-Electric

Super High PARF Of \$11,755. Comes With Honda Sensing. Original Condition From Day 1. Almost New Unit That Has Been Unused. Genuine Mileage Of 42km Only. Comes With Beautiful Nice 3 Digits Number. Vehi...

**DIRECT OWNER**

Posted: 12-Mar-2019    Tags: 2018 Honda Vezel, 2018 honda vezel, Honda Vezel, honda vezel, Honda, Vezel, vezel, Used Honda



### Sell your Car for \$3,000 More

With over 15K cars sold via Auction and a 500+ Dealer Network, cars on sgCarMart Quotz typically receive up to \$3,000 above market value. Quotz Guarantees the Highest Selling Price in Singapore - if we fail, you get \$100 cash from us. Get your Car Listed Today.

Find out more!



**Honda Vezel 1.5A X**      **\$75,888**      **\$7,500 /yr**      **26-Jun-2018**      **1,496 cc**      **-**      **SUV**      **Available**

3 Years Or 100k Km Warranty, High Trade In. In-house Loan Available.

Prime Motor & Leasing

Posted: 24-Mar-2019    Tags: 2018 Honda Vezel, 2018 honda vezel, Honda Vezel, honda vezel, Honda, Vezel, vezel, Used Honda



**Honda Vezel Hybrid 1.5A**      **\$91,800**      **\$9,060 /yr**      **27-Jun-2018**      **1,496 cc**      **5,000 km**      **SUV**      **Available**

**Fuel Type:** Petrol-Electric

Almost New 2018 New Facelifted Honda Vezel Hybrid. Best Fuel Consumption SUV In Town. 10 Years Repayment, In House Loan Or Balloon Scheme Available. Make And Assemble In Japan. 3 Years/100000km Warran...

**PREMIUM AD**

Trust Motoring

Posted: 20-Mar-2019    Tags: 2018 Honda Vezel, 2018 honda vezel, Honda Vezel, honda vezel, Honda, Vezel, vezel, Used Honda



**Honda Vezel 1.5A X Honda Sensing**      **\$79,800**      **\$7,910 /yr**      **27-Jun-2018**      **1,496 cc**      **13,000 km**      **SUV**      **Available**

1 Owner. Honda Sensing Safety. Facelift Model. 100% Accident Free. White Exterior With Black Leather Interior. Front And Back HD Recorder. Highest Trade-In. Std Bank Loan, Balloon Loan, In-House Loan....

**PREMIUM AD**

Posted: 07-Feb-2019    Tags: 2018 Honda Vezel, 2018 honda vezel, Honda Vezel, honda vezel, Honda, Vezel, vezel, Used Honda



**Honda Vezel 1.5A X Honda Sensing**      **\$85,800**      **\$8,520 /yr**      **28-Jun-2018**      **1,496 cc**      **1,100 km**      **SUV**      **Available**

Honda Sensing Technology With 1 Owner, Almost Brand New Condition, Beautiful And Exquisite Red Exterior And Black Interior. In House Loan Available With High Approval Rate. Owner Sold Due To Requireme...

HTS Motor

Posted: 25-Feb-2019    Tags: 2018 Honda Vezel, 2018 honda vezel, Honda Vezel, honda vezel, Honda, Vezel, vezel, Used Honda



**Honda Vezel 1.5A X**      **\$81,988**      **\$8,220 /yr**      **29-Jun-2018**      **1,496 cc**      **30 km**      **SUV**      **Available**

Brand New Car! Comes With 3 Years Warranty, Absolute The Best Value! Most Popular Suv On The Road, Low On Maintenance, High On Fuel Efficiency, Honda Sensing With Intelligent Adaptive Cruise Control, ...

Posted: 14-Feb-2019    Tags: 2018 Honda Vezel, 2018 honda vezel, Honda Vezel, honda vezel, Honda, Vezel, vezel, Used Honda



**Honda Vezel 1.5A X Honda Sensing**      **\$83,800**      **\$7,660 /yr**      **28-Aug-2018**      **1,496 cc**      **15 km**      **SUV**      **Available**

(Latest 2018 Facelift Sensing Model) Elegance White With Brown Leathers Seats, Come Lots Of Accessories, Brand New Vitas Ready Stock Available, Call Now To Find Out More!

Posted: 22-Mar-2019    Tags: 2018 Honda Vezel, 2018 honda vezel, Honda Vezel, honda vezel, Honda, Vezel, vezel, Used Honda



**Honda Vezel Hybrid 1.5A X Honda Sensing**      **\$104,988**      **\$10,230 /yr**      **28-Aug-2018**      **1,496 cc**      **74 km**      **SUV**      **Available**

**Fuel Type:** Petrol-Electric

nd Assemble In Japan. 5 Years Or 100,000Km Warranty! View To Appreciate. Call Now.

**PREMIUM AD**

Compare

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	14/03/2019 16:30
Date Of Accident	13/03/2019 19:05
Exact Location Of Accident	BLK 103 HOUGANG AVE 1 CARPARK
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SMA7057G
Insured/Policyholder	
Name Of Registered Owner	NEO CHI KIAH
NRIC No	S1480509E
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-96680817
Alternative Phone No	OFFICE-96680817
Vehicle Particulars	
Manufacturer	HONDA
Model	VEZEL-1.5 X CVT (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	SOMPO INSURANCE SINGAPORE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	D18MTPV01011096
Cover Note Number	
Driver	
Name of Driver	NEO CHI KIAH
NRIC No	S1480509E
Date Of Birth	29/05/1954
Occupation	INDOOR
Date Of Driving Pass	04/01/1978
Driving Experience	41 YEARS AND 2 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96680817
Fax Number	
Contact Number	OFFICE-96680817
EEmail Address	NOEMAIL

Address	BLK 103 HOUGANG AVE 1 #02-1131
Postcode	530103
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-

#### General Information of the Accident

Type Of Accident	HIT AND RUN / VANDALISM / DAMAGED WHILST PARKED
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	0

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

MY CAR WAS STATIONARY AT BLK 103 HOUGANG AVE 1 CARPARK ON 14/03/2019. AT ABOUT 10AM, I WENT DOWN TO CARPARK. I SAW MY VEHICLE (SMA7057G) WAS DAMAGED. THERE WAS A WITNESS NOTE FOR THIS ACCIDENT. VEHICLE B (SGL6128E) WAS REVERSING INTO CARPARK LOT AND HIT MY VEHICLE AT 19.05HRS - 19.08HRS ON 13/03/2019.

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### Details of Witness 1

Name	
Phone Number	87179897
Email Address	

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SGL6128E
Vehicle Make/Model/Colour	
Details Of Properties	VEHICLE B
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)


**SKETCH PLAN**

**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow Insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all Insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.


  
Policyholder's Signature  
Date & Time:

  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

\_\_\_\_\_  
Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

KCN YUN AUTO

SKETCH PLAN



A: SMA 7057G

B: SGL 6128E

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

My car was stationary at B1K106 Hujung Ave 1 car park.  
 14/03/2019 at about 10:00 am I went down to car park.  
 I saw my vehicle SMA 7057G was damaged. There was a  
 witness note for this accident, vehicle B: SGL 6128E  
 was reversing into car park lot & hit my vehicle at 19:05-19:08 P.M.  
 12/03/2019 (witness number: 87179897)

DECLARATION

I/We declare the foregoing particulars are true in every respect.

x [Signature]  
 Policyholder's Signature  
 Date & Time:

x [Signature]  
 Driver's Signature  
 (If driver is not the policyholder)  
 Date & Time:

14/3/19 2.32 PM  
[Signature]  
 Reporting Centre Personnel's Signature  
 Name:  
 NRIC/FIN No.:

**...CLAIM SUBFOLDER...(Pending for Survey Report)**

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	03 Apr 2019 16:13		18 Mar 2019 09:13 <a href="#">Edit Adj Rpt</a>	<b>S\$0.00</b> <a href="#">Edit Estimates</a>	<b>S\$0.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b>		<b>[Created by insurer]</b>							
Insured:	<b>Ong Buck Cheng</b> , ID: S0377012E								
Main Claimant:	<b>NEO CHI KIAH</b> , ID: S1480509E								
Vehicle Reg. No.:	<b>SMA7057G</b>	Date of Loss:	13/03/2019 00:00 - :59 [8 Months and 23 Days From LTA Reg Date (Man Yr)]						
Claim Type:	<b>TP</b>	Policy/Cover Note No.:	28821881QMX (TP, Fire & Theft) Coverage: 22/09/2016 - 22/09/2019						
Vehicle Reg. No. (Insured):	<b>SGL6128E</b>	Policy No. (Claimant):							
		Excess:							
Repairer:	<b>Xin Yun Auto Private Limited (HQ)</b> 1 Kaki Bukit Avenue 6, #01-59 Autobay @ Kaki Bukit, 417883 Kaki Bukit - Tel: 8226 5945 / 9136 8884								
Handling Insurer:	<b>MSIG Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: +65 6827 7888 ... [Handled by <b>Monica Chung Pei Zhen</b> - 6594 2552]								
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>Lim Teow Guan</b> ] ... [Imm.Advice due 19/03/2019]								
Adj Asg. Remarks:	on WP. LIAB 100% SJE DISAGREE APPOINT LKK. Arrange @ Block 8 Kaki Bukit Avenue 4 #05-23 Premier @ Kaki Bukit Singapore 415875 and contact 9839 1555 (Yi Xin).								
<b>ASSOCIATED MAIL RECEIVED</b>			<a href="#">View All</a>	<a href="#">Compose Case Mail</a>					
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b>			<a href="#">View All</a>	<a href="#">Search Tasks</a>					
			<a href="#">Create New Task</a>	<a href="#">Complete</a>					
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

**\*SMA7057G**  
**[SGL6128E]**  
**TP**  
**NEO CHI KIAH**  
**Mar 13 2019 12:00AM**  
**[Ong Buck Cheng]**  
**Xin Yun Auto Private Limited**

<a href="#">Upload Documents</a>   <a href="#">Upload Photos</a>   <a href="#">Compose New Letter</a>			View <input type="button" value="View in Browser"/>
Photos/Images			3 per page <input type="button" value="v"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail <input type="checkbox"/>
1	02/04/19 15:45	General View	<input checked="" type="checkbox"/>
2	02/04/19 15:45	General View	<input checked="" type="checkbox"/>
3	02/04/19 15:45	General View	<input checked="" type="checkbox"/>
4	02/04/19 15:45	General View	<input checked="" type="checkbox"/>
5	02/04/19 15:45	General View	<input checked="" type="checkbox"/>
6	02/04/19 15:45	General View	<input checked="" type="checkbox"/>
7	02/04/19 15:45	General View	<input checked="" type="checkbox"/>
8	02/04/19 15:45	General View	<input checked="" type="checkbox"/>
9	02/04/19 15:45	General View	<input checked="" type="checkbox"/>
10	02/04/19 15:45	General View	<input checked="" type="checkbox"/>
11	02/04/19 15:45	General View	<input checked="" type="checkbox"/>
12	02/04/19 15:45	General View	<input checked="" type="checkbox"/>
13	02/04/19 15:45	General View	<input checked="" type="checkbox"/>
14	02/04/19 15:45	General View	<input checked="" type="checkbox"/>
15	02/04/19 15:45	General View	<input checked="" type="checkbox"/>
16	02/04/19 15:45	General View	<input checked="" type="checkbox"/>
17	02/04/19 15:45	General View	<input checked="" type="checkbox"/>
18	02/04/19 15:45	General View	<input checked="" type="checkbox"/>
19	02/04/19 15:45	General View	<input checked="" type="checkbox"/>
20	02/04/19 15:45	General View	<input checked="" type="checkbox"/>
21	02/04/19 15:45	General View	<input checked="" type="checkbox"/>
22	02/04/19 15:45	General View	<input checked="" type="checkbox"/>
23	02/04/19 15:45	General View	<input checked="" type="checkbox"/>
24	02/04/19 15:45	General View	<input checked="" type="checkbox"/>
25	02/04/19 15:45	General View	<input checked="" type="checkbox"/>
26	02/04/19 15:45	General View	<input checked="" type="checkbox"/>
27	02/04/19 15:45	General View	<input checked="" type="checkbox"/>
28	02/04/19 15:45	General View	<input checked="" type="checkbox"/>
29	02/04/19 15:45	General View	<input checked="" type="checkbox"/>
30	02/04/19 15:45	General View	<input checked="" type="checkbox"/>
31	02/04/19 15:45	General View	<input checked="" type="checkbox"/>
32	02/04/19 15:45	General View	<input checked="" type="checkbox"/>
33	02/04/19 15:45	General View	<input checked="" type="checkbox"/>
34	02/04/19 15:45	General View	<input checked="" type="checkbox"/>
35	02/04/19 15:45	General View	<input checked="" type="checkbox"/>
36	02/04/19 15:45	General View	<input checked="" type="checkbox"/>
37	02/04/19 15:45	General View	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	02/04/19 15:45	General View	 Load JPG	<input checked="" type="checkbox"/>
39	02/04/19 15:45	General View	 Load JPG	<input checked="" type="checkbox"/>
40	02/04/19 15:45	General View	 Load JPG	<input checked="" type="checkbox"/>
41	02/04/19 15:45	General View	 Load JPG	<input checked="" type="checkbox"/>
42	02/04/19 15:45	General View	 Load JPG	<input checked="" type="checkbox"/>
43	02/04/19 15:45	General View	 Load JPG	<input checked="" type="checkbox"/>
44	02/04/19 15:45	General View	 Load JPG	<input checked="" type="checkbox"/>
45	02/04/19 15:45	General View	 Load JPG	<input checked="" type="checkbox"/>
46	02/04/19 15:45	General View	 Load JPG	<input checked="" type="checkbox"/>
47	02/04/19 15:45	General View	 Load JPG	<input checked="" type="checkbox"/>
48	02/04/19 15:45	General View	 Load JPG	<input checked="" type="checkbox"/>

Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	14/03/19 16:17	WORKSHOP DETAILS	 Load PDF	
2	15/03/19 17:23	SJE DISAGREE APPOINT LKK	 Load PDF	
3	15/03/19 17:23	OI Accident Report	 Load PDF	
4	15/03/19 17:31	TP SMA7057G E-REPORT	 Load PDF	

### Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b>			
<div style="border: 1px solid black; width: 100%; height: 100%;"></div>			
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

### VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS3/MSG19004852/BCD3E2

**Date:** 04/04/2019

#### REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	28821881QMX
<b>Claimant Vehicle No :</b> SMA7057G	<b>Insured Vehicle No :</b>	SGL6128E
Date of Loss: 13/03/2019	Nature of Claim:	TP
		Claim No: N/A

#### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SMA7057G</b>	Engine No:	L15B5552117
Make & Model:	HONDA VEZEL, 1.5 1.5X CVT (A)	Chassis No:	RU11302110
Reg. Date:	18/06/2018 (Man. Year: 2018)	Odometer:	14517 km
Colour:	White		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

#### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

#### CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	Dunlop 6 mm	Rear Right Side:	Dunlop 6 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

#### INSPECTION

Date of Assignment:	18/03/2019	
Date Inspected:	18/03/2019	Inspected At: Xin Yun Auto Private Limited (HQ) 1 Kaki Bukit Avenue 6, #01-59 Autobay @ Kaki Bukit Singapore 417883
Estimated Period of Repair:	4.0 days	

**Adjuster:** Lim Teow Guan

**Manager:** CELINE FONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.  
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,000.00 -\$4,000.00

## REPAIR DETAILS

<b>Reference</b>	
<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 03 Apr 2019)
<b>Parts:</b> M1-SUV	HONDA VEZEL 1.5 1.5X CVT (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b> (Unsubmitted, no print-code for SMA7057G)	
<b>Validity:</b> These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b> Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >