

ASS. REC. BY:

REF:

4/LPC19004854 Gvd3 12

Special Instruction:

SURVAYOR

Hennrich Two Day ASSIGNMENT (Office)

From (Person):

Ong Li Li

of

LPC

Date/Time:

18/3/19

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SDZ 6779M

Insured:

42 47734

at Workshop m/s

Hong Hwa

Tel:

98261331 / 64578084

of

S/M

Policy No:

Claim No:

18/19/19/VCC00/021530

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

15/3/19

CA / REV / REP. / REV 24 HRS

LWP.

18/3/19

H.O.D. Endorsement:

Date/Time:

Person Contacted:

Vehicle IN / OUT

Date/Time

Action/Instruction (✓) Estimate

SDZ 6779M x

42 47734 x

21/03/19

@ 10:30am revised PO to Ong Li Li via email.

15/4/19

@ 952am Final fig \$1724.35 confirmed with ms chig  
(Red 1201.45, 419)

Surveyor: GA

REF: UPC

2808E

### ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
OD / TP / WS / TP RES / OD RES / EVA / INV / MV  
 To inspect Vehicle No: \_\_\_\_\_  
 at Workshop m/s Hong Huat  
 of \_\_\_\_\_  
 Insured: \_\_\_\_\_  
 Policy No. \_\_\_\_\_  
 Claims No. \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
 repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \_\_\_\_\_  
 IDAC Accident Rpt.: \_\_\_\_\_ Consistent? : Yes or No  
 GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No  
 Est. Repairs: 3 days Res.: Yes or No  
 Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

Veh No: SD86779M Yr Regn: 17 Aug 2017  
 Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota AX10 C.C. 1496  
 Colour: Beige A/C: Insured / Std / NI / NA  
 Sp. Reading: 48761 T/Radio: Insured / Std / NI / NA  
 Eng/No: \_\_\_\_\_

C/No: NZE1617124378

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195/60 R15  
 R: "

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
 TOYO / YOKO or

Front

R/Bal. 6 mm

L/Bal. 6 mm

D.O.A.

Survey held at w/s

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

RECEIVED 15 APR 2019

Date/Time, File Pass to? ☐ : Preli. Report

1) ☐ : Final Report

Date/Time, File Return to?

2) 15/4 - typist

Report Format : TP

Lump Sum / I.B.I: (\$) 1704.35

Days Of Repair: 3

Resurvey No. of Trip: 1

Add Fee: ☐ : Site Insp (\$)

☐ : Interview (\$)

☐ : Tech. Invs (\$)

☐ : Weekend (\$)

Survey Fee:

Transportation:

) S + RS, SI

) Photos

) Others

TOTAL



Auto  
Consultants  
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: 18/19/19/VC00/021530

Date: 21 March 2019

Our Ref: CS/LPC19004854/Gvd3

The Motor Claims Department  
Lonpac Insurance Bhd

Dear Sir/Madam,


**INITIAL INSPECTION REPORT OF VEHICLE NO. SDZ 6779M .**

Please be informed that we had conducted the inspection of the abovementioned vehicle on 19/03/2019 at the premises of M/s Hong Huat Motor Services and have the following to report:-

Workshop Estimate Amount	: S\$ <u>2,651.70</u> .
Revised Estimate Amount (lump sum)	: S\$ <u>1,450.23</u> .
"Check" Items Amount	: S\$ _____ .
Market Value	: S\$ _____ .
LTA Reimbursement Value	: S\$ _____ .
Nett Value	: S\$ _____ .

**Description of Damage:**

The vehicle sustained damages at the front o/s portion.



**Comments/ Present Status:**

Damages Consistent.

Repair days: 3 Days

Yours faithfully,  
Xing Guo Qiang  
Automotive Assessor

## Nivitha (LKK Auto)

---

**From:** ONG LI LI <llong@lonpac.com>  
**Sent:** Monday, 18 March 2019 2:10 PM  
**To:** jactan@visionlawllc.com; assignments@lkkauto.com; Admin-D (LKKAuto)  
**Cc:** MT\_Claim\_SG  
**Subject:** Your Ref: AM.jt.N57.SZ6779M.19 Our Ref: 18/19/19/VC00/021530 GZ4773G &SDZ6779M on 15/3/19 [External General]  
**Attachments:** 2846\_001.pdf

### Lonpac External - General

Without Prejudice


Dear Jac

Thank you for confirming the appointment of a Single Joint Expert.

Dear Nivitha

Please see attached and arrange Kenneth Kong to conduct TP survey.

Regards,  
Ong Li Li  
Senior Claims Executive | Lonpac Insurance Bhd  
300 Beach Road #17-04/07 The Concourse Singapore 199555  
Tel : (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706



*Lonpac External - General data is for internal / external use.*

**From:** ct-admin@visionlawllc.com [mailto:ct-admin@visionlawllc.com]  
**Sent:** Monday, 18 March, 2019 1:46 PM  
**To:** ONG LI LI; MT\_Claim\_SG  
**Subject:** Scan Image

# VISION LAW LLC

Advocates & Solicitors - Notary Public - Commissioner for Oaths  
Agents for Trade Marks

(Incorporated with limited liability)

ERIC NG CHING BOON  
WONG KENG LEONG RAYNEY  
AUDREY WONG SU-HSIEN  
PAUL YAP TAI SAN  
ANJALLI D/O MUNIANDY  
SEGA PARAM  
ANG KIM NOI DIANE  
RAVENDRA KRISHNASAMY  
JANICE HAN JIA LIN  
TAN YINGXIAN, SELWYN  
CHEONG YUNHUI, CLARISSA  
EDISON TAM CHYI EU

Unique Entity Number :200721148H  
✓ **HEAD OFFICE:** 133 New Bridge Road  
#18-01/02 Chinatown Point  
Singapore 059413

Branch: 490 Toa Payoh Lorong 6  
#03-11 HDB Hub  
Singapore 310490

## ✓ HEAD OFFICE

TEL : (65) 65342811 (Hunting)  
FAX ✓ : (65) 65356802 (General)  
: (65) 65355905 (Litigation)  
E-mail : jactan@visionlawllc.com

## BRANCH

TEL : 65 63580703  
FAX : 65 63580448 (Conveyancing)

WHEN REPLYING PLEASE QUOTE OUR REFERENCE- KINDLY REPLY TO HEAD OFFICE FOR THIS MATTER

Our Ref: AM.jt.Ins.H49.109898.19 (sj)  
Your Ref: 18/19/19/VC00/021530

18 March 2019

## LONPAC INSURANCE BERHAD

300 Beach Road  
#17-04/07 The Concourse  
Singapore 199555

Attention: Motor Claims Department

BY FAX: 6296 2706

Email: llong@lonpac.com  
Email: mt\_claim@lonpac.com

Dear Sirs,

**ACCIDENT INVOLVING SDZ 6779 M & GZ 4773 G ON 15 MARCH 2019 ALONG CARPARK AT BUKIT BATOK WEST AVENUE 6 AT ABOUT 1220 HOURS**

We refer to your letter dated 18 March 2019 informing that you wish to conduct a pre-repair survey and your List of Surveyors.

Our client confirmed appointment of Kenneth Kong as the Single Joint Expert for this matter.

Please be informed that the said vehicle can be inspected at:

**Venue:** Hong Huat Motor Services  
Block 18 Sin Ming Road  
#01-31  
Singapore 575676  
**Contact Person:** Ms Sallem (6457 8084)

If you fail to conduct the pre-repair inspection within the next 2 working days excluding any intervening Saturday, Sunday or Public Holiday, the said workshop will commence repairs thereafter without further reference to you.

Yours faithfully

ANJALLI M  
(HEAD OFFICE)



## FOR SURVEYOR

Please initial here after completion of pre-repair inspection. Thank you.

Appointed surveyor :  
(Name & Signature)

Date & Time of Inspection :

cc: SDZ 6779 M – By Fax: 6457 8441

**NB.: Any settlement of offer is on the express condition that this settlement is in respect of our client's claim for property-related damages only and shall not preclude our client from claiming injury-related damages arising from this accident.**

## CONFIDENTIALITY

THE INFORMATION CONTAINED IN THESE DOCUMENTS MAY BE PRIVILEGED AND CONFIDENTIAL AND IS INTENDED FOR THE EXCLUSIVE USE OF THE ADDRESSEE DESIGNATED ABOVE. If you are not the addressee, any disclosure, reproduction, distribution or other dissemination or use of this communication is strictly prohibited. If you have received this transmission in error please contact us immediately by telephone so that we can arrange for its return.

## Shirley Hiew (LKK Auto)

---

**From:** Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>  
**Sent:** Thursday, 21 March 2019 10:30 AM  
**To:** 'MT\_Claim\_SG'; 'ONG LI LI'  
**Cc:** assignments; SUR; Admin-D (LKKAuto)  
**Subject:** RE: Your Ref: AM.jt.N57.SZ6779M.19 Our Ref: 18/19/19/VC00/021530 GZ4773G &SDZ6779M on 15/3/19 [External General]  
**Attachments:** SDZ 6779M - Preli Advise.pdf

Dear Li Li,

Enclosed preliminary revised of vehicle SDZ 6779M.

Thank you.

Best Regards,

Shirley Hiew | Case Handler (On Behalf Veron)

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [Sur@lkkauto.com](mailto:Sur@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Admin-D (LKKAuto) [mailto:admin-d@lkkauto.com]  
**Sent:** Monday, 18 March 2019 2:26 PM  
**To:** 'ONG LI LI' <llong@lonpac.com>; jactan@visionlawllc.com; assignments <assignments@lkkauto.com>  
**Cc:** 'MT\_Claim\_SG' <mt\_claim@lonpac.com>; SUR <sur@lkkauto.com>  
**Subject:** RE: Your Ref: AM.jt.N57.SZ6779M.19 Our Ref: 18/19/19/VC00/021530 GZ4773G &SDZ6779M on 15/3/19 [External General]

Dear Ms Ong,

Thank you for the assignment.

Please be informed that the repairer arrange survey on 19/03/2019.

G.Nivitha | Admin

**LKK Auto Consultants Pte Ltd**

Phone: 6841-1972 | email: [assignments@lkkauto.com](mailto:assignments@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** ONG LI LI [mailto:llong@lonpac.com]  
**Sent:** Monday, 18 March 2019 2:10 PM  
**To:** jactan@visionlawllc.com; assignments@lkkauto.com; Admin-D (LKKAuto) <admin-d@lkkauto.com>  
**Cc:** MT\_Claim\_SG <mt\_claim@lonpac.com>

**Subject:** Your Ref: AM.jt.N57.SZ6779M.19 Our Ref: 18/19/19/VC00/021530 GZ4773G &SDZ6779M on 15/3/19  
[External General]

## **Lonpac External - General**

Without Prejudice

Dear Jac

Thank you for confirming the appointment of a Single Joint Expert.

Dear Nivitha

Please see attached and arrange Kenneth Kong to conduct TP survey.


Regards,

Ong Li Li

Senior Claims Executive | Lonpac Insurance Bhd

300 Beach Road #17-04/07 The Concourse Singapore 199555

Tel : (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706




*Lonpac External - General data is for internal / external use.*

**From:** [ct-admin@visionlawllc.com](mailto:ct-admin@visionlawllc.com) [<mailto:ct-admin@visionlawllc.com>]

**Sent:** Monday, 18 March, 2019 1:46 PM

**To:** ONG LI LI; MT\_Claim\_SG

**Subject:** Scan Image



This email has been checked for viruses by AVG antivirus software.

[www.avg.com](http://www.avg.com)

## &gt; Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	2808E
Vehicle Details	
Vehicle No.:	SDZ6779M
Vehicle to be Exported:	No
Intended Deregistration Date:	20 Mar 2019
Vehicle Make:	TOYOTA
Vehicle Model:	COROLLA AXIO 1.5G MT ABS D/AIRBAG 2WD
Primary Colour:	Beige
Manufacturing Year:	2017
Engine No.:	1NZE8217377
Chassis No.:	NZE1617124378
Maximum Power Output:	80.0 kW (107 bhp)
Open Market Value:	\$17,744.00
Original Registration Date:	17 Aug 2017
First Registration Date:	17 Aug 2017
Transfer Count:	0
Actual ARF Paid:	\$12,744.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	16 Aug 2027
PARF Rebate Amount:	\$9,558.00
Intended COE Rebate Details	
COE Expiry Date:	16 Aug 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$45,201.00
COE Rebate Amount:	\$37,995.00
<b>Total Rebate Amount:</b>	<b>\$47,553.00</b>

The information contained herein is correct as at 20 Mar 2019

OK



## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	15/03/2019 13:47
Date Of Accident	15/03/2019 12:20
Exact Location Of Accident	CARPARK AT BUKIT BATOK WEST AVE 6
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SDZ6779M
<b>Insured/Policyholder</b>	
Name Of Registered Owner	LIM KANG HOCK
NRIC No	S0132808E
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-96726589
Alternative Phone No	OFFICE-96726589

### Vehicle Particulars

Manufacturer	TOYOTA
Model	COROLLA AXIO-1.5 X (A)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

### Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5093372881-01 (CLASSIC)
Cover Note Number	

### Driver

Name of Driver	LIM KANG HOCK
NRIC No	S0132808E
Date Of Birth	02/08/1952
Occupation	INDOOR
Date Of Driving Pass	07/10/1974
Driving Experience	44 YEARS AND 5 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96726589
Fax Number	
Contact Number	OFFICE-96726589
EEmail Address	NOEMAIL

Address	710 JURONG WEST STREET 71 #14-18
Postcode	S640710
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	0

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

PLEASE SEE ATTACHED SKETCH PLAN

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### Details of Witness 1

Name	LIM HENG GUAN
Phone Number	98772199
Email Address	IC : S1278082F

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GZ4773G
Vehicle Make/Model/Colour	TOYOTA VAN
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	GUO CHUANGHONG
NRIC/Passport Number	G2025526P
Contact Number	
Address	
Postcode	
Insurance Company Name	

Nature Of Damage

No. Of Passenger (Including Driver)

**SKETCH PLAN**


**IMPORTANT NOTICE**


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.


**8. Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

  
Policyholder's Signature  
Date & Time:


  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

  
Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

IDAC BUKIT BATON (VAC)  
511 Bukit Batok Street 23  
Singapore 659545  
Tel: 6560 3312 Fax: 6569 0722  
Email: vacbb@singnet.com.sg

15 MAR 2019

SKETCH PLAN



Veh A: 50Z6779M

Veh B: 6Z4773G

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On the stated date & time, My vehicle was parking stationary at Blk 109 Bukit Batok West Ave 6 car park Lot 39. Vehicle B (6Z4773G) was trying to drive out from Lot 38 but there was vehicle ~~there~~ so vehicle B reverse ~~back~~ back into lot 38 and the vehicle middle body hit onto my vehicle front right portion.

There is witness for this accident.

Witness Name: Lim Heng Ewen

Witness NRIC: S1278082F

Witness HP: 98772199

DECLARATION

I/We declare the foregoing particulars are true in every respect.

15 MAR 2019

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

IDAC BUKIT BATOK (PAC)  
511 Bukit Batok Street 23  
Singapore 651515  
Tel: 6736 3212 Fax: 6736 3211  
Email: idac@idac.gov.sg

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

lhhmotorco@gmail.com

# HONG HUAT MOTOR SERVICES

11 Sin Ming Road, #01-23 Thomson V Two Singapore 575629

Tel : 64578084 (5Lines) , Fax: 64578441

Dealers In New & second Hand Vehicle, Hire-Purchase & General Insurance

15 MARCH 2019

OUR REF: TP/6779/2019

ACCIDENT DATE: 15/03/2019

OUR INSURED: SDZ6779M

YOUR INSURED: GZ4773G

OWNER: LIM KANG HOCK

BLK 710 JURONG WEST ST 71 #14-18 SINGAPORE 640710

*21/3/19  
part by part.  
before parts photos.  
Emp. Qup.  
19/3/19.*

DEAR SIR,

## ESTIMATE COST OF REPAIR FOR VEHICLE SDZ6779M TOYOTA AXIO

1 PC. FRONT BUMPER ASSY	<i>re</i>	\$	881.60	<i>350.9</i>
1 PC. FRONT BUMPER RH RETAINER	<i>nt</i>		89.20	<i>44.6</i>
		\$	970.80	<i>395.5</i>
	LESS 25%		242.70	
		\$	728.10	<i>296.63</i>

## NETT ITEM

1 PC. FRONT RH HEADLAMP ASSY	<i>nt</i>	\$	698.10	<i>/</i>
1 PC. FRONT RH MUDFLAP	<i>nt</i>		44.20	<i>/</i>
1 PC. FRONT RH FOG LIGHT COVER	<i>nt</i>		61.70	<i>/</i>
		\$	804.00	
	LESS 10%		80.04	
		\$	723.60	

## LABOUR

LABOUR CHARGE FOR ADJUSTING, KNOCKING, CHECKING, WELDING., CUTTING, REPAIRING AND REPLACEMENT OF PARTS

TO PUTTY AND SPRAY PAINTING TO THE DAMAGED PORTION

TO TUFF KOTTE

TO CHECK WIRING

TO CHECK WIRING

- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

500.00	<i>200</i>
500.00	<i>200</i>
120.00	<i>X NN</i>
80.00	<i>30</i>
<i>2925.80</i>	
TOTAL	\$ 2,651.70 <i>430</i>

*Total: 1450.23*

# HONG HUAT MOTOR SERVICES

11 Sin Ming Road, #01-23 Thomson V Two Singapore 575629

Tel : 64578084 (5Lines) , Fax: 64578441

Dealers In New & second Hand Vehicle, Hire-Purchase & General Insurance

20 MARCH 2019

OUR REF: TP/6779/2019

ACCIDENT DATE: 15/03/2019

OUR INSURED: SDZ6779M

YOUR INSURED: GZ4773G

OWNER: LIM KANG HOCK

BLK 710 JURONG WEST ST 71 #14-18

SINGAPORE 640710

DEAR SIR,

## SUPPLEMENTARY COST OF REPAIR FOR VEHICLE SDZ6779M TOYOTA AXIO

1 PC. FRONT BUMPER SPONGE	✓	CRA	\$	126.30
1 PC. FRONT GRILLE	✓	BR		239.20
				-----
			\$	365.50
		LESS 25%		91.40
				-----
			\$	274.10

TWO HUNDRED AND SEVENTY-FOUR AND CENTS TEN ONLY.)

1728.<sup>35</sup>33



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

LONPAC INSURANCE BHD

Ref : CS/LPC19004854/Gvd3n2

300 BEACH ROAD

#17-04/07 THE CONCOURSESINGAPORE 199555

Date : 25-04-2019

Code : LPC2



## 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GZ 4773G	Veh. Inspected	SDZ 6779M
Policy No.		Coverage (\$)	0.00
Claim No.	18/19/19/VC00/021530	Excess (\$)	0.00
Assign From	ONG LI LI	Assign Date	18/03/2019

## 2. Vehicle Particulars & Condition

Make & Model	TOYOTA AXIO	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	NZE1617124378	Colour	BEIGE
Odometer	48761	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

## 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/60 R15	MICHELIN	6 mm
L/H Front Tyre	195/60 R15	MICHELIN	6 mm
R/H Rear Tyre	195/60 R15	MICHELIN	6 mm
L/H Rear Tyre	195/60 R15	MICHELIN	6 mm

## 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION.  
DAMAGES SEE DETAILS.

## 5. General Information

Accident Date	15/03/2019	Inspection Date	19/03/2019
Survey held at	HONG HUAT MOTOR SERVICES 11 SIN MING ROAD #01-23 THOMSON V TWO SINGAPORE 575629		

## 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.  
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

## 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	3 Working Days
-------------------------------------	----------------





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SDZ 6779M

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	FRONT BUMPER ASSY	DEFORMED	881.60	350.90
1	FRONT BUMPER RH RETAINER	CUT	89.20	44.60
1	FRONT BUMPER SPONGE (ADDITIONAL)	CRACKED	126.30	126.30
1	FRONT GRILLE (ADDITIONAL)	BROKEN	239.20	239.20
	LESS 25% DISCOUNT		-334.08	-190.25
			1,002.22	570.75
<b>NETT ITEMS</b>				
1	FRONT RH HEADLAMP ASSY (N)	CUT	698.10	698.10
1	FRONT RH MUDFLAP (N)	TORN	44.20	44.20
1	FRONT RH FOG LIGHT COVER (N)	DEFORMED	61.70	61.70
	LESS 10% DISCOUNT		-80.40	-80.40
			723.60	723.60
<b>LABOUR</b>				
	LABOUR CHARGE FOR ADJUSTING,KNOCKING,CHECKING, WELDING,CUTTING,REPAIRING AND REPLACEMENT OF PARTS.		500.00	200.00
	TO PUTTY AND SPRAY PAINTING TO THE DAMAGED PORTION.		500.00	200.00
	TO TUFF KOTE.	NOT NECESSARY	120.00	-
	TO CHECK WIRING.		80.00	30.00
			1,200.00	430.00
<b>GRAND TOTAL</b>			<b>2,925.82</b>	<b>1,724.35</b>
<b>RECOMMENDED COST OF REPAIRS</b>				<b>1,724.35</b>

Report Ref No. CS/LPC19004854/Gvd3n2

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.