Estimated C		174	CT L Bill to:		Onte/Time: 18.3.	209 12:54.00
TO Implect /	ehicle No. SLC	6603 M	MV/CS		SALLEZAA	
of BIK I	mova A 002 Bt Mulah	utomotive Lare 3 #10	Pte Hd.	Tel:	62 72389 7	
Foncy No:			Claim No:			
Sum Invaried			Exogni;			
Make of Velo (Client's Recor			I.M. Cont.		21.1.201	
		rewp	,	D	.O.A. 31-1. 201	٦
Date/Time_I	1 REP. / REV 241	LRS Person Conf	377	Vcl	H.O.D. Endorsement	
Date/Fime	Action/Instruction	(J) In	inca le			
	SL(6603n	- V	ants (c			
	SJH 638A	-/				

72/m/2000

		ASSIGNMENT
	Pi	Veh No SLC 6603 M 1281811 23/95/16
From	Date:	
Estimated Cost		Type: M.Carl M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
QD/TP/WS/TP RES/OD F	RES/EVA/INV/MV	Truck/Trailer or
Fo Inspect Vehicle No:		Make: Mitsubshi Outpander 2.4
at Workshop m/h		Colour White A/C Insured/Std/NI/NA
of		Sp.Reading 43941 T/Radio Insured / Std / NI / NA
Insured .		Eng/No:
Policy Na	500	CINO: IMYXTGF3WGZ003952
Clains: No		Gen. Cond; Good / Fair / Poor / Burnt
Sum Insured	Excess:	Steering: Inorder / Jammed / Leaked / Burnt or
(Client's Record)		Brake: Ingrdeg/ Jammed / Leaked / Burnt or
Make of Vels.		Modi: NII / S/Rim / STD A/Rim or
		Tyro Size: F: 225/5588
(Policy Condition)		R: '1
Remark: The veh had commo	nced its N/S (D/S BS / DUN / EXNOVA / GY/ FS / LIZA / MIC / OHTSU / PIR / SUMI /
repair at the time of	Inspection.	TOYO/YOKO or
Bal. or Market Value:		Front Roar
IDAC Accident Rport:	Consistent? : Yes or No	R/Bal. 7 mm R/Bal. 2 mm
GIA / PR Seen:	Consistent?: Yes or No	UBal. 7 mm L/Bal. 7
Est. Repairs:	days Res.: Yes or No	D.O.A. 31/1/19 D.O.I. 18/3/19
Lum Sum:	% 3 Val.: Yes or No	Survey held at Mova But t meich
CA / REV / REP. / 24 F	HRS	Des. of Demages : Frt I Rear I O/S I N/S I U/C I Rooftop or
Date: Person C	Vehiclo: IN / C	
Date / Time / Action / Instru	Contacted:	The U/C / Chassis frame / Body Structure affected due to collision.
MV- 8		
9 12 9		^ \
(13)19 12.20am Fin	with Mr Wei J.	1750, 2 days / monts
(\$1.	636.69_ Red -	43%)
		/
	_	, = [1/3/23/Q
	PECEIVED 2 6 MAR	3010 ", 56/3/5862.
	RECEIVED 2 6 MAR	5018 " , 56/3/586d.
•	RECEIVED 2 6 MAR	5018 ", 56/3/586d.
•	RECEIVED 2 6 MAR	2019 " 26/3/2019. Days Of Repair: 2
Distortune. Film Pass 10.7/19 :	To the second of	
Distortune. Filin Pass 10.7 / 9 : 3 / 9 / 5 / 5 / 5 / 5 / 5 / 5 / 5 / 5 / 5	Proll. Report Final Report	Days Of Repair: 2 Resurvey No. of Trip: Survey Fee: 1 Transportation
Distortune. Film Pass 10.7/19 :	Proll. Report	Days Of Repair: 2 Resurvey No. of Trip: Survey Fee: Iransportation See: Site Insp (\$) 5-87. 54
Distortune. Filin Pass 10.7 / 9 : 3 / 9 / 5 / 5 / 5 / 5 / 5 / 5 / 5 / 5 / 5	Proll. Report Final Report Add F	Days Of Repair: 2 Resurvey No. of Trip: Survey Fee:

Nivitha (LKK Auto)

From:

Chong Boon Sen <booksen.chong@sg.cntaiping.com>

Sent:

Monday, 18 March 2019 12:54 PM

To:

EST.PDF; RPT.PDF

Cc:

'AVRIL HO'; tanyw@mova.com.sg; assignments

Subject:

RE: TP CLAIMS - SLC6603M AGAINST SJH638A DOA 31/01/2019 AT SECOND LINK

STURE.

Attachments:

Without Prejudice

Dear Nitha,

We appoint LKK.

Dear LKK,

PIs pri.

Regards,

Chong Boon Sen

Claims Executive

Claims

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower Singapore 079909 Co. Reg. No. 200208384E

DID: 63896171 Fax: 62247175

Email: boonsen.chong@sg.cmtaiping.com

Website: www.sg.cntaiping.com

Disclaimer:

This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclasure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

Erom: Nitha Imailte-nitha@mass com and

Steve Chen (LKK Auto)

From:

Tan Yoong Wei <tanyw@mova.com.sg>

Sent:

Tuesday, March 26, 2019 9:46 AM

To:

Steve Chen (LKK Auto)

Subject:

RE: SJH638A Finalize

close

Best Regards, Tan Yoong Wei Estimator

Mova Automotive Pte Ltd Tel: 6272 3892 Fax: 6270 8314



This message is confidential and is for the use of the intended recipient only. If you have received this message in error, please do not copy, disclose or use its content. We would be grateful if you would notify us by email and delete the original transmission and any attachment from your system. Any attachment to this e-mail may contain software viruses that could damage your computer system. Although we will take reasonable precaution to minimize this risk, we do not accept any liability resulting from software viruses. Please carry out your own virus checks before opening any attachment.

From: Steve Chen (LKK Auto) [mailto:SteveChen@lkkauto.com]

Sent: Thursday, 21 March 2019 9:44 AM

To: Tan Yoong Wei Subject: SJH638A Finalize

Dear Ah Wei,

Herewith attached the above vehicle finalize \$1750. 2 days.

Kindly check.

Thanks

Best Regards, Steve Chen | Assistant Automotive Assessor LKK Auto Consultants

Phone: 6256 3561 | Email: <u>SteveChen@lkkauto.com</u> | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID: Vehicle Details	0983D
Vehicle No.:	SLC6603M
Vehicle to be Exported:	No
Intended Deregistration Date:	18 Mar 2019
Vehicle Make:	MITSUBISHI
Vehicle Model:	OUTLANDER 2.4 CVT AWD S/R FACELIFT
Primary Colour:	White
Manufacturing Year:	2016
Engine No.:	4B12RM7318
Chassis No.:	JMYXTGF3WGZ003952
Maximum Power Output:	123.0 kW (164 bhp)
Open Market Value:	\$22,635.00
Original Registration Date:	23 May 2016
First Registration Date:	23 May 2016
Transfer Count:	0
Actual ARF Paid: Intended PARF Rebate Details	\$23,689.00
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	22 May 2026
PARF Rebate Amount: Intended COE Rebate Details	\$17,766.00
COE Expiry Date:	22 May 2026
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$47,000.00
COE Rebate Amount:	\$33,733.00
Total Rebate Amount:	\$51,499.00

The information contained herein is correct as at 18 Mar 2019

OK

SGCARMART.COM

Login Sign up

New Cars

Used Cars

Sell My Car

Directory

Products

Insurance

Articles

Forum

Resour

Invest with Fast Direct Execution

Multi-awarded, multi-regulated broker

Our nervices involv as of your it

Post an Advertisement Sell it yourself! Advertise it at just \$58 until it's SOLD!



Interce 2 Years Warrents. 1905 Down Monthly Tram \$585. GV Credit Pte Ltd Stanfel



Browse by Category

Post an Ad Advertiser Login Ways of Selling

8 vehicles

Mitsubishi Outlander

Price

Depreciation

New 10 Years Coe Renewal Toyota Estima 2,4A

Rito, Date: 2016 Eng Cap

Mileage

Sort by Date Posted

Advanced Search

Ven Type

Any

5UV

Status Availabl

20 results/page

Search Selection

Mitsubishi Outlander

Απν \$78,800

\$10,060 /yr

Any

21-Jan-2016

2.360 cc

74,000 km

Availabi

Facelifted Model, Well Maintain By 1 Owner, 7 Seaters Sunroof Cavernous SUV, 5 Years Warranty And 10 Years Engine Warranty. Fully Agent Serviced By Cycle And Carriage. Bank Or In House Loan Available....

Mitsubishi Outlander 2.4A

Pure Motors Pte Ltd

Suproof

Posted: T5-Mar-2019

Tags: 2016 Mitsubishi Dutlander, 2016 mitsubishi outlander, Mitsubishi Outlander, mitsubishi outlander, Mitsubishi, Outlander, outlander, Used Mitsubishi

Mitsubishi Outlander 2.4A Sunroof

\$81,000

\$9,400 /yr

08-Jul-2016

2,360 cc

SUV

Availab

Selling A 2.4L Cheaper Than A 2L! Loan/Trade In Available. Agent Unit, Unlimited Mileage Warranty From Cycle & Carriage Till Mid 2021, Warranty For Engine Till End Of Drive By C&C Themselves! Worry Fr...

Cars 88 Pte Ltd

Tags: 2016 Mitsubishi Dutlander, 2016 mitsubishi outlander, Mitsubishi Outlander, mitsubishi butlander, Postod: 14-Mar-2019

Mitsubishi, Outlander, outlander, Used Mitsubishi



Mitsubishi Outlander 2.4A Sunroaf

\$80,833

\$10,320 /yr

07-Jan-2016

2.360 cc

39,600 km

56,500 km

Availabi

Mileage Only 39000KM1 New Facelift Model High Specs Unit, Fully Agent Serviced! Original Paintwork And Accident Free! Exterior And Interior Of Vehicle Like New! Seldom Use Well Maintained By Ex Carefu...

Posted: 13-Mari-2019 Tags: 2016 Mitsubishi Outlander, 2016 mitsubishi outlander, Mitsubishi Outlander, mitsubishi outlander, mitsubishi outlander, outlander, utlander, outlander, outlander, outlander, outlander, outlander



Mitsubishi Outlander 2.4A Sunroof

\$82,000

\$10,060 /yr

05-Jun-2016

2,360 cc

78,000 km

SUV

Availabl

Enjoy Loan Interest Rate At 2.28%! With Agent Warranty Of 5 Years Or 100K Km, Extremely Well Maintained! Up To 80% Financing Possible! Trade In Welcome! Call/SM5 To Arrange A Viewing Today

Tags: 2016 Mitsubishi Outlander, 2016 mitsubishi outlander, Mitsubishi Outlander, mitsubishi outlander, Mitsubishi, Outlander, outlander, Used Mitsubishi Posted: 11-Mar-2019



Hardrace Hardened Rubber Engine Mountings

Harden rubber mounts create more strength than OE rubber mounts. Immediately experience th e direct feedback from engine

More info about this product



Mitsubishi Outlander 2.4A Sunroof

\$96,800

\$11,270 /yr

07-Sep-2016

2.360 cc

74,000 km

SUV

Availabi

Powerful And Spacious 4WD 7 Seater SUVI Special Red Colour With Well Maintained Upholstery, 5 Years Warranty, Flexible Loan Scheme Available, Consignment Unit, Call Us Now To Make Appointment To View ...

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver,
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

5. Any false reporting may be referred to the Police for investigation.

- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available

 By the longement of this report to the insurers, you hereby con aforesaid. 	issent to the archiving of this report at the centre and to copies of the report being made available
	ACCIDENT STATEMENT
Date Of Report	01/02/2019 08:37
Date Of Accident	31/01/2019 17:00
Exact Location Of Accident	SECOND LINK
Country/State of Loss	SINGAPORE
والمراجع والمساواة	DETAILS OF OWN VEHICLE
Vehicle Registration Number	SLC6603M
Insured/Policyholder	
Name Of Registered Owner	CHOONG KAM CHOON
NRIC No	S7470983D
Email Address	CHOONGSAMSON@YAHOO.COM.SG
Mobile Phone No	(LOCAL) +65-91828951
Alternative Phone No	OFFICE-NOPHONE
Vehicle Particulars	
Manufacturer	MITSUBISHI
Model	OUTLANDER 2.4 CVT AWD S/R FACELIFT
Exact Purpose for which vehicle was being used a time of accident	it .
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY

Vehicle Category

PRIVATE CAR

Insurance Company

Name of Insurance Company

NTUC INCOME INSURANCE CO-OPERATIVE LTD

Type Of Coverage

COMPREHENSIVE

Fleet Policy

NO

Policy Number

5100404041

Cover Note Number

Driver

Name of Driver CHOONG KAM CHOON

NRIC No S7470983D Date Of Birth 18/06/1974 Occupation INDOOR Date Of Driving Pass 17/10/1994

Driving Experience 24 YEARS AND 3 MONTHS

Gender MALE

Mobile Number (LOCAL) +65-91828951

Fax Number

Contact Number OFFICE-NOPHONE

EMail Address CHOONGSAMSON@YAHOO.COM.SG Address

24 BT BATOK ST 52 GUILIN VIEW

#04-03

Postcode

659246

Was driver an employee of the Insured's Company NO

If No. Relationship of the Driver with the Insured

OWNER

Vehicle Registration Number of Driver's Own

Vehicle

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident

CHAIN COLLISION

Weather Conditions

CLEAR

Road Surface

DRY

Other Information

Was any foreign vehicle involved in this accident?

YES

Foreign Vehicle Registration Number

JSN6603 (PRIVATE CAR)

Number of vehicles (including own vehicle)

involved in the accident

Was any body injured in the Accident?

NO

Was any injured conveyed to hospital by

NO

ambulance?

Was any other material or property damaged?

Number of Passengers (Including Driver)

YES

I have been approached by unknown person(s)

NO

soliciting/offering accident claims assistance.

5

Passenger 1

NAME:

: NGAH CHEE

GENDER:

: FEMALE

Passenger 2

NAME:

: CHOONG KAM WING

GENDER:

: MALE

Passenger 3

NAME:

: CHONNG KAM CHUNG

GENDER:

: MALE

Passenger 4

NAME:

: CHOONG KAM WAI

GENDER:

: MALE

Details of Police Action

Was the accident reported to the police?

YES

If Yes Please state which Police Station

Police Station Name HONG KAH NORTH NEIGHBOURHOOD POLICE POST

Police Station Address

ROAD: BLK 370 BUKIT BATOK STREET 31 , POSTCODE: 650370 .

COUNTRY: SINGAPORE

Police Station Contact

TEL NO: 1800-5679999 - FAX NO: 65652508

Was notice of intended Prosecution given?

NO

If Yes, against whom?

Circumstances of Accident

PLEASE REFER TO THE SKETCH PLAN

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

NO

Was there any audio recorded?

NO

Page 2 of 24

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

SJH638A

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

Name of Driver

PRIVATE CAR

ONG SWEE LYE

NRIC/Passport Number

S1499493I 94555016

Contact Number

Address Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number

JSN6603

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 3

Vehicle Registration Number

AKW7363

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

NGUEH ENG KONG

NRIC/Passport Number

951031085021

Contact Number

96115092

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 4

Vehicle Registration Number

SKM940M

Vehicle Make/Model/Colour

Details Of Properties

PRIVATE CAR

Vehicle Category Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 5

Vehicle Registration Number

SLH8405D

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 6

Vehicle Registration Number

SLQ546K

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

SKETCH PLAN

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as <u>truthful and accurate as possible</u>. Any wilful misrepresentation or withholding of material facts may allow insurance companies to <u>repudiate policy liability</u>.
- The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (iii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - [iv] administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); anti/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature Date & Time: Oriver's Signature (If driver is not the policyholder) Date & Time:

Name: NRIC/FIN No.:

Reporting Centre Personnel's Signature

Sketch Plan Pg. 2

KETCH PLAN			
	Pls re	on to attachment	
ESCRIBE CIRCUMSTANCES	OF THE ACCIDENT		
CENSE PLATE: SLC6	603M	ACCIDENT DATE & TIME:	31 Can 2019
ONTACT NUMBER: 918	28951	E-MAIL ADDRESS: Choone	samson Oyghos com
ocation and Link Ti	ias	C	30.00.10 97
	al	1 0 1	
	pls refent	o Police Report.	
		, (
MOTE: DI EASE MOTE T	HAT VOUD INCUDED M	AY HAVE 14 DAYS TIME FRAME	PAR MAN TO SUBMER MAN
	The second secon		
OWN DAMAGE CLAIM UNI	DER YOUR OWN POLICY	PLEASE CHECK YOUR POLICE	FOR MORE INFORMATION
sase state:			
() Claim Own Policy	Claim Third Party	Claim OD/TP at other worksho	p () Reporting Only
CLARATION			3763
ve declare the follegoing partic	ulars are true in every resp	ect.	
() 1/2/20			
licyholder's Signature	Driver's Signature		ng Centre Personnel's Signature

(If driver is not the policyholder) Date & Time:

Name: NRIC/FIN No.:

Page 6 of 24

SG Cista withmin (DD moder to anti-JVU 4509957S LUNS #889/HSS HSP3 VKM 6603 28N 05048 my scars

sketch Man

Page 7 of 24

Sketch Plan Pg. 4





Police Station Of Origin: Hong Kah North NPP 370 Bukit Batok Street 31 #01-201 SINGAPORE 650370 Tel No: 1800-5679999

1 of 4 Report No. T/20190131/2152

REPORT OF A TRAFFIC ACCIDENT

	ne Report N 019 19:23	/lade:	Vide Report No.:	Station Diary No.: 77	
Informa	nt's Partic	ulars	CHEST AND LABOR PRINCES		
	f Informant: IG KAM CH		Address: 24 BUKIT BATOK STI	REET 52 #04-03 SINGAPORE 659246	
	D Type / ID No.: NRIC NO / S7470983D		Contact No.: Home/Office: Mobile: 91828951		
	lationality: INGAPORE CITIZEN		Email: Mobile: 91828951		
Sex: Male	Age:	Date of Birth: 18/06/1974	Type of Informant:		
Race: Chinese			Language:	Institution / School Name:	
Occupat PROFE:	tion: SSIONAL		Driving Licence Inform Class: 2B,3	nation: Date of Expiry:	

Type of Accident:	Non-Injury Others	Drink Drive: No	Date/Time of Accident: 31/01/2019 17:00	Type of Location	
Location: Along Road 1 SECOND LIN		eway, (Singapore Side			
Weather:	e le omgapore ouus	Road Surface:		oad Speed Limit:	
Traffic Flow:		Traffic Control:	Tr	Traffic Volume:	
Traffic Plow:				COURT CONTENT OF THE	

Vehicle No.	Туре	Make	Model	Color	Condition	No of Passenger
AKW7363	Car					0
JSN6603	Car					0
SJH638A	Car					0
SKM940M	Car					0





2 of 4

Report No. T/20190131/2152

Police Station Of Origin: Hong Kah North NPP 370 Bukit Batok Street 31 #01-201 SINGAPORE 650370 Tel No: 1800-5679999

CONTINUATION OF REPORT

Vehicle No	Туре	Make	Model	Color	Condition	No of Passenger
SLC6603M	Car	MITSUBISHI	OUTLANDE R 2.4 CVT AWD S/R FACELIFT	White		0
SLH8405D	Car					0
SLQ546K	Car					0

Details of V	ehicle Insurance			MI TIPLE
Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
SLC6603M	NTUC Income Insurance Co-Operative Limited	5100404041	23/05/2018	22/05/2019

rary redeadatairii	volved: No				
No. of Pedestrian	s Injured: NIL	Use of Pede	estrian C	rossing: NA	
Driver			1000		10000
Name	ONG SWEE LYE		ID No.	\$1499493	
Related Vehicle	SJH638A (Car)		Contact	No. NIL	
Hospital/Clinic	NIL		Class of Driving Licence Expiry D	Date of Ex	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Disch	arge N	IIL	
No. of Days gran	ted Medical Leave NIL	Degree of I	njury N	IIL	
Driver				e Tradelana	
Name	CHOONG KAM CHOON		ID No.	\$7470983	D
Related Vehicle	SLC6603M (Car)		Contact	No. 91828951	
Hospital/Clinic	NIL		Class of Driving Licence Expiry D	Date of Ex	
Date Treatment	NIL	Date Disch	arge 1	VIL.	
No. of Days gran	ted Medical Leave NIL	Degree of	njury N	VIL.	



T/20190131/2152

Police Station Of Origin: Hong Kah North NPP 370 Bukit Batok Street 31 #01-201

SINGAPORE 650370 Tel No: 1800-5679999 3 of 4 Report No. T/20190131/2152

CONTINUATION OF REPORT

Brief Details.

On 31/01/2019 at around 1700hrs, I was driving my car bearing plate number V1)SLC6603M along the causeway from Johor to Singapore. There was a jam ahead and all of the cars were stationary. Hence I stopped and joined the queue. While waiting for the traffic to move, I suddenly felt something hit against my vehicle. I came out to make a check and discovered that a vehicle, bearing plate number V2) SJH638A had hit against the rear right side of my vehicle. The collision caused some damages to my vehicle. The rear right side of my bumper is cracked and broken. The rear signal light was also damaged. No one was injured. According to the driver of V2, a Malaysian vehicle bearing plate number V3) JSN6603 has collided onto him which caused his car to hit against mine. There were several other vehicles involved in the chain accident. The vehicles involved are as follows,

- V1) SLC6603M
- V2) SJH638A
- V3) JSN6603
- V4) AKW7363
- V5) SKM940M
- V6) SLH8405D
- V7) SLQ546K

At that point of time, I had 4 passengers in the car and nobody was injured. I have an in built car camera however I am unsure if the incident was captured. No traffic police was at scene.





4 of 4

Report No. T/20190131/2152

Police Station Of Origin: Hong Kah North NPP 370 Bukit Batok Street 31 #01-201 SINGAPORE 650370 Tel No: 1800-5679999


CONTINUATION OF REPORT

-						
	-	tc		п.	-	
-	к из	400	n	-	-	m

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the **report number** as reference.

Signature Of Officer Recording The Report:	Signature Of Informant:
Sgt 2 MUHAMMAD SYAFIQ BIN MOHD RAFE	- Lulling
Signature Of Interpreter: Not applicable	Date/Time: 31/01/2019 19:23
Officer In Charge Of Case	Classification Of Case:
Staff Sgt WONG SIEU LUI Contact No.: 65476151 SN 116	
Substitution Stamp. Piss. Singapore Police Force	



Estimate

CHINA TAIPING INSURANCE (S) PTE LTD

08/02/2019

3 Anson Road

Singapore 079909.

Attention :- XA017

#16-00 Springleaf Tower

2 chyr

18/3/9 1.31/m



Main Office:

Mova Building No. 22, Jalan Kilang. Singapore 159419 Tal. (65) 6476 3333 Fax: (65) 6271 5891 Www.mova.com.sg

Workshop Dept: Block 1008.

Block 1008. Bukit Memh Lane 3, #01-04/06/08/94 Singapore 159722

Tel: (65) 6272 3892 Fax: (65) 6270 8314

Co. Reg. 198904033G GST Reg. M2-0088864-2

Page #

age #

- SLC6603M

MITSUBISHI OUTLANDER 2.4 CVT

Veh Model :-

- CVA1066

Estimate# :-

:- CK418666

Claim #

ACC. Date :- 31/01/19

Terms

- C.O.D Days

L/S-1745 (S 749 = 1750 2182.27

Remarks :-

No.	Description	Qty U.P	rice Amounts S\$
1. 2. 3. 4. 5.	LIST ITEMS: REAR BUMPER / // REAR BUMPER LOWER GARNISH CENTRE (SILVER) / CHT REAR REFLECTOR LIGHT RH // REAR BUMPER RETAINER RH // REAR REINFORCEMENT BRACKET RH // // LIST TOTAL S\$ 10% DISCOUNT S\$	1 PC 389/45 1 PC 16 1 PC 84/15	30.00 1,530.00 36.20 436.20 65.30 165.30 48.00 48.00 94.60 194.60 2,374.10
		1442.97	2,136.69
	LABOUR: TO REPAIR REAR FENDER RH, REAR END PANEL AND OTHER ATTACHMENT PARTS. TO REMOVE & REPLACE ALL ACCIDENT DAMAGED PARTS		Juny 600.00
	TO SPRAY PAINT ON ACCIDENT DAMAGED PARTS		490 550.00
	TO REMOVE REAR PARKING SENSOR & CHECK WIRING		20.00
	TO INSPECT REAR TAIL LAMP WATER LEAKAGE TEST		Ø- 60.00
	LABOUR TOTAL S\$		740 1,250.00
***	E. 8 O.E	NON-TAX AMOUNT S AMOUNT S\$	3,386.69
	LKK Auto Consultants hence notify the Repairer of the following:	GST @ 7 %	237.07
	To resurvey before/after spray painting To display damaged partial during resurvey.	AMOUNT DUE S\$	3,623.76

Customer's Signature/Co. Stamp MOVA AUTOMOTIVE PTE LTD

. No illegal modification(s) is allowed

Acknowledged by Repairer

Signature: Date:

 Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company Merimen e-Claims Page 1 of 1

...CLAIM SUBFOLDER...(Pending for Survey Report)

LAIM SUB	FOLDER TRAC	KING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	A	dj Submitted	Ins Auth'ed	Status	
Main	03 Apr 2019 17:19		18 Mar 2019 14:51 Edit Adj Rpt	S\$1,750.00 Edit Estima		\$1,750.00 View Rpt		Report Cancel	for Survey
	Main	Refe	erence	Claim	Details		Documents		Show All
CLAIM SU	BFOLDER DE	TAILS				[Created by	insurer]		
Insured:	-, ID: -								
Main Claimant:	CHOONG N	CAM CHOON, ID:	S7470983D						
Vehicle Reg No.:	SLC6603	м		Date	of Loss:	31/01/2019 1 [32 Months a	17:00 - :59 and 8 Days From	LTA Reg Date	(Man Yr)]
Claim Type	TP				y/Cover No.:				
Vehicle Reg No. (Insured):	SJH638A				Policy No. 5100404041				
				Exce	158	S\$0.00			
Repairer:	Mova Auto 62723892/6	motive Pte Ltd (8 64763333	lukit Merah) Blk 1	008, #01-04/0	6/08/94,	Bukit Merah Le	ine 3, 159722 Bu	ikit Merah - Te	st:
Handling Insurer:	China Taip	ing Insurance (Si	ngapore) Pte. Ltd	I. (HQ) - Tel: (5389 611	1 [Handled b	y Chong Boon	Sen]	
Claimant's Insurer:		ome Insurance Co		77					
Adjuster:	LKK Auto (Consultants Pte L	td (HQ) - Tel: 6256	5-3561 [Han	dled by C	CHEN TSUE YE	E] [Final R	pt due 27/0	3/2019]
ASSOCIAT	ED MAIL REC	EIVED					View	All Comp	ose Case Mail
There are n	o mail for this o	case.							
ALL ASSO	CIATED TASK	KS□				View All Sec	arch Tasks Cre	eate New Task	Complete
Due Date	e Priority	Type Task G	roup Subject	Handler	Assign	ned By C	ompleted On	Created (On Done?


Claim Documents

*SLC6603M [SJH638A] TP CHOONG KAM CHOON Jan 31 2019 5:00PM [-] Mova Automotive Pte Ltd

Uţ	pload Documents (/)	sload Photos Compose New Letter	View View in	niuwpe	-
Ass	sessment Reports		1 per page	\vee	V
Νo	Finalized On	Mova Automotive Pte Ltd (Bukit Merah)	Thumb	-	Prin
1	01/02/19 09:25	Accident Statement	O Load P	ITM.	
Pho	otos/Images		3 per page	V	8
Νo	Finalized On	Mova Automotive Pte Ltd (Bukit Merah)	Thumb	nail I	Prin
1	01/02/19 09:10	Accident Photo [Linked Accident Report Documents]	■ Load 3	IPG	V
2	01/02/19 09:10	Accident Photo [Linked Accident Report Documents]	① Load:	IPG	V
3	01/02/19 09:10	Accident Photo [Linked Accident Report Documents]	■ Load 2	IPG	7
4	01/02/19 09:10	Accident Photo [Linked Accident Report Documents]	1 Load :	PG	V
5	01/02/19 09:10	Accident Photo [Linked Accident Report Documents]	① Load :	IPG	Ø
6	01/02/19 09:10	Accident Photo [Linked Accident Report Documents]	O Load	IPG	V
7	01/02/19 09:10	Accident Photo [Linked Accident Report Documents]	O Load I	PG	V
В	01/02/19 09:10	Accident Photo [Linked Accident Report Documents]	1 toad 1	PG	V
9	01/02/19 09:10	Accident Photo [Linked Accident Report Documents]	O Load 2	PG	1
10	01/02/19 09:10	Accident Photo [Linked Accident Report Documents]	■ Load I	PG	V
11	01/02/19 09:10	Accident Photo [Linked Accident Report Documents]	① Load I	PG	V
12.	01/02/19 09:10	Accident Photo [Linked Accident Report Documents]	① Load I	PG	V
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumb	nall F	Prin
1	18/03/19 18:51	General View	■ Load J	PG	$\overline{\mathbf{v}}$
2	18/03/19 18:51	General View	1 Load 3	PG	8
3	18/03/19 18:51	General View	■ Load 3	PG	V
4	18/03/19 18:51	General View	■ Load 3	PG	V
5	18/03/19 18:51	General View	■ Load 3	PG	3
6	18/03/19 18:51	General View	€ Load 3	PG	V
,	18/03/19 18:51	General View	■ Load 3	PG	V
В	18/03/19 18:51	General View	O Load 3	20.7	V
9	18/03/19 18:51	General View	O tond 2		N
10	18/03/19 18:51	General View	O Load 3		V
11	18/03/19 18:51	General View	O Load J		V
12	18/03/19 18:51	General View	€ Load 3		A)
3	18/03/19 18:51	General View	1 Load 3		N
4	18/03/19 18:51	General View	O Load 3	_	N.
15	18/03/19 18:51	General View			N N
16	18/03/19 18:51	Odometer Reading			N.
17	18/03/19 18:51	Chassis Number	O Load 3		(X)

Ass	essment Reports		1 per	page V	2
No	Finalized On	Mova Automotive Pte Ltd (Bukit Merah)		Thumbnail	Print
		100000000000000000000000000000000000000			V
18	18/03/19 18:51	General View	0	Load JPG	V
19	18/03/19 18:51	General View	0	Load JPG	V
			-	-	
Doc	umentation		1 per i	page V	~
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	18/03/19 14:51	prs contact	0	Load PDF	
No	Finalized On	Mova Automotive Pte Ltd (Bukit Merah)		Thumbnail	Print
1	01/02/19 09:10	Sketch Plan [Linked Accident Report Documents]	0	Load TIF	

Linked Accident Report Documents



Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
			5
Show Remarks To: Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No:

CS/CTI19004859/ESD3Q2

Date:

04/04/2019

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd.

Policy No:

Claimant Vehicle

e SLC6603M

Insured Vehicle No :

SJH638A

No : Date of Loss:

31/01/2019

Nature of Claim:

TP

Claim No: N/A

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:

SLC6603M

Make & Model:

MITSUBISHI OUTLANDER, 2.4 2.4 CVT AWD S/R

Engine No:

4B12RM7318

Reg. Date:

FACE (A)

Chassis No:

JMYXTGF3WGZ003952

Colour:

23/05/2016 (Man. Year: 2016)

Odometer:

43941 km

Engine Capacity:

2360 cc

Market Value/New Car Price: N/A

Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes Engine Modification:

No Pre-accident Condition:

res

CONDITION OF TYRES

Front Tyre Size:

225/55 R18

Rear Tyre Size:

225/55 R18

Front Left Side:

Goodyear 7 mm

Rear Left Side:

Goodyear 7 mm

Front Right Side:

Goodyear 7 mm

Rear Right Side:

Goodyear 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		2,136.69	1,442.07	694.62	32.51
Miscellaneous Items		0.00	0.00	0.00	
Labour		1,250.00	740.00	510.00	40.80
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Calculated Gross Total (S\$)	3,386.69	2,182.07	1,204.62	35.57
	Approved Total (Overridden) (S\$)		1,750.00		
	(S\$)	3,386.69	1,750.00	1,636.69	48.33
	+ GST 7.00/7.00% (S\$)	237.07	122.50	114.57	48.33
	Nett Amount (S\$)	3,623.76	1,872.50	1,751.26	48.33

INSPECTION

Date of Assignment:

18/03/2019

Date Inspected:

18/03/2019 Inspected At:

Mova Automotive Pte Ltd (Bukit Merah)

Blk 1008, #01-04/06/08/94, Bukit Merah

Lane 3

Singapore 159722

Estimated Period of Repair:

2.0 days

Adjuster: CHEN TSUE YEE Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 03 Apr 2019)

Parts: M1-SUV MITSUBISHI OUTLANDER 2.4 2.4 CVT AWD S/R FACE (A) (Catalogue: Merimen Singapore

1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SLC6603M)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page

numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Dented	1,530.00 FL	*916.00 FL
2	1		*REAR BUMPER LOWER GARNISH CENTRE (SILVER)	Cut	436.20 FL	*389.00 FL
3	1		*REAR REFLECTOR LIGHT RH	Broken	165.30 FL	*165.30 FL
4	1		*REAR BUMPER RETAINER RH	Broken	48.00 FL	*48.00 FL
5	1		*REAR REINFORCEMENT BRACKET RH	Bent	194.60 FL	*84.00 FL
F=Fra	inchise	part. L=Listf	temDisc.	,		
				Sub Total (S\$)	2,374.10	1,602.30
			- List Item Discount on L Items 1	0.00/10.00% (S\$)	237.41	160.23
				Total Parts (S\$)	2,136.69	1,442.07

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	TO REPAIR REAR FENDER RH ,REAR END PANEL AND OTHER ATTACHMENT PARTS .TO REMOVE & REPLACE ALL ACCIDENT DAMAGED PARTS	New	600.00	300.00
2	TO SPRAY PAINT ON ACCIDENT DAMAGED PARTS	New	550.00	400.00
3	TO REMOVE REAR PARKING SENSOR & CHECK WIRING	New	40.00	20.00
4	TO INSPECT REAR TAIL LAMP WATER LEAKAGE TEST	New	60.00	20.00
	Gross Labou	r Cost (S\$)	1,250.00	740.00
	Report was unsubmitted during	this print-out.		

< END OF ESTIMATES >