

ASS. REC. BY:

REF: CS3/LPC 19004870/R1qd3n2

Special Instruction:

Surveyor: Rasu

ASSIGNMENT (Office)

From (Person): Gerald Poh

of LPC

Date/Time: 18-3-2019 3:47pm

Estimated Cost:

Bill to:

OD (TP) / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLC 7764A

Insured: SLR 4620Y

at Workshop m/s: Fix Auto Pte LTD

Tel: 67104077

of 5 soon Lee street # 01-61

Policy No:

Claim No: 18/19/19/VP05/021525

Sum Insured:

Excess:

Make of Veh:
(Client's Record)

D.O.A. 17/3/19

CA / REV / REP. / REV 24 HRS

"wp"

I.O.D. Endorsement:

Date/Time: 18-3-2019

Person Contacted: Irene Lee

Vehicle: (IN) / OUT

Date/Time	Action/Instruction (X)	Estimate
	SLC 7764A X	SLR 4620Y X
22/3/19	Submit PAS.	

Nivitha (LKK Auto)

From: Mei Kwan (LKKAuto) <Meikwan@lkkauto.com>
Sent: Monday, 18 March 2019 3:00 PM
To: assignments
Subject: FW: RE:PRE-REPAIR SURVEY OF SLC7764A.YOUR REF :18/19/19/VP05/021525.OUR REF.:1903-7145(FIX) [External Confidential]

'WITHOUT PREJUDICE'
SAVE AS TO COSTS

Dear Sir / Madam,

To check availability of the case handler, you may contact the undersigned.

Thank you.

Best Regards,

Mei Kwan | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366 0055 | email: MeiKwan@lkkauto.com | fax: 67414108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

*PASUL
X EST*

From: GERALD POH WEE BIN <geraldpoh@lonpac.com>
Sent: Monday, 18 March, 2019 2:50 PM
To: Admin A <admin-a@lkkauto.com>; SUR <sur@lkkauto.com>
Cc: MT_Claim_SG <mt_claim@lonpac.com>; wendy_jiang@rssolomon.com
Subject: FW: RE:PRE-REPAIR SURVEY OF SLC7764A.YOUR REF :18/19/19/VP05/021525.OUR REF.:1903-7145(FIX) [External Confidential]

Lonpac External - Confidential

Our Ref : 18/19/19/VP05/021525

Dear Nivitha,

Kindly proceed as arranged.

Kindly proceed


Best Regards

Gerald Poh

Senior Claims Executive | Lonpac Insurance Bhd

300 Beach Road, #17-04/07 The Concourse, Singapore 199555

Tel: (65) 6250 7388 Ext.255 | Fax: (65) 6296 2706



Lonpac External - Confidential data is for use by authorised external parties only.

From: Wendy Jiang [mailto:wendy_jiang@rssolomon.com]

Sent: Monday, 18 March, 2019 2:25 PM

To: GERALD POH WEE BIN

Cc: Natalie Ng; account@fixauto.biz

Subject: RE:PRE-REPAIR SURVEY OF SLC7764A.YOUR REF :18/19/19/VP05/021525.OUR REF.:1903-7145(FIX)

Dear Gerald,

We refer to your fax of even date.

We regret to inform that our client will be appointing his own Surveyors.

In this respect, please contact Ms. Irene Lee of Fix Auto Pte Ltd at tel No. 6710 4077 for a pre-repair survey of our client's vehicle located at 5 Soon Lee Street #01-61 (Pioneer Point) Singapore 627607.

Thank you and Best Regards,

Yours sincerely

Wendy Jiang | Legal Executive

R. S. Solomon LLC | 正氣律師事務所

Advocates & Solicitors | Commissioner for Oaths

300 Beach Road The Concourse #12-03/04 Singapore 199555

t +65 6817 7498 | f +65 6292 2665 | e wendy_jiang@rssolomon.com | w www.rssolomon.com

The contents of this email (including any attachment) are strictly confidential and may contain privileged information.

If you are not the intended recipient, please notify us IMMEDIATELY and delete this email (including any attachments) from your computer system.

Thank you.




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT			
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555		Ref: CS3/LPC19004870/R1qd3n2 Date: 01-04-2019 Code: LPC2	
1. Policy Particulars :- (THIRD PARTY CLAIM)			
Insured Veh.	SLR4620Y	Veh. Inspected	SLC 7764A
Policy No.		Coverage (\$)	0.00
Claim No.	18/19/19/VP05/021525	Excess (\$)	0.00
Assign From	GERALD POH	Assign Date	18/03/2019
2. Vehicle Particulars & Condition			
Make & Model	HONDA VEZEL 1.5X	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	RU11111560	Colour	BLACK
Odometer	39096 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	215/60 R16	DUNLOP	5 mm
L/H Front Tyre	215/60 R16	DUNLOP	5 mm
R/H Rear Tyre	215/60 R16	DUNLOP	5 mm
L/H Rear Tyre	215/60 R16	DUNLOP	5 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION.			
5. General Information			
Accident Date	13/03/2019	Inspect Date / Time	18/03/2019 (04:57 PM)
Survey held at	FIX IT AUTO PTE LTD NO. 5 SOON LEE STREET #01-61 PIONEER POINT SINGAPORE 627607		
5a. Remarks			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.			

Report Ref No. CS3/LPC19004870/R1qd3n2

Inspected By

MRB

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

K.K.LAU

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No: 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT			
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555		Ref: CS3/LPC19004870/R1qd3n2 Date: 01-04-2019	
Code: LPC2			
1. Policy Particulars :- (THIRD PARTY CLAIM)			
Insured Veh.	SLR4620Y	Veh. Inspected	SLC 7764A
Policy No.		Coverage (\$)	0.00
Claim No.	18/19/19/VP05/021525	Excess (\$)	0.00
Assign From	GERALD POH	Assign Date	18/03/2019
2. Vehicle Particulars & Condition			
Make & Model	HONDA VEZEL 1.5X	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	RU11111560	Colour	BLACK
Odometer	39096 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	215/60 R16	DUNLOP	5 mm
L/H Front Tyre	215/60 R16	DUNLOP	5 mm
R/H Rear Tyre	215/60 R16	DUNLOP	5 mm
L/H Rear Tyre	215/60 R16	DUNLOP	5 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION.			
5. General Information			
Accident Date	13/03/2019	Inspect Date / Time	18/03/2019 (04:57 PM)
Survey held at	FIX IT AUTO PTE LTD NO. 5 SOON LEE STREET #01-61 PIONEER POINT SINGAPORE 627607		
5a. Remarks			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.			

Report Ref No. CS3/LPC19004870/R1qd3n2

Inspected By

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MinstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or form, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.