

ASS. REC. BY:

REF:

CB3/07119004879/Gcd3m

Special Instruction:

Surveyor: GQ

ASSIGNMENT (Office)

From (Person): Chong Boon Sen of GTI Date/Time: 8/3/19

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: GBJ 4034 Insured: GBH 39864

at Workshop m/s YONG SING MOTOR Tel: 91820027 Sam Sim

of 53 DEPU LANE 12

Policy No: DMCVN18154418000 Claim No: SNM190201222C02

Sum Insured: Excess:

Make of Veh: D.O.A. 12/3/19

(Client's Record)

CA / REV / REP. / REV 24 HRS 20/3/19 @ 2m owner waiting

Date/Time: H.O.D. Endorsement:

Person Contacted: Vehicle IN / OUT

Date/Time	Action/Instruction (X) Estimate
	GBJ 4034 x
	GBH 39864 x
	Dismantle: 21/3/2019
	After repair: 22/3/2019

PRS

600

REF:

C71

C8458M

ASSIGNMENT

Date

20/3/19

Estimated Cost

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

Inspected Vehicle No:

GBJ 4034

at Workshop m/s:

YONG SING MOTOR

of

53 DEPU LANE 12

Insured

Policy No

Claim No

Sum Insured

Excess:


(Client's Record)

Make of Veh.

2pm owner waiting

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Est. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repair:

4

days

Res.: Yes or No

Lump Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

lup

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No

GBJ 4034

Yt Regn

05 Dec 2018

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toyota Hiace

G.C. 2982

Colour

white

A/C Insured / Std / NI / NA

Sp. Reading

12317

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JTFHT02P800246449

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

195 R15

R:

11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

8

mm

R/Bal.

8

mm

L/Bal.

8

mm

L/Bal.

8

mm

D.O.A.

D.O.I.

20-03-19

Survey held at

w/s

2pm

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time

Action / Instruction

\$2000 - \$2500

Date/Time, File Pass for?



Prof. Report

1)



Final Report

Date/Time, File Return for?

2)

Report Format

PRO

Lump Sum / LRA / CS

Days Of Repair:

4

Resurvey No. of Trip:

2

Add Fee:



Site Insp (\$



Interview (\$



Tech Insp (\$



Weekend (\$

Survey Fee.

190

Transportation

1) S / R / G

2) Photos

3) Other

4) Other

100%

190

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	13 May 2019		13 May 2019 10:41 Edit Adj Rpt				Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS			[Created by insurer]						
Insured:									
Main Claimant: ahmad bashir bin mohamad									
Vehicle Reg. No.: GBJ403U		Date of Loss: 12/03/2019 00:00 - :59							
Claim Type: TP / SNM19D201222C02		Policy/Cover Note No.: DMCVSN18154418000							
Vehicle Reg. No. (Insured): GBH3986U		Policy No. (Claimant):							
		Excess: S\$0.00							
Repairer: Yong Sing Motor Works (HQ) No. 10 Defu Lane Singapore 539315, 539315 Defu Lane - Tel: 82677782									
Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 23/05/2019]									
ASSOCIATED MAIL RECEIVED				View All Compose Case Mail					
There are no mail for this case.									
ALL ASSOCIATED TASKS <input type="checkbox"/>				View All Search Tasks Create New Task Complete					
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Nivitha (LKK Auto)

From: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>
Sent: Monday, 18 March 2019 4:51 PM
To: Jennifer Guay
Cc: 'Yong Sing'; assignments
Subject: RE: OUR REF :AW-INS-Y45-109897.19.jgv & YR REF: GBH3986U

Without Prejudice

Dear Sir,

We will appoint LKK.

Pls provide all necessary details.

Dear LKK,

Pls pri.

Regards,

Chong Boon Sen

Claims Executive

Claims

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower

Singapore 079909

Co. Reg. No. 200208384E

DID: 63896171

Fax: 62247175

Email: boonsen.chong@sg.cntaiping.com

Website: www.sg.cntaiping.com

20/3/19 @ 2pm
owner waiting.

Disclaimer :

This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

From: Jennifer Guay [mailto:jenniferguay@visionlawllc.com]
Sent: Monday, 18 March, 2019 4:37 PM
To: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>
Cc: 'Yong Sing' <yongsingmotors@gmail.com>
Subject: RE: OUR REF :AW-INS-Y45-109897.19.jgv & YR REF: GBH3986U
Importance: High

PRE - REPAIR SURVEY

CLAIMANT: 4RIZ SERVICES PTE LTD

ACCIDENT INVOLVING GBJ403U & GBH3986U ON 12 MARCH 2019 ALONG CENTRAL BOULEVARD

Without Prejudice

Dear Boon Sen

Dear Sirs

Refer to your email of 18 March 2019 informing that you wish to conduct a pre-repair survey and to your list of surveyors.

TAKE NOTICE that we object to all your surveyors stated in your said List, for appointment as the Single Joint Expert.

Pursuant to Pre-Action Protocol for NIMA cases, we now propose for appointment as Single Joint Expert the following surveyors for your consideration:-

1. Mc-Coy Appraiser Pte Ltd

Please also be informed that our client's vehicle can be inspected as follows :

Venue : Yong Sing Motor Works
53 Defu Lane 12
Singapore 539144

Contact Person : Sam Sim 9182 0027

Please let us hear from you by 18 March 2019. Thank you.

Regards

Jennifer Guay

(Secretary for Ms Audrey Wong)

VISION LAW LLC

133 New Bridge Road #18-01

Chinatown Point

Singapore 059413

Tel : 6534 2811 (Ext 116)

Fax : 6535 6802

From: Chong Boon Sen [<mailto:boonsen.chong@sg.cntaiping.com>]

Sent: Monday, 18 March, 2019 3:32 PM

To: Jennifer Guay

Subject: RE: OUR REF :AW-INS-GBJ403U-19.jgv & YR REF: GBH3986U

Without Prejudice

Dear Sir,

We intend to conduct a pre-repair survey of the damage to your client's vehicle jointly with your client/your motor workshop. We propose to use one of the following motor surveyors to conduct the joint pre-repair survey as a single joint expert.

ADRIAN LING
Kelvin Ang
SEE CHEW SENG

MOHD FADHILAH BIN OSMAN
XING QUO QIANG
KENNETH KONG
SIMON HO
CHUA WEIJIE
MARCUS CHUA
HENRY NG

Please let us know within two(2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.

You may select one of the listed motor surveyors and we will bear the cost of the pre-repair survey carried out by the single joint expert.

Regards,

Chong Boon Sen

Claims Executive
Claims

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower

Singapore 079909

Co. Reg. No. 200208384E

DID: 63896171

Fax: 62247175

Email: boonsen.chong@sg.cntaiping.com

Website: www.sg.cntaiping.com

Disclaimer :

This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

From: Jennifer Guay [<mailto:jenniferguay@visionlawllc.com>]

Sent: Monday, 18 March, 2019 3:03 PM

To: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>

Subject: FW: OUR REF :AW-INS-GBJ403U-19.jgv & YR REF: GBH3986U

Importance: High

From: Jennifer Guay [<mailto:jenniferguay@visionlawllc.com>]

Sent: Monday, 18 March, 2019 9:35 AM

To: Claims Dept of CTI; Hwang Shiang Yi; Irene Tay

Subject: FW: OUR REF :AW-INS-GBJ403U-19.jgv & YR REF: GBH3986U

Importance: High

From: Jennifer Guay [<mailto:jenniferguay@visionlawllc.com>]

Sent: Friday, 15 March, 2019 4:32 PM

To: 'claimsdept@sg.cntaping.com'

Cc: 'yongsingmotors@gmail.com'

Subject: OUR REF :AW-INS-GBJ403U-19.jgv & YR REF: GBH3986U

Importance: High

PRE - REPAIR SURVEY

CLAIMANT: 4RIZ SERVICES PTE LTD

ACCIDENT INVOLVING GBJ403U & GBH3986U ON 12 MARCH 2019 ALONG CENTRAL BOULEVARD

Dear Sirs

We are instructed by **4RIZ SERVICES PTE LTD** to notify you of a road accident on **12 March 2019** at about 14.50hr **ALONG CENTRAL BOULEVARD** involving our client's **GBJ 403 U & GBH 3986 U** driven by your driver at the material time.

As a result of the accident, our client's vehicle has been damage. Before our client proceed to repair the damage vehicle, please let us know within 2 working days of your receipt of this notice whether you or your insurer would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you.

Regards

Jennifer Guay

(Secretary)

VISION LAW LLC

133 New Bridge Road #18-01

Chinatown Point

Singapore 059413

Tel : 6534 2811 (Ext 116)

Fax : 6535 6802

For Surveyor

Please initial here after completion of pre-repair survey.
Thank you.

Appointed Surveyor: _____

Name & Signature

Contact: _____

Date & Time _____

Surveyor during repair: _____

Date & Time: _____

Surveyor after repair: _____

Date & Time: _____

VISION LAW LLC

Advocates & Solicitors

(Incorporated with limited liability)

Unique Entity No. 200721148H

Head Office: 133 New Bridge Road #18-01/02 Chinatown Point, Singapore 059413

Branch: 490 Lorong 6 Toa Payoh #03-11 HDB Hub (Biz 3 Lobby 1), Singapore 310490

DISCLAIMER:

The contents of this email (including any attachments) are confidential and privileged and only intended for the recipient(s) addressed above. If you received this email by error, please notify the sender immediately and destroy it (and all attachments) without reading, storing and/or disseminating any of its contents (in any form) to any person. Email communication is not secure. Vision Law LLC is not liable for any losses arising out of any errors or omissions in the contents resulting from email transmission or any illegal or unauthorised usage or tampering of its email system.

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

VISION LAW LLC
Advocates & Solicitors
(Incorporated with limited liability)
Unique Entity No. 200721148H
Head Office: 133 New Bridge Road #18-01/02 Chinatown Point, Singapore 059413
Branch: 490 Lorong 6 Toa Payoh #03-11 HDB Hub (Biz 3 Lobby 1), Singapore 310490

DISCLAIMER:

The contents of this email (including any attachments) are confidential and privileged and only intended for the recipient(s) addressed above. If you received this email by error, please notify the sender immediately and destroy it (and all attachments) without reading, storing and/or disseminating any of its contents (in any form) to any person. Email communication is not secure. Vision Law LLC is not liable for any losses arising out of any errors or omissions in the contents resulting from email transmission or any illegal or unauthorised usage or tampering of its email system.

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	8458M
Vehicle Details	
Vehicle No.:	GBJ403U
Vehicle to be Exported:	No
Intended Deregistration Date:	21 Mar 2019
Vehicle Make:	TOYOTA
Vehicle Model:	HIACE VAN TURBO 5DR MT
Primary Colour:	White
Manufacturing Year:	2018
Engine No.:	1KD2832303
Chassis No.:	JTFHT02P800246449
Maximum Power Output:	-
Open Market Value:	\$28,136.00
Original Registration Date:	05 Dec 2018
First Registration Date:	05 Dec 2018
Transfer Count:	0
Actual ARF Paid:	\$1,407.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	04 Dec 2028
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$27,509.00
COE Rebate Amount:	\$26,690.00
Total Rebate Amount:	\$26,690.00

The information contained herein is correct as at 21 Mar 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	13/03/2019 17:03
Date Of Accident	12/03/2019 14:50
Exact Location Of Accident	ALONG CENTRAL BOULEVARD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	GBJ403U
Insured/Policyholder	
Name Of Registered Owner	4RIZ SERVICES PTE. LTD.
Co Reg No	201318458M
Email Address	4RIZSERVICES@GMAIL.COM
Mobile Phone No	(LOCAL) +65-81314926
Alternative Phone No	OFFICE-83319014

Vehicle Particulars

Manufacturer	TOYOTA
Model	HIACE
Exact Purpose for which vehicle was being used at time of accident	WORK PURPOSE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5105990506
Cover Note Number	

Driver

Name of Driver	AHMAD BASHIR BIN MOHAMAD
NRIC No	S7113709J
Date Of Birth	19/04/1971
Occupation	OUTDOOR
Date Of Driving Pass	13/11/2009
Driving Experience	9 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-81314926
Fax Number	
Contact Number	OFFICE-83319014
Email Address	4RIZSERVICES@GMAIL.COM

Address	APT BLK 469 ANG MO KIO AVENUE 10 #02-938 SINGAPORE
Postcode	560469
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
Insurance Company of Driver's Own Vehicle	-

General Information of the Accident

Type Of Accident	COLLISION - CHANGE/CROSS LANE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	3
Passenger 1	NAME: : NUR SARAH BTE MAHAT GENDER: : FEMALE
Passenger 2	NAME: : NA GENDER: : MALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO ATTACHED

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBH3986U
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	VEEMAN RAJEV GANDHI
NRIC/Passport Number	033677707
Contact Number	82883793
Address	
Postcode	

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

13/3/19
1420 hrs


Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

[Signature]

Sketch Plan #2 Pg. 1

SKETCH PLAN

A = GBJ 403 U
B = GBH 3986 U



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 12/3/19, I was driving along Central Blvd before CBD gantry, a pick-up lorry suddenly hit my left side van. I was on the 4th lane. The lorry from lane 5 swerved to my lane and hit my left van side. My van sustained broken side mirror and dent and scratches on my left side van.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	13 May 2019		13 May 2019 10:41 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	-, Co. Reg. No.: -								
Main Claimant:	ahmad bashir bin mohamad								
Vehicle Reg. No.:	GBJ403U	Date of Loss:	12/03/2019 00:00 - :59 [3 Months and 7 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / SNM19D201222C02	Policy/Cover Note No.:	DMCVSN18154418000						
Vehicle Reg. No. (Insured):	GBH3986U	Policy No. (Claimant):							
		Excess:	S\$0.00						
Repairer:	Yong Sing Motor Works (HQ) No. 10 Defu Lane Singapore 539315, 539315 Defu Lane - Tel: 82677782								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 23/05/2019]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***GBJ403U (SNM19D201222C02)**
[GBH3986U]




































TP

ahmad bashir bin mohamad

Mar 12 2019 12:00AM

[-]

Yong Sing Motor Works

Upload Documents			Upload Photos		Compose New Letter		View		View in Browser	
Photos/Images							3 per page		<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print	
1	22/05/19 16:57	General View						Load JPG	<input checked="" type="checkbox"/>	
2	22/05/19 16:57	General View						Load JPG	<input checked="" type="checkbox"/>	
3	22/05/19 16:57	General View						Load JPG	<input checked="" type="checkbox"/>	
4	22/05/19 16:57	General View						Load JPG	<input checked="" type="checkbox"/>	
5	22/05/19 16:57	General View						Load JPG	<input checked="" type="checkbox"/>	
6	22/05/19 16:57	General View						Load JPG	<input checked="" type="checkbox"/>	
7	22/05/19 16:57	General View						Load JPG	<input checked="" type="checkbox"/>	
8	22/05/19 16:57	General View						Load JPG	<input checked="" type="checkbox"/>	
9	22/05/19 16:57	General View						Load JPG	<input checked="" type="checkbox"/>	
10	22/05/19 16:57	General View						Load JPG	<input checked="" type="checkbox"/>	
11	22/05/19 16:57	General View						Load JPG	<input checked="" type="checkbox"/>	
12	22/05/19 16:57	General View						Load JPG	<input checked="" type="checkbox"/>	
13	22/05/19 16:57	General View						Load JPG	<input checked="" type="checkbox"/>	
14	22/05/19 16:57	General View						Load JPG	<input checked="" type="checkbox"/>	
15	22/05/19 16:57	General View						Load JPG	<input checked="" type="checkbox"/>	
16	22/05/19 16:57	General View						Load JPG	<input checked="" type="checkbox"/>	
17	22/05/19 16:57	General View						Load JPG	<input checked="" type="checkbox"/>	
18	22/05/19 16:57	General View						Load JPG	<input checked="" type="checkbox"/>	
19	22/05/19 16:57	General View						Load JPG	<input checked="" type="checkbox"/>	
20	22/05/19 16:57	General View						Load JPG	<input checked="" type="checkbox"/>	
21	22/05/19 16:57	General View						Load JPG	<input checked="" type="checkbox"/>	
22	22/05/19 16:57	General View						Load JPG	<input checked="" type="checkbox"/>	
23	22/05/19 16:57	General View						Load JPG	<input checked="" type="checkbox"/>	
24	22/05/19 16:57	General View						Load JPG	<input checked="" type="checkbox"/>	
25	22/05/19 16:57	General View						Load JPG	<input checked="" type="checkbox"/>	
26	22/05/19 16:57	General View						Load JPG	<input checked="" type="checkbox"/>	
27	22/05/19 16:57	Photographs of Damaged Parts						Load JPG	<input checked="" type="checkbox"/>	
28	22/05/19 16:57	Photographs of Damaged Parts						Load JPG	<input checked="" type="checkbox"/>	
29	22/05/19 16:57	Photographs of Damaged Parts						Load JPG	<input checked="" type="checkbox"/>	
30	22/05/19 16:57	Photographs of Damaged Parts						Load JPG	<input checked="" type="checkbox"/>	
31	22/05/19 16:57	Photographs of Damaged Parts						Load JPG	<input checked="" type="checkbox"/>	
32	22/05/19 16:57	Photographs of Damaged Parts						Load JPG	<input checked="" type="checkbox"/>	
33	22/05/19 16:57	Photographs of Damaged Parts						Load JPG	<input checked="" type="checkbox"/>	
34	22/05/19 16:57	Photographs of Damaged Parts						Load JPG	<input checked="" type="checkbox"/>	
35	22/05/19 16:58	Photo After Spray						Load JPG	<input checked="" type="checkbox"/>	
36	22/05/19 16:58	Photo After Spray						Load JPG	<input checked="" type="checkbox"/>	
37	22/05/19 16:58	Photo After Spray						Load JPG	<input checked="" type="checkbox"/>	

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	22/05/19 16:58	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
39	22/05/19 16:58	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
40	22/05/19 16:58	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	13/05/19 10:42	pri contact	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/CTI19004879/GCD3E2

Date: 24/05/2019

REFERENCE

Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMCVSN18154418000

Claimant Vehicle
No : GBJ403UInsured Vehicle
No : GBH3986U

Date of Loss: 12/03/2019

Nature of Claim: TP

Claim
No: SNM19D201222C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: GBJ403U

Make & Model: TOYOTA HIACE, 3.0 (A)

Engine No: 1KD2832303

Reg. Date: 05/12/2018 (Man. Year: 2018)

Chassis No: JTFHT02P800246449

Colour: White

Odometer: 12317 km

Engine Capacity: 2982 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195 R15	Rear Tyre Size:	195 R15
Front Left Side:	Bridgestone 8 mm	Rear Left Side:	Bridgestone 8 mm
Front Right Side:	Bridgestone 8 mm	Rear Right Side:	Bridgestone 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 13/05/2019

Date Inspected: 20/03/2019 Inspected At:

53 Defu Lane 12

Repairer : Yong Sing Motor Works (HQ)

Estimated Period of Repair: 4.0 days

Adjuster: XING GUO QIANG

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$2,000.00 -\$2,500.00

REPAIR DETAILS

Reference		
Part Source:		(Last Synchronised: 24 May 2019)
Parts:	N/A	TOYOTA HIACE 3.0 (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBJ403U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >