

Circular

REF: FWD

ASSIGNMENT

From:

Date: 18/3/19

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: FBL 205P

at Workshop m/s Erofia Motor

of 1 Kaki Bukit Ave 6 # 02-62

Insured:

Policy No.

Claims No.


Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt: Consistent?: Yes or No

GIA / PR Seen: Consistent?: Yes or No

Est. Repairs: 3 days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: FBL 205P Yr Regn: 3/5/2016

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: YAMAHA YBR 125 C.C. 124

Colour: Black A/C: Insured / Std / NI / NA

Sp. Reading: 10118 T/Radio: Insured / Std / NI / NA

Eng/No: E3F5E04173A

C/No: LBPRED1000056951

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 90/90 18 Cheng

R: 2.75 -18 CTS

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Cheng / CTS

Front

Rear

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. 13/3/19 D.O.I. 18/3/19

Survey held at Erofia Motor

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

M.V. 6500/2
 P.V. 4628/4
 N.V. 1872/2

Regin Lin
 29/3/19

Date/Time, File Pass to?

☐: Preli. Report

1)

Date/Time, File Return to?

☐: Final Report

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee: ☐: Site Insp (\$)☐: Interview (\$)☐: Tech. Invs (\$)☐: Weekend (\$)

) \$ + RS. SI

) Photos

) Others

Report Format:

Lump Sum / I.B.I.: (\$)

TOTAL