



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD 36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Ref: CS/FCI19004883/Gtd3e2	
			Date: 11/06/2019	
			Code: FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHD 7198D	Veh. Inspected	SLA 5001S	
Policy No.		Coverage (\$)	0.00	
Claim No.	D19001863MFSH	Excess (\$)	0.00	
Assign From	EILEEN LEE	Assign Date	18/03/2019	
2. Vehicle Particulars & Condition				
Make & Model	NISSAN X-TRAIL	c.c	1997	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	JN1JANT32Z0000704	Colour	RED	
Odometer	82995 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	225/60 R18	BRIDGESTONE	8 mm	
L/H Front Tyre	225/60 R18	BRIDGESTONE	8 mm	
R/H Rear Tyre	225/60 R18	BRIDGESTONE	8 mm	
L/H Rear Tyre	225/60 R18	BRIDGESTONE	8 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	11/03/2019	Inspection Date	19/03/2019	
Survey held at	AH LIM MOTOR COMPANY NO 10 ANG MO KIO IND PK 2A #01-09 AMK AUTOPOINT SINGAPORE 568047			
5a. Remarks				
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			5 Working Days	