

VGS Singapore

247
Alexandra Road
159934 Singapore

Phone No. +65 6305 7299
Fax No. +65 6474 3643
E-Mail service@vw.com.sg

VGS Singapore, 247, 159934 Singapore

TERENCE YEO JOO WAH
863 YISHUN AVENUE 4
#10-79
Singapore, 760863
Singapore

VAT Registration No. M20098505-2
Tax No. 199101494Z

Service Quote

Customer No. CV042759
Quote No. SER/QUO/19SP0013
QuoteDate 15/03/19
Salesperson Elaine Ong
Page 1

THIS IS NOT AN OFFICIAL TAX INVOICE

Make	Model Description	Mileage	Service Advisor
Skoda Auto	Karoq 1.5 110kW Style	15	Kong Charmaine
License No.	VIN	Initial Registration	Sales Advisor
SKM357Y	TMBKR7NU4K5016596	30/11/18	Elaine Ong
Engine Code	Labor Type	Engine No.	Model Code
		DAD 344127	NU74ND

No.	Description	Qty.	UoM	Unit Price	Amount
P B&P ALEX LABOUR	REPLACE REAR WINDSCREEN	1	Labor		840.00
P B&P ALEX LABOUR	R&R ROOF LINING	1	Labor		420.00
P B&P ALEX LABOUR	R&R SIDE GARNISH TRIM	1	Labor		420.00
P B&P ALEX LABOUR	LABOUR	5	Labor		2100.00
P B&P ALEX PAINT	SPRAY PAINT	4	Labor		1200.00
P B&P SOLAR FILM V-KOO	B&P SOLAR FILM -V-KOOL	1	Labor		400.00
P B&P DIAG	PROGRAMMING & CALIBRATION	1	Time Un		480.00
P B&P MECH	CHECK WIRE HARNESS, ECU, S	1	Time Un		280.00
	Sum Labor				11,080.00
P 565853621A FOD	REAR SKODA BADGE	1	Pieces		56.12
P 575807305B	BUMPER RETAINER	1	Pieces		428.25
P 575827705A 9B9	BOOT WTHRSTRIP	1	Pieces		118.84
P 57A807083 9B9	BUMPER ADAPTER LH	1	Pieces		42.43
P 57A807084 9B9	BUMPER ADAPTER RH	1	Pieces		42.43
P 57A807377	BUMPER GUIDE LH	1	Pieces		305.11
P 57A807378	BUMPER GUIDE RH	1	Pieces		305.11
P 57A807393	BUMPER BRACKET LH	1	Pieces		274.91
P 57A807394	BUMPER BRACKET RH	1	Pieces		274.91
P 57A807521 9B9	REAR BUMPER COVER UPPER B	1	Pieces		1,127.60
P 57A807835 2ZN	BUMPER COVER LOWER BLACK	1	Pieces		519.89
P 57A807863	STRIP	1	Pieces		46.37
P 57A807983 GRU	BUMPER COVER LH	1	Pieces		197.17
P 57A827025B	LID	1	Pieces		2,927.36
P 57A845049 NVB	REAR WINDSCREEN GLASS	1	Pieces		1,355.77
P 57A853687A 2ZZ	LETTERING KAROQ	1	Pieces		77.63
	Sum carried forward				19,179.90

Payments to:

- BBN: - Acc.-No.:

VGS Singapore, 247, 159934 Singapore

TERENCE YEO JOO WAH
863 YISHUN AVENUE 4
#10-79
Singapore, 760863
Singapore

VGS Singapore
247
Alexandra Road
159934 Singapore

Phone No. +65 6305 7299
Fax No. +65 6474 3643
E-Mail service@vw.com.sg

VAT Registration No. M20098505-2
Tax No. 199101494Z

Service Quote

Customer No. CV042759
Quote No. SER/QUO/19SP0013
QuoteDate 15/03/19
Salesperson Elaine Ong
Page 2

THIS IS NOT AN OFFICIAL TAX INVOICE

Make	Model Description	Mileage	Service Advisor
Skoda Auto	Karoq 1.5 110kW Style	15	Kong Charmaine
License No.	VIN	Initial Registration	Sales Advisor
SKM357Y	TMBKR7NU4K5016596	30/11/18	Elaine Ong
Engine Code	Labor Type	Engine No.	Model Code
		DAD 344127	NU74ND

Continued			19,179.90
P 57A919485B	SENSOR BRACKET <i>neu</i>	1 Pieces	88.01
P 57A919485C	SENSOR BRACKET <i>neu</i>	1 Pieces	88.01
P 57A919486B	SENSOR BRACKET <i>neu</i>	1 Pieces	62.88
P 57A919486C	SENSOR BRACKET <i>neu</i>	1 Pieces	62.88
P 57A945701A	REFLECTOR LHR <i>Bld</i>	1 Pieces	29.96
P 5JA853687 2ZZ	NAME PLATE SKODA <i>neu</i>	1 Pieces	85.05
P D 00920002	PRIMER <i>neu</i>	1 Pieces	30.51
P D 00940104	CLEANER <i>neu</i>	1 Pieces	105.97
66H3 Service Campaign (GOLF)			
P D 00950025	APPLICATOR <i>neu</i>	2 Pieces	22.24
P D 169300M2	1K adhes. <i>neu</i>	1 Pieces	39.71
P D 180KU2A1	2KADHESIVE <i>neu</i>	1 Pieces	94.32
P D 181802M1	ACTIVATOR <i>neu</i>	1 Pieces	27.84
P D 822150A1	BONDAGENT <i>neu</i>	1 Pieces	67.48
Sum Item			8,904.76

Sum Labor	11,080.00
Sum Item	8,904.76

Total SGD	19,984.76
7% GST	1,398.93
Total SGD Incl. GST	21,383.69

Payments to: - BBN: - Acc.-No.:

VGS Singapore, 247, 159934 Singapore

TERENCE YEO JOO WAH
863 YISHUN AVENUE 4
#10-79
Singapore, 760863
Singapore

VGS Singapore
247
Alexandra Road
159934 Singapore

Phone No. +65 6305 7299
Fax No. +65 6474 3643
E-Mail service@vw.com.sg

VAT Registration No. M20098505-2
Tax No. 199101494Z

Service Quote

Customer No. CV042759
Quote No. SER/QUO/19SP0013
QuoteDate 15/03/19
Salesperson Elaine Ong
Page 3

THIS IS NOT AN OFFICIAL TAX INVOICE

Make	Model Description	Mileage	Service Advisor
Skoda Auto	Karoq 1.5 110kW Style	15	Kong Charmaine
License No.	VIN	Initial Registration	Sales Advisor
SKM357Y	TMBKR7NU4K5016596	30/11/18	Elaine Ong
Engine Code	Labor Type	Engine No.	Model Code
		DAD 344127	NU74ND

Explanations

P = Proportionately Charged

Payment Terms No Credit

Paul
Hp 900000
5-6 days
28/03/19 @ 1100
Reay seting paint

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: