

22/03/2002

ASS. REC. BY:

REF: CS / INC 19004935 / ESD 302

Special Instruction:

Surveyor: Steve

ASSIGNMENT (Office)

From (Person): Cynthia Ang

of

INC

Date/Time:

14/3/19 @ 9:36am

Estimated Cost:

Bill to:

OD ~~TH~~ / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

YN 1675B

Insured:

YP 2007M

at Workshop m/s

Sin Sheng Engineering

Tel:

6863 9595

of

3 tech park crescent

Policy No:

Claim No:

MT/1034290-002

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

1/3/2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 10:25am 14/3/19

Person Contacted:

Susan

Vehicle: IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	YN 1675B - X
	YP 2007M - NA / INC 170 20930 / r 3
	D.O.A. - 01/11/2017

INVOICE

Steve

REF:

# ASSIGNMENT

From \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost \_\_\_\_\_  
QD / TP / WS / TP RES / OD RES / EVA / INV / MV  
 To Inspect Vehicle No: \_\_\_\_\_  
 at Workshop m/s \_\_\_\_\_  
 of \_\_\_\_\_  
 Insured \_\_\_\_\_  
 Policy No \_\_\_\_\_  
 Claims No \_\_\_\_\_  
 Sum Insured \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days Res.: Yes or No

Lum Sum:

% 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time : Action / Instruction

11/4/19 Finalize \$3750, 4 days.

( \$ 3,502.56 Red - 48% )

Veh No YN1675B Yt Regn. 3/12/10  
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Mitsubishi FK61

G.C. 7545

Colour

A/C Insured / Std / NI / NA

Sp. Reading

267993

T/Radio: Insured / Std / NI / NA

Eng/No:

Ci/No:

FK61FMA 00154

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Loaked / Burnt or

Brake: Inorder / Jammed / Loaked / Burnt or

Modi: Nil / S/Rim. / STD A/Rim or

Tyre Size:

F:

8-25R16

R:

11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
 TOYO / YOKO or

Aurstone

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

11/3/19

D.O.I.

19/3/19

Survey held at

Sin Sheng

1135AM

Des. of Damages: Frnt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

RECEIVED 12 APR 2019

*[Signature]*

12/4/2019

Date/Time: File Pass to:

☐

: Proll. Report

☒

: Final Report

4) Typ: SA

Date/Time: File Return to:

Days Of Repair:

4

Resurvey No. of Trip:

1

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Survey Fee:

250

Transportation

) S + R + G

) Photos

) Fuel

)

TOTAL

250

Report Format:

Lump Sum / I.B.L: (\$ 3,750/- L/S,

**Nivitha (LKK Auto)**

**From:** Cynthia Ang <Cynthia.Ang@income.com.sg>  
**Sent:** Tuesday, 19 March 2019 9:36 AM  
**To:** assignments@lkkauto.com  
**Cc:** Toh Choon Hin; Daniel Koh; Thio Tse Kiat  
**Subject:** TP CASES FARMED OUT TO LKK ON 19/03/2019

Dear Veron / Nivitha,

Please assist to survey the vehicles as per Mr Toh's instruction :-

SN	Surveyor	Claim No.	Vehicle	WorkShop Name	WorkShop Address	WorkShop Contact	Survey Type	Survey Time	OI Veh	DOA	Additional Remarks
1	Corinne Hoo	MT/1034290-002	YN1675B	SIN SHENG ENGINEERING SERVICES	3 TECH PARK CRESCENT TUAS TECH PARK SINGAPORE 638129	Susan / 6863 9595	Physical Survey		YP2007M	01/03/2019	
2	Juliana Lee	MT/1034369-002	SLG8350H	AMA AUTOMOTIVE PTE LTD	36 TOH GUAN ROAD EAST #01-36	Melvin / 9017 3393	Physical Survey		SJW7775L	03/03/2019	
3	Jeff Lin	MT/1036403-002	SIH7493D	BP AUTO	48 TOH GUAN ROAD EAST #01-121 ENTERPRISE HUB SINGAPORE 608586	/ 6266 0555	Physical Survey		SJL615U	16/03/2019	

**Please contact workshops.**

Please ack.

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Company
Owner ID:	1196N
<b>Vehicle Details</b>	
Vehicle No.:	YN1675B
Vehicle to be Exported:	No
Intended Deregistration Date:	19 Mar 2019
Vehicle Make:	MITSUBISHI
Vehicle Model:	FK61FMJ1RDEA
Primary Colour:	White
Manufacturing Year:	2010
Engine No.:	6M60148999
Chassis No.:	FK61FMA00154
Maximum Power Output:	-
Open Market Value:	\$57,348.00
Original Registration Date:	03 Dec 2010
First Registration Date:	03 Dec 2010
Transfer Count:	0
Actual ARF Paid:	\$2,868.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	02 Dec 2020
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$30,889.00
COE Rebate Amount:	\$5,259.00
<b>Total Rebate Amount:</b>	<b>\$5,259.00</b>

The information contained herein is correct as at 19 Mar 2019

OK

[> Back to OneMotoring](#)

## Enquire Transfer Fee

Vehicle Details			
Vehicle No. :	YN1675B		
Vehicle Type :	A50 - Goods (Closed) Van/Van Panel (Delivery)		
Vehicle Attachment 1 :	With Power Tailgate		
Vehicle Scheme :	Normal		
Vehicle Make :	MITSUBISHI		
Vehicle Model :	FK61FMJ1RDEA		
Chassis No. :	FK61FMA00154		
Propellant :	Diesel		
Engine No. :	6M60148999		
Engine Capacity :	7545 cc		
Maximum Power Output :	-		
Maximum Laden Weight :	10400 kg		
Unladen Weight :	6020 kg		
Year Of Manufacture :	2010		
Original Registration Date :	03 Dec 2010		
Lifespan Expiry Date :	02 Dec 2030		
COE Category :	C - Goods Vehicle & Bus		
Quota Premium :	\$30,889.00		
COE Expiry Date :	02 Dec 2020		
Road Tax Expiry Date :	02 Dec 2019		
Inspection Due Date :	02 Dec 2019		
Intended Transfer Date :	19 Mar 2019		
CO2 Emission :	-		
CO Emission :	-		
HC Emission :	-		
NOx Emission :	-		
PM Emission :	-		
Late renewal fee(s) will be imposed if road tax / lay up has expired. Please use Enquire Road Tax Payable for fee(s) payable.			
Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.			
Amount Payable			
	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee :	25.00	-	25.00
Total Amount Payable :			25.00

You may print this page for reference.

OK

Print

## Steve Chen (LKK Auto)

---

**From:** sinsheng engineering services <sinsheng1981@gmail.com>  
**Sent:** Thursday, April 11, 2019 11:41 AM  
**To:** Steve Chen (LKK Auto)  
**Subject:** Re: YN1675B Finalize

Yes, confirmed.

*Thank You  
Regards*

*Susan  
Sin Sheng Engineering Services  
3 Tech Park Crescent  
Tuas Tech Park  
Singapore 638129  
Tel: 6863 9595  
Fax: 6863 6477*

On Wed, 10 Apr 2019 at 16:33, Steve Chen (LKK Auto) <[SteveChen@lkkauto.com](mailto:SteveChen@lkkauto.com)> wrote:

Hi Susan,

The above vehicle finalize L/S \$3750. 4 days.

Kindly confirm.

Thanks

Best Regards,

Steve Chen | Assistant Automotive Assessor

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	05/03/2019 20:45
Date Of Accident	01/03/2019 19:00
Exact Location Of Accident	90 ALPS AVE (FEDEX)
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	YN1675B
<b>Insured/Policyholder</b>	
Name Of Registered Owner	GOLDBELL LEASING PTE LTD
Co Reg No	199001196N
Email Address	ISAACNGCL@GOLDBELLCORP.COM
Mobile Phone No	
Alternative Phone No	OFFICE-64942897
<b>Vehicle Particulars</b>	
Manufacturer	MITSUBISHI
Model	FK61FMJ1RDEA
Exact Purpose for which vehicle was being used at time of accident	COMMERCIAL
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE
<b>Insurance Company</b>	
Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	THIRD PARTY
Fleet Policy	YES
Policy Number	29090793
Cover Note Number	
<b>Driver</b>	
Name of Driver	DHATCHANAMOORTHY SELLAMUTHU
Work Permit No	G8470299X
Date Of Birth	21/07/1986
Occupation	OUTDOOR
Date Of Driving Pass	11/06/2012
Driving Experience	6 YEARS AND 8 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-90876204
Fax Number	
Contact Number	
EMail Address	SUGHOTHRA@GMAIL.COM

Address	NA
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	HIT AND RUN / VANDALISM / DAMAGED WHILST PARKED
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

My lorry YN1675B was parked (stationary) at FEDEX (90 ALPS) loading/unloading Bay when vehicle YP2007M reverse & hit onto my front of my lorry YN1675B. No injuries involved. That's all.

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	YP2007M
Vehicle Make/Model/Colour	UD TRUCKS MKB8ELN5AA / WHITE
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	DHILLON JAGTAR
NRIC/Passport Number	S27380061
Contact Number	96492506
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	



## Sketch Plan

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available application by interested parties.
7. By the lodgement of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**  
I understand, acknowledge, agree and consent that:  
(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:  
(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;  
(ii) investigating the accident and/or my claims;  
(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;  
(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or  
(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.  
(collectively the "Purposes")  
(b) all insurers who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and  
(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.


VERIFIED BY AJAX MARS  
REPORTING OFFICER  
MOHD FADZLY BIN ISMAIL

Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre  
Personnel

### Sketch Plan



ACCIDENT STATEMENT (2000 characters)

My lorry YN1675B was parked (stationary) at FEDEX (90 ALPS) loading/unloading Bay when vehicle YP2007M reverse & hit onto my front of my lorry YN1675B. No injuries involved. That's all.

Taxi Voucher No.:

DECLARATION

I/We declare that the above particulars & information provided above are true in every aspect

VERIFIED BY AJAX MARS REPORTING OFFICER -  
MOHD FADZLY BIN ISMAIL



MARS Officer

Registered Owner or Driver's Signature

Job Complete Date/Time

Date/Time:

5 March 2019 at 4:50 PM

5 March 2019 at 4:50 PM

# SIN SHENG ENGINEERING SERVICES

3 TECH PARK CRESCENT

SINGAPORE 638129

Tel No. : 6863-9595 Fax No. : 6863-6477

E-Mail : sinsheng1981@gmail.com

Buss. Reg. No. : 312029/00D

GOLDBELL LEASING PTE LTD

59 SENOKO ROAD

SINGAPORE 758123

Attention : Motor Claim Department

Contact : 6861 0007 Fax No. : 6753 7780

Estimate : ES002782

Date : 18/03/2019

Vehicle Num. : YN1675B

Make/Model : MITSUBISHI FK 61-2010

Chassis/Eng# : FK61FMA00154/6M60148999

Accident Date : 01/03/2019

Claim No. :

Reference : YP2007M

Policy No. : 29090793

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

LIST ITEMS :				
1.	1	FRONT PANEL ✓ DD		3,295.71 2711.52
2.	21	STRIKER FRONT PANEL LATCH ✓ NH RH ✓ DT	125.50	254.00 125.50
3.	2	LATCH, FR PANEL OPENER ✓ NH	265.20	530.40 X
4.	1	CABLE, FR PANEL OPENER ✓ NH		198.20 X
5.	1	CORNER PANEL, RHS ✓ RPT		453.32 X
6.	1	FRONT GRILLE ✓ CRU		728.24 ✓
7.	1	MITSUBISHI LOGO ✓ NEC		95.50 ✓
8.	2	HINGE FR PANEL ✓ NH	145.50	291.00 X
9.	1	SIGNAL LAMP, RHS ✓ R		280.80 X
10.	1	RADIATOR SPARE TANK ✓ CRU		293.50 ✓
List TotalS\$ :			3954.26	6,417.67
25.00% Discount S\$ :			- 25%	1,604.42
			2965.69	4,813.25

## LABOUR :

TO PANEL BEAT/REPAIR FR BODY

TO DISMANTLE/REPLACE ABOVEMENTIONED PARTS

, SPRAY PAINTING

TO APPLY TUFF KOTE

300 750.00

50550 750.00

90 100.00

870

CONTINUE / ...

P - 2965.69  
 L - 870  
 Supp - 839.31  
 4675  
 L/S - 3740  
 = 3750

# SIN SHENG ENGINEERING SERVICES

3 TECH PARK CRESCENT

SINGAPORE 638129

Tel No. : 6863-9595 Fax No. : 6863-6477

E-Mail : sinsheng1981@gmail.com

Buss. Reg. No. : 312029/00D

GOLDBELL LEASING PTE LTD

59 SENOKO ROAD

SINGAPORE 758123

Attention : Motor Claim Department

Contact : 6861 0007 Fax No. : 6753 7780

Estimate : ES002782

Date : 18/03/2019

Vehicle Num. : YN1675B

Make/Model : MITSUBISHI FK 61-2010

Chassis/Eng# : FK61FMA00154/6M60148999

Accident Date : 01/03/2019

Claim No. :

Reference : YP2007M

Policy No. : 29090793

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

LOSS OF USE : 5 DAYS @ \$ 180/DAY

*Exclude*

Labour Total S\$ :

1,600.00

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

*7252.56*

Total S\$ : 6,413.25

=====

SIN SHENG ENGINEERING SERVICES

**LKK Auto Consultants hence notify the Repairer of the following:**

- To reserve damaged parts (third reserve)
- To display damaged parts (third reserve)
- Parts prices are subject to confirmation
- Third party survey is on a "Warranty/Workbook" basis
- No legal responsibility (third reserve)
- Supplementary terms and conditions and is subject to final approval (Insurance Company)

**Acknowledged by Repairer:**

**Signature:**

**Date:**

# SIN SHENG ENGINEERING SERVICES

3 TECH PARK CRESCENT

SINGAPORE 638129

Tel No. : 6863-9595 Fax No. : 6863-6477

E-Mail : sinsheng1981@gmail.com

Buss. Reg. No. : 312029/00D

GOLDBELL LEASING PTE LTD

59 SENOKO ROAD

SINGAPORE 758123

Attention : Motor Claim Department

Contact : 6861 0007 Fax No. : 6753 7780

Supplementary Estimate : ES002813

Date : 10/04/2019

Vehicle Num. : YN1675B

Make/Model : MITSUBISHI FK 61-2010

Chassis/Eng# : FK61FMA00154/6M60148999

Accident Date : 01/03/2019

Claim No. :

Reference : YP2007M

Policy No. : 29090793

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

1.	1	LIST ITEMS : CORNER PANEL (RH) DR A		1,119.08
		List TotalS\$ :		1,119.08
		25.00% Discount S\$ :		279.77
				839.31

Total S\$ : 839.31

*Susan*

SIN SHENG ENGINEERING SERVICES


**GOLDBELL**  
**ENGINEERING**

Industrial Vehicles.  
 20,000 Served. And Counting.

**GOLDBELL ENGINEERING PTE LTD**  
 Main Office: 8 Tuas Avenue 18 Singapore 638892 Tel: 6861 0007 Fax: 6861 3676  
 Finance: 8 Tuas Avenue 18 Singapore 638892 Tel: 6861 0007 Fax: 6862 3500  
 Website: www.goldbell.com.sg  
 Co. Reg. No.: 19803963C

### SALES QUOTATION

TO: SIN SHENG ENGINEERING SERVICES  
 NO. 3 TECH PARK CRESCENT TUAS TECH PARK,  
 SINGAPORE 638129

ATTN: MS ENRICA WONG

SALES QUOTATION NO GBE-005600  
 DATE 10 April 2019  
 VALIDITY DATE 10 May 2019  
 CUSTOMER REFERENCE YN1675B  
 TERMS OF PAYMENT NETT 30 DAYS  
 CURRENCY SGD  
 SERVED BY JACQUELINE LEE

S/N	PART CODE	DESCRIPTION	HS CODE	QTY	UOM	STK	WEIGHT	UNIT PRICE	PRICE AFTER DISCOUNT	AMOUNT
1	MK547432	PANEL, FR CORN(NATURALWHIT		1	PCS	N	1.96	1,119.08	1,119.0800	1,119.08
2	MK703312	PANEL ASSY,FR OSTA DOM FK6		1	PCS	N	3.20	2,711.52	2,711.5200	2,711.52
TOTAL WEIGHT							5.16	SUB AMOUNT		3,830.60
GST (7%)										268.14
GRAND TOTAL										4,098.74

REMARKS:

Amount: Singapore Dollar Four Thousand Ninety Eight and Seventy Four cents only  
 Stock and pricing are depend on availability.

**bizSAFE**  
 STAR



Certificate No: AJA(13)17/Q1243

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

**DAMAGE ASSESSMENT REPORT**

NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: CS/INC19004935/Esd3e2

73 BRAS BASAH ROAD  
#05-01 NTUC TRADE UNION HOUSESINGAPORE  
189556

Date: 23-04-2019



ATTN : CORINNE HOO

Code: INC

**1. Policy Particulars :- THIRD PARTY CLAIM**

Insured Veh.	YP 2007M	Veh. Inspected	YN 1675B
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1034290-002	Excess (\$)	0.00
Assign From	CYNTHIA ANG	Assign Date	19/03/2019

**2. Vehicle Particulars & Condition**

Make & Model	mitsubishi FK61FMJ1RDEA	c.c	7545
Engine No.	HIDDEN	Year of Reg.	2010
Chassis No.	FK61FMA00154	Colour	WHITE
Odometer	267993 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	FAIR		

**3. Conditions of Tyres**

	Size	Make	Balance
R/H Front Tyre	8.25 R16	AUSTONE	6 mm
L/H Front Tyre	8.25 R16	AUSTONE	6 mm
R/H Rear Tyre	8.25 R16	AUSTONE	6 mm
L/H Rear Tyre	8.25 R16	AUSTONE	6 mm

**4. Description of Damages**

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.
---

**5. General Information**

Accident Date	01/03/2019	Inspect Date / Time	19/03/2019 ( 11:35 AM )
Survey held at	SIN SHENG ENGINEERING SERVICES 3 TECH PARK CRESCENT TUAS TECK PARK SINGAPORE 638129		

**5a. Remarks**

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

**5b. Estimate Days of Repair**

ESTIMATED NORMAL PERIOD FOR REPAIR:	<b>4 Working Days</b>
-------------------------------------	-----------------------





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. YN 1675B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	FRONT PANEL	DENTED	3,295.71	2,711.52
2	STRIKER FRONT PANEL LATCH @\$125.50	O/S BENT	251.00	125.50
2	LATCH, FR PANEL OPENER @\$265.20	NOT NECESSARY	530.40	-
1	CABLE, FR PANEL OPENER	NOT NECESSARY	198.20	-
1	CORNER PANEL, RHS	REPEATED	453.32	-
1	FRONT GRILLE	CRUSHED	728.24	728.24
1	MITSUBISHI LOGO	NECESSARY	95.50	95.50
2	HINGE FR PANEL @\$145.50	NOT NECESSARY	291.00	-
1	SIGNAL LAMP, RHS	TO REPAIR SEE LABOUR	280.80	-
1	RADIATOR SPARE TANK		293.50	293.50
1	CORNER PANEL (RH) (ADDITIONAL)	BROKEN	1,119.08	1,119.08
	LESS 25% DISCOUNT		-1,884.19	-1,268.34
			5,652.56	3,805.00
	<b><u>LABOUR</u></b>			
	TO PANEL BEAT / REPAIR FR BODY.		750.00	300.00
	TO DISMANTLE / REPLACE ABOVEMENTIONED PARTS.			
	INCLUSIVE OF THE REPAIR OF SIGNAL LAMP, RHS.			
	SPRAY PAINTING.		750.00	550.00
	TO APPLY TUFF KOTE.		100.00	20.00
			1,600.00	870.00
	<b>GRAND TOTAL</b>		<b>7,252.56</b>	<b>4,675.00</b>
	<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)</b>			<b>3,750.00</b>

Report Ref No. CS/INC19004935/Esd3e2

CHEN TSUE YEE

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons), B.Bus, MBA, PEng, PE,  
MInstAEA, MASME, MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.