



Case Details

Case Reference Number : BUS/11/18/5016
 Type of Repair : Accident Repair
 Vehicle Registration Number : SMB1443J

Company Type : SMRT Buses Ltd
 Estimation ID : EST-6127-ID
 Assigned By : Eileen Bay Yee Ling

Insurance Company Name : AIG Asia Pacific Insurance Pte Ltd
 Accident Date and Time : 10/11/2018 12:37 PM
 Vehicle Age(In Months) : 52

Documents / Photographs

[View Documents / Photographs](#)

Total Documents: 1

Estimation Details

Spare Part's Cost Detail

SMRT Recommendation										Surveyor Approval				
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
Total Spare Part Cost										0.00	Surveyor Total		0.00	
Lump Sum Discount (%)										0.00	Lump Sum Dis (%)		0	
Final Spare Part Cost										0.00	Final Sur Total		0.00	

Labour's Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPAIR REAR PORTION RH	1,060.00	530	
Total:			1,060.00	530.00	

Spray Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO PUTTY & RESPRAY	878.00	708	
Total:			878.00	708.00	

Other Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
Total:			0.00	0.00	

Summary

	Estimator Assessment(\$)	Surveyor Assessment(\$)
Total Spare Part Detail	0.00	0.00
Total Labour Cost	1,060.00	530.00
Total Spray Painting	878.00	708.00
Other	0.00	0.00
Overall Total	1,938.00	1,238.00
Lump Sum Repair Option	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Lump Sum Total	0.00	1,250.00
Surveyor Approved Amount		1,250.00
No of Repair Days*	3	2
Remarks	-	L/S Repair . photo after pain!
Surveyor Name		Hwee je

Signature	Estimator Assessment(\$)	Surveyor Assessment(\$)
		 <input type="button" value="Save"/> <input type="button" value="Clear"/>
Survey Date	18/03/2019	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: