

INS CASE OWNER:

CC 4, Assm 1900

4948, K1 pasg

LAA: IDAC

104931

Surveyor:

Karl

DOI:

ASSIGNMENT

15/4/19

Date / Time

19/3/2019

Registered in Motor:

Pre-assign / CCU / FTE



Insured Vehicle No.:

SJH 580 G

Name of Insured:

WAT PUN UN PABAYAN

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A.:

26/2/19

Is driver the owner?

(YES / NO)

Nature of Accident:

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No

SJPS816C

SJH 580 G

SOB 80062



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date / Time

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

SS

days) Reduction:

%

Email ☐ Call ☐

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email ☐ Call ☐

Final Liability:

%

Agreed / Assessed) BOLA S/N No.:

If NO or B 28, Ass. Lia

Repair Cost:

SS

Loss of Rental (LOR):

SS

(2

days)

Loss of Use (LOU):

SS

(\$

x

days)

Loss of Income (LOI):

SS

(\$

x

days)

LOR only ☐ LOU only ☐LOR + LOU ☐LOR + LOI ☐

[Tick only one]

GIA/LTA Search

SS

Medical:

SS

Disbursement:

SS

(e.g. Tow/ Independent)

Legal Cost

SS

Total:

SS

Global Sum SS: 3070-W

FINAL PAYMENT

Date/Time:

Confirm with:

Email ☐ Call ☐

Payee 1:

SS

Name 1:

Mara Automotive Rec Tel

Payee 2: (Strike if N.A.)

SS

Name 2:

Payee 3: (Strike if N.A.)

SS

Name 3:

1) Claim status: Non-Report/Reject/Private Settle

2) Report Format:


3) Survey fee:

1/7/19

B 35000

ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV  
 To inspect Vehicle No: **SDB 80062**  
 at Workshop m/s: **MOVA**  
 of: **BUKIT MERAH**  
 Insured: **ASA (AXA)**  
 Policy No: \_\_\_\_\_  
 Claims No: \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_  
 (Policy Condition)  
 Remark: The veh had commenced its repair at the time of inspection.  
 Bal. or Market Value: \_\_\_\_\_  
 IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No  
 GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No  
 Est. Repairs: **2** days Res.: Yes or No  
 Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No  
 CA / REV / REP. / 24 HRS  
 Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT



Veh No: **SDB 80062** Yr Regn: **2016 / OCT**  
 Type: **Car** / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
 Truck / Trailer or  
 Make: **B.M.W 528I A** C.C: **1997**  
 Colour: **Grey** A/C: Insured / Std / NI / NA  
 Sp. Reading: **43872** TIRadio: Insured / Std / NI / NA  
 Eng/No: \_\_\_\_\_  
 C/No: **WBA 5A 520 406 390 313**  
 Gen. Cond: Good / Fair / Poor / Burnt  
 Steering: **Order** / Jammed / Leaked / Burnt or  
 Brake: **Order** / Jammed / Leaked / Burnt or  
 Modi: **Nil** / S/Rim / STD A/Rim or  
 Tyre Size: F: **245/40R17**  
 R: \_\_\_\_\_  
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
 TOYO / YOKO or  
 Front: **6** mm R/Bal: **6** mm  
 L/Bal: **6** mm U/Bal: **6** mm  
 D.O.A: **26/02/19** D.O.L: **15/04/19**  
 Survey held at: **MOVA CBM**  
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or  
**Rear N/S**  
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<b>MV 138K</b>
	<b>PIP # 2611.09 (Ref # 0 / 07)</b>

Date/Time, File Pass to? ☐ : Preli. Report ☐ : Final Report  
 1) \_\_\_\_\_  
 Date/Time, File Return to? \_\_\_\_\_  
 2) \_\_\_\_\_  
 Report Format : \_\_\_\_\_  
 Lump Sum / I.B.I: (\$) \_\_\_\_\_

Days Of Repair: \_\_\_\_\_  
 Resurvey No. of Trip: \_\_\_\_\_

Add Fee: ☐ Site Insp (\$) ☐ Interview (\$) ☐ Tech. Insp (\$) ☐ Weekend (\$)

Survey Fee: \_\_\_\_\_  
 Transportation: \_\_\_\_\_  
 ) S + RS, SA \_\_\_\_\_  
 ) Photos \_\_\_\_\_  
 ) Others \_\_\_\_\_  
 ) \_\_\_\_\_  
 TOTAL \_\_\_\_\_

## Nivitha (LKK Auto)

---

**From:** Mei Kwan (LKKAuto) <Meikwan@lkkauto.com>  
**Sent:** Tuesday, 19 March 2019 11:41 AM  
**To:** assignments  
**Subject:** FW: TP CLAIMS - SDB8006Z AGAINST SJH580G DOA 26/02/2019 AT UPPER CHANGI ROAD EAST  
**Attachments:** RPT.pdf; EST.pdf

12:12pm @ 19/3/19

Nitha  
vehicle not in.

Hi team

*Kindly assist. TP smart.*

Thank you.

Best Regards,

Mei Kwan | Admin

**LKK Auto Consultants Pte Ltd**

Phone: 6366 0055 | email: [MeiKwan@lkkauto.com](mailto:MeiKwan@lkkauto.com) | fax: 67414108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Nitha <nitha@mova.com.sg>  
**Sent:** Monday, 18 March, 2019 6:52 PM  
**To:** SG AXA Insurance SM AXA SGP - Motor Survey <motor.survey@axa.com.sg>  
**Cc:** 'Keong' <keong@mova.com.sg>; suann@mova.com.sg  
**Subject:** TP CLAIMS - SDB8006Z AGAINST SJH580G DOA 26/02/2019 AT UPPER CHANGI ROAD EAST

Dear All,

Kindly assist to assign surveyor and revert liability for the above mention case.

Thank you.

Best Regards,

Nitha

Claims Officer

Mova Automotive Pte Ltd

Tel: 6272 3892 Fax: 6270 8314



**MOVA Automotive Pte Ltd**  
**Blk 1008, Bukit Merah Lane**  
**3, #01-04/06/08. Singapore**  
**159722**

**Claim Reference:**  
**Assessment number: ck133496**  
**Version: 1810**  
**Date calculated: 03/18/2019 05:47 PM**

**Full Report**  
**Registration: SDB8006Z**  
**Printed: 18/03/2019 5:47 PM**

---

**Summary Information**

<b>Claim</b>			
Location:	Singapore (SG)	Work Provider:	AXA Insurance Pte Ltd
Printed by:	GOH CHAI HOCK	Currency:	SGD
Claim Reference:		Date of Incident:	2019-02-26
Estimated Repair Time:		Hire Car Start:	
Actual Repair Days:		Hire Car End:	

---

**Vehicle Details**

**Vehicle**

Manufacturer:	BMW
Model:	5 SERIES F10
Sub Model:	528 I
Model Sheet Number:	01 4A 02
Registration:	SDB8006Z
VIN number:	WBA5A52040G390313
Odometer:	

**Model Specs**

FROM 11/2015	EDITION SPORT	THROUGH LOAD SYSTEM	AIR CON AUTO 2-ZONES
COMFORT ACCESS SYST	DIP REAR VIEW MIRROR	WHEEL 8.5/9J X19 ALU	NAVIG SYSTEM PROFESS
HI-FI SPEAKER SYSTEM	LED HEADLAMP	LED FOG LAMPS	HIGH BEAM ASSISTANT
INTER LIGHT AMBIENCE	HEADLAMP WASHERS	DAKOTA LEATHER TRIM	FRT SPORT SEATS
MULTIFUNCT DISPLAY	ELEC/SEAT ADJ MEMORY	AUTO TAILGATE CONTR	HEAD-UP DISPLAY
DIP REAR VIEW MIRROR	FRT/RR PARK DIST CON	REARVIEW CAMERA	2.0 LTR 180KW
M LEATHER STRG WHEEL	8-GEAR AUTOMATIC	245/40-/275/35 YR 19	WINDOW FRAME BLACK
INT MOULDING BLACK	TWO COAT METALLIC	TYRE W/FLAT RUNNING	

**MOVA Automotive Pte Ltd**  
**Blk 1008, Bukit Merah Lane**  
**3, #01-04/06/08. Singapore**  
**159722**

Claim Reference:  
 Assessment number: ck133496  
 Version: 1810  
 Date calculated: 03/18/2019 05:47 PM

**Full Report**  
**Registration: SDB8006Z**  
**Printed: 18/03/2019 5:47 PM**


## Vehicle Condition

### Vehicle Status

Pre-Accident Damage:  
 Date of Inspection:

### Damage Areas

All ☐  
 Underbody ☐



## Labour

Code	Description	Time Base 12 WU/h	Price = 45.00 SGD/h	
			WU	Price SGD
NO NUMBER	ADD/TIME FOR MAIN WORK		1.0	3.75
51 12 656	R + R REAR BUMPER		6.0	22.50
51 12 657	RENEW REAR BUMPER TRIM (BUMPER REMOVED)		3.0	11.25
NO NUMBER	R + R REAR LOWER BUMPER GUIDE		3.0	11.25
66 20 602	ADD/WORK PARK DISTANCE CONTROL		2.0	7.50
2931	BOOTLID/TAILGATE REPAIR		10.0*	37.50
2611	L/R REFLECTOR CHECK			
2643	REAR BUMPER CARRIER CHECK		10.0*	37.50
2644	RR BUMPER CTR GUIDE CHECK			
<b>Labour Cost</b>		<b>Hrs</b>	<b>WU</b>	
<b>Panel / Mechanical Labour</b>		<b>2.90</b>	<b>35.0</b>	<b>131.25</b>
<b>Total of Labour</b>				<b>131.25</b>

**MOVA Automotive Pte Ltd**  
**Blk 1008, Bukit Merah Lane**  
**3, #01-04/06/08. Singapore**  
**159722**

Claim Reference:  
 Assessment number: ck133496  
 Version: 1810  
 Date calculated: 03/18/2019 05:47 PM

Full Report  
 Registration: SDB8006Z  
 Printed: 18/03/2019 5:47 PM

**Paint**

Paint Work	SYSTEM AZT	Time Basis 10WU/h	
Code	Description - TWO COAT METALLIC	WU	Price SGD
	REAR BUMPER COVER NEW PART PAINT K1R	14.0	
	BOOTLID/TAILGATE REPAIR PAINTING <50%	19.0	
	L/OUT U-SONIC SENDER SURFACE PAINT PLAST.	3.0	
	R/OUT U-SONIC SENDER SURFACE PAINT PLAST.	3.0	
	R/INN U-SONIC SENDER SURFACE PAINT PLAST.	3.0	
	L/R SIDE PANEL SURFACE PAINT	7.0	
	R/R SIDE PANEL SURFACE PAINT	7.0	

**Paint Material Per Part**

Code	Description	Price SGD
2583	REAR BUMPER COVER NEW PART PAINT K1R	73.31
2931	BOOTLID/TAILGATE REPAIR PAINTING <50%	35.21
2671	L/OUT U-SONIC SENDER SURFACE PAINT PLAST.	0.37
2672	R/OUT U-SONIC SENDER SURFACE PAINT PLAST.	0.37
2674	R/INN U-SONIC SENDER SURFACE PAINT PLAST.	0.37
3481	L/R SIDE PANEL SURFACE PAINT	18.18
3482	R/R SIDE PANEL SURFACE PAINT	18.18

**Labour Cost - Paint**

Factor	45.00 SGD/h	Hrs	WU	Price SGD
Time Paint			56.0	
Preparation Main Work Metal		2.10	21.0	94.50
Preparation Comp. Work Plastic		0.50	5.0	22.50
<b>Total</b>	<b>10 WU/h</b>	<b>8.20</b>	<b>82.0</b>	<b>369.00</b>
<b>Total</b>	<b>12 WU/h</b>	<b>8.20</b>	<b>98.4</b>	<b>369.00</b>

**Material Cost - Paint**

	Price SGD
New Part Painting - Plastic K1R	73.31
Repair Painting	35.21
Surface-/Blend Paint	36.36
Surface Painting Plastic	1.11
Material-constant Metal	18.10
Material-constant Plastic	9.00
<b>Total</b>	<b>173.09</b>

**MOVA Automotive Pte Ltd**  
**Blk 1008, Bukit Merah Lane**  
**3, #01-04/06/08. Singapore**  
**159722**

Claim Reference:  
 Assessment number: ck133496  
 Version: 1810  
 Date calculated: 03/18/2019 05:47 PM

Full Report  
 Registration: SDB8006Z  
 Printed: 18/03/2019 5:47 PM

**Spare Parts**

				prices as at 2018-09-10/02
Code	Description	Part Number	Supplier	Price SGD
2583	REAR BUMPER COVER	51 12 7 332 764	CRA	1,400.00
2624	CTR LWR BUMPER GUIDE	51 12 7 184 765	CRA	75.00
2650	REAR BUMPER MNTG KIT	51 12 2 452 063	NR	25.00
2673	L/INN U-SONIC SENDER	66 20 9 233 044	NR	185.00
f: OEM Parts				0.00
n: Non-OEM Parts				1,685.00
u: Used parts				252.75
<b>Savings</b>				
<b>Subtotal</b>				
<b>Addition(+15.00%)</b>				
<b>Total</b>				<b>1,937.75</b>

**Final Calculation**

	SGD	SGD
<b>Parts</b>	1,685.00	
Addition(+15.00%)	252.75	
<b>Total Parts</b>		<b>1,937.75</b>
<b>Labour Time Base 12 WU/h</b>		
Total 35.0 WU X 45.00 SGD/h	131.25	
<b>Total of Labour</b>		<b>131.25</b>
<b>Paint Work Time Base 10 WU/h</b>		
Labour Cost 82.0 WU X 45.00 SGD/h	369.00	
Material Cost	173.09	
<b>Total Paint Including Material</b>		<b>542.09</b>
<b>Repair Cost Excludes GST</b>		<b>2,611.09</b>
GST (+7.00%)		182.78
<b>Repair Cost Included GST</b>		<b>2,793.87</b>

**MOVA Automotive Pte Ltd**  
**Blk 1008, Bukit Merah Lane**  
**3, #01-04/06/08. Singapore**  
**159722**

Claim Reference:  
Assessment number: ck133496  
Version: 1810  
Date calculated: 03/18/2019 05:47 PM

Full Report  
Registration: SDB8006Z  
Printed: 18/03/2019 5:47 PM

**Comments**

\* - USER SUPPLIED DATA  
NN - NO MANUFACTURERS CODE EXISTS  
) - WU PARTIAL INCL IN OTHER POSITIONS

Let Auto Confirm the Repairs:

- To receive below after repair
- To display damaged parts
- Parts prices are subject to change
- Third party survey is on a "Without Prejudice" basis
- No illegal modifications allowed
- Supplementary charges subject to final approval from insurance Company

Acknowledged by Repairer:

Signature:

Date:

Let Auto Confirm the Repairs:

- To receive below after repair
- To display damaged parts
- Parts prices are subject to change
- Third party survey is on a "Without Prejudice" basis
- No illegal modifications allowed
- Supplementary charges subject to final approval from insurance Company

Acknowledged by Repairer:

Signature:

Date:

4p 90000068  
p/p or lump sum?  
15/04/19 @ 1220  
Ray after or by paint?  
2 days



**MOVA Automotive Pte Ltd**  
**Blk 1008, Bukit Merah Lane**  
**3, #01-04/06/08. Singapore**  
**159722**

**Claim Reference:**

**Assessment number: ck133496**

**Version: 1810**

**Date calculated: 03/18/2019 05:47 PM**

**Full Report**

**Registration: SDB8006Z**

**Printed: 18/03/2019 5:47 PM**

---

### Summary Information

#### Claim

Location:	Singapore (SG)	Work Provider:	AXA Insurance Pte Ltd
Printed by:	GOH CHAI HOCK	Currency:	SGD
Claim Reference:		Date of Incident:	2019-02-26
Estimated Repair Time:		Hire Car Start:	
Actual Repair Days:		Hire Car End:	

---

### Vehicle Details

#### Vehicle

Manufacturer:	BMW
Model:	5 SERIES F10
Sub Model:	528 I
Model Sheet Number:	01 4A 02
Registration:	SDB8006Z
VIN number:	WBA5A52040G390313
Odometer:	

#### Model Specs

FROM 11/2015	EDITION SPORT	THROUGH LOAD SYSTEM	AIR CON AUTO 2-ZONES
COMFORT ACCESS SYST	DIP REAR VIEW MIRROR	WHEEL 8.5/9J X19 ALU	NAVIG SYSTEM PROFESS
HI-FI SPEAKER SYSTEM	LED HEADLAMP	LED FOG LAMPS	HIGH BEAM ASSISTANT
INTER LIGHT AMBIENCE	HEADLAMP WASHERS	DAKOTA LEATHER TRIM	FRT SPORT SEATS
MULTIFUNCT DISPLAY	ELEC/SEAT ADJ MEMORY	AUTO TAILGATE CONTR	HEAD-UP DISPLAY
DIP REAR VIEW MIRROR	FRT/RR PARK DIST CON	REARVIEW CAMERA	2.0 LTR 180KW
M LEATHER STRG WHEEL	8-GEAR AUTOMATIC	245/40-/275/35 YR 19	WINDOW FRAME BLACK
INT MOULDING BLACK	TWO COAT METALLIC	TYRE W/FLAT RUNNING	

**MOVA Automotive Pte Ltd**  
**Blk 1008, Bukit Merah Lane**  
**3, #01-04/06/08. Singapore**  
**159722**

Claim Reference:  
 Assessment number: ck133496  
 Version: 1810  
 Date calculated: 03/18/2019 05:47 PM

Full Report  
 Registration: SDB8006Z  
 Printed: 18/03/2019 5:47 PM

## Vehicle Condition


### Vehicle Status

Pre-Accident Damage:

Date of Inspection:

### Damage Areas

All ☐  
 Underbody ☐



## Labour

Code	Description	Time Base 12 WU/h	Price = 45.00 SGD/h	
			WU	Price SGD
NO NUMBER	ADD/TIME FOR MAIN WORK		1.0	3.75
51 12 656	R + R REAR BUMPER		6.0	22.50
51 12 657	RENEW REAR BUMPER TRIM (BUMPER REMOVED)		3.0	11.25
NO NUMBER	R + R REAR LOWER BUMPER GUIDE		3.0	11.25
66 20 602	ADD/WORK PARK DISTANCE CONTROL		2.0	7.50
2931	BOOTLID/TAILGATE REPAIR		10.0*	37.50
2611	L/R REFLECTOR CHECK			
2643	REAR BUMPER CARRIER CHECK		10.0*	37.50
2644	RR BUMPER CTR GUIDE CHECK			
<b>Labour Cost</b>			<b>Hrs</b>	<b>WU</b>
<b>Panel / Mechanical Labour</b>			<b>2.90</b>	<b>35.0</b>
<b>Total of Labour</b>				<b>131.25</b>

**MOVA Automotive Pte Ltd**  
**Blk 1008, Bukit Merah Lane**  
**3, #01-04/06/08. Singapore**  
**159722**

Claim Reference:

Assessment number: ck133496

Version: 1810

Date calculated: 03/18/2019 05:47 PM

Full Report

Registration: SDB8006Z

Printed: 18/03/2019 5:47 PM

**Paint**

Paint Work	SYSTEM AZT	Time Basis 10WU/h
Code	Description - TWO COAT METALLIC	WU Price SGD
	REAR BUMPER COVER NEW PART PAINT K1R	14.0
	BOOTLID/TAILGATE REPAIR PAINTING <50%	19.0
	L/OUT U-SONIC SENDER SURFACE PAINT PLAST.	3.0
	R/OUT U-SONIC SENDER SURFACE PAINT PLAST.	3.0
	R/INN U-SONIC SENDER SURFACE PAINT PLAST.	3.0
	L/R SIDE PANEL SURFACE PAINT	7.0
	R/R SIDE PANEL SURFACE PAINT	7.0

**Paint Material Per Part**

Code	Description	Price SGD
2583	REAR BUMPER COVER NEW PART PAINT K1R	73.31
2931	BOOTLID/TAILGATE REPAIR PAINTING <50%	35.21
2671	L/OUT U-SONIC SENDER SURFACE PAINT PLAST.	0.37
2672	R/OUT U-SONIC SENDER SURFACE PAINT PLAST.	0.37
2674	R/INN U-SONIC SENDER SURFACE PAINT PLAST.	0.37
3481	L/R SIDE PANEL SURFACE PAINT	18.18
3482	R/R SIDE PANEL SURFACE PAINT	18.18

**Labour Cost - Paint**

Factor	45.00 SGD/h	Hrs	WU	Price SGD
Time Paint			56.0	
Preparation Main Work Metal		2.10	21.0	94.50
Preparation Comp. Work Plastic		0.50	5.0	22.50
<b>Total</b>	<b>10 WU/h</b>	<b>8.20</b>	<b>82.0</b>	<b>369.00</b>
<b>Total</b>	<b>12 WU/h</b>	<b>8.20</b>	<b>98.4</b>	<b>369.00</b>

**Material Cost - Paint**

	Price SGD
New Part Painting - Plastic K1R	73.31
Repair Painting	35.21
Surface-/Blend Paint	36.36
Surface Painting Plastic	1.11
Material-constant Metal	18.10
Material-constant Plastic	9.00
<b>Total</b>	<b>173.09</b>

**MOV Automotive Pte Ltd**  
**Blk 1 08, Bukit Merah Lane**  
**3, #0 -04/06/08. Singapore**  
**159722**

Claim Reference:  
 Assessment number: ck133496  
 Version: 1810  
 Date calculated: 03/18/2019 05:47 PM

Full Report  
 Registration: SDB8006Z  
 Printed: 18/03/2019 5:47 PM

### Spare Parts

				prices as at 2018-09-10/02
Code	Description	Part Number	Supplier	Price SGD
2583	REAR BUMPER COVER	51 12 7 332 764	CRA	1,400.00 ✓
2624	CTR LWR BUMPER GUIDE	51 12 7 184 765	7.04	75.00 ✓
2650	REAR BUMPER MNTG KIT	51 12 2 452 063	7.04	25.00 ✓
2673	L/INN U-SONIC SENDER	66 20 9 233 044	7.04	185.00 ✓
f: OEM Parts	Savings			0.00
n: Non-OEM Parts	Subtotal			1,685.00
u: Used parts	Addition(+15.00%)			252.75
	Total			1,937.75

### Final Calculation

	SGD	SGD
Parts		
Addition(+15.00%)	1,685.00	
Total Parts	252.75	1,937.75
Labour Time Base 12 WU/h		
Total 35.0 WU X 45.00 SGD/h		
Total of Labour	131.25	131.25
Paint Work Time Base 10 WU/h		
Labour Cost 82.0 WU X 45.00 SGD/h		
Material Cost	369.00	
Total Paint Including Material	173.09	542.09
Repair Cost Excludes GST		2,611.09
GST (+7.00%)		182.78
Repair Cost Included GST		2,793.87

*16/04/19*

*COR \$2611.09*

**MOVA Automotive Pte Ltd**  
**Blk 1008, Bukit Merah Lane**  
**3, #01-04/06/08. Singapore**  
**159722**

Claim Reference:

Assessment number: ck133496

Version: 1810

Date calculated: 03/18/2019 05:47 PM

**Full Report**

**Registration: SDB8006Z**

**Printed: 18/03/2019 5:47 PM**

**Comments**

\* - USER SUPPLIED DATA

NN - NO MANUFACTURERS CODE EXISTS

) - WU PARTIAL INCL IN OTHER POSITIONS

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

*John*  
*4p 9000068*  
*7/p or lump sum?*  
*18/03/19 @ 1220*  
*Resy after or by paint?*  
*2 days*  
*COR \$2611.09*

**TAX INVOICE**

INVOICE NO. **8143999**

DATE	15/04/2019	PAGE	1
TERM	30 Days Net	SALESMAN	Alan Tan
CUSTOMER REF.	SDB8006Z	OUR REF.	58972

ROUTE  
IRBM1

ACCOUNT NUMBER: MOVAAUT3 TIME:14:22  
 MOVA AUTOMOTIVE PTE. LTD  
 BLK 1008, BUKIT MERAH  
 LANE 3, #01-08,  
 SINGAPORE 159722  
 Telephone No : 62723892

DELIVER TO :

MOVA AUTOMOTIVE PTE. LTD  
 BLK 1008, BUKIT MERAH  
 LANE 3, #01-51  
 SINGAPORE 159722



PART NO.	PARTICULARS	LOC	QUANTITY	UNIT PRICE	AMOUNT
1 BW51 12 7 332 764	REAR BUMPER PDC	6H-2C	1 PC	1,400.00	1,400.00
2 BW66 20 9 270 495	PDC SENSOR	1C-04G	1 PC	185.00	185.00
3 BW51 12 7 184 765	GUIDE RR BUMPER BOTTOM	6D-1B	1 PC	75.00	75.00
4 BW51 16 1 881 149	RIVET	1D-04F	10 PCS	2.50	25.00
*GOODS SOLD ARE NOT RETURNABLE. *OVERDUE ACCOUNTS SHALL BEAR INTEREST AT UOB'S PREVALENT LENDING RATE *CASH INVOICE MUST BE PAID WITHIN 7 DAYS FROM DATE OF INVOICE.					TOTAL SIN 1,685.00 ADD GST 7% 117.95 AMOUNT DUE 5IN 1,802.95

Payment via telegraphic transfer to  
 Name of Bank: United Overseas Bank  
 Account Name: Min Ghee Auto Pte Ltd  
 Branch Code: 046  
 Account No.: 503-309-511-3  
 \*Please send a screen shot of your payment/transfer confirmation to  
 account@minghee.com

Exclusive Distributor  
**HDK**  
 Stockists



SIGN & COMPANY'S STAMP

DATE

ALL CHEQUES MUST BE MADE PAYABLE TO  
 MIN GHEE AUTO PTE. LTD.

For MIN GHEE AUTO PTE. LTD.

## Hsiao Tong (LKKAUTO)

---

**From:** Hsiao Tong (LKKAUTO)  
**Sent:** Sunday, 24 March 2019 11:33 AM  
**To:** AVRIL HO  
**Cc:** suann@nova.com.sg; Admin A; assignments  
**Subject:** Re: ACCIDENT INVOLVING SDB8006Z & SJH580G \*LKK REF: CC4/ASM19004947/pa3

### Without Prejudice

Dear Sirs/Mdm,

We refer to the above matter.

Please be informed that basing on the accident statements submitted by both parties, the liability is clear and shall proceed with direct settlement for the above mentioned case.

Please note that this e-mail is on without prejudice basis which does not amount to an authorisation of repair to your client's vehicle.

The final repair cost is subjected to the consistency of the damages according to the nature of the accident.

And the days of LOU/ LOR will be based on the number of days of repair as recommended by our surveyor.

Please note that all finalisation subject insurer's approval.

**\*\*Kindly arrange for survey.**

"Please note that our proposal and correspondence with you is strictly on a without prejudice basis and should not be construed as an admission of liability on our part and/or that of our policyholder and/or the authorised driver. The terms of our without prejudice engagement should not be disclosed in any other related matter(s) in respect of this accident nor should it be binding in any other related claims."

Best Regards,  
**Hsiao Tong, Chew** | Case Handler  
**LKK Auto Consultants Pte Ltd**  
Phone: 6742-3197 | email: [chewht@lkkauto.com](mailto:chewht@lkkauto.com) | fax: 6741-4108  
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** AVRIL HO <[avril@nova.com.sg](mailto:avril@nova.com.sg)>  
**Sent:** Friday, 22 March 2019 6:25 PM  
**To:** Hsiao Tong (LKKAUTO)  
**Cc:** suann@nova.com.sg  
**Subject:** RE: ACCIDENT INVOLVING SDB8006Z & SJH580G

Dear Hsiao Tong,

Is your insured reported for this case? Any update?

Our client is chasing for the liability. Please kindly revert the liability to us.

Thank you!

Best Regards,

**AVRIL HO**

Claims Asst.

Mova Automotive Pte Ltd

Email: [avril@mov.com.sg](mailto:avril@mov.com.sg)

Address: Blk 1008 Bt Merah Lane 3

#01-04/06/08

Singapore 159722

Telephone: 6272 3892 Fax: 6270 8314



This message is confidential and is for the use of the intended recipient only. If you have received this message in error, please do not copy, disclose or use its content. We would be grateful if you would notify us by email and delete the original transmission and any attachment from your system. Any attachment to this e-mail may contain software viruses that could damage your computer system. Although we will take reasonable precaution to minimize this risk, we do not accept any liability resulting from software viruses. Please carry out your own virus checks before opening any attachment.

---

**From:** AVRIL HO [<mailto:avril@mov.com.sg>]  
**Sent:** Thursday, 21 March 2019 8:49 AM  
**To:** 'Hsiao Tong (LKKAUTO)'  
**Cc:** 'suann@mov.com.sg'  
**Subject:** RE: ACCIDENT INVOLVING SDB8006Z & SJH580G

Dear Hsiao Tong,

Any update for this case? Our client is chasing.

Thank you!

Best Regards,

**AVRIL HO**

Claims Asst.

Mova Automotive Pte Ltd

Email: [avril@mov.com.sg](mailto:avril@mov.com.sg)

Address: Blk 1008 Bt Merah Lane 3

#01-04/06/08

Singapore 159722

Telephone: 6272 3892 Fax: 6270 8314



This message is confidential and is for the use of the intended recipient only. If you have received this message in error, please do not copy, disclose or use its content. We would be grateful if you would notify us by email and delete the original transmission and any attachment from your system. Any attachment to this e-mail may contain software viruses that could damage your computer system. Although we will take reasonable precaution to minimize this risk, we do not accept any liability resulting from software viruses. Please carry out your own virus checks before opening any attachment.

---

**From:** AVRIL HO [<mailto:avril@mov.com.sg>]  
**Sent:** Tuesday, 19 March 2019 12:18 PM  
**To:** 'Hsiao Tong (LKKAUTO)'  
**Cc:** 'suann@mov.com.sg'  
**Subject:** ACCIDENT INVOLVING SDB8006Z & SJH580G

Dear Hsiao Tong,

Refer to the attachment, please kindly revert the liability to us.

Thank you!



Best Regards,

**AVRIL HO**

Claims Asst.

Mova Automotive Pte Ltd

Email: [avril@moval.com.sg](mailto:avril@moval.com.sg)

Address: B1k 1008 Bt Merah Lane 3

#01-04/06/08

Singapore 159722

Telephone: 6272 3892 Fax: 6270 8314



This message is confidential and is for the use of the intended recipient only. If you have received this message in error, please do not copy, disclose or use its content. We would be grateful if you would notify us by email and delete the original transmission and any attachment from your system. Any attachment to this e-mail may contain software viruses that could damage your computer system. Although we will take reasonable precaution to minimize this risk, we do not accept any liability resulting from software viruses. Please carry out your own virus checks before opening any attachment.

## Hsiao Tong (LKKAUTO)

---

**From:** Kuru & Co <kurulegal@yahoo.com.sg>  
**Sent:** Monday, 8 April 2019 9:38 AM  
**To:** Hsiao Tong (LKKAUTO)  
**Cc:** Aaron  
**Subject:** Mutual Client | Our ref: L19.0254.pl (PD) & L19.0387.jt (Injury) | Your ref: CC4/ASM19004947/pa3 - SJH 580G, SJP 5816C & SDB 8006Z on 26.02.2019

Dear Hsiao Tong,

We refer to the above matter where we act for Loh Peilin Pearlyn and Foo Siang Siong, owner and driver respectively of SJH 580G in their property damage and personal injury claim and refer to your letter dated 28 March 2019 addressed to our mutual client.

Our client's video footage is not available.

Please refer to the following link for:-

- 1) Coloured accident scene photographs;
- 2) Copy of driver's Identity Card and Driving Licence (submitted in SAS);
- 3) Front & rear video footage of SDB 8006Z.

<https://www.dropbox.com/sh/797du88vj7pg1q0/AABPH3lqseT4ws52kzMglJaaa?dl=0>

As we are instructed to proceed further for our client's claim, as such, please do not prejudice our client's rights and interest pertaining to the above matter.

We shall keep you informed of any material developments and trust you to do the same.

Regards,

Judy Tan  
Kuru & Co  
Advocates & Solicitors  
Tel: (65) 6532 2009  
Fax: (65) 6532 2007



## <MANDATE IA> - S9M01HEW [ACCIDENT INVOLVING SKH 580G(OI)/ SDB 8006Z(TP) / OTHERS ON 26/02/2019]

Type

🔗 Question

Message

Liability: 100%. 3 vehicles chain collision whereby insured was the 2nd car. Inform OI about third party claim. Agreed to settle at best and aware NCD issue. We seek your mandate at \$3,146.30(if claim LOU) - \$3,327.80(if claim LOR). Mandate IA had been uploaded in Smartclaims. Kindly let us have your approval/instruction. Hsiao Tong – 25 May 2019

Reply



Auto  
Consultants  
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

## Immediate Advice

To : AXA Insurance Pte Ltd

Date: 25/5/2019

### Survey Details:

Date of loss	26-Feb-19
Date of appointment	19-Mar-19
Date of survey	15-Apr-19
Location of survey	MOVA AUTOMOTIVE PTE LTD

### Vehicle Details:

Claim Type:	THIRD PARTY CLAIM
Vehicle number	SDB8006Z
Make and Model	B.M.W. 528I AT D/AB LED NAV HUD
Date of registration	31-Oct-16
Parf Rebate	
Market Value	\$ 138,000.00
Parf Rebate	\$ 86,157.00
Nett Loss	\$ 51,843.00

### Repair details:

Initial Estimate	\$ 2,611.09
------------------	-------------

### Proposed/Revised repair cost:

Parts	\$ 1,937.75
Check items (estimate)	
Labour	\$ 673.34
Total	\$ 2,611.09
Lump Sum(if applicable)	\$ -

Number of days for repair	2
---------------------------	---



Auto  
Consultants  
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

**Remarks:**

--

**Mandate:**

Liability(TP)	100%	
Proposed repair cost(w/GST)	\$ 2,793.87	\$ 2,793.87
Loss of use (3days x 100.00)	\$ 300.00	NIL
Loss of rental (3days x \$150.00)(w/GST)	NIL	\$ 481.50
Loss of income	NIL	NIL
LTA search fees	\$ 7.49	\$ 7.49
Others (Audatex Fee)	\$ 44.94	\$ 44.94
Proposed Total	\$ 3,146.30	\$ 3,327.80



**Re:<MANDATE IA> - S9M01HEW [ACCIDENT INVOLVING  
SKH 580G(OI)/ SDB 8006Z(TP) / OTHERS ON 26/02/2019]**

Type

 Question

Message

PLS PROCEED AS PROPOSED

Reply

## Hsiao Tong (LKKAuto)

---

**From:** Suann <suann@moval.com.sg>  
**Sent:** Tuesday, 28 May 2019 2:23 PM  
**To:** Hsiao Tong (LKKAuto); Admin A  
**Subject:** SDB8006Z & SJH580G on 26/2/19  
**Attachments:** 28052019141931.pdf



Dear sir / mdm

Attached is our letter of demand.  
Please look into it & let us have your offer.

Thank you

Best Regards  
**Suanne Chiu**  
Claims Asst. Manager  
**MOVA Automotive Pte Ltd**  
Tel: +65 6272 3892  
Fax: +65 6270 8314



Connect with us on  

Privileged/Confidential Information may be contained in this message. If you are not the addressee indicated in this message (or responsible for delivery of the message to such person), you may not copy or deliver this message to anyone. In such case, you should destroy this message and kindly notify the sender by reply email. All opinions, conclusions and other information expressed in this message not of an official nature shall not be deemed as unless otherwise indicated by an authorized representative independent of this message.

## Hsiao Tong (LKKAuto)

---

**From:** Suann <suann@moval.com.sg>  
**Sent:** Thursday, 6 June 2019 9:34 AM  
**To:** Hsiao Tong (LKKAuto)  
**Cc:** Admin A  
**Subject:** RE: SDB8006Z & SJH580G on 26/2/19 \*LKK REF: CC4/ASM19004947/R1pa3

Dear Hsiao Tong

We accept your offer.

Thank you

Best Regards  
**Suanne Chiu**  
Claims Asst. Manager  
**MOVA Automotive Pte Ltd**  
Tel: +65 6272 3892  
Fax: +65 6270 8314



Connect with us on  

Privileged/Confidential information may be contained in this message. If you are not the addressee indicated in this message (or responsible for delivery of the message to such person), you may not copy or deliver this message to anyone. In such case, you should destroy this message and kindly notify the sender by reply email. All opinions, conclusions and other information expressed in this message not of an official nature shall not be deemed as unless otherwise indicated by an authorized representative independent of this message.

---

**From:** Hsiao Tong (LKKAuto) [mailto:chewht@lkkauto.com]  
**Sent:** Wednesday, 5 June 2019 8:31  
**To:** Suann  
**Cc:** Admin A  
**Subject:** RE: SDB8006Z & SJH580G on 26/2/19 \*LKK REF: CC4/ASM19004947/R1pa3

**Without Prejudice**

Dear Sirs/Mdm,

We refer to your below email.

We propose settlement at a global sum of **\$3,070.00(all-in).**

Please confirm acceptance.

"Please note that our proposal and correspondence with you is strictly on a without prejudice basis and should not be construed as an admission of liability on our part and/or that of our policyholder and/or the authorised driver. The terms of our without prejudice engagement should not be disclosed in any other related matter(s) in respect of this accident nor should it be binding in any other related claims."

Best Regards,  
**Hsiao Tong, Chew** | Case Handler  
**LKK Auto Consultants Pte Ltd**  
Phone: 6742-3197 | email: [chewht@lkkauto.com](mailto:chewht@lkkauto.com) | fax: 6741-4108  
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



---

**From:** Suann <suann@moval.com.sg>

**Sent:** Tuesday, 28 May 2019 2:23 PM

**To:** Hsiao Tong (LKKAuto) <chewht@lkkauto.com>; Admin A <admin-a@lkkauto.com>

**Subject:** SDB8006Z & SJH580G on 26/2/19

Dear sir / mdm

Attached is our letter of demand.

Please look into it & let us have your offer.

Thank you

Best Regards

**Suanne Chiu**

Claims Asst. Manager

**MOVA Automotive Pte Ltd**

Tel: +65 6272 3892

Fax: +65 6270 8314



Connect with us on  

Privileged/Confidential Information may be contained in this message. If you are not the addressee indicated in this message (or responsible for delivery of the message to such person), you may not copy or deliver this message to anyone. In such case, you should destroy this message and kindly notify the sender by reply email. All opinions, conclusions and other information expressed in this message not of an official nature shall not be deemed as unless otherwise indicated by an authorized representative independent of this message.

Workshop Address: Blk 1008, Bukit Merah Lane 3  
# 01-04/06/08  
Singapore 159722



**"WITHOUT PREJUDICE"**

Your Ref : SJH580G  
Our Ref : SDB8006Z / T150519

Date : 21 June 2019

**LKK AUTO CONSULTANT PTE LTD**  
51, Ubi Avenue 1  
#01-25 Paya Ubi Industrial Park  
Singapore 408933.

ATTN : MOTOR CLAIMS DEPT

Dear Sir / Madam,

**ACCIDENT INVOLVING SDB8006Z & SJH580G ON 26/02/2019 ALONG  
UPPER CHANGI ROAD EAST**

We refer to the above.

Enclosed herewith are documents for your attention and actions.

Please issue payment in favor of **MOVA AUTOMOTIVE PTE LTD.**

If you have any enquiries, please contact us at 6272 3892 or alternatively:

1. Ms Vivian, [vivianwkl@mova.com.sg](mailto:vivianwkl@mova.com.sg) for feedback, workshop & claims matters, Lawyer Cases and all Own Damages & Windscreen matters.
2. Ms Suanne Chiu, [suann@mova.com.sg](mailto:suann@mova.com.sg) for all Third Party matters.

Thank you.

**Note:** Enclosed tax invoice & discharge voucher.

Yours faithfully  
For Claims Manager  
Claims Department  
Tel: 62723892  
Fax: 627083149



Automotive Pte Ltd

**Main Office:**  
Mova Building  
No. 22, Jalan Kilang,  
Singapore 159419  
Tel: (65) 6476 3333  
Fax: (65) 6271 5891  
www.mova.com.sg

**Workshop Dept:**  
Block 1008,  
Sikit Merah Lane 3,

**VIA EMAIL**  
**WITHOUT PREJUDICE**  
01-04/06/08/94  
Singapore 159722

Tel: (65) 6272 3892  
Fax: (65) 6270 8314

Co. Reg. 198904033G  
GST Reg. M2-0088864-2

Our Ref : SDB8006Z / T150519  
Your Ref : SJH580G

Date : 28 May 2019

**AXA INSURANCE PTE LTD**  
8 Shenton Way  
#27-01  
Singapore 068811.

**Attn: Motor Claims Department**

Dear Sir/Mdm

**ACCIDENT INVOLVING: SDB8006Z & SJH580G**

**DATE OF ACCIDENT: 26 FEBRUARY 2019**

**ALONG: UPPER CHANGI ROAD EAST**

We refer to the above mentioned accident. We are claiming as per below:

Cost of Repairs	\$ 2,793.87
Loss of Use (\$__x__ days)	\$
Loss of Rental (\$ 180.00 x 02 days) + 7% GST	\$ 385.20
Loss of Income (\$__x__ days)	\$
Taxi Fees / E-License / Others	\$
LTA /GIA Search	\$ 7.49
Medical Fees	\$
Towing Fees	\$
<b>Grand Total</b>	<b>\$ 3,186.56</b>

Car date in: 15/04/2019 Car date out: 16/04/2019

Authorized Repair Days: 02 (TP/ODWS/Recovery of Incidental Costs)

Please pay the amount of **S\$ 3,186.56** in favor of **MOVA AUTOMOTIVE PTE LTD.**

If you have any enquiries, please call Ms Suann @ 62723892 or email [suann@moval.com.sg](mailto:suann@moval.com.sg)

Yours faithfully,  
**MOVA AUTOMOTIVE PTE LTD**  
For Claims Manager

**NOTE:** # Please note that the Loss of Use will be paid based on negotiation and on the NIMA Protocol (Court Guideline).

- This is a computer generated letter and does not need a signature.

6301576

## Performa Invoice

21/05/2019

AXA INSURANCE PTE LTD  
8 SHENTON WAY  
AXA TOWER #27-01  
SINGAPORE 068811

Page # :- 1  
Veh # :- SDB8006Z  
Veh Model :- BMW 528I  
Performa# :- CK508247  
Claim # :- T150519  
ACC. Date :- 00/00/00  
Terms :- C.O.D Days  
Remarks :-

**Main Office:**  
Mova Building  
No. 22, Jalan Klang,  
Singapore 159419  
Tel: (65) 6476 3333  
Fax: (65) 6271 5891  
www.mova.com.sg

**Workshop Dept:**  
Block 1008,  
Bukit Merah Lane 3,  
#01-04/05/08/94  
Singapore 159722  
Tel: (65) 6272 3892  
Fax: (65) 6270 8314  
Co. Reg. 198904033G  
GST Reg. M2-0088864-2

Attention :- XA009

No.	Description	Qty	U.Price	Amounts S\$
	SPECIAL NET ITEMS :			
	COST OF REPAIR			2,611.09
	SPECIAL NET TOTAL S\$			2,611.09

E. & O.E

NON-TAX AMOUNT S

AMOUNT S\$ 2,611.09

GST @ 7 % 182.78

AMOUNT DUE S\$ 2,793.87

Customer's Signature/Co. Stamp  MOVA AUTOMOTIVE PTE LTD



Auto  
Consultants  
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

28 MARCH 2019

LOH PEILIN PEARLYN  
APT BLK 678A PUNGGOL DRIVE  
#15-806  
SINGAPORE 821678

Dear Sir/ Mdm

OUR REF : CC4/ASM19004947/pa3

YOUR REF : SJH 580G

ACCIDENT INVOLVING SJH 580G / SDB 8006Z/ OTHERS ALONG/AT UPP CHANGI  
ROAD EAST TWDS BEDOK ON 26/02/2019

We refer to the above subject matter. We write to inform you that we are the loss adjuster appointed by your motor insurer, AXA Insurance Pte Ltd to deal with the third party claim against your policy.

We have received a claim from MOVA AUTOMOTIVE PTE LTD acting on behalf of the owner of SDB 8006Z against your motor insurance policy.

Pursuant to the above said accident wherein you and/or your authorized driver had amongst other information given us your version of how the accident had occurred, we as the appointed agent of your insurers shall proceed to negotiate for an amicable settlement with third party claimant.

Please be informed that your No Claim Discount (NCD) may be affected as a result of the claim against your policy.

We shall proceed to deal with the claim(s) subject to the merits of the case and according to the rights afforded under the policy. Should you not be seeking the protection of your policy and seek to take conduct of third party claim(s) arising from this incident, at your own cost and defence, please reply to us within 10 days from the date of this letter. Your intent must be formally expressed to us and acknowledged by us.

Your full co-operation in the handling of the claim is required and kindly submit the following to [chewht@lkkauto.com](mailto:chewht@lkkauto.com) within 10 days from the date of this letter **if not provided at our reporting centre**. The list below is not all inclusive and further document may be required:

- Police report, Police Investigation result, appeal against the Traffic Police offence and status (if any)
- Driver's driving license or foreign driving license (if any)
- Coloured photographs of accident scene (if any)
- Coloured photographs of damage to all vehicles involved (If any)
- Video footage of accident (if any)
- Statement and/or police report from independent witness(es) (if any)
- If you or your passenger(s) are filing a claim against any of the involved Third Party(s), you are to keep us informed of your legal representative(s) and the status of the claim

To protect your interest(s) in the handling of this claim, please do not discuss liability with any of the Third Party(s) and/or their legal representatives, or make any compromise or settlement without AXA's prior knowledge and consent.


This letter should **not** be regarded as a waiver by AXA of their rights to repudiate any claim because of any breach of policy terms and conditions you and/or your authorised driver may have committed.

In the event of receiving and handling of any third party injury claim(s), AXA shall keep you informed of the final indemnity upon conclusion of the matter(s).

If you need any clarification, please do not hesitate to contact us at 6742 3197 or email us at [chewht@lkkauto.com](mailto:chewht@lkkauto.com).

Please quote the claim reference when you contact us that we can assist you more effectively.

Yours sincerely



Chew Hsiao Tong

Case Handler

DID: 6742 3197

FAX: 6741 4108

EMAIL: [chewht@lkkauto.com](mailto:chewht@lkkauto.com)

Cc *AXA Insurance Pte Ltd*  
*(Motor Claims Dept)*

AUTHORIZATION TO ACT


I, Poh Yee Tioung ("the third party claimant")  
of 1 Peck Hay Road #13-04, S(228305) (address),  
owner of SDB 8006Z (vehicle no.) hereby authorize  
MOVA AUTOMOTIVE PTE LTD


("the workshop") to act for me with respect to my claim for  
repair costs and/or rental and/or loss of use ("claim") for my  
vehicle no. SDB 8006Z that was damaged pursuant to the  
accident which occurred on 26/02/19 (date) along  
Upper Changi Road East (location)  
involving vehicle no/s 8JH5806  
("the accident").

I further authorize the workshop to settle my above mentioned  
claim in a manner that they deem fit and the workshop is further  
authorized to receive payment further to settlement of my claim  
with payment cheque/s being made in favour of the workshop.

I further acknowledge that any settlement the workshop may reach  
on my behalf is on a without prejudice and without admission of  
liability basis insofar as the driver/owner/insurers of the other  
vehicle/s is concerned.

Dated this 16 day of April (month) 20 19 (year)

  
Signed by "the third party claimant"

  
Signed by "the workshop"  
(with chop)



The acceptance of this offer is without prejudice to any personal injury claim/insure's claim/expenses

### AXA THIRD PARTY DIRECT SETTLEMENT

Vehicle No:	SJH 580G (Insd veh)	Model: BMW 528i (1997cc)
	SDB 8006Z (TP veh)	
Date of Accident/ Time:	26/02/2019	

Repair Estimate	: S	2,793.87	
Final Repair Cost	: S		
Loss of Use	: S		days at 5 per day
Rental (if any)	: S		days at 5 per day
LTA / GIA Search Fee	: S		
Others:	: S		
	: S		
Final Settlement Sum (Global Sum)	: S	3,070.00	

Payee Name : Mova Automotive Pte Ltd

Is Third Party Workshop GIA Registered? ☒ YES ☐ NO (Kindly indicate below)

A)	For Non GIA Registered Workshop:	Agreed Liability _____ (%)
B)	For GIA Registered Workshop:	BOLA Applicable: Yes/ <input checked="" type="checkbox"/> BOLA Scenario No: 28
	BOLA Liability: 100 (%)	Assessed Liability (*): 0 (%)

\* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.

Remarks:

#### NOTE:

- PLEASE EXPRESSLY RESERVE YOUR CLIENT'S RIGHTS IF SO REQUIRED IN THIS SETTLEMENT DOCUMENT.
- THIS SETTLEMENT IS ON A WITHOUT PREJUDICE BASIS AND SHOULD NOT CONSTRUED AS AN ADMISSION OF LIABILITY ON AXA AND THEIR CLIENT/TORTFEASOR IN ANY MANNER WHATSOEVER.
- AXA RESERVES THEIR RIGHTS UNDER THE POLICY TERMS & CONDITIONS AS WELL AS THEIR RIGHTS IN LAW.

Only applicable to rental claim - All document are to be submitted with this settlement confirmation. In the event, rental agreement / invoices are **not received within 7 days** of this signed confirmation, we will automatically revert to loss of use claim per the NIMA rates.


We/I confirmed that this is a **full and final settlement** that we and or our client have/had/has against you (AXA and their policyholder/authorised driver/tortfeasor) for any and all losses (past/present/future) arising from this accident.

We confirmed that we have the authority of our client to act for and on their behalf in this accident.

Signature of workshop representative / Workshop stamp

Name of Representative: Avril Ho

Date: 21/6/19



Signature of Witness / Workshop stamp (if applicable)

Name of Witness:

Date: 21/6/2019

MOVA AUTOMOTIVE PTE LTD  
Blk 100K, URAH LANE 3  
#01-04 (S) 150722  
Tel: 62723892 Fax: 62708314  
GST Reg No : M2-0088864-2

Signature of AXA's surveyor/representative:

Name of AXA's surveyor/representative:

Date:

1/7/2019



# Tax Invoice

21/06/2019

**AXA INSURANCE PTE LTD**  
**8 SHENTON WAY**  
**AXA TOWER #27-01**  
**SINGAPORE 068811**

Attention :- **XA009**

Page # :- 1  
 Veh # :- SDB8006Z  
 Veh Model :- BMW 528i  
 Tax # :- CK630558  
 Claim # :- T150519  
 ACC. Date :- 00/00/00  
 Terms :- C.O.D Days  
 Remarks :-

**Main Office:**  
 Mova Building  
 No. 22, Jalan Kiang,  
 Singapore 150419  
 Tel : **(65) 6476 3333**  
 Fax : (65) 6271 5891  
 www.mova.com.sg

**Workshop Dept:**  
 Block 1008,  
 Bukit Merah Lane 3,  
 #01-04/06/08/94  
 Singapore 159722  
 Tel : **(65) 6272 3892**  
 Fax : (65) 6270 8314  
 Co. Reg. 198904033G  
 GST Reg. M2-0088864-2

No.	Description	Qty	U.Price	Amounts S\$
<b>SPECIAL NET ITEMS :</b>				
	COST OF REPAIR			2,611.09
	<b>SPECIAL NET TOTAL S\$</b>			<b>2,611.09</b>

E. & O.E

**NON-TAX AMOUNT S**  
**AMOUNT S\$** 2,611.09  
**GST @ 7 %** 182.78  
**AMOUNT DUE S\$** 2,793.87

Customer's Signature/Co. Stamp **MOVA AUTOMOTIVE PTE LTD**

RENTAL DETAILS			INSURANCE EXCESS AMOUNT		
Vehicle Make/Model:	T- Wish	Vehicle No: 3LS8576K	Singapore	Malaysia	Signature
Date/Time Out:	15/4/17	11:20	S\$ 3500	S\$ —	/
Petrol Level Out:	E 1/8 1/4 3/8 1/2 5/8 3/4 7/8 F		Per Accident	Per Accident	
Date/Time In:	15/4/17	@ 21:20 hrs	Charges		
Petrol Level In:	E 1/8 1/4 3/8 1/2 5/8 3/4 7/8 F		Months @ \$	Per Month	360.00
Change Over 1:	Date:	Initial:	Weeks @ \$	Per Week	
Change Over 2:	Date:	Initial:	Days @ \$ 80.00	Per Day	
KM Out:	KM In:		Hours @ \$	Per Hour	
HIRER DETAILS			Sub-Total		
Named Hirer			Less Discount	%	
Name:	Poh Yee Ting		Rental Charges		
Address:	100-1/11		CDW @ \$	per day / week / month	
	100-1/11		PAI @ \$	per day / week / month	
	100-1/11		Petrol Top-Up		
Identity Card No:	100-1/11		Misc Charges		
Date of Birth:	100-1/11		GST 7/10		75.20
Driving License:	100-1/11		Total		385.20
Country of Issue:	100-1/11		VISA / MASTER CARD / AMEX	CASH / COMPANY BILLING / OTHERS	
Tel:	(HP)	(O)	Pre-Payment		
Nationality:			Downpayment and Deposit		
Effective Date:			Amount Refunded/ Due		
			Signature of Refund		
Additional Hirer			Remarks:		
Name:					
Address:					
			Invoice No:	Ref. No:	
			Checked Out By:	Checked In By:	Checked By:
Identity Card No:					
Date of Birth:					
Driving License:					
Country of Issue:					
Tel:	(HP)	(O)	Sales-In Charge:		
Nationality:			Past 3 years accidents YES <input type="checkbox"/> NO <input checked="" type="checkbox"/>		
Effective Date:					

I fully understand and agreed to the terms and condition appended on both sides of this Vehicle Rental Agreement. I also agreed that if there is any outstanding amount payable after the conclusion of my rental not restricted to parking or traffic infringements during my period of hire, I will agree that these outstanding payment be billed to my charge/ credit card voucher given above. All above information given by me are true in connection to this agreement.

Hirer's Signatory / Company Stamp (if corporate hirer)

Authorised Manager Signature

Date &amp; Time

**IMPORTANT**

- Only authorized drivers with valid driving license of minimum 2 years may drive the rental vehicle.
- All rental vehicles are strictly for Singapore use only, and may not be driven outside Singapore without prior approval of MOVA Automobile.
- In any accident, the Hirer must report to MOVA Automobile immediately. The Hirer shall endeavor to assist in all manners possible.
- The Hirer shall be liable for all excess charges (if any) for late return at the hourly rate shown, inclusive of CDW and PAI. Late return of more than 4 hours will be considered as a day rental.
- All traffic infringements and summons (if any) are the responsibility of the Hirer.



# Thank you

Chiu Nyet Fah has successfully logged out.

Your last login date and time was 27 Feb 2019, 11:30:07.

To return to ONE.MOTORING, please click [here](#)

For security reasons, please **CLEAR YOUR CACHE** after each session.

## Session Transaction History

S/No.	Asset Type	Asset ID	Asset Owner ID	Transaction Type	Transaction Amount(S\$)	Log Date/Time
1	Vehicle	SJH580G	-	18.32 Insurance Enquiry (GIRO Payment)	7.49	27 Feb 2019 / 11:30:56

Enquire Vehicle Insurer

Vehicle No.	Incident Date/Time	Search Status	Insurance Company Code	Insurance Company Name
SJH580G	26 Feb 2019 / 17:30:20	Successful	A12	AXA INSURANCE PTE LTD

Previous OK



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD		Ref : CC4/ASM19004947/R1pa3q2		
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:KIAN CHUAN		Date : 16-07-2019		
		Code : ASM		
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SJH 580G	Veh. Inspected	SDB 8006Z	
Policy No.	CN895015	Coverage (\$)	0.00	
Claim No.	S9M01HEW	Excess (\$)	0.00	
Assign From		Assign Date	19/03/2019	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	B.M.W. 528I A	c.c	1997	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	WBA5A52040G390313	Colour	GREY	
Odometer	43872	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	245/40 R17	GOODYEAR	6 mm	
L/H Front Tyre	245/40 R17	GOODYEAR	6 mm	
R/H Rear Tyre	245/40 R17	GOODYEAR	6 mm	
L/H Rear Tyre	245/40 R17	GOODYEAR	6 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	26/02/2019	Inspection Date	15/04/2019	
Survey held at	MOVA AUTOMOTIVE PTE LTD BLK 1008 BUKIT MERAH LANE 3 #01-04/06/08 SINGAPORE 159722			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days		



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SDB 8006Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b>REPLACEMENT OF PARTS</b>			
1	REAR BUMPER COVER (CONSISTENT) (WCP)	CRACKED	1,400.00	1,400.00
1	CTR LWR BUMPER GUIDE (CONSISTENT) (WCP)	CRACKED	75.00	75.00
1	REAR BUMPER MNTG KIT (CONSISTENT) (WCP)	NECESSARY	25.00	25.00
1	L/INN U-SONIC SENDER (CONSISTENT) (WCP)	NECESSARY	185.00	185.00
	COST PLUS 15%		252.75	252.75
			1,937.75	1,937.75
	<b>LABOUR</b>			
	35.0 WU X45.00 SGD/H.		131.25	131.25
	LABOUR COST 82.0 WU X45.00 SGD/H.		369.00	369.00
	MATERIAL COAT.		173.09	173.09
			673.34	673.34
	<b>GRAND TOTAL</b>		<b>2,611.09</b>	<b>2,611.09</b>
	<b>RECOMMENDED COST OF REPAIRS</b>			<b>2,611.09</b>

Report Ref No. CC4/ASM19004947/R1pa3q2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.

Service Request Details

Claim	S9M011HEW	Vehicle Information	
Reference	CC4/ASM19004947/R1pa3q2	Incident Vehicle Registration #	5D8B006Z
Loss Date	26 February 2019	Make	TPVD BMW
Report Date	19 Mar 2019 8:53:29 AM	Model	530i-2.0 F10 (A)
Request Date	17 April 2019	Service Address	...
Due Date			

Actions

Next Step

Wait for Approve Invoice















Approve Invoice

Vendor Name	LOK AUTO CONSULTANTS PTE LTD (TP)	Primary Contact/Insured	
Type of Loss	Third Party Vehicle Damage	LOH PEILYN PEARLYN	
Services	Pending verification - Direct Settlement	BLK 67BA PUNGGOL DRIVE, #15-806, 821678, Singapore	

Claim Handler	
	CHAN Kian Chuan
	6568804269
	kianchuan.chan@axa.com.sg

Additional Instructions

Messages	Invoices	History	Documents	Assessment	Metrics	Notes
Document Type: Document SubType						
<div><div></div><div></div></div>						
<div><div></div><div></div></div>						
NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED		
<div><div></div><div>LKKInvoice1 (111).pdf</div></div>	Invoice	Surveyor/ Assessor expense	LKK AUTO CONSULTANTS PTE LTD (TP)	18 July 2019		

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
 RENTAL RECEIPT.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	18 July 2019
 LIA SEARCH.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	18 July 2019
 LKKInspection (6).pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	18 July 2019
 LKKAdjustment1a (8).pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	18 July 2019
 PAYMENT BREAKDOWN EXPRESS SETTLEMENT FORM.pdf	Forms / Claim Documents	Satisfaction / Discharge Voucher	LKK AUTO CONSULTANTS PTE LTD (TP)	18 July 2019
 AUTHORIZATION TO ACT FORM.pdf	Forms / Claim Documents	POA / Authority Letter	LKK AUTO CONSULTANTS PTE LTD (TP)	18 July 2019
 WORKSHOP INVOICE.pdf	Invoice	Repairer	LKK AUTO CONSULTANTS PTE LTD (TP)	18 July 2019
 LETTER TO OI.pdf	Letters and Correspondence	Policy Holders / Insured	LKK AUTO CONSULTANTS PTE LTD (TP)	18 July 2019
 Mandate LA dd 250519.pdf	Forms / Claim Documents	Assessment	LKK AUTO CONSULTANTS PTE LTD (TP)	25 May 2019
 Audatex Report_SDB8006Z.pdf	Reports & Statement	Estimate / Quotation	LKK AUTO CONSULTANTS PTE LTD (TP)	25 May 2019
 LKK Resurvey Photos.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	25 May 2019
 LKK Survey Photos.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	25 May 2019
 SDB 8006Z vs SJH 580G .TP VIDEO_READ.mp4	Evidence	Videos	LKK AUTO CONSULTANTS PTE LTD (TP)	1 May 2019
 SDB 8006Z vs SJH 580G .TP VIDEO_FRONT.mp4	Evidence	Videos	LKK AUTO CONSULTANTS PTE LTD (TP)	1 May 2019



NAME	TYPE	SUB TYPE	AUTHOR	DATE UPLOADED
 TP ESTIMATE - MARKED.pdf	Reports & Statement	Estimate / Quotation	LKK AUTO CONSULTANTS PTE LTD (TP)	17 April 2019
 LA.pdf	Forms / Claim Documents	Assessment	LKK AUTO CONSULTANTS PTE LTD (TP)	17 April 2019
 SIHSBGG INSD GIA REPORT.PDF	Reports & Statement	GIA Report	DHAKAL Raghav	19 March 2019
 TP PH FROM WORKSHOP WITH GIA AND ESTIMATE.png	Letters and Correspondence	Workshop	DHAKAL Raghav	19 March 2019
 SUPSBAC GIA REPORT.PDF	Reports & Statement	GIA Report	DHAKAL Raghav	19 March 2019