



## Immediate Advice

To : AXA Insurance Pte Ltd

Date: 4/4/2019

### Survey Details:

Date of loss	17-Mar-19
Date of appointment	19-Mar-19
Date of survey	18-Mar-19
Location of survey	COMFORTDELGRO ENGINEERING PTE LTD

### Vehicle Details:

Claim Type:	THIRD PARTY CLAIM
Vehicle number	SHD 7197D
Make and Model	HYUNDAI I40 - 1685cc
Date of registration	17-Nov-16
Parf Rebate	
Market Value (est)	\$ -
Parf Rebate (est)	\$ -
Nett Loss (est)	\$ -

### Repair details:

Initial Estimate	4,596.92
------------------	----------

### Proposed/Revised repair cost:

Parts	\$ 693.72
Check items (estimate)	\$ -
Labour	\$ 1,420.00
<b>Total</b>	<b>\$ 2,113.72</b>
<b>Lump Sum(if applicable)</b>	<b>\$ 1,700.00</b>

<b>Number of days for repair</b>	<b>3 days</b>
----------------------------------	---------------



**Remarks:**

We have not authorized repairs. Insured Driver reported that he as moving out from c/p lot when hit by TP vehicle. BOLA 24. TP LOD IN.

**Mandate:**

<b>Liability(TP)</b>		<b>100%</b>	
Proposed repair cost (w/gst)	\$	1,819.00	
Loss of use (TBC)	\$	-	no. of days
Loss of rental	\$	338.01	\$112.67 x 3 days
Loss of income	\$	150.00	\$50 x 3 days
LTA search fees	\$	-	
Others			
<b>Proposed Total</b>	<b>\$</b>	<b>2,307.01</b>	
***TBC = To Be Confirmed			