



Case Details

Case Reference Number : BUS/03/19/5036
 Type of Repair : Accident Repair
 Vehicle Registration Number : SMB104U

Company Type : SMRT Buses Ltd
 Estimation ID : EST-6139-ID
 Assigned By : Bus Claims Manager Team

Insurance Company Name : AXA Insurance Singapore Pte Ltd
 Accident Date and Time : 15/03/2019 07:50 AM
 Vehicle Age(In Months) : 116

Documents / Photographs

View Documents / Photographs

Total Documents: 1

Estimation Details

Spare Part's Cost Detail

SMRT Recommendation											Surveyor Approval				
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks	
Standard	Main	VE	6009700	LAMP,BLINKER,FRONT,LEFT,FOR MB OC 500 LE	1	155.30	155.30	10.00	139.77	Replace	1	139.77	Replace v	CRA	
									Total Spare Part Cost	139.77			Surveyor Total	139.77	
							Lump Sum Discount (%)	20.00					Lump Sum Dis (%)	20	
									Final Spare Part Cost	111.82			Final Sur Total	111.82	

Labour's Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REMOVE & REPLACE ABOVE ITEMS AND REPAIR FRONT LH PORTION.	530.00	265	
Total:			530.00	265.00	

Spray Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO PUTTY & RESPRAY	432.00	262	
Total:			432.00	262.00	

Other Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
Total:			0.00	0.00	

Summary

	Estimator Assessment(\$)	Surveyor Assessment(\$)
Total Spare Part Detail	111.82	111.82
Total Labour Cost	530.00	265.00
Total Spray Painting	432.00	262.00
Other	0.00	0.00
Overall Total	1,073.82	638.82
Lump Sum Repair Option		
Lump Sum Total	0.00	650.00
Surveyor Approved Amount		650.00
No of Repair Days*	2	1
Remarks	-	L/S repair. Photo after paint
Surveyor Name		Hwee Jie

20/2019

Surveyor Assessment(s)

Estimator Assessment(s)

Signature



Save Clear

Survey Date

20/03/2019

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: