

REF CS3/SPF/9004957/6435

Special Instructions

ASSIGNMENT (Office)

From (Person): Hafizul Furkan

SPF

Date/Time: 19/3/19 @ 3:13pm

Estimated Cost

Bill to

OD/CTP/WS/TP/RIS/OD/RIS/EVA/INV/MTCS

To Inspect Vehicle No

SKB 5676B

Insured

QX 6435

at Workshop no

Hemmy Motor

Tel

6583 0001

of

BK10 Amk Ind. park 2A #02-12

Policy No

Claim No

2019/042

Sum Insured

Excess

Make of Veh

D.O.A 16.3.2019

(Client's Record)

CA / REV / REP / REV 24 HRS

H.O.D. Endorsement

Date/Time: 3:21pm 19/3/19 Person Contacted

Eunice

Vehicle IN/OUT

Date/Time Action/Instruction (H) Estimate

SKB 5676B - X

QX 6435 - X

Do Not Finalise

DAR - LS \$2800, 6 days

(COR range \$2800 - \$3600, weekend = 02 days)

Garrett

PRS
62

REF:

SPE

721J


(-2021)

ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
OD ☒ TP ☐ WS ☐ TP RES ☐ OD RES ☐ EVA ☐ INV ☐ MV
To Inspect Vehicle No: _____
at Workshop m/s Harmony Motor
of _____
Insured: _____
Policy No. _____
Claims No. _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: \$25K
IDAC Accident Rpt.: _____ Consistent?: Yes or No
GIA / PR Seen: _____ Consistent?: Yes or No
Est. Repairs: 6 days Res.: Yes or No
Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SKB5676B Yr Regn: 13 Jun 2011
Type: ☒ M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or
Make: KIA Cerato Forte C.C. 1591
Colour: Black A/C: Insured / Std / NI / NA
Sp. Reading: 112/21 T/Radio: Insured / Std / NI / NA
Eng/No: _____
C/No: KNAFU41MB5376239
Gen. Cond: ☒ Good / Fair / Poor / Burnt
Steering: ☒ In order / Jammed / Leaked / Burnt or
Brake: ☒ In order / Jammed / Leaked / Burnt or
Modi: Nil / S/Rim / STD ☒ A/Rim or
Tyre Size: F: 195/65 R15
R: U
BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or
Front: _____ Rear: _____
R/Bal: 6 mm R/Bal: 6 mm
L/Bal: 6 mm L/Bal: 6 mm
D.O.A.: _____ D.O.I.: 19-03-19
Survey held at w/s 4pm
Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
O/S rear
The ☒ U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction
COC: 16868.

RECEIVED 26 JUL 2019

Date/Time, File Pass to? ☐ : Preli. Report
1) 25/7 2011 ☐ : Final Report
Date/Time, File Return to?

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

\$ * RS, \$

Photos

Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$) _____

Add Fee: ☐ : Site Insp (\$ _____)

☐ : Interview (\$ _____)

☐ : Tech. Invs (\$ _____)

☐ : Weekend (\$ _____)

220

Nivitha (LKK Auto)

From: Hafizul Farhan RAHMAT (SPF) <Hafizul_Farhan_RAHMAT@spf.gov.sg>
Sent: Tuesday, 19 March 2019 3:13 PM
To: Admin-D (LKKAuto); Olivia Lau (LKKAuto); Shiau Chan (LKKAuto)
Cc: Frankie THAY (SPF)
Subject: Survey of SKB5676B (QX643S)

Hi,

Kindly survey **SKB5676B** at: (accident on 16/3/2018)

Harmony Motor (AMK) Pte Ltd
Blk 10 Ang Mo Kio Industrial Park 2A
AMK Autopoint #02-12
S (568047)
Tel: 6583 0001 (Eunice)

Thank you.

Best Regards,

*Hafizul Farhan Bin Rahmat
AEMD / PLD*

Singapore Police Force

DID: (65) 6478 4840 / FAX: (65) 6478 4850



HOME TEAM
TRANSFORMATION 2025
One Home, One Team
Building Our Future Together

WARNING "Privileged/Confidential information may be contained in this message. If you are not the intended addressee, you must not copy, distribute or take any action in reliance thereon. Communication of any information in this email to any unauthorized person is an offence under the Official Secrets Act (Cap 213). Please notify the sender immediately if you receive this in error."

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	18/03/2019 14:51
Date Of Accident	16/03/2019 15:20
Exact Location Of Accident	JURONG POLICE DIVISIONAL HQ (S) 649482
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKB5676B
Insured/Policyholder	
Name Of Registered Owner	MUHAMMAD HIZAM BIN KAMIS
NRIC No	S8827211J
Email Address	HIZAM.KAMIS@GMAIL.COM
Mobile Phone No	(LOCAL) +65-93822410
Alternative Phone No	HOME-63683274

Vehicle Particulars

Manufacturer	KIA
Model	CERATO EX FORTE 1.6L 6A/T ABS AB 2WD 4DR
Exact Purpose for which vehicle was being used at time of accident	GOING FOR AN APPOINTMENT
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5108155134
Cover Note Number	

Driver


Name of Driver	MUHAMMAD HIZAM BIN KAMIS
NRIC No	S8827211J
Date Of Birth	01/08/1988
Occupation	INDOOR
Date Of Driving Pass	18/03/2008
Driving Experience	10 YEARS AND 11 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-93822410
Fax Number	
Contact Number	HOME-63683274
EMail Address	HIZAM.KAMIS@GMAIL.COM

No. Of Passenger (Including Driver)

2

Sketch Plan #2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 16/03/2019 around 1520 hrs, I just started and went into my car (Kia Cerato Forte Ex) at the surface parking of Jurong Police Division. The surface parking had a two-way road and I drove out from my parking lot towards the left lane (correct direction lane).

I saw a police vehicle (QX683S) which was parked stationary at the opposing lane. I proceeded to drive my car in my lane as it was my right of way (and the Police vehicle was still stationary). Just as I was passing by the Police vehicle, the Police vehicle suddenly swerved into my lane and hit the right side of my rear wheel. I did not recall the Police vehicle giving the signal to change into my lane.

I stopped my car to make a check and found

After experiencing the impact, I stopped my vehicle to assess the situation. The rear bumper of my car was damaged and had dropped off. There were also scratch and paint marks made by the Police vehicle near the rear wheel side of my car. The Police vehicle's front bumper was also damaged and had dropped off.

I exchanged my particulars with the driver of the Police vehicle. There were no injuries reported by either party.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time: 18/03/2019

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name: Joelle Tan
NRIC/TIN No.: AMK AUTOPPOINT PTE LTD
18.03.2019

AMK AUTOPPOINT PTE LTD

Police Report



**SINGAPORE
POLICE FORCE**



J/20190316/2062

1 of 2

POLICE REPORT (NP299)

Report No. J/20190316/2062

Police Station Of Origin
Nanyang N.P.C
2 Jurong West Avenue 5 SINGAPORE
649482
Tel No: 1800-7929999


Date/Time Report Made 16/03/2019 16:18	Vide Report No.	Station Diary No. 77
Name Of Informant MUHAMMAD HIZAM BIN KAMIS	Address APT BLK 345 WOODLANDS STREET 32 #05-206 SINGAPORE 730345	
ID Type / ID No. NRIC NO / S8827211J	Contact No. Home/Office	Mobile 93822410
Nationality SINGAPORE CITIZEN	Email Address	
Occupation SENIOR PROPOSAL SPECIALIST	Sex Male	Age 30
Institution/School Name	Date of Birth 01/08/1988	Race Boyanese
Date/Time Of Incident 16/03/2019 15:20	Location Of Incident 2 JURONG WEST AVENUE 5 JURONG POLICE DIVISIONAL HQ* SINGAPORE 649482 Outside of level 1 lobby	

Brief details.

On 16/03/2019 around 1520 hours. I was in my Car, black color Kia Cerato Forte EX. I was driving out from Jurong Police Division when I felt a bump in the right side of my rear wheel. I stopped my car and made a check and realized that a Police Car, number plate: QX643S had hit my car. I would like to verify that there was no injuries. My car back bumper was damaged and dropped off. The police car front bumper was also damaged and dropped off.

Signature Of Officer Recording The Report: J / Sgt 2 AMRITPAL SINGH SANDHU	Signature Of Informant:
Signature Of Interpreter: Not applicable	Date/Time: 16/03/2019 16:16
Officer In-Charge Of Case: J / Jurong Police Divisional Investigation Branch / SI GUK HWEE KIAN Contact No.:	Classification Of Case:

Authentication Stamp



> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Singapore NRIC
Owner ID:	7211J

Vehicle Details

Vehicle No.:	SKB5676B
Vehicle to be Exported:	No
Intended Deregistration Date:	20 Mar 2019
Vehicle Make:	KIA
Vehicle Model:	CERATO EX FORTE 1.6L 6A/T ABS AB 2WD 4DR
Primary Colour:	Black
Manufacturing Year:	2010
Engine No.:	G4FCAH302797
Chassis No.:	KNAFU411MB5376239
Maximum Power Output:	91.2 kW (122 bhp)
Open Market Value:	\$10,425.00
Original Registration Date:	13 Jun 2011
First Registration Date:	13 Jun 2011
Transfer Count:	2
Actual ARF Paid:	\$10,425.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	12 Jun 2021
PARF Rebate Amount:	\$6,255.00

Intended COE Rebate Details

COE Expiry Date:	12 Jun 2021
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$47,604.00
COE Rebate Amount:	\$10,613.00
Total Rebate Amount:	\$16,868.00

The information contained herein is correct as at 20 Mar 2019

OK

► Kia Cerato forte Used Vehicle List (13 vehicles)

Car Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Company	Availabi
Kia Cerato Forte 1.6A SX	\$28,800	\$8,930 /yr	29-Sep-2011	1,591 cc	-		Availal
Well Maintained And Clean Interior Unit. Original Paint Work. Low Fuel Consumption! Low Maintenance! Smooth And Reliable Engine. Office No. - - Eddie - 81130873							
Kia Cerato Forte 1.6A SX	\$28,800	\$9,270 /yr	23-Aug-2011	1,591 cc	150,000 km	Elite Autostyle Pte Ltd	Availal
Serviced By Choon Motor. Frequent Servicing. Great Vehicle. Consignment Unit. Trade Ins, Loans, Insurance Available. Please Contact Me Fo More Information. Office No. - - Dave - 90480809 Zhi Rong - 93654050							
Kia Cerato Forte 1.6A SX	\$26,800	\$8,710 /yr	27-Jul-2011	1,591 cc	82,234 km	Mayfair Motoring	Availal
High Specs SX Model With Push Start! Beautiful Blue Paintwork With Genuine Low Mileage Done! One Owner Unit! Serviced By Cycle And Carriage! Low Depreciation! Full Loan Available! Call For A Viewing A... Office No. - 64792220 Kenny Toh - 91871230 Terry Cheah - 84840005 Kohji - 97327889							
Kia Cerato Forte 1.6M SX	\$27,800	\$9,080 /yr	27-Jul-2011	1,591 cc	105,000 km	Hua Yang Credit Pte Ltd	Availal
100% Loan Available! Best For Short Term Drivers. Very Well Kept, No Further Repair Needed, Buy With A Peace Of Mind. Test Drive It Now Office No. - 64625111 Chin Chee - 96708227 Faisal - 87527405 Sky - 84371619 Miss Tan - 86864198							
Kia Cerato Forte 1.6A SX	\$25,888	\$8,620 /yr	24-Jun-2011	1,591 cc	-	Sincere Motoring	Availal
(100% Quality Buy!) 1St Owner Unit. Drive With Confident From CaseTrust Accredited Dealer. Vehicle Fully Maintain By Agent (C&C) With Servicing History Since Day One. Purchase Comes With 6 Months Engr... Office No. - 67476066 David - 98529920 Edwin - 92331607 Hermann - 98595755							
Kia Cerato Forte 1.6M SX	\$22,000	\$7,510 /yr	23-May-2011	1,591 cc	125,000 km	Hou Auto	Availal
1 Owner! Real Man Drive Manual! SX Model. High Trade In. Easy Loan. Enjoy The Fun Of Driving! View Now! Office No. - 94574576 Black - 94574576							
Kia Cerato Forte 1.6A SX	\$24,500	\$8,570 /yr	27-Apr-2011	1,591 cc	-	Carz Avenue	Availal
Agent C&C Service Till Date. Very Well Maintain Interior & Exterior. Test Drive Welcome. Contact Us For An Appointment. Confirm No Regret Office No. - 66598786 Sam - 82829994 Han - 91682969							
Kia Cerato Forte 1.6A SX	\$26,000	\$9,440 /yr	13-Apr-2011	1,591 cc	-	360 VR Cars	Availal
Full Service Record At Cycle And Carriage, Front And Rear I-road V9 Cameras, Tyres Changed In Sep 2018, Servicing Done In Sep 2018, We Maintain, High Loan And Trade In Available! Call Now! Viewing B... Office No. - 69310005 Pauline - 96211963 James Tan - 90700005							
Kia Cerato Forte Koup 1.6A SX (OPC)	\$19,900	\$6,190 /yr	30-Mar-2011	1,591 cc	128,000 km	Wang Motor Pte Ltd	Availal
OPC Sporty White Kia Koup Sunroof Model. Newly Painted Pearl White. New 6 Months Road Tax. Very Well Kept By Mature Owner, Hardly Driven. Genuine Low Mileage Clocked. Only 2 Owner. Call Now To Make An... Office No. - 67473193 Christopher - 91822299							

(01)Bent (2)Dented (3)Distorted (4)Cracked (5)Cut (6)Scratched
(07)Deformed (08)Shifted (09)Buckled (10)Broken (11)Necessary
(12)Missing (13)Torn (14)Unconfirmed (15)Not Working

MOTORCAR (Rear)

(1)Replace (✓) (2)Repair(0) (3)Check (C)
(4)Not Consistent (NC)

Rear Portion

NAC	INC	Item	CON	AC	Qty
1137	993626	Rear Number Plate			
1138	993627	Rear Number Plate Base			
1139	993630	Rear Number Plate Garnish			
1140	993632	Rear Number Plate Lamp			
1141	992958	Rear Bumper	607	BR	1
1142	993085	Rear Bumper Upper			
1143	993017	Rear Bumper Lower			
1144	993054	Rear Bumper Side			
1145	993103	Rear Bumper Tow Cover			
1146	992341	Rear Bumper Clips	35	MC	1
1147	992976	Rear Bumper Bracket			
1148	993068	Rear Bumper Side Retainer	RH	DL	1
1149	993045	Rear Bumper Reinforcement			
1150	992970	Rear Bumper Beam			
1151	993077	Rear Bumper Sponge			
1152	992999	Rear Bumper Damper			
1153	993040	Rear Bumper Protector			
1154	993036	Rear Bumper Pad			
1155	993026	Rear Bumper Moulding			
1156	993044	Rear Bumper Reflector			
1157	993023	Rear Bumper Lower Spoiler			
1158	994023	Reverse Sensor	20. (SN)	DM	1
1159	993327	Rear End Panel			
1160	993339	Rear End Panel Top Garnish			
1161	993333	Rear End Panel Inner Trim			
1162	990333	Boot Compartment Inner Trim			
1163	993851	Rear LH Taillamp			
1164	993853	Rear LH Taillamp Garnish			
1165	993859	Rear LH Taillamp Panel			
1166	995116	Rear RH Taillamp			
1167	993853	Rear RH Taillamp Garnish			
1168	993859	Rear RH Taillamp Panel			
1169	993554	Rear Apron Panel			
1170	992895	Bootlid			
1171	991328	Bootlid Emblem			
1172	990356	Bootlid Handle			
1173	995250	Bootlid Moulding			
1174	990376	Bootlid Reflector			
1175	995222	Bootlid Lamp LH			
1176	992899	Bootlid Lamp RH			
1177	995243	Bootlid Lock			
1178	990377	Bootlid Rubber			
1179	990382	Bootlid Hinge			
1180	993877	Bootlid Spoiler			
1181	994543	Tailgate			
1182	991328	Tailgate Emblem	1428		
1183	994643	Tailgate Outer Handle			
1184	994640	Tailgate Moulding	10/2095	1102.4	
1185	994545	Tailgate Garnish			
1186	994648	Tailgate Reflector			
1187	994549	Tailgate Lamp			
1188	994646	Tailgate Protector	3/12.4		
1189	994676	Tailgate Wiper Arm			
1190	994677	Tailgate Wiper Blade			
1191	994679	Tailgate Wiper Nozzle	20%: 2500		
1192	994555	Tailgate Wiper Motor			
1193	994602	Tailgate Glass			
1194	994606	Tailgate Glass Rubber			
1195	994604	Tailgate Glass Moulding			
1196	994607	Tailgate Glass Sealant			
1197	994629	Tailgate Lock			
1198	994651	Tailgate Rubber			
1199	994611	Tailgate Hinge			
1200	994594	Tailgate Damper			
1201	994613	Tailgate inner Board			

Vehicle No:

NAC	INC	Item	CON	AC	Qty
1202	993784	Spare Tyre Board			
1203	994328	Spare Tyre Panel			
1204	995065	Spare Tyre			
1205	994326	Spare Tyre Lock Screw			
1206	993787	Spare Tyre Cover			
1207	995323	Triangle Breakdown Sign			
1208	990507	CD Changer Assy			
1209	990164	Antenna			
1210	990534	Centre Exhaust Pipe Assy			
1211	990532	Centre Exhaust Mounting			
1212	993364	Rear Exhaust Pipe			
1213	993357	Rear Exhaust Chrome Pipe			
1214	993361	Rear Exhaust Mounting			
1215	993358	Rear Exhaust Heat Shield			
1216	995223	Rear LH Chassis Member			
1217	993165	Rear RH Chassis Member			
1218	993436	Rear LH Fender			
1219	993449	Rear LH Fender Protector			
1220	993420	Rear LH Fender Inner Panel			
1221	993431	Rear LH Fender Inner Trim			
1222	993415	Rear LH Fender Inner Garnish			
1223	993425	Rear LH Fender Inner Shield			
1224	993621	Rear LH Mudflap			
1225	993933	Rear LH Wheel Rim			
1226	994025	Rear LH Rim Cover			
1227	995065	Rear LH Tyre			
1228	993456	Rear RH Fender	720	Buc	1
1229	993450	Rear RH Fender Protector			
1230	993420	Rear RH Fender Inner Panel			
1231	993431	Rear RH Fender Inner Trim			
1232	993415	Rear RH Fender Inner Garnish			
1233	993425	Rear RH Fender Inner Shield	TN	1	44
1234	993622	Rear RH Mudflap			
1235	993934	Rear RH Wheel Rim	300(SN)	Int	1
1236	994025	Rear RH Rim Cover			
1237	995065	Rear RH Tyre			
1238	995162	Rear Fender Extension Panel LH			
1239	993401	Rear Fender Extension Panel RH			
1240	993430	Rear Fender Inner Top Garnish			
1241	993673	Rear Fender 1/4 Glass			
1242	993452	Rear Fender 1/4 Glass Rubber			
1243	993453	Rear Fender 1/4 Glass Sealant			
1244	993949	Rear Windscreen Glass			
1245	993976	Rear Windscreen Rubber			
1246	993961	Rear Windscreen Moulding			
1247	993955	Rear Windscreen Sealant			
1248	994729	Third Brake Light			
1249	993385	Rear Fender Air Grille			
1250	992167	Fuel Lid			
1251	992168	Fuel Neck			
1252	992179	Fuel Tank			
1253	992184	Fuel Tank Bracket			
1254	992191	Fuel Tank Float			
1136	990247	Sticker			
		Rear RH Door	Repair	x	794.8
		rear RH wheel hub bearing			rec 326.1
		panel beating			600
		spray painting			600
		wiring			30
		Anti rust			60
		Remove & refit sensor			60
		wheel Alignment			60
		Remove & refit bearing			80

No of Items:

Assessor:

1470

07/12/2017

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT

AUTOMOTIVE ENGINEERING & MGT DIVISION

Ref: CS3/SPF19004957/Gqd3s2

ACCIDENT CLAIM SECTION (SPORE POLICE
FORCE) 1 MOUNT PLEASANT ROAD BLK 8 OLD
POLICE ACADEMY SINGAPORE 298333

Date: 26-07-2019



ATTN: HAFIZUL FARHAN

Code: SPF

1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	QX 643S	Veh. Inspected	SKB 5676B
Policy No.		Coverage (\$)	0.00
Claim No.	2019/042	Excess (\$)	0.00
Assign From	HAFIZUL FARHAN	Assign Date	19/03/2019

2. Vehicle Particulars & Condition

Make & Model	KIA CERATO FORTE	c.c	1591
Engine No.	HIDDEN	Year of Reg.	2011
Chassis No.	KNAFU411MB5376239	Colour	BLACK
Odometer	112121 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/65R15	MICHELIN	6 mm
L/H Front Tyre	195/65R15	MICHELIN	6 mm
R/H Rear Tyre	195/65R15	MICHELIN	6 mm
L/H Rear Tyre	195/65R15	MICHELIN	6 mm

4. Description of DamagesTHE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION. THE
UNDERCARRIAGE AFFECTED DUE TO COLLISION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	16/03/2019	Inspect Date / Time	19/03/2019 (04:00 PM)
Survey held at	HARMONY MOTOR (AMK) PTE LTD BLK 10 ANG MO KIO IND. PARK 2A #02-12 AMK AUTOPOINT SINGAPORE 568047		

5a. Remarks

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	6 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

OPINION ON REPAIR COST FOR VEHICLE NO. SKB 5676B

Qty	Description of Parts	Condition	Recommended (\$)
	<u>REPLACEMENT OF PARTS</u>		
1	REAR BUMPER	BROKEN	607.00
1	REAR BUMPER CLIPS	NECESSARY	35.00
1	REAR BUMPER SIDE RETAINER RH	DEFORMED	22.00
1	REAR RH FENDER	BUCKLED	720.00
1	REAR RH FENDER INNER SHIELD	TORN	44.00
1	REAR RH DOOR	TO REPAIR SEE LABOUR	-
1	REAR RH WHEEL HUB BEARING	NECESSARY	326.10
	LESS 10% DISCOUNT		-175.41
			1,578.69
	<u>SPECIAL NETT ITEMS</u>		
1	REVERSE SENSOR (SN)	DAMAGED	200.00
1	REAR RH WHEEL RIM (SN)	CUT	300.00
			500.00
	<u>LABOUR</u>		
	PANEL BEATING. INCLUSIVE OF THE REPAIR OF REAR RH DOOR.		600.00
	SPRAY PAINTING.		600.00
	WIRING.		30.00
	ANTI RUST.		60.00
	REMOVE & REFIT SENSOR.		40.00
	WHEEL ALIGNMENT.		60.00
	REMOVE & REFIT BEARING.		80.00
			-
			-
			-
			-
			-
			-
			1,470.00
	GRAND TOTAL		3,548.69
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			2,800.00

Report Ref No. CS3/SPF19004957/Gqd3s2



Report Ref No. CS3/SPF19004957/Gqd3s2

THE ESTIMATED UPPER RANGE OF REPAIR COST FOR THE DAMAGED VEHICLE IS IN THE REGION OF \$2,800.00 - \$3,600.00

RECOMMENDED REPAIR DAYS : 6

WEEKENDS : 2

TOTAL DAYS : 8

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.