

Surveyor: Kelvin

REF:

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD/TP/WS/TP RES/OD RES/EVA/INV/INV

To Inspected Vehicle No: _____

at Workshop m/s _____

at _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Date / Time Action / Instruction

Date/Time, File Pass to?

☐ : Prel. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Payable By:

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$

☐ : Interview (\$

☐ : Test Drive (\$

☐ : Test and

Survey Fee:

Transportation:

\$ + \$5.00

Photos

Other

614-66

Veh No:

SHD 6837Y

Yr Regn:

25 Sep, 2015

Type: M.Car / M.Cycle / Bus / Van / Lorry / T/O / Prime Mover /

Truck / Trailer or

Make:

Hyundai Ix

c.c 1.63x

Colour

Blue

A/C: Insured / Std / Nil / NA

Sp. Reading

445703

T/Radio: Insured / Std / Nil / NA

Eng/No:

C/No:

KMH108410064078322

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD / Rim or

Tyre Size:

205/60R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Harika

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

15/3/19

D.O.I.

18/3/19

Survey held at

C D G E (Loyang)

Des. of Damages: Frt / Rear / O/S / N/S / VIC / Roof/lop or

Rear

The VIC / Chassis frame / Body Structure affected due to collision.

CTZ
4s.

Workshops

59 Loyang Drive Singapore 508969
383 Sin Ming Drive Singapore 575717
45 Pandan Road Singapore 609286

24 Senoko Loop Singapore 758156
7 Sungei Kadut Way Singapore 728791
501 Yishun Industrial Park A Singapore 768732

member of COMFORTDELGRO

Date/Time: 16.03.2019 08:57

Page : 1

Team: ARC Repair TP(CLS0)1

JOB CARD

Sales Order: 3906765

JC NO.: 305278135

COMER	REGN NO.: SHD6837Y	MILEAGE
IS	MAKE : HYUNDAI	FUEL
COMER NO. 7010045	MODEL I-40	E.....1/2.....F
RESS 383 SIN MING DRIVE	YR OF MANU 25.09.2015	DATE/TIME IN 16.03.2019 10:05
Singapore SINGAPORE 575717	CHASSIS CODE KMHLB41UMGU078329	TARGET DATE
65508755 (R) (O) (P)	COMPLETION DATE/TIME:	
OUNT CARD NO.		

Accident Date: 15.03.2019
NATURE: 3P 15.03.19/B


JOB DESCRIPTION

CHINA

S/NO

LABOR CODE

DESCRIPTION



CKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

wedgement Slip

Exit Pass

No.: SHD6837Y FZ CHINA

Vehicle No.: SHD6837Y

of Service Advisor

Signature/Date

Name of Service Advisor

Date

returned to Service Reception upon collection

To be kept by Security Guard