

Consumer

ASS. REP. REF.

FILE CS3/ALG19004966/Ecd3L2

Special Instruction

SUN Veyor

Steve

ASSIGNMENT (Office)

From (Person)

Chin Lee Ying

of

ALG

Date/Time

19/3/19 @ 2:34pm

Estimated Cost

Bill to

OIL / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No.

SGU 2306L

Insured

SLN 66H

at Workshop in/a

Sheng Hi Hai

Tel.

68420302

of

2 Kaki Bkt Ave 2 # 01-36

Policy No.

2100503664.

Claim No.

#70277818596

Sum Insured

Excess

Make of Veh.

(Client's Record)

D.O.A

14/3/19

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement

Date/Time

2:45pm @ 19/3/19

Person Contacted

Mr. Low

Vehicle

IN/OUT

Date/Time	Action/Instruction (X) Estimate	
	SLN 66H - H - NA / INC 19004819 / h4	D.O.A - 14/3/2019
	SGU 2306L - NA / INC 19004819 / h4	D.O.A - 14/3/2019
	Dismantle: 28/2/2019.	

ASSIGNMENT

From _____ Date: _____
 Estimated Cost _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s _____
 of _____
 Insured _____
 Policy No _____
 Claims No _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 6 days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No SGU 2306L Yt Regn. 7/05/2007
 Type: M.Car M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or

Make: Honda Civic 1.8 CC 1.8
 Colour Silver A/C Insured / Std / NI / NA
 Sp. Reading 346358 T/Ratio: Insured / Std / NI / NA

Eng/No: _____
 C/No: FD 11101620
 Gen. Cond: Good Fair Poor / Burnt

Steering: Inorder Jammed / Leaked / Burnt or

Brake: Inorder Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/552R16
 R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or NEXEN

Front	Rear
R/Bal. <u>7</u> mm	R/Bal. <u>7</u> mm
L/Bal. <u>7</u> mm	L/Bal. <u>7</u> mm
D.O.A. <u>14/3/19</u>	D.O.A. <u>19/3/19</u>

Survey held at Sheng Li Lai

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

front RH

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time : _____ Action / Instruction

MV- 23,000
 PV- 16,194
 NV- 6806

RECEIVED 29 MAR 2019

Date/Time: File Pass to?

☐ : Prel. Report

4)

Date/Time: File Return to?

☐ : Final Report

2)

Report Format :

DAR

Lump Sum / I.B.E. (\$) _____

Days Of Repair: 6

Resurvey No. of Trip: 1

Add Fee: ☐ : Site Insp (\$)

☐ : Interview (\$)

☐ : Tech Invs (\$)

☐ : Weekend (\$)

Survey Fee:

Transportation

) \$ - R.C. \$

) Photos

) Other

)

TOTAL

180
10
190

- PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURE...

From: Chin, Lee-Ying
To: assignments@lkkauto.com, admin-a@lkkauto.com
Cc: Fong, Andy-SY
Sent: 19/3/2019 2:34:06 PM
Attachments:  tmp1FE8.tif

Hi LKK,

Kindly assist to survey, vehicle in workshop.

Thanks.

Best Regards

Lee Ying, Chin

AIG

Claims | AIG Asia Pacific Insurance Pte. Ltd.

78 Shenton Way #08-16 Singapore 079120

Tel +(65) 6419 1947

Lee-Ying.Chin@aig.com | www.aig.sg

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

ONG & SHAN LLC

ADVOCATES & SOLICITORS
COMMISSIONERS FOR OATHS
NOTARIES PUBLIC

Our Counter-Signatory's Email Notifications:
Lawyer : ongshanllc@gmail.com
Secretary :

Please send all correspondences to:

- ☐ 2 Kallang Avenue #08-19 Singapore 339407
Tel: 6444 7845 | Fax: 6444 5847
- ☐ 101 Upper Cross Street #06-15B Singapore 058357
Tel: 6536 7991 | Fax: 6536 7995
- ☒ 184 Toa Payoh Central #02-364 Singapore 310184
Tel: 6224 9847 | Fax: 6254 7261

WE DO NOT ACCEPT SERVICE BY FAX

Our Ref : SRSTP.3616.19
Your Ref : Your Insured SLN 616H
Date : 18 March 2019

AIG Asia Pacific Insurance Pte Ltd
AIG Building
78 Shenton Way
#07-16
Singapore 079120

BY FAX ONLY 6835 7416

Dear Sirs

**NOTICE OF ACCIDENT
ROAD TRAFFIC ACCIDENT INVOLVING MOTOR VEHICLES SGU 2306L & SLN 616H
ON 14.03.2019 ALONG UPPER THOMSON ROAD @ 1815 HRS**

We act for the owner who has appointed the under-mentioned workshop to repair their motor vehicle no. SGU 2306L.

Please be informed that the said vehicle can be inspected at:

Name of workshop : Sheng Li Lai
Address : Kaki Bukit Auto Hub 2 Kaki Bukit Ave 2 #01-36 Singapore
417921
Contact person : Mr. Low
Telephone no. : 6842 0302
Fax no. : 6746 0295

We hereby give you 2 clear days' notice to conduct a pre-repair inspection of the said vehicle at the above-mentioned workshop during office hours.

ONG & SHAN LLC

A LIMITED LIABILITY CORPORATION | COMPANY REGISTRATION NUMBER 201408968D

THIS DOCUMENT IS FOR THE ADDRESSEE (S) ONLY & MAY CONTAIN CONFIDENTIAL INFORMATION &/OR MAY BE SUBJECT TO LEGAL PRIVILEGE. IF YOU HAVE RECEIVED THIS IN ERROR, PLEASE CONTACT US IMMEDIATELY.

ONG & SHAN LLC

... PAGE 2

Please note that if you fail to conduct the pre-repair inspection within the next 2 working days (excluding any intervening Saturday, Sunday and/or Public Holiday) you will be deemed to have waived your rights to a pre-repair inspection. The above-mentioned workshop will commence repairs thereafter without further notice to you. They will also be entitled to claim for the additional loss of use/rental arising as a consequence of this notification.

Yours faithfully,

ONG & SHAN LLC

Cc: Client
(By Fax Only)

ONG & SHAN LLC

A LIMITED LIABILITY CORPORATION | COMPANY REGISTRATION NUMBER 201408968D

THIS DOCUMENT IS FOR THE ADDRESSEE (S) ONLY & MAY CONTAIN CONFIDENTIAL INFORMATION &/OR MAY BE SUBJECT TO LEGAL PRIVILEGE. IF YOU HAVE RECEIVED THIS IN ERROR, PLEASE CONTACT US IMMEDIATELY.


> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Business
Owner ID:	1445M
Vehicle Details	
Vehicle No.:	SGU2306L
Vehicle to be Exported:	No
Intended Deregistration Date:	19 Mar 2019
Vehicle Make:	HONDA
Vehicle Model:	CIVIC 1.8B A
Primary Colour:	Silver
Manufacturing Year:	2007
Engine No.:	R18A1031726
Chassis No.:	FD11101620
Maximum Power Output:	103.0 kW (138 bhp)
Open Market Value:	\$18,190.00
Original Registration Date:	07 May 2007
First Registration Date:	07 May 2007
Transfer Count:	2
Actual ARF Paid:	\$20,009.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	30 Apr 2022
COE Category:	E - Open Category
COE Period(Years):	5
PQP Paid:	\$26,004.00
COE Rebate Amount:	\$16,194.00
Total Rebate Amount:	\$16,194.00
Message	
Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 19 Mar 2019

OK



[Advance Search](#)
[Home](#) » [Used Cars](#) » [Monster Motors Pte Ltd](#) » [Honda Civic 1.8A VTi-S \(COE till 02/2022\)](#)

Honda Civic 1.8A VTi-S (COE till 02/2022)

[Overview](#)
[Financial](#)
[Insurance](#)
[Accessories](#)
[Similar](#)
[Research](#)
[Photos](#)
[Map](#)
[PREMIUM AD](#)

CONSIGNMENT / BUY / SELL / SCRAP / EXPORT
Price \$23,800

Depreciation ⑦ \$8,130 /yr

Reg Date 21-Feb-2007
(2yrs 11mths 1day COE left)

Mileage 137,000 km (11.3k /yr)

Manufactured ⑦ 2006

Road Tax ⑦ \$1,174 /yr

Transmission Auto

Dereg Value ⑦ \$15,252 as of today (change)

OMV ⑦ \$20,032

COE ⑦ \$26,039

ARF ⑦ \$22,036

Engine Cap 1,799 cc

Power 103.0 kW (138 bhp)

Curb Weight ⑦ 1,219 kg

No. of Owners ⑦ 3

Type of Vehicle Mid-Sized Sedan

Features

1.8L 16 Valves I-VTEC Engine, 138 BHP, 5 Speed Automatic With Paddle Shifters, ABS, Airbags, Digital Climatic Aircon Controls. View specs of the Honda Civic (2006-2012)

Accessories

Sports Rims, Retractable Side Mirrors, Reverse Sensors.

Description

Full Loan Available, Easily One Of The Best Condition Civics In The Market. Loan Up To 90% Easy Loan Approval, High Trade In. Buy With Trust And Assur



Category

COE Car, Premium Ad Car

Status

Available

Re: [Compare](#)


[Location Map](#)
[Shortlist](#)
[Compare](#)
[Add note](#)
[Report Error](#)
[More Actions](#)

Seller Information

Company	Monster Motors Pte Ltd » dealer's pricelist » 53 vehs sold 141 vehs available
Address	453 Tagore Industrial Avenue #01-02 Search cars nearby this location
Location	Sindo Industrial Estate
Website	www.monstermotors.com.sg
Contact Person(s)	Enzo 975981



Enjoy rates from **3.7% p.a. (EIR 7% p.a.)**
plus **S\$88 Cash Back.**

Honda Civic

Price Range ▾

Depreciation ▾

> 10 year(s) ▾

Vehicle Type ▾

Advanced
Search

Home » Used Cars » D&L Auto Trading » Honda Civic 1.8A VTi-S (COE till 07/2022)

Honda Civic 1.8A VTi-S (COE till 07/2022)

Overview

Financial

Insurance

Accessories

Similar

Research

Photos

Map

Price **\$23,800**

Depreciation ⑦ **\$7,130 /yr**

Reg Date 20-Jul-2007
(3yrs 4mths COE left)

Mileage 138,000 km (11.8k /yr)

Manufactured ⑦ 2007

Road Tax ⑦ **\$1,174 /yr**

Transmission Auto

Dereg Value ⑦ **\$17,511 as of today (change)**

OMV ⑦ **\$19,453**

COE ⑦ **\$26,237**

ARF ⑦ **\$21,399**

Engine Cap 1,799 cc

Power 103.0 kW (138 bhp)

Curb Weight ⑦ 1,219 kg

No. of Owners ⑦ 4

Type of Vehicle Mid-Sized Sedan

Features

I-VTEC Engine, 138BHP, 5 Speed Auto, 2 x SRS Airbags, 4 x ABS Disc Brakes, Paddle Shifter, Auto Climatic Aircon Control, Knockdown Rear Seats. View specs of the Honda Civic (2006-2012)

Accessories

Genuine Leather Seats, New Sports Rims, New Tyres, Japan Factory Fitted Audio, Auto Retractable Side Mirror, Reverse Sensors, Door Visors.

Description

100% Guaranteed Accident Free, Beautiful Leather Interior, Extremely Well Maintained, Wear And Tear Fully Replaced, 90% Loan At 3.18%, Guaranteed Loan For Bad Credit/Ex Bankruptcy, View After Lunch Till 11PM Daily, Please Call To Arrange Viewing.

Category

COE Car

Status

Available

Resources



Car Valuation - Free

Compare

Get the market value of your existing car for free. Get started



Location Map

Shortlist

Compare

Add note

Report Error

More Actions

Seller Information

Company

D&L Auto Trading

» dealer's pricelist

» 29 vehs sold | 26 vehs availab

Address

200 Jalan Sultan #04-20

Search cars nearby this location

Location

Textile Centre

Office No

62960188

Contact Person(s)

Darren Low

96236

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	18/03/2019 08:51
Date Of Accident	14/03/2019 18:15
Exact Location Of Accident	UPP THOMSON RD JUNC WITH MARYMOUNT LN
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SGU2306L
Insured/Policyholder	
Name Of Registered Owner	STEAMMAPLEH
Co Reg No	53321445M
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-96968147
Alternative Phone No	OFFICE-96968147

Vehicle Particulars

Manufacturer	HONDA
Model	CIVIC
Exact Purpose for which vehicle was being used at time of accident	COMMERCIAL
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5100067093
Cover Note Number	-

Driver

Name of Driver	TONY YAU SUN ANN
NRIC No	S7285188I
Date Of Birth	12/11/1972
Occupation	OUTDOOR
Date Of Driving Pass	24/03/1995
Driving Experience	23 YEARS AND 11 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96968147
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	BLK 274A COMPASSVALE BOW #12-535
Postcode	541274
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - CROSS JUNCTION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : UNKNOWN
	GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE REFER TO ATTACHED STATEMENT.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	WITH DRIVER
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLN616H
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name	TONY YAU SUN ANN
Approximate Age	
Injuries Sustain	BODY
Injured person in which vehicle?	SGU2306L
Were seat belts worn?	YES
Was this injured conveyed to hospital by ambulance?	NO
Address	
Postcode	

DETAILS OF INJURED PERSON 2

Name	GRAB PASSENGER
Approximate Age	
Injuries Sustain	BODY
Injured person in which vehicle?	SGU2306L
Were seat belts worn?	YES
Was this injured conveyed to hospital by ambulance?	NO
Address	
Postcode	

Accident Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the extent of the accident to "pick up" the claims process.
2. This form must be **completed by the Policyholder and/or the Authorized Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this form by insurance companies **is not an admission of policy liability** on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers to the Traffic and Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that report of this report will for a time be made available upon application by interested parties.
7. By the signing of this report, the insured, jointly and severally, consents to the archiving of this report at the centre and for copies of the report being made available aforesaid.

Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my work insurer and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Ministry of Transport, Singapore and any relevant government agency/authority (such as the police) for the purpose(s)
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my claim(s) or responding to any enquiries by me;
 - (iv) administering my claims (including the receipt of, verification of, statements, invoices, reports or notices to me which could involve disclosure of certain part of a data about me to bring about delivery of the services with all or part of external contractors/agent/intermediaries, etc.);
 - (v) complying with statutory law enforcement, processing, handling and/or dealing with my claims (collectively the "Purposes");
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents including their lawyers/law firms, which may be located outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management, prevention and all future claims;
- (e) the information collected under (b) above may be shared, processed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulation, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any regulations, laws or court orders.

STEAMMAPLEH


Policyholder's Signature
(Type A, B, C, D, E)

Insurer's Signature
(Type A, B, C, D, E)
Date & Time

Insurer's Signature
Name
NRIC / N No.

Accident Sketch Plan

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Please Refer to Statement

DECLARATION

I hereby declare the foregoing particulars are true to my knowledge.

STEAMMAPLEH

Poleholder's Signature
Date & Time:

Driver's Signature
(If driver is not the poleholder)
Date & Time:

Reporting Centre Person's Signature
Name:
NPR 1114/14

Accident Sketch Plan

I WAS TRAVELLING ALONG UPP THOMSON RD WHILE APPROACHING TRAFFIC JUNC OF MARYMOUNT LANE, THE TRAFFIC LIGHT WAS ON MY FAVOR, I PROCEED TO CROSS THE JUNCTION. SUDDENLY VEH B (BEARING NO SLN616H) FROM OPPOSITE DIRECTION MAKE A RIGHT TURN, AS THE RESULT, MY VEH CANNOT STOP IN TIME AND HIT ONTO THE VEH LEFT FRONT PORTION.

STEAMMAPLEH

*Front Portion

NAC	INC	Item	CON	Ac	Qty
1001	991886	Frt Number Plate			
1002	991887	Frt Number Plate Base			
1003	991889	Frt Number Plate Garnish			
1004	991300	Frt Bumper	CR	✓	
1005	992341	Frt Bumper Clips	NEC	✓	
1006	991325	Frt Bumper Bracket			
1007	991462	Frt Bumper Side Retainer			
1008	991433	Frt Bumper Reinforcement	CR	✓	2
1009	991318	Frt Bumper Beam	DO	✓	
1010	991468	Frt Bumper Sponge			
1011	991427	Frt Bumper Protector			
1012	991420	Frt Bumper Pad			
1013	991363	Frt Bumper Grille			
1014	991301	Frt Bumper Moulding			
1015	991407	Frt Bumper Lower Spoiler	CR	✓	
1016	991438	Frt Bumper Sensor			
1017	995100	Frt LH Bumper Fog Lamp Cover			
1018	991355	Frt RH Bumper Fog Lamp Cover	CR	✓	
1019	995079	Frt LH Bumper Fog Lamp			
1020	995080	Frt RH Bumper Fog Lamp			
1021	991793	Frt Grille			
1022	991328	Frt Grille Emblem	CR	✓	
1023	991799	Frt Grille Chrome Moulding	NEC	✓	
1024	991222	Frt Apron Panel	CR	✓	
1025	992013	Frt Support Panel		R	
1026	992025	Frt Support Panel Top Garnish Cover			
1027	992416	Horn			
1028	991277	Frt Brace Panel			
1029	995153	Frt LH Headlamp Assy			
1030	991821	Frt RH Headlamp Assy			
1031	995088	Frt LH Side Lamp	CR	✓	
1032	995089	Frt RH Side Lamp			
1033	990248	Bonnet			
1034	991328	Bonnet Emblem		R	
1035	990287	Bonnet Lock			
1036	990285	Bonnet Insulator			
1037	990273	Bonnet Hinge			
1038	990261	Bonnet Damper			
1039	990305	Bonnet Rubber			
1040	990252	Bonnet Cable			
1041	990311	Bonnet Stand			
1042	990119	Air Con Condenser			
1043	990122	Air Con Fan Assy			
1044	990134	Air Con Suction Pipe (Low Pressure)			
1045	990118	Air Con Suction Hose			
1046	990133	Air Con Discharge Pipe (High Pressure)			
1047	990114	Air Con Discharge Hose			
1048	990149	Air Con Liquid Pipe			
1049	995066	Air Con Receiver Drier			
1050	990111	Air Con Compressor Assy			
1051	995294	Air Con Belt			
1052	995074	Radiator			
1053	992738	Radiator Cowling			
1054	992742	Radiator Fan Assy			
1055	992745	Radiator Fan Clutch			
1056	992758	Radiator Hose Top			
1057	992757	Radiator Hose Bottom			
1058	992741	Radiator Expansion Tank			
1059	990151	Air Duct			
1060	990070	Air Cleaner Assy			
1061	990056	Air Cleaner Hose			
1062	990339	Air Cleaner Resonator			
1063	991712	Frt Exhaust Manifold			
1064	991713	Frt Exhaust Manifold Cover			
1065	991054	Frt Exhaust Manifold Sensor (Oxygen)			
1066	991714	Front Exhaust Pipe			
1067	990219	Battery			
1068	990154	Battery Cover			

front RH Absorber
Knuckle arm bearing

BT	✓
GT	✓
GT	✓

MOTOR CAR (Fri)

NAC	INC	Item	QTY	UNIT	AMT	DATE
1071	992205	Fuse Box				
1072	994011	Relay Box				
1073	995053	Wiper Washer Tank				
1074	995052	Wiper Washer Tank Motor				
1075	990159	Alternator Assy				
1076	990160	Alternator Belt				
1077	992688	Power Steering Pump				
1078	992669	Power Steering Belt				
1079	994431	Power Steering Cooler Pipe				
1080	992692	Power Steering Hose				
1081	990010	ABS Pump Control Unit				
1082	990427	Brake Master Pump Assy				
1083	990403	Brake Booster Pump Assy				
1084	991005	Engine Top Cover				
1085	991011	Engine Under Cover				
1086	990946	Engine Mounting				
1087	990949	Engine Mounting Frt				
1088	990950	Engine Mounting LH				
1089	990952	Engine Mounting RH				
1090	990951	Engine Mounting Rear				
1091	992234	Gear Box Mounting				
1092	991520	Frt LH Chassis Member				
1093	991520	Frt RH Chassis Member				
1094	990728	Frt Vertical Cross Member				
1095	991863	Frt Lower Cross Member				
1096	995070	Frt LH Fender				
1097	995072	Frt LH Fender Inner Panel				
1098	995147	Frt LH Fender Lamp				
1099	995148	Frt LH Fender Protector				
1100	991740	Frt LH Fender Inner Shield				
1101	995179	Frt LH Mudflap				
1102	995170	Frt LH Wheel Rim				
1103	994025	Frt LH Rim Cover				
1104	995065	Frt LH Tyre				
1105	995071	Frt RH Fender	00	✓		
1106	991739	Frt RH Fender Inner Panel				
1107	991744	Frt RH Fender Lamp	CRW	✓		
1108	991752	Frt RH Fender Protector				
1109	991740	Frt RH Fender Inner Shield	CRW	✓		
1110	991884	Frt RH Mudflap				
1111	992087	Frt RH Wheel Rim	CRW	✓		
1112	994025	Frt RH Rim Cover				
1113	995065	Frt RH Tyre	CRW	✓		
1114	992093	Frt Windscreen Glass				
1115	992117	Frt Windscreen Rubber				
1116	992108	Frt Windscreen Moulding				
1117	992092	Frt Windscreen Sealant				
1118	991019	ERP Bracket				
1119	991020	ERP Unit				
1120	992140	Frt Wiper Arm				
1121	992142	Frt Wiper Blade				
1122	995045	Wiper Panel Garnish				
1123	991126	Firewall Panel				
1124	990753	Dashboard Assy				
1125	992282	Glove Box Cover				
1126	992281	Glove Box Compartment				
1127	994453	Steering Wheel Airbag				
1128	994455	Steering Wheel Airbag Sensor				
1129	990749	Dashboard Airbag				
1130	990750	Dashboard Airbag Sensor				
1131	990029	Airbag Control Unit				
1132	990864	Frt Driver Seat				
1133	991922	Frt RH Seat Belt Assy				
1134	991899	Frt Passenger Seat				
1135	995182	Frt LH Seat Belt Assy				
1136	990247	Shocker				

2/3/2019

...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

CLAIM SUBFOLDER TRACKING






































Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	20 Mar 2019 Edit Reg		19 Mar 2019 00:00 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case






























Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	Tan Guan Hock, ID: S1426466C, Tel: +6599999999								
Main Claimant:	-								
Vehicle Reg. No.:	SGU2306L	Date of Loss:	14/03/2019 00:00 - :59 [142 Months and 7 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 9663451420SG	Policy/Cover Note No.:	2100503664 (Comprehensive) Coverage: 14/03/2019 - 13/03/2020						
Vehicle Reg. No. (Insured):	SLN616H	Policy No. (Claimant):							
		Excess:							
Repairer:	Sheng Li Lai (KAKI BUKIT) NO. 2 KAKI BUKIT AVE 2, # 01-36 AUTOHUB KAKI BUKIT, 417921 Kaki Bukit - Tel: 91119222								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Loh, Chee-Heng] Chee-Heng.Loh@aig.com								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by CHEN TSUE YEE] ... [Final Rpt due 28/03/2019]								
Claimant's Solicitor:	ONG & SHAN LLC - Tel: 62249847								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
<ul style="list-style-type: none"> AIG_SG (20/03/2019): No OI GIA Report AIG_SG (20/03/2019): Request To Upload TP GIA Report 									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SGU2306L (9663451420SG)**
[SLN616H]
TP

-
Mar 14 2019 12:00AM
[Tan Guan Hock]
Sheng Li Lai

Upload Documents		Upload Photos		Compose New Letter		Upload Video		Upload Audio		View		View in Browser	
Photos/Images										3 per page		<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)								Thumbnail	Print		
1	29/03/19 12:35	General View								 Load JPG	<input checked="" type="checkbox"/>		
2	29/03/19 12:35	General View								 Load JPG	<input checked="" type="checkbox"/>		
3	29/03/19 12:35	General View								 Load JPG	<input checked="" type="checkbox"/>		
4	29/03/19 12:35	General View								 Load JPG	<input checked="" type="checkbox"/>		
5	29/03/19 12:35	General View								 Load JPG	<input checked="" type="checkbox"/>		
6	29/03/19 12:35	General View								 Load JPG	<input checked="" type="checkbox"/>		
7	29/03/19 12:35	General View								 Load JPG	<input checked="" type="checkbox"/>		
8	29/03/19 12:35	General View								 Load JPG	<input checked="" type="checkbox"/>		
9	29/03/19 12:35	General View								 Load JPG	<input checked="" type="checkbox"/>		
10	29/03/19 12:35	General View								 Load JPG	<input checked="" type="checkbox"/>		
11	29/03/19 12:35	General View								 Load JPG	<input checked="" type="checkbox"/>		
12	29/03/19 12:35	General View								 Load JPG	<input checked="" type="checkbox"/>		
13	29/03/19 12:35	General View								 Load JPG	<input checked="" type="checkbox"/>		
14	29/03/19 12:35	General View								 Load JPG	<input checked="" type="checkbox"/>		
15	29/03/19 12:35	General View								 Load JPG	<input checked="" type="checkbox"/>		
16	29/03/19 12:35	General View								 Load JPG	<input checked="" type="checkbox"/>		
17	29/03/19 12:35	General View								 Load JPG	<input checked="" type="checkbox"/>		
18	29/03/19 12:35	General View								 Load JPG	<input checked="" type="checkbox"/>		
19	29/03/19 12:35	General View								 Load JPG	<input checked="" type="checkbox"/>		
20	29/03/19 12:35	General View								 Load JPG	<input checked="" type="checkbox"/>		
21	29/03/19 12:35	General View								 Load JPG	<input checked="" type="checkbox"/>		
22	29/03/19 12:35	General View								 Load JPG	<input checked="" type="checkbox"/>		
23	29/03/19 12:35	General View								 Load JPG	<input checked="" type="checkbox"/>		
24	29/03/19 12:35	General View								 Load JPG	<input checked="" type="checkbox"/>		
25	29/03/19 12:35	General View								 Load JPG	<input checked="" type="checkbox"/>		
26	29/03/19 12:35	General View								 Load JPG	<input checked="" type="checkbox"/>		
27	29/03/19 12:35	General View								 Load JPG	<input checked="" type="checkbox"/>		
28	29/03/19 12:35	General View								 Load JPG	<input checked="" type="checkbox"/>		
29	29/03/19 12:35	General View								 Load JPG	<input checked="" type="checkbox"/>		
30	29/03/19 12:35	General View								 Load JPG	<input checked="" type="checkbox"/>		
31	29/03/19 12:35	General View								 Load JPG	<input checked="" type="checkbox"/>		
32	29/03/19 12:35	General View								 Load JPG	<input checked="" type="checkbox"/>		
33	29/03/19 12:35	General View								 Load JPG	<input checked="" type="checkbox"/>		
34	29/03/19 12:35	General View								 Load JPG	<input checked="" type="checkbox"/>		
35	29/03/19 12:35	General View								 Load JPG	<input checked="" type="checkbox"/>		
36	29/03/19 12:35	General View								 Load JPG	<input checked="" type="checkbox"/>		
37	29/03/19 12:35	General View								 Load JPG	<input checked="" type="checkbox"/>		

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/ Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	29/03/19 12:35	General View	 Load JPG	<input checked="" type="checkbox"/>
39	29/03/19 12:35	General View	 Load JPG	<input checked="" type="checkbox"/>
40	29/03/19 12:35	General View	 Load JPG	<input checked="" type="checkbox"/>
41	29/03/19 12:35	General View	 Load JPG	<input checked="" type="checkbox"/>
42	29/03/19 12:35	General View	 Load JPG	<input checked="" type="checkbox"/>
43	29/03/19 12:35	General View	 Load JPG	<input checked="" type="checkbox"/>
44	29/03/19 12:35	General View	 Load JPG	<input checked="" type="checkbox"/>
45	29/03/19 12:36	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
46	29/03/19 12:36	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
47	29/03/19 12:36	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
48	29/03/19 12:36	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
49	29/03/19 12:36	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
50	29/03/19 12:36	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
51	29/03/19 12:36	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
52	29/03/19 12:36	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
53	29/03/19 12:36	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
54	29/03/19 12:36	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
55	29/03/19 12:36	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
56	29/03/19 12:36	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
57	29/03/19 12:36	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
58	29/03/19 12:36	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
59	29/03/19 12:36	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
60	29/03/19 12:36	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
61	29/03/19 12:36	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
62	29/03/19 12:36	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
63	29/03/19 12:36	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
64	29/03/19 12:36	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
65	29/03/19 12:36	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
66	29/03/19 12:36	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
67	29/03/19 12:36	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
68	29/03/19 12:36	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
69	29/03/19 12:36	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
70	29/03/19 12:36	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
71	29/03/19 12:36	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
72	29/03/19 12:36	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
73	29/03/19 12:36	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
74	29/03/19 12:36	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
75	29/03/19 12:36	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	20/03/19 16:10	OI GIA REPORT	 Load PDF	
2	26/03/19 10:18	TP GIA	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST			Reset	Save	Print
There are no document checklists configured.					

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**Show Remarks To:** ☐ Handling InsurerNote: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG19004966/ECD3E2

Date: 01/04/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No: 2100503664

Claimant Vehicle No : SGU2306L

Insured Vehicle No : SLN616H

Date of Loss: 14/03/2019

Nature of Claim: TP

Claim No: 9663451420SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SGU2306L

Make & Model: HONDA CIVIC, 1.8 (A)

Engine No: R18A1031726

Reg. Date: 07/05/2007 (Man. Year: 2007)

Chassis No: FD11101620

Colour: Silver

Odometer: 346358 km

Engine Capacity: 1799 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55Z R16

Rear Tyre Size: 205/55Z R16

Front Left Side: Nexen 7 mm

Rear Left Side: Nexen 7 mm

Front Right Side: Nexen 7 mm

Rear Right Side: Nexen 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (\$\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 19/03/2019

Date Inspected: 19/03/2019 Inspected At:

Sheng Li Lai (KAKI BUKIT)
NO. 2 KAKI BUKIT AVE 2, # 01-36
AUTOHUB KAKI BUKIT
Singapore 417921

Estimated Period of Repair: 6.0 days

Adjuster: CHEN TSUE YEE

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT BUMPER	Broken	0.00 F	*- F
2	1		*FRT BUMPER CLIPS	Necessary	0.00 F	*- F
3	2		*FRT BUMPER SIDE RETAINER	Broken	0.00 F	*- F
4	1		*FRT BUMPER REINFORCEMENT	Dented	0.00 F	*- F
5	1		*FRT BUMPER LOWER SPOILER	Cut	0.00 F	*- F
6	1		*FRT RH BUMPER FOG LAMP COVER	Broken	0.00 F	*- F
7	1		*FRT GRILLE	Cut	0.00 F	*- F
8	1		*FRT GRILLE EMBLEM	Necessary	0.00 F	*- F
9	1		*FRT GRILLE CHROME MOULDING	Cut	0.00 F	*- F
10	1		*FRT APRON PANEL	Repair	0.00 F	*- F
11	1		*FRT LH HEADLAMP ASSY	* Check	0.00 F	*- F
12	1		*FRT RH HEADLAMP ASSY	Broken	0.00 F	*- F
13	1		*BONNET	Repair	0.00 F	*- F
14	1		*FRT RH FENDER	Dented	0.00 F	*- F
15	1		*FRT RH FENDER INNER GARNISH	Crumpled	0.00 F	*- F
16	1		*FRT RH FENDER INNER SHIELD	Crumpled	0.00 F	*- F
17	1		*FRT RH WHEEL RIM	Cut	0.00 F	*- F
18	1		*FRT RH TYRE	Cut	0.00 F	*- F
19	1		*FRONT RH ABSORBER	Bent	0.00 F	*- F
20	1		*FRONT RH KNUCKLE ARM	Bent	0.00 F	*- F
21	1		*FRONT RH KNUCKLE ARM BEARING	Bent	0.00 F	*- F
22	1		*FRT RH BUMPER FOG LAMP	* Check	0.00 F	*- F

F=Franchise part.

Total Parts (S\$)	0.00	0.00
-------------------	------	------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >