

ASS. REC. HY

REF: C83/CTI 1004967/Gudzen

Special Instruction:

Surveyor

GL

ASSIGNMENT (Office)

From (Person):

Chong Jansen

of

CTE

Date/Time:

19/3/19

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MYTC

To Inspect Vehicle No:

SLQ 9529B

Insured:

GLIY

at Workshop in:

Reliable Carz

Tel:

81669797

of

8 Laki Bkt Ave 4 # 05-50

Policy No:

Claim No:

3NM19D201207

Sum Insured:

Excess:

Make of Veh.

D.O.A.

15/03/19

(Client's Record)

CA / REV / REP. / REV 24 HRS

20/3/19

(I.O.D. Endorsement)

Date/Time:

4:08pm 19/3/19

Person Contacted:

Joson

Vehicle

IN/OUT

Date/Time

Action/Instruction (X) Estimate

SLQ 9529B - NA / INC 19004831 / h4

2019. 15/3/19

GLIY - X

Dismantle: 21/3/2019

After repair: 29/3/2019

Surveyor

PRS  
60

REF: CR

C1527N

### ASSIGNMENT

From: \_\_\_\_\_ Date: 20/3/19

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLQ 9529B

at Workshop m/s Reliable Carz

of 8 kaki Bkt Ave 4 # 05-50

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_


Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: 5 days Res: Yes or No

Lum Sum: 2. % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Veh No: SLQ 9529B Yr Regn: 27 Jul 2017

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda Shuttle C.C. 1496

Colour: Red A/C: Insured / Std / NI / NA

Sp. Reading: 96925 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: GP 71114315

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 185/60 R15

R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. \_\_\_\_\_ D.O.I. 20-03-19

Survey held at w/s 4pm

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

\$4000 - \$5000

Date/Time, File Pass to?

☐ : Preli. Report

Days Of Repair: 5

1)

☐ : Final Report

Resurvey No. of Trip: 2

Date/Time, File Return to?

Survey Fee:

2)

Add Fee: ☐ : Site Insp (\$)

Transportation:

Report Format: PRS

☐ : Interview (\$)

Photos

☐ : Tech. Insp (\$)

Others

☐ : Weekend (\$)

TOTAL

Lump Sum / I.B.I: (\$ \_\_\_\_\_)

190

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	(Not Notified)		06 Jun 2019 09:13 <a href="#">Edit Adj Rpt</a>				<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	<a href="#">Show All</a>					
<b>CLAIM SUBFOLDER DETAILS</b>			<b>[Created by insurer]</b>						
Insured:									
Main Claimant: <b>RELIABLE RIDES PTE LTD, Co. Reg. No.: 201611527N</b>									
Vehicle Reg. No.: <b>SLQ9529B</b>		Date of Loss: 15/03/2019 10:00 - :59							
Claim Type: <b>TP</b>		Policy/Cover Note No.:							
Vehicle Reg. No. (Insured): <b>GL11Y</b>		Policy No. (Claimant): 5092730558-01							
		Excess: S\$0.00							
Repairer: <b>Reliable Carz Pte Ltd (HQ) 8 Kaki Bukit Ave 4, #05-50, 415875 Kaki Bukit - Tel:</b>									
Handling Insurer: <b>China Taiping Insurance (Singapore) Pte. Ltd, (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]</b>									
Claimant's Insurer: <b>NTUC Income Insurance Co-operative Ltd (HQ) - Tel:</b>									
Adjuster: <b>LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 17/06/2019]</b>									
<b>ASSOCIATED MAIL RECEIVED</b>				<a href="#">View All</a> <a href="#">Compose Case Mail</a>					
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b>				<a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a>					
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

**Nivitha (LKK Auto)**

---

**From:** Chong Boon Sen <boonsen.chong@sg.cntaiping.com>  
**Sent:** Tuesday, 19 March 2019 3:36 PM  
**To:** Hui Ting  
**Cc:** Corene; assignments  
**Subject:** RE: OUR REF: SNM19D201207 - & Yr client's vehicle no. SLQ9529B (RC); Your insured's vehicle no. GL11Y - PRI  
**Attachments:** Reliable Carz - Pre-Repair Notice (CHINA)(SLQ9529B).pdf

WITHOUT PREJUDICE  
SAVE AS TO COSTS

Dear Sir,

We refer to your email.

We regret to inform that we are not agreeable to your list of proposed surveyors and will be assigning our panel surveyor, M/s LKK Auto Consultants to conduct the Pre-repair survey.

Please contact our surveyor to conduct the post repair inspection before returning the repaired vehicle to the claimant.

Aside to LKK,

Please refer to the email below and liaise with third party workshop accordingly.

Thank you.

Regards,  
**Chong Boon Sen**  
Claims Executive  
Claims

**China Taiping Insurance (Singapore) Pte. Ltd.**  
3 Anson Road #16-00 Springleaf Tower  
Singapore 079909  
Co. Reg. No. 200208384E  
DID: 63896171  
Fax: 62247175  
Email: boonsen.chong@sg.cntaiping.com  
Website: www.sg.cntaiping.com

*Disclaimer :*

*This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.*

---

**From:** Hui Ting [mailto:huiting@crossbordersllc.com]  
**Sent:** Tuesday, 19 March, 2019 3:25 PM  
**To:** Chong Boon Sen <boonsen.chong@sg.cntaiping.com>  
**Cc:** Corene <corene@crossbordersllc.com>  
**Subject:** RE: OUR REF: SNM19D201207 - & Yr client's vehicle no. SLQ9529B (RC); Your insured's vehicle no. GL11Y - PRI

Your attention is drawn to the CONFIDENTIALITY NOTICE below.

---

**WITHOUT PREJUDICE**

Dear Boon Sen

1. We refer to your email dated 19 March 2019.
2. Our client objects appointing your surveyors as a single joint expert.
3. We propose one of the motor surveyors named in the list below to conduct the joint pre-repair survey as a single joint expert:-
  - a) Mr Dave Sincere Appraisal Services
  - b) Dennis Yap PAL'S Appraiser Pte Ltd
  - c) Dave Chang Sincere Appraisal Services
  - d) Yap Teck Chye MC-Coy Appraiser Pte Ltd
  - e) Dixon Yeo Treasure Appraiser Pte Ltd
  - f) Andrew How Prominent Appraiser Services
  - g) Alan Cheong K.H. C L Appraiser Pte Ltd
  - h) T.T. Rajan ST Appraisal Services
  - i) Sebastian Lim Constanct Appraiser Services
  - j) Aeon Auto Consultants LLP
4. Please let us know within two (2) working days whether you are agreeable to the appointment of any of the above motor surveyors as a single joint expert.

Thank You.

Regards  
Huiting  
TEL: 6438 1323 ext 2006

CrossBorders LLC  
133 New Bridge Road  
#23-03/04/05 Chinatown Point  
Singapore 059413  
Tel: (65) 6438 1323  
Fax: (65) 6438 2313

**CONFIDENTIALITY NOTICE**

This e-mail from CrossBorders LLC (including any attachment(s) to it) is confidential and may also be privileged and exempt from disclosure under applicable law. Accordingly, if you are not the intended recipient please notify us immediately, delete this e-mail (including any attachment to it) from your computer system and do not disclose or distribute it to any other person or continue to read this e-mail. Thank you.

**CrossBorders LLC DOES NOT ACCEPT SERVICE OF COURT DOCUMENTS OR NOTICE OF ANY PROCEEDINGS BY FACSIMILE OR EMAIL**

**From:** Chong Boon Sen <[boonsen.chong@sg.cntaiping.com](mailto:boonsen.chong@sg.cntaiping.com)>

**Sent:** Tuesday, 19 March 2019 3:24 PM

**To:** Corene <[corene@crossbordersllc.com](mailto:corene@crossbordersllc.com)>; Hui Ting <[huiting@crossbordersllc.com](mailto:huiting@crossbordersllc.com)>

**Subject:** RE: OUR REF: SNM19D201207 - & Yr client's vehicle no. SLQ9529B (RC); Your insured's vehicle no. GL11Y - PRI

Without Prejudice

Dear Sir,

We intend to conduct a pre-repair survey of the damage to your client's vehicle jointly with your client/your motor workshop. We propose to use one of the following motor surveyors to conduct the joint pre-repair survey as a single joint expert.

ADRIAN LING
Kelvin Ang
SEE CHEW SENG
MOHD FADHILAH BIN OSMAN
XING QUO QIANG
KENNETH KONG
SIMON HO
CHUA WEIJIE
MARCUS CHUA
HENRY NG

Please let us know within two(2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.

You may select one of the listed motor surveyors and we will bear the cost of the pre-repair survey carried out by the single joint expert.

Regards,

**Chong Boon Sen**

Claims Executive

Claims

**China Taiping Insurance (Singapore) Pte. Ltd.**

3 Anson Road #16-00 Springleaf Tower

Singapore 079909

Co. Reg. No. 200208384E

DID: 63896171

Fax: 62247175

Email [boonsen.chong@sg.cntaiping.com](mailto:boonsen.chong@sg.cntaiping.com)

Website [www.sg.cntaiping.com](http://www.sg.cntaiping.com)

*Disclaimer :*

*This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.*

**From:** Hui Ting [<mailto:huiting@crossbordersllc.com>]

**Sent:** Monday, 18 March 2019 12:05 PM

To: Claims Dept of CTI <[claimsdept@sg.cntaiping.com](mailto:claimsdept@sg.cntaiping.com)>

Cc: Corene <[corene@crossbordersllc.com](mailto:corene@crossbordersllc.com)>

Subject: Our client's vehicle no. SLQ9529B (RC); Your insured's vehicle no. GL11Y - PRI

Your attention is drawn to the CONFIDENTIALITY NOTICE below.

---

**WITHOUT PREJUDICE**

Dear Sirs

1. Please find attached our PRI notice dated 18 March 2019 for your kind attention.
2. Please reply email to [corene@crossbordersllc.com](mailto:corene@crossbordersllc.com) & [huiting@crossbordersllc.com](mailto:huiting@crossbordersllc.com)

Thank You.

Regards

Huiting

TEL: 6438 1323 ext 2006

CrossBorders LLC  
133 New Bridge Road  
#23-03/04/05 Chinatown Point  
Singapore 059413  
Tel: (65) 6438 1323  
Fax: (65) 6438 2313

**CONFIDENTIALITY NOTICE**

This e-mail from CrossBorders LLC (including any attachment(s) to it) is confidential and may also be privileged and exempt from disclosure under applicable law. Accordingly, if you are not the intended recipient please notify us immediately, delete this e-mail (including any attachment to it) from your computer system and do not disclose or distribute it to any other person or continue to read this e-mail. Thank you.

CrossBorders LLC DOES NOT ACCEPT SERVICE OF COURT DOCUMENTS OR NOTICE OF ANY PROCEEDINGS BY FACSIMILE OR EMAIL

---

This email has been scanned by the Symantec Email Security.cloud service.  
For more information please visit <http://www.symanteccloud.com>

---

---

This email has been scanned by the Symantec Email Security.cloud service.  
For more information please visit <http://www.symanteccloud.com>

---

# CrossBORDERS LLC

Advocates & Solicitors | Commissioner for Oaths | Notary Public

Our Ref: AJ.tk.RC (SLQ9529B)  
Your Ref: GL11Y

18 March 2019

✓ China Taiping Insurance (Singapore) Pte. Ltd.  
3 Anson Road  
#16-00 Springleaf Tower  
Singapore 079909  
Attn: Motor Claims Department

BY FAX: 6224 7478 & EMAIL

URGENT

MAIN OFFICE  
133 NEW BRIDGE ROAD  
#23-03/04/05  
CHINATOWN POINT  
SINGAPORE 059413  
TEL: 6438 1323  
FAX: 6438 2313

BRANCH OFFICE  
1 JALAN BERSEH  
#03-12 NEW WORLD CENTRE  
SINGAPORE 209037

PLEASE SEND ALL  
CORRESPONDENCES TO  
THE MAIN OFFICE

WE DO NOT ACCEPT  
SERVICE BY FAX

Dear Sirs

NOTICE TO INSURER TO CONDUCT PRE-REPAIR INSPECTION  
CLAIMANT: LIM PECK SIONG  
TRAFFIC ACCIDENT ON 15 MARCH 2019 AT 10:00 HRS ALONG AYE TOWARDS CTE  
(MCE) AFTER LOWER DELTA INVOLVING VEHICLES NO. SLQ9529B & GL11Y &  
SFV2488B

We are instructed by Lim Peck Siong to notify you of a road accident on 15 March 2019 at about 10:00 hrs along AYE towards CTE (MCE) after Lower Delta involving our client's vehicle registration number SLQ9529B and vehicle registration number GL11Y driven by your insured at the material time. A copy of the Singapore accident statement/traffic police report filed is enclosed.

As a result of the accident, our client's vehicle has been damaged. Before our client proceeds to repair the damaged vehicle, please let us know within 2 working days (excluding any intervening Saturday, Sunday and Public Holiday) of your receipt of this notice whether you or your insurer would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you.

Please be informed that the said vehicle can be inspected at:

Venue: Reliable Carz Pte Ltd -  
Address: 8 Kaki Bukit Avenue 4  
#05-50  
Singapore 4157875  
Contact: Jason Lee (8166 9797)

Please liaise with the above workshop directly.

Yours faithfully

*CrossBorders LLC*  
CrossBorders LLC  
Email: [corene@crossbordersllc.com](mailto:corene@crossbordersllc.com) /  
[huiting@crossbordersllc.com](mailto:huiting@crossbordersllc.com)  
encs

PLEASE LET US KNOW THE DATE  
OF THE PRE-REPAIR INSPECTION

## CONFIDENTIALITY CAUTION

THIS DOCUMENT IS FOR THE ADDRESSEE(S) ONLY AND MAY CONTAIN CONFIDENTIAL INFORMATION AND/OR MAY BE SUBJECT TO LEGAL PRIVILEGE. IF YOU HAVE RECEIVED THIS IN ERROR, PLEASE CONTACT US IMMEDIATELY.

## CrossBORDERS LLC

A LIMITED LIABILITY CORPORATION, REGISTRATION NUMBER 201305284K  
GST REGISTRATION NUMBER 201305284K



> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	1527N
Vehicle Details	
Vehicle No.:	SLQ9529B
Vehicle to be Exported:	No
Intended Deregistration Date:	21 Mar 2019
Vehicle Make:	HONDA
Vehicle Model:	SHUTTLE HYBRID 1.5X AUTO
Primary Colour:	Red
Manufacturing Year:	2017
Engine No.:	LEB6317442
Chassis No.:	GP71114315
Maximum Power Output:	101.0 kW (135 bhp)
Open Market Value:	\$26,421.00
Original Registration Date:	27 Jul 2017
First Registration Date:	27 Jul 2017
Transfer Count:	0
Actual ARF Paid:	\$5,000.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	26 Jul 2027
PARF Rebate Amount:	\$3,750.00
Intended COE Rebate Details	
COE Expiry Date:	26 Jul 2027
COE Category:	E - Open - all except motorcycle
COE Period(Years):	10
QP Paid:	\$50,526.00
COE Rebate Amount:	\$41,825.00
<b>Total Rebate Amount:</b>	<b>\$45,575.00</b>

The information contained herein is correct as at 21 Mar 2019

OK

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	15/03/2019 11:45
Date Of Accident	15/03/2019 10:00
Exact Location Of Accident	AYE TWDS CTE(MCE) AFTER LOWER DELTA
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SLQ9529B
<b>Insured/Policyholder</b>	
Name Of Registered Owner	RELIABLE RIDES PTE LTD
Co Reg No	201611527N
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-81669797
<b>Vehicle Particulars</b>	
Manufacturer	HONDA
Model	SHUTTLE
Exact Purpose for which vehicle was being used at time of accident	COMMERCIAL
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE
<b>Insurance Company</b>	
Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5092730558-01
Cover Note Number	-
<b>Driver</b>	
Name of Driver	LIM PECK SIONG (LIN BOXIANG)
NRIC No	S7416052B
Date Of Birth	22/05/1974
Occupation	OUTDOOR
Date Of Driving Pass	08/03/2013
Driving Experience	6 YEARS AND 0 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-84887480
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address	BLK 485D CHOA CHU KANG AVE 5 #08-134
Postcode	684485
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	3
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : SIVVIN GENDER: : FEMALE

#### Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	CHOA CHU KANG NPC
Police Station Address	ROAD: 20 CHOA CHU KANG ST 52 #01-02 , POSTCODE: 689286 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: - FAX NO:
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

I WAS TRAVELLING ALONG AYE TWDS CTE(MCE) AFTER LOWER DELTA ON THE SECOND LANE, SUDDENLY A LORRY FROM THE THIRD LANE ABRUPTLY CUT INTO MY LANE AND HIT ONTO MY VEH LEFT SIDE MIRROR. AFTER THE IMPACT, I STOP MY VEH, THE SAY LORRY NEVER STOP AND LEAVE THE SCENE, MOMENT LATER I FELT ANOTHER IMPACT FROM THE REAR, AFTER THE INCIDENT, I ALIGHTED FROM MY VEH AND REALIZED VEH B(BEARING NO SFV2488B) HIT ONTO MY VEH REAR PORTION. VEH B BEEN HIT BY ANOTHER VEH C (BEARING NO GL11Y) FROM THE REAR.

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	WITH DRIVER
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SFV2488B
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR

Name of Driver  
NRIC/Passport Number  
Contact Number  
Address  
Postcode  
Insurance Company Name  
Nature Of Damage  
No. Of Passenger (Including Driver)

#### DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number GL11Y  
Vehicle Make/Model/Colour  
Details Of Properties  
Vehicle Category COMMERCIAL VEHICLE  
Name of Driver  
NRIC/Passport Number  
Contact Number  
Address  
Postcode  
Insurance Company Name  
Nature Of Damage  
No. Of Passenger (Including Driver)

#### DETAILS OF OTHER VEHICLE PROPERTY 3

Vehicle Registration Number UNKNOWN  
Vehicle Make/Model/Colour  
Details Of Properties  
Vehicle Category COMMERCIAL VEHICLE  
Name of Driver  
NRIC/Passport Number  
Contact Number  
Address  
Postcode  
Insurance Company Name  
Nature Of Damage  
No. Of Passenger (Including Driver)

#### DETAILS OF INJURED PERSON 1

Name LIM PECK SIONG (LIN BOXIANG)  
Approximate Age  
Injuries Sustain BODY  
Injured person in which vehicle? SLQ9529B  
Were seat belts worn? YES  
Was this injured conveyed to hospital by ambulance? NO  
Address  
Postcode

#### DETAILS OF INJURED PERSON 2

Name SIVVIN  
Approximate Age  
Injuries Sustain BODY  
Injured person in which vehicle? SLQ9529B  
Were seat belts worn? YES

## Accident Sketch Plan

### SKETCH PLAN

#### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

# Accident Sketch Plan

## SKETCH PLAN

A = SLR 95298  
B = SFV 24228  
C = GL 11Y  
D = Unknown

AVE 1400; CTE (HCE)

## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Please refer to statement

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

## POLICE REPORT



**SINGAPORE  
POLICE FORCE**



T201903160138

1 of 4

Report No. T201903160138

Police Station Of Origin  
Choa Chu Kang N.P.C.  
20 Choa Chu Kang Street 52 #01-02  
SINGAPORE 689286  
Tel No. 1800-7859999

## REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made 15/03/2019 17:07	Vote Report No.	Station Diary No. 151
---	-----------------	--------------------------

## Informant's Particulars

Name of Informant LIM PECK SIONG		Address APT BLK 485D CHOA CHU KANG AVENUE 5 #08-134 SINGAPORE 684655	
ID Type / ID No. NRIC NO / 57416052B		Contact No. Home/Office Mobile 94587400	
Nationality SINGAPORE CITIZEN		Email	
Sex Male	Age 44	Date of Birth 22/05/1974	Type of Informant Driver
Race Chinese		Language	Institution / School Name
Occupation GRAB DRIVER		Driving Licence Information Class: 3 Date of Expiry	

## General Information of the Accident

Type of Accident	Injury Hit and Run	Drink Drive No	Date/Time of Accident 15/03/2019 10:00	Type of Location Straight Road
Location Along Road 1 AYER RAJAH EXPRESSWAY				
Along AYE towards CTEMCE after Jover Delta on the second lane				
Weather Clear	Road Surface Dry	Road Speed Limit		
Traffic Flow One Way	Traffic Control Not Controlled	Traffic Volume Light		
Type of Collision Between Moving Vehicles - Side Swipe - Same Direction				Anyone conveyed by ambulance No

## Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No. of Passengers
GL11Y	Van				Slightly Damaged	0
5PV2488B	Car				Slightly Damaged	0
SLO9529B	Car				Slightly Damaged	0

## POLICE REPORT



**SINGAPORE  
POLICE FORCE**

Police Station Of Origin:  
Choa Chu Kang N.P.C.  
20 Choa Chu Kang Street 52 #01-02  
SINGAPORE 680286  
Tel No: 1800-7659999



1301803160135

2 of 4

Report No: 1301803160135

## CONTINUATION OF REPORT


Details of Person Involved			
Any Pedestrian Involved: No		Use of Pedestrian Crossing: NA	
No. of Pedestrians Injured: NIL			
<b>Driver:</b>			
Name	Lee Poh Chuan	ID No.	S1278730H
Related Vehicle	GL11Y (Van)	Contact No.	84285279
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
<b>Driver:</b>			
Name	Chee Kok Weng	ID No.	S0143067Z
Related Vehicle	SFV2488B (Car)	Contact No.	81003545
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
<b>Driver:</b>			
Name	LIM PECK SIONG	ID No.	S7416052B
Related Vehicle	SLQ9529B (Car)	Contact No.	84887480
Hospital/Clinic	NG TENG FONG GENERAL HOSPITAL	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	15/03/2019	Date Discharge	NIL
No. of Days granted Medical Leave	07	Degree of Injury	Slight

**Brief Details:**


On 15/03/2019 at about 0855hrs to 1010hrs, I was driving my car (SLQ9529B) along AYE towards CTE(MCE) after lower Delta on the second lane, sending my passenger to his destination. Suddenly, a lorry came from my car (SLQ9529B) left side in high speed and his vehicle right side swipe with my car (SLQ9529B) left side which causes my front bumper to drop off. The lorry did not stop his vehicle and drove off. As I stopped my car (SLQ9529B) due to the hit and run, the car (SFV2488B) behind me could not stop his car (SFV2488B) in time hence his car (SFV2488B) front hit onto my car (SLQ9529B) rear. There is another van (GL11Y) hit onto the car (SFV2488B) rear. All parties came out of their vehicles & exchanged particulars. All parties ensure that there is no immediate medical attention needed. No police



POLICE REPORT


 **SINGAPORE  
POLICE FORCE**

Police Station Of Origin:  
Choa Chu Kang N.P.C  
20 Choa Chu Kang Street S2 801-02  
SINGAPORE 680286  
Tel No: 1800-7659999

  
T201902192130  
3 of 4  
Report No. T201902192130

CONTINUATION OF REPORT

not ambulance were at scene. No government property damaged. I have an in car camera which recorded the lorry that side swipe with my car (SLQ95298) however the footage could not see the lorry plate number



# POLICE REPORT



**SINGAPORE  
POLICE FORCE**

Police Station Of Origin  
Choa Chu Kang N.P.C.  
20 Choa Chu Kang Street 52 #01-02  
SINGAPORE 680208  
Tel No: 1800-7650009



Report No: T201903160105

CONTINUATION OF REPORT

## Sketch Plan

Informant is not able to provide sketch plan

**IMPORTANT:** Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference

Signature Of Officer Recording The Report

J /  
Sgt Z 600 AU EN

Signature Of Interpreter  
Not Applicable

Officer In Charge Of Case

TP / HRT /  
Sr Staff Sgt ESTHER CHONG  
Contact No: 65476368

Authentication Stamp  
wmsa

Signature Of Informant

Date/Time  
16/03/2019 17:07

Classification Of Case

Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo





Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo





Accident Photo



## ...CLAIM SUBFOLDER...(Pending for Survey Report)






























CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	10 Jun 2019 09:20		06 Jun 2019 09:13 <a href="#">Edit Adj Rpt</a>	<b>S\$0.00</b> <a href="#">Edit Estimates</a>	<b>S\$0.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>


















































  

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by insurer]</span>									
Insured:	-, Co. Reg. No.: -								
Main Claimant:	<b>RELIABLE RIDES PTE LTD</b> , Co. Reg. No.: 201611527N								
Vehicle Reg. No.:	<b>SLQ9529B</b>	Date of Loss:	15/03/2019 10:00 - :59 [19 Months and 16 Days From LTA Reg Date (Man Yr)]						
Claim Type:	<b>TP</b>	Policy/Cover Note No.:							
Vehicle Reg. No. (Insured):	<b>GL11Y</b>	Policy No. (Claimant):	5092730558-01						
		Excess:	S\$0.00						
Repairer:	<b>Reliable Carz Pte Ltd (HQ)</b> 8 Kaki Bukit Ave 4, #05-50, 415875 Kaki Bukit - Tel:								
Handling Insurer:	<b>China Taiping Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: 6389 6111 ... [Handled by <b>Chong Boon Sen</b> ]								
Claimant's Insurer:	<b>NTUC Income Insurance Co-operative Ltd (HQ)</b> - Tel:								
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>XING GUO QIANG</b> ] ... [Final Rpt due 17/06/2019]								
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents


















\*SLQ9529B  
[GL11Y]  
TP  
RELIABLE RIDES PTE LTD  
Mar 15 2019 10:00AM  
[-]  
Reliable Carz Pte Ltd

<a href="#">Upload Documents</a> <a href="#">Upload Photos</a> <a href="#">Compose New Letter</a>			<b>View</b> <a href="#">View in Browser</a>	
<b>Assessment Reports</b>			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	National Assessment Centre Services (Ubi)	Thumbnail	Print
1	18/03/19 11:47	<b>Accident Statement</b>	 Load HTML	
<b>Photos/Images</b>			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	National Assessment Centre Services (Ubi)	Thumbnail	Print
1	15/03/19 13:29	<b>Accident Photo</b> [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
2	15/03/19 13:29	<b>Accident Photo</b> [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
3	15/03/19 13:29	<b>Accident Photo</b> [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
4	15/03/19 13:29	<b>Accident Photo</b> [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
5	15/03/19 13:29	<b>Accident Photo</b> [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
6	15/03/19 13:29	<b>Accident Photo</b> [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
7	15/03/19 13:29	<b>Accident Photo</b> [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
8	15/03/19 13:29	<b>Accident Photo</b> [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
9	15/03/19 13:29	<b>Accident Photo</b> [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
10	15/03/19 13:29	<b>Accident Photo</b> [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
11	15/03/19 13:29	<b>Accident Photo</b> [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
12	15/03/19 13:29	<b>Accident Photo</b> [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
13	15/03/19 13:29	<b>Accident Photo</b> [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
14	15/03/19 13:29	<b>Accident Photo</b> [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
15	15/03/19 13:29	<b>Accident Photo</b> [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	06/06/19 14:12	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
2	06/06/19 14:12	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
3	06/06/19 14:12	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
4	06/06/19 14:12	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
5	06/06/19 14:12	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
6	06/06/19 14:12	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
7	06/06/19 14:12	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
8	06/06/19 14:12	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
9	06/06/19 14:12	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
10	06/06/19 14:12	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
11	06/06/19 14:12	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
12	06/06/19 14:12	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
13	06/06/19 14:12	<b>General View</b>	 Load JPG	

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	National Assessment Centre Services (Ubi)	Thumbnail	Print
				<input checked="" type="checkbox"/>
14	06/06/19 14:12	General View	 Load JPG	<input checked="" type="checkbox"/>
15	06/06/19 14:12	General View	 Load JPG	<input checked="" type="checkbox"/>
16	06/06/19 14:12	General View	 Load JPG	<input checked="" type="checkbox"/>
17	06/06/19 14:12	General View	 Load JPG	<input checked="" type="checkbox"/>
18	06/06/19 14:12	General View	 Load JPG	<input checked="" type="checkbox"/>
19	06/06/19 14:12	General View	 Load JPG	<input checked="" type="checkbox"/>
20	06/06/19 14:12	General View	 Load JPG	<input checked="" type="checkbox"/>
21	06/06/19 14:12	General View	 Load JPG	<input checked="" type="checkbox"/>
22	06/06/19 14:12	General View	 Load JPG	<input checked="" type="checkbox"/>
23	06/06/19 14:12	General View	 Load JPG	<input checked="" type="checkbox"/>
24	06/06/19 14:12	General View	 Load JPG	<input checked="" type="checkbox"/>
25	06/06/19 14:12	General View	 Load JPG	<input checked="" type="checkbox"/>
26	06/06/19 14:12	General View	 Load JPG	<input checked="" type="checkbox"/>
27	06/06/19 14:12	General View	 Load JPG	<input checked="" type="checkbox"/>
28	06/06/19 14:12	General View	 Load JPG	<input checked="" type="checkbox"/>
29	06/06/19 14:13	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
30	06/06/19 14:13	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
31	06/06/19 14:13	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
32	06/06/19 14:13	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
33	06/06/19 14:13	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
34	06/06/19 14:13	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
35	06/06/19 14:13	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
36	06/06/19 14:13	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
37	06/06/19 14:13	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
38	06/06/19 14:13	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
39	06/06/19 14:13	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
40	06/06/19 14:13	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
41	06/06/19 14:13	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
42	06/06/19 14:13	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
43	06/06/19 14:13	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
44	06/06/19 14:13	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
45	06/06/19 14:13	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
46	06/06/19 14:13	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
47	06/06/19 14:13	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
48	06/06/19 14:13	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
49	06/06/19 14:13	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
50	06/06/19 14:13	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
51	06/06/19 14:13	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
52	06/06/19 14:13	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
53	06/06/19 14:13	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
54	06/06/19 14:13	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
55	06/06/19 14:13	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
56	06/06/19 14:13	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
57	06/06/19 14:13	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
58	06/06/19 14:13	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
59	06/06/19 14:13	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
60	06/06/19 14:14	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
61	06/06/19 14:14	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
62	06/06/19 14:14	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	National Assessment Centre Services (Ubi)	Thumbnail	Print
63	06/06/19 14:14	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
64	06/06/19 14:14	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
65	06/06/19 14:14	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
66	06/06/19 14:14	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
67	06/06/19 14:14	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
68	06/06/19 14:14	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
69	06/06/19 14:14	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
70	06/06/19 14:14	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
71	06/06/19 14:14	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
72	06/06/19 14:14	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	06/06/19 09:14	pri contact	 Load PDF	<input checked="" type="checkbox"/>
No	Finalized On	National Assessment Centre Services (Ubi)	Thumbnail	Print
1	15/03/19 13:32	Accident Sketch Plan [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
2	15/03/19 13:32	Accident Sketch Plan [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
3	18/03/19 11:44	POLICE REPORT [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
4	18/03/19 11:44	POLICE REPORT [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
5	18/03/19 11:44	POLICE REPORT [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
6	18/03/19 11:44	POLICE REPORT [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>

## Linked Accident Report Documents

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	National Assessment Centre Services (Ubi)	Thumbnail	Print
1	18/03/19 11:47	Accident Statement	 Load HTM	<input checked="" type="checkbox"/>
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	National Assessment Centre Services (Ubi)	Thumbnail	Print
1	15/03/19 13:29	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
2	15/03/19 13:29	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
3	15/03/19 13:29	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
4	15/03/19 13:29	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
5	15/03/19 13:29	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
6	15/03/19 13:29	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
7	15/03/19 13:29	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
8	15/03/19 13:29	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
9	15/03/19 13:29	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
10	15/03/19 13:29	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
11	15/03/19 13:29	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
12	15/03/19 13:29	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
13	15/03/19 13:29	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
14	15/03/19 13:29	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
15	15/03/19 13:29	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	National Assessment Centre Services (Ubi)	Thumbnail	Print
1	15/03/19 13:32	Accident Sketch Plan	 Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	National Assessment Centre Services (Ubl)	Thumbnail	Print
2	15/03/19 13:32	Accident Sketch Plan	 Load JPG	<input checked="" type="checkbox"/>
3	18/03/19 11:44	POLICE REPORT	 Load JPG	<input checked="" type="checkbox"/>
4	18/03/19 11:44	POLICE REPORT	 Load JPG	<input checked="" type="checkbox"/>
5	18/03/19 11:44	POLICE REPORT	 Load JPG	<input checked="" type="checkbox"/>
6	18/03/19 11:44	POLICE REPORT	 Load JPG	<input checked="" type="checkbox"/>

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

<p><b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b></p> <div style="border: 1px solid black; height: 40px; width: 100%;"></div> <p> <b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer  <small>Note: Remarks are private unless you show it to other parties.</small> </p>
---

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/CTI19004967/GCD3E2

Date: 10/06/2019

## REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd.

Policy No:

Claimant Vehicle No: SLQ9529B

Insured Vehicle No: GL11Y

Date of Loss: 15/03/2019

Nature of Claim: TP Claim No: N/A

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No:	SLQ9529B	Engine No:	LEB6317442
Make & Model:	HONDA SHUTTLE, 1.5 (A)	Chassis No:	GP71114315
Reg. Date:	27/07/2017 (Man. Year: 2017)	Odometer:	96925 km
Colour:	Red		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size:	185/60 R15	Rear Tyre Size:	185/60 R15
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (\$\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

## INSPECTION

Date of Assignment: 06/06/2019

Date Inspected: 20/03/2019

Inspected At:

Reliable Carz Pte Ltd (HQ)  
8 Kaki Bukit Ave 4, #05-50  
Singapore 415875

Estimated Period of Repair: 5.0 days

Adjuster: XING GUO QIANG

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.  
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$4,000.00 - \$5,000.00



## REPAIR DETAILS

### Reference

**Part Source:** (Last Synchronised: 10 Jun 2019)

**Parts:** N/A HONDA SHUTTLE 1.5 (A) (Model not available in database)

**Labour:** Repairer's (Price-denominated Standard List)

**Print Code:** (Unsubmitted, no print-code for SLQ9529B)

**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.

### Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.
---

< END OF ESTIMATES >