

ASS. REC. BY:

REP:

CS3/CTI 1900 4973/Bcd3

Special Instruction:

SMV (V/M)

From (Person)

Mr. Kim
Irene Tay

ASSIGNMENT (Office)

of CTI

Date/Time: 19/3/19 @ 1:30pm

Estimated Cost:

Bill to:

OD (TP) WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SMC 4862H

Insured:

GBG 9007L

at Workshop m/s

Bliss Garage

Tel:

9619 9144

of

25 Keki Blk Rd # 40333

Policy No:

DMCVSN30672318000

Claim No:

SNM19D201140C02

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

8/3/2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

3:34pm 19/3/19

Person Contacted:

Zoran

Vehicle

IN/OUT

Date/Time

Action/Instruction

(X)

Estimate

SMC 4862H-X

GBG 9007L-X

Dismantle: 20/3/2019

After repair: 22/3/2019

REF:

CTI

ASSIGNMENT

From:

Date: 12/3/19

Veh No:

SMC 4862H

Yr Regn:

30/6/2018

Estimated Cost:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

Truck / Trailer or

To Inspect Vehicle No:

SMC 4862H

Make:

Honda Shuttle 1.5G C.C. 1496

at Workshop m/s

Biss Garage

Colour:

Black

A/C:

Insured / Std / NI / N

of

25 Naki Bukit

#03-33

Sp. Reading

57130

T/Radio:

Insured / Std / NI / N

Insured:

Eng/No:

L15B5AG2287

Policy No.

C/No:

GK91201954

Claims No.

Gen. Cond: Good / Fair / Poor / Burnt

Sum Insured:

Excess:

Steering: Inorder / Jammed / Leaked / Burnt or

(Client's Record)

Brake: Inorder / Jammed / Leaked / Burnt or

Make of Veh:

Modi: Nil / S/Rim / STD A/Rim or

(Policy Condition)

Tyre Size:

F: 205/50R16

R: 205/50R16

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Falken

Bal. or Market Value:

Front

Rear

IDAC Accident Rpt:

Consistent?: Yes or No

R/Bal.

6 mm

R/Bal.

6 mm

GIA / PR Seen:

Consistent?: Yes or No

L/Bal.

6 mm

L/Bal.

6 mm

Est. Repairs:

4 days

Res.: Yes or No

D.O.A.

8/3/19

D.O.I.

19/3/19

Lum Sum:

%

3 Val.: Yes or No

Survey held at

Biss Garage

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Date:

Person Contacted:

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time

Action / Instruction

Range 3000/- - 4000/-

RECEIVED 10 APR 2019

8/4/2019

MV 72,600/-

PV 38,055/-

NV 38,945/-

TTCM file 5/4/19

Date/Time, File Pass to?

☐

Preli. Report

Days Of Repair:

1)

Date/Time, File Return to?

☐

Final Report

Resurvey No. of Trip:

Survey Fee:

2)

Transportation:

Report Format:

Lump Sum / I.B.I. (\$))

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

) \$ + RS. \$

) Photos

) Others

TOTAL

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	19 Mar 2019		19 Mar 2019 13:30 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	OPTIMA (DC) SOLUTIONS & SERVICES PTE LTD, Co. Reg. No.: 200303297W		
Main Claimant:	KOH CHENG WAH, ID: S1660623E		
Vehicle Reg. No.:	SMC4862H	Date of Loss:	08/03/2019 15:00 - :59 [8 Months and 8 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / SNM19D201140C02	Policy/Cover Note No.:	DMCVSN30672318000 (Comprehensive) Coverage: 29/11/2018 - 28/11/2019
Vehicle Reg. No. (Insured):	GBG9007L	Policy No. (Claimant):	5101703623
		Excess:	S\$0.00
Repairer:	Bliss Garage Pte Ltd (Synergy) 25 Kaki Bukit Road 4, Synergy@Kaki Bukit, #03-33 Freesion Auto Drive, 417800 Kaki Bukit - Tel:		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]		
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 28/03/2019]		
Driver/Custodian (Insured):	CHAN CHEA LIANG (36 / Male) , NRIC: S8362806E Email:		

ASSOCIATED MAIL RECEIVED

[View All](#)

[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)

[Search Tasks](#)

[Create New Task](#)

[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
----------	----------	------	------------	---------	---------	-------------	--------------	------------	-------

No results.

Your Ref : SNM19D201140

Our Ref : **SMC 4862H/BG/jp/ps**

Date : 19 March 2019

Fax : **6538 3708**

Tel : **3152 0984**

Email : **accident@kscgp.com**

China Taiping Insurance (Singapore) Pte. Ltd.

BY EMAIL ONLY

DATE OF ACCIDENT: 8 MARCH 2019

NOTICE TO INSURER TO CONDUCT PRE-REPAIR SURVEY / INSPECTIONS

We refer to your email on 19 March 2019.

Please be informed that our client is not agreeable to your proposed motor surveyors. Instead we propose you to choose a surveyor from our client's list of surveyors as appended below:-

S/No.	Name of Surveyor
1	Ho Joo Loong, Danny
2	Lee Kok Weng
3	Seah Kwang Boon

Please be informed that if we do not hear from you within 2 working days from the date hereof, we will assume, as per the Protocol, that you have no objections to our list of motor surveyors. You will be deemed to have agreed to any of the above motor surveyors as a "single joint expert". We will inform you who the "single joint expert" is in due course.

If you object to our client's list of motor surveyors, we will accordingly inform the client to instruct his choice of motor surveyor to conduct the pre-repair survey. Also, please let us know within 2 working days excluding any intervening Saturday, Sunday and/or Public Holiday of your receipt of this notice whether you would like to conduct a pre-repair survey of the vehicle failing which our client will commence repairs thereafter without any further notice or reference to you. Please be informed that the said vehicle can be surveyed / inspected at:

Address : Bliss Garage Pte Ltd
25 Kaki Bukit Road 4
#03-33 Synergy @ Kaki Bukit
Singapore 417800

Contact Person/Tel : Zoron Koh / 9619 9144

Yours faithfully,

PS

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	11/03/2019 10:44
Date Of Accident	08/03/2019 15:55
Exact Location Of Accident	JUNCTION OF MARINA BOULEVARD & BAYFRONT AVE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMC4862H
Insured/Policyholder	
Name Of Registered Owner	KOH CHENG WAH
NRIC No	S1660623E
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-90042059
Alternative Phone No	Office-90042059

Vehicle Particulars

Manufacturer	HONDA
Model	SHUTTLE
Exact Purpose for which vehicle was being used at time of accident	PRIVATE HIRER USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5101703623
Cover Note Number	

Driver

Name of Driver	KOH CHENG WAH
NRIC No	S1660623E
Date Of Birth	29/06/1964
Occupation	OUTDOOR
Date Of Driving Pass	29/07/1985
Driving Experience	33 YEARS AND 7 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-90042059

Fax Number	
Contact Number	OFFICE-90042059
EMail Address	NOEMAIL
Address	APT BLK 109D EDGEDALE PLAINS #06-145
Postcode	824109
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - CHANGE/CROSS LANE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	Name: : LAY MEI Gender: : Female

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO ATTACHED

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBG9007L
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	CHAN CHEA LIANG
NRIC/Passport Number	S8362806E
Contact Number	
Address	

Postcode
insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name	KOH CHENG WAH
Approximate Age	
Injuries Sustain	
Injured person in which vehicle?	SMC4862H
Were seat belts worn?	YES
Was this injured conveyed to hospital by ambulance?	NO
Address	APT BLK 109D EDGEDALE PLAINS #06-145
Postcode	824109

Sketch Plan


SKETCH PLAN


IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)


I understand, acknowledge, agree and consent that:

- (a) My Insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



A = SMC4862H
B = GIBG9007L

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 8/3/2019, I was travelling along Mannar Boulevard.


When I approached the traffic light junction, the traffic light was green, thus I started to turn left into Bayfront Ave. Suddenly I felt a ^{huge} impact on my left and realised that vehicle B has collided on my vehicle.


As a result, my car sustained damages on the left portion.


After the incident I felt neck pain and back pain. I wish to state that my passenger will be my witness.

DECLARATION

I/We declare the foregoing particulars are true in every respect.


Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	0623E
Vehicle Details	
Vehicle No.:	SMC4862H
Vehicle to be Exported:	No
Intended Deregistration Date:	05 Apr 2019
Vehicle Make:	HONDA
Vehicle Model:	SHUTTLE 1.5G CVT
Primary Colour:	Black
Manufacturing Year:	2018
Engine No.:	L15B5462287
Chassis No.:	GK81201954
Maximum Power Output:	97.0 kW (130 bhp)
Open Market Value:	\$18,749.00
Original Registration Date:	30 Jun 2018
First Registration Date:	30 Jun 2018
Transfer Count:	0
Actual ARF Paid:	\$8,749.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	29 Jun 2028
PARF Rebate Amount:	\$6,561.00
Intended COE Rebate Details	
COE Expiry Date:	29 Jun 2028
COE Category:	E - Open - all except motorcycle
COE Period(Years):	10
QP Paid:	\$34,400.00
COE Rebate Amount:	\$31,494.00
Total Rebate Amount:	\$38,055.00

The information contained herein is correct as at 05 Apr 2019

OK

Aug dep 8,000/yr

MV 77,000/2
PV 38,055/2
NY 38,745/2

Teo Min Hui
5/4/19



Trust Motoring

Posted: 20-Mar-2019

Tags: 2018 Honda Shuttle, 2018 honda shuttle, Honda Shuttle, honda shuttle, Honda, Shuttle, shuttle, Used Honda

**Honda Shuttle Hybrid 1.5A**

-

N.A

25-Jul-2018

1,496 cc

-

Stationwagon

SOLD**Fuel Type:** Petrol-Electric

2018 New Facelifted Honda Shuttle Hybrid. LED Edition. Low Fuel Consumption. 10 Years Repayment, In House Loan Or Balloon Scheme Available. Make And Assemble In Japan. 3 Years Or 100000km Warranty. Vi...

PREMIUM AD

Trust Motoring

Posted: 08-Feb-2019

Tags: 2018 Honda Shuttle, 2018 honda shuttle, Honda Shuttle, honda shuttle, Honda, Shuttle, shuttle, Used Honda

**Honda Shuttle Hybrid 1.5A****\$87,800****\$8,730 /yr**

24-Jul-2018

1,496 cc

8,000 km

Stationwagon

Available**Fuel Type:** Petrol-Electric

2018 New Facelifted Honda Shuttle Hybrid. LED Edition. Low Fuel Consumption. 10 Years Repayment, In House Loan Or Balloon Scheme Available. Make And Assemble In Japan. 3 Years Or 100000km Warranty. Vi...

PREMIUM AD

Trust Motoring

Posted: 20-Mar-2019

Tags: 2018 Honda Shuttle, 2018 honda shuttle, Honda Shuttle, honda shuttle, Honda, Shuttle, shuttle, Used Honda

**Honda Shuttle Hybrid 1.5A****\$87,800****\$8,730 /yr**

24-Jul-2018

1,496 cc

8,000 km

Stationwagon

Available**Fuel Type:** Petrol-Electric

Newly Registered Honda Hybrid, 2018 Facelifted Model, 10 Years Repayment, In House Loan Or Balloon Scheme Available! Lowest Interest Rate In Town! Lowest Depreciation Ever! Make And Assemble In Japan....

PREMIUM AD

Trust Motoring

Posted: 20-Mar-2019

Tags: 2018 Honda Shuttle, 2018 honda shuttle, Honda Shuttle, honda shuttle, Honda, Shuttle, shuttle, Used Honda

**Find the right car through consignment.**

Purchase pre-loved, owner consigned cars at affordable prices through our dedicated consignment agents. Arrange a test drive today.

Find out more!

**Honda Shuttle Hybrid 1.5A X**

-

N.A

30-Jun-2018

1,496 cc

-

Stationwagon

SOLD**Fuel Type:** Petrol-Electric

5 Years Warranty Or 130,000km Whichever Comes First With Liberty Insurance! Call Our Friendly Salesman For Viewing Now!

Posted: 24-Jan-2019

Tags: 2018 Honda Shuttle, 2018 honda shuttle, Honda Shuttle, honda shuttle, Honda, Shuttle, shuttle, Used Honda

**Honda Shuttle Hybrid 1.5A**

-

N.A

29-Jun-2018

1,496 cc

-

Stationwagon

SOLD**Fuel Type:** Petrol-Electric

Ready Stock. LED Edition. New Facelifted Honda Shuttle Hybrid. Ready Stock! Low Fuel Consumption. Make And Assemble In Japan. 3 Years Or 100000km Warranty. View To Appreciate. Call Our Friendly Sales ...

PREMIUM AD

Straits Euro Motors Pte Ltd

Posted: 23-Jan-2019

Tags: 2018 Honda Shuttle, 2018 honda shuttle, Honda Shuttle, honda shuttle, Honda, Shuttle, shuttle, Used Honda

**Honda Shuttle 1.5A G****\$72,800****\$7,400 /yr**

27-Jun-2018

1,496 cc

5,000 km

Stationwagon

Available

2018 New Facelifted Honda Shuttle 1.5 With Fog Lamp, LED Edition. Best Fuel Efficient Stationwagon In Town. Almost New Honda Shuttle. 10 Years Repayment, In House Loan Or Balloon Scheme Available. Dif...

PREMIUM AD

Trust Motoring

Posted: 20-Mar-2019

Tags: 2018 Honda Shuttle, 2018 honda shuttle, Honda Shuttle, honda shuttle, Honda, Shuttle, shuttle, Used Honda

**Honda Shuttle Hybrid 1.5A****\$85,988****\$9,040 /yr**

27-Jun-2018

1,496 cc

60 km

Stationwagon

Available**Fuel Type:** Petrol-Electric

90% Loan Available, High Trade In, Call For Viewing Or Test Drive.

Posted: 12-Feb-2019

Tags: 2018 Honda Shuttle, 2018 honda shuttle, Honda Shuttle, honda shuttle, Honda, Shuttle, shuttle, Used Honda

**Honda Shuttle 1.5A G****\$80,988****\$8,280 /yr**

25-Jun-2018

1,496 cc

80 km

Stationwagon

Available

3 Years Warranty Provided. Loan Available, Flawless And Pristine Condition, Perfect Paintwork, View To Believe. Hurry Up, Arrange An Appointment With Us Now.

Posted: 24-Feb-2019

Tags: 2018 Honda Shuttle, 2018 honda shuttle, Honda Shuttle, honda shuttle, Honda, Shuttle, shuttle, Used Honda

**Honda Shuttle 1.5A G****\$80,988****\$8,310 /yr**

23-Jun-2018

1,496 cc

75 km

Stationwagon

Available

3 Years Warranty Provided. Loan Available, Flawless And Pristine Condition, Perfect Paintwork, View To Believe. Hurry Up, Arrange An Appointment With Us Now.

Posted: 24-Feb-2019

Tags: 2018 Honda Shuttle, 2018 honda shuttle, Honda Shuttle, honda shuttle, Honda, Shuttle, shuttle, Used Honda

Honda Shuttle 1.5A G (OPC)**\$62,800****\$6,320 /yr**

21-Jun-2018

1,496 cc

8,000 km

Stationwagon

Available

Glossy Midnight Blue Exterior With Black Interior For Easy Maintenance, Low Fuel Consumption, A Popular & Reliable Stationwagon That Suits Your

Compare

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	19 Mar 2019		19 Mar 2019 13:30 Edit Adj Rpt	\$0.00 Edit Estimates	\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS			[Created by insurer]						
Insured: OPTIMA (DC) SOLUTIONS & SERVICES PTE LTD , Co. Reg. No.: 200303297W									
Main Claimant: KOH CHENG WAH , ID: S1660623E									
Vehicle Reg. No.: SMC4862H		Date of Loss: 08/03/2019 15:00 - :59 [8 Months and 8 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / SNM19D201140C02		Policy/Cover Note No.: DMCVSN30672318000 (Comprehensive) Coverage: 29/11/2018 - 28/11/2019							
Vehicle Reg. No. (Insured): GBG9007L		Policy No. (Claimant): 5101703623							
		Excess: \$0.00							
Repairer: Bliss Garage Pte Ltd (Synergy) 25 Kaki Bukit Road 4, Synergy@Kaki Bukit, #03-33 Freesion Auto Drive, 417800 Kaki Bukit - Tel:									
Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]									
Claimant's Insurer: NTUC Income Insurance Co-operative Ltd (HQ) - Tel:									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Lim Teow Guan] ... [Final Rpt due 28/03/2019]									
Driver/Custodian (Insured): CHAN CHEA LIANG (36 / Male), NRIC: S8362806E Email:									
ASSOCIATED MAIL RECEIVED				View All Compose Case Mail					
There are no mail for this case.									
ALL ASSOCIATED TASKS			View All Search Tasks Create New Task Complete						
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SMC4862H (SNM19D201140C02)**
[GBG9007L]

TP

KOH CHENG WAH

Mar 8 2019 3:00PM

[OPTIMA (DC) SOLUTIONS & SERVICES PTE LTD]


Bliss Garage Pte Ltd

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)

[View](#)
[View in Browser](#)


























Assessment Reports

1 per page ☒

No	Finalized On	Yew Tee Automobile Tech Pte Ltd (Kaki Bukit)	Thumbnail	Print
1	11/03/19 10:50	Accident Statement	 Load HTM	<input checked="" type="checkbox"/>

Photos/Images

3 per page ☒

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	10/04/19 10:16	General View	 Load JPG	<input checked="" type="checkbox"/>
2	10/04/19 10:16	General View	 Load JPG	<input checked="" type="checkbox"/>
3	10/04/19 10:16	General View	 Load JPG	<input checked="" type="checkbox"/>
4	10/04/19 10:16	General View	 Load JPG	<input checked="" type="checkbox"/>
5	10/04/19 10:16	General View	 Load JPG	<input checked="" type="checkbox"/>
6	10/04/19 10:16	General View	 Load JPG	<input checked="" type="checkbox"/>
7	10/04/19 10:16	General View	 Load JPG	<input checked="" type="checkbox"/>
8	10/04/19 10:16	General View	 Load JPG	<input checked="" type="checkbox"/>
9	10/04/19 10:16	General View	 Load JPG	<input checked="" type="checkbox"/>
10	10/04/19 10:16	General View	 Load JPG	<input checked="" type="checkbox"/>
11	10/04/19 10:16	General View	 Load JPG	<input checked="" type="checkbox"/>
12	10/04/19 10:16	General View	 Load JPG	<input checked="" type="checkbox"/>
13	10/04/19 10:16	General View	 Load JPG	<input checked="" type="checkbox"/>
14	10/04/19 10:16	General View	 Load JPG	<input checked="" type="checkbox"/>
15	10/04/19 10:16	General View	 Load JPG	<input checked="" type="checkbox"/>
16	10/04/19 10:16	General View	 Load JPG	<input checked="" type="checkbox"/>
17	10/04/19 10:16	General View	 Load JPG	<input checked="" type="checkbox"/>
18	10/04/19 10:16	General View	 Load JPG	<input checked="" type="checkbox"/>
19	10/04/19 10:16	General View	 Load JPG	<input checked="" type="checkbox"/>
20	10/04/19 10:16	General View	 Load JPG	<input checked="" type="checkbox"/>
21	10/04/19 10:16	General View	 Load JPG	<input checked="" type="checkbox"/>
22	10/04/19 10:16	General View	 Load JPG	<input checked="" type="checkbox"/>
23	10/04/19 10:16	General View	 Load JPG	<input checked="" type="checkbox"/>
24	10/04/19 10:16	General View	 Load JPG	<input checked="" type="checkbox"/>
25	10/04/19 10:16	General View	 Load JPG	<input checked="" type="checkbox"/>
26	10/04/19 10:16	General View	 Load JPG	<input checked="" type="checkbox"/>
27	10/04/19 10:16	General View	 Load JPG	<input checked="" type="checkbox"/>
28	10/04/19 10:16	General View	 Load JPG	<input checked="" type="checkbox"/>
29	10/04/19 10:16	General View	 Load JPG	<input checked="" type="checkbox"/>
30	10/04/19 10:16	General View	 Load JPG	<input checked="" type="checkbox"/>
31	10/04/19 10:16	General View	 Load JPG	<input checked="" type="checkbox"/>
32	10/04/19 10:16	General View	 Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Yew Tee Automobile Tech Pte Ltd (Kaki Bukit)	Thumbnail	Print
33	10/04/19 10:16	General View	Load JPG	<input checked="" type="checkbox"/>
34	10/04/19 10:16	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
35	10/04/19 10:16	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
36	10/04/19 10:16	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
37	10/04/19 10:16	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
38	10/04/19 10:16	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
39	10/04/19 10:16	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
40	10/04/19 10:16	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
41	10/04/19 10:16	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
42	10/04/19 10:16	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
43	10/04/19 10:16	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
44	10/04/19 10:16	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
45	10/04/19 10:16	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
46	10/04/19 10:17	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
47	10/04/19 10:17	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
48	10/04/19 10:17	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
49	10/04/19 10:17	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	19/03/19 13:31	PRS	Load PDF	
2	19/03/19 13:31	INSD GIA Report	Load PDF	

Linked Accident Report Documents

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Yew Tee Automobile Tech Pte Ltd (Kaki Bukit)	Thumbnail	Print
1	11/03/19 10:50	Accident Statement	Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Yew Tee Automobile Tech Pte Ltd (Kaki Bukit)	Thumbnail	Print
1	11/03/19 10:47	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
2	11/03/19 10:47	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
3	11/03/19 10:47	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
4	11/03/19 10:47	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
5	11/03/19 10:47	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
6	11/03/19 10:47	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
7	11/03/19 10:47	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Yew Tee Automobile Tech Pte Ltd (Kaki Bukit)	Thumbnail	Print
1	11/03/19 10:47	Sketch Plan	Load TIF	
2	11/03/19 10:47	Sketch Plan #2	Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**Show Remarks To:** ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/CTI19004973/BCD3S2

Date: 12/04/2019

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSN30672318000

Claimant Vehicle No: SMC4862H Insured Vehicle No: GBG9007L

Date of Loss: 08/03/2019 Nature of Claim: TP Claim No: SNM19D201140C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SMC4862H

Make & Model: HONDA SHUTTLE, 1.5 G CVT (A) Engine No: L15B5462287

Reg. Date: 30/06/2018 (Man. Year: 2018) Chassis No: GK81201954

Colour: Black Odometer: 57130 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Fair Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/50R16 Rear Tyre Size: 205/50R16

Front Left Side: Falken 6 mm Rear Left Side: Falken 6 mm

Front Right Side: Falken 6 mm Rear Right Side: Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 19/03/2019

Date Inspected: 19/03/2019 Inspected At: 25 KAKI BUKIT ROAD 4 #03-33
Repairer: Bliss Garage Pte Ltd

Estimated Period of Repair: 4.0 days

Adjuster: Lim Teow Guan

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,000.00 - \$4,000.00

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 11 Apr 2019)

Parts: N/A HONDA SHUTTLE 1.5 G CVT (A) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SMC4862H)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >