

ASS. REC. BY:

REF: CS/CTI19004931/Eg, d3<sup>72</sup>

Special Instruction:

SUNJOY

ASSIGNMENT (Office)

From (Person): Chong Boon Sen

of

CTIDate/Time: 19.3.2019 4.31p.m

Estimated Cost:

Bill to:

OD / (II) / WS / TP RES / OD RES / EVA / INV / MV / CSTo Inspect Vehicle No: SJG 6126 BInsured: GBD 7134 Gat Workshop m/s: cycle & carriageTel: 7144 9137of 209 Pandan GardensPolicy No: DMCVSN30183718011Claim No: SNM190701731002

Sum Insured:

Excess:

Make of Veh:  
(Client's Record)D.O.A. 05.03.2019

CA / REV / REP. / REV 24 HRS

"wp"

I.O.D. Endorsement:

Date/Time: 19.3.2019 5.00pm

Person Contacted:

AndreVehicle IN (OUT)

Date/Time	Action/Instruction ( <input checked="" type="checkbox"/> ) Estimate
	<u>SJG 6126 B - x</u>
	<u>GBD 7134 G - x</u>

(08/11/13)

ASS. REC. BY:

Steve

REF

(71)

## ASSIGNMENT

From:

Date:

3.6.2019

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SJG 6126 B

at Workshop m/s Cycle &amp; Camacol

of 209 Pandan Garden

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:


(Client's Record)

Make of Veh:

owner waiting

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 3 days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No:

SJG 6126 B

Yr Regn:

2/7/18

Type: ☒ M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

KIA Stinger

c.c.

1998

Colour:

Grey

A/C:

Insured / Std / NI / NA

Sp. Reading:

13822

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

KMA E3SIAM J6938670

Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ Inorder / Jammed / Leaked / Burnt orBrake: ☒ Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

225/45R18

R:

11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Continental

Front

Rear

R/Bal.

7

mm

R/Bal.

7

mm

L/Bal.

7

mm

L/Bal.

7

mm

D.O.A.

5/3/19

D.O.I.

3/6/19

Survey held at

C &amp; C

KIA

Des. of Damages: ☒ Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

27/6/19

MV-139K

Finalise condition with JDS &amp; IGIS. Joke's (Ref #299, 16%)

RECEIVED 27 JUN 2019

27/6/2019

Date/Time, File Pass to?



: Preli. Report

1) 24/6/19



: Final Report

Date/Time, File Return to?

2)

Days Of Repair: 3

Resurvey No. of Trip:

Report Format:

MER-19

Lump Sum / I.B.I: (\$

1615

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech. Invs (\$



: Weekend (\$

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

220

## Nivitha (LKK Auto)

---

**From:** Chong Boon Sen <boonsen.chong@sg.cntaiping.com>  
**Sent:** Tuesday, 19 March 2019 4:31 PM  
**To:** Andre Chow En De  
**Cc:** Don Bong Kiong Hua; Coco Lu Ting; Tay Jian Ye; Edwin Abcede Caina; assignments  
**Subject:** RE: OUR REF: SNM19D201231- TP China Taiping Claim SJG6126B against GBD7134G DOA 05.03.2019 (ANR)  
**Attachments:** SJG6126B GIA REPORT AND ESTIMATE.PDF; SJG6126B FRONT CAM.MP4

Without prejudice

Dear Sir,

We will appoint LKK.

Dear LKK,

Pls pri.

p. Andre

V: Dux

E: ✓

T: 5.4p.m

Regards,

**Chong Boon Sen**

Claims Executive

Claims

**China Taiping Insurance (Singapore) Pte. Ltd.**

3 Anson Road #16-00 Springleaf Tower

Singapore 079909

Co. Reg. No. 200208384E

DID: 63896171

Fax: 62247175

Email: boonsen.chong@sg.cntaiping.com

Website: www.sg.cntaiping.com

*Disclaimer :*

*This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.*

**From:** Andre Chow En De [mailto:andre.chow@cyclecarriage.com.sg]

**Sent:** Tuesday, 19 March, 2019 4:23 PM

**To:** Chong Boon Sen <boonsen.chong@sg.cntaiping.com>

**Cc:** Don Bong Kiong Hua <kionghua.bong@cyclecarriage.com.sg>; Coco Lu Ting <coco.lu@cyclecarriage.com.sg>; Tay Jian Ye <jianye.tay@cyclecarriage.com.sg>; Edwin Abcede Caina <edwin.caina@cyclecarriage.com.sg>

**Subject:** RE: OUR REF: SNM19D201231- TP China Taiping Claim SJG6126B against GBD7134G DOA 05.03.2019 (ANR)

Hi Boon Sen,

We choose Xing Quo Qiang.

Kindly revert with the liability.

Regards

Andre

**From:** Chong Boon Sen [mailto:boonsen.chong@sg.cntaiping.com]

**Sent:** Tuesday, 19 March, 2019 4:15 PM

**To:** Andre Chow En De; Coco Lu Ting

**Subject:** RE: OUR REF: SNM19D201231- TP China Taiping Claim SJG6126B against GBD7134G DOA 05.03.2019 (ANR)

Without Prejudice

Dear Sir,

We intend to conduct a pre-repair survey of the damage to your client's vehicle jointly with your client/your motor workshop. We propose to use one of the following motor surveyors to conduct the joint pre-repair survey as a single joint expert.

ADRIAN LING
Kelvin Ang
SEE CHEW SENG
MOHD FADHILAH BIN OSMAN
XING QUO QIANG
KENNETH KONG
SIMON HO
CHUA WEIJIE
MARCUS CHUA
HENRY NG

Please let us know within two(2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.

You may select one of the listed motor surveyors and we will bear the cost of the pre-repair survey carried out by the single joint expert.

Regards,

**Chong Boon Sen**

Claims Executive

Claims

**China Taiping Insurance (Singapore) Pte. Ltd.**

3 Anson Road #16-00 Springleaf Tower

Singapore 079909

Co. Reg. No. 200208384E

DID: 63896171

Fax: 62247175

Email: [boonsen.chong@sg.cntaiping.com](mailto:boonsen.chong@sg.cntaiping.com)

Website: [www.sg.cntaiping.com](http://www.sg.cntaiping.com)

*Disclaimer :*

*This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.*

**From:** Andre Chow En De [mailto:andre.chow@cyclecarriage.com.sg]

**Sent:** Wednesday, 13 March 2019 11:00 AM

**To:** Claims Dept of CTI <[claimsdept@sg.cntaiping.com](mailto:claimsdept@sg.cntaiping.com)>; Hwang Shiang Yi <[shiangyi.hwang@sg.cntaiping.com](mailto:shiangyi.hwang@sg.cntaiping.com)>  
**Cc:** Don Bong Kiong Hua <[kionghua.bong@cyclecarriage.com.sg](mailto:kionghua.bong@cyclecarriage.com.sg)>; Coco Lu Ting <[coco.lu@cyclecarriage.com.sg](mailto:coco.lu@cyclecarriage.com.sg)>;  
Edwin Abcede Caina <[edwin.caina@cyclecarriage.com.sg](mailto:edwin.caina@cyclecarriage.com.sg)>; Tay Jian Ye <[jianye.tay@cyclecarriage.com.sg](mailto:jianye.tay@cyclecarriage.com.sg)>  
**Subject:** TP China Taiping Claim SJG6126B against GBD7134G DOA 05.03.2019

To Officer In charge,

My client who is driving SJG6126B wants to claim against GBD7134G which was insured by you.

Attach is the SAS report and repair quotation for your reference.

Kindly let me know the liability.

Best Regards,

Andre Chow  
Asst Manager – Aftersales Operations



WE DRIVE FIRST CLASS

Cycle & Carriage Singapore • 209 Pandan Gardens, Singapore 609339  
T: +65 6568 4501 • F: +65 6569 1240 • H: +65 9144 9137 • [www.cyclecarriage.com.sg](http://www.cyclecarriage.com.sg)

 A member of the Jardine Cycle & Carriage Group

DISCLAIMER:- This email and any attachment to it is confidential and intended only for the use of the individual or entity named above and may contain information that is privileged. If you are not the intended recipient, you are notified that any dissemination, distribution or copying of this email or any attachment is strictly prohibited. If you have received this email in error, please notify us immediately by return email and destroy the original message. Any views expressed are those of the individual sender, and not necessarily the views of Cycle Carriage Industries Pte Ltd and/or any of its related corporations.

---

This email has been scanned by the Symantec Email Security.cloud service.  
For more information please visit <http://www.symanteccloud.com>

---

DISCLAIMER:- This email and any attachment to it is confidential and intended only for the use of the individual or entity named above and may contain information that is privileged. If you are not the intended recipient, you are notified that any dissemination, distribution or copying of this email or any attachment is strictly prohibited. If you have received this email in error, please notify us immediately by return email and destroy the original message. Any views expressed are those of the individual sender, and not necessarily the views of Cycle Carriage Industries Pte Ltd and/or any of its related corporations.

---

This email has been scanned by the Symantec Email Security.cloud service.  
For more information please visit <http://www.symanteccloud.com>

---

[> Back to OneMotoring](#)

## Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	4076C
Vehicle Details	
Vehicle No.:	SJG6126B
Vehicle to be Exported:	No
Intended Deregistration Date:	03 Jun 2019
Vehicle Make:	KIA
Vehicle Model:	STINGER 2.0A 2WD SUNROOF
Primary Colour:	Grey
Manufacturing Year:	2018
Engine No.:	G4KLJH016676
Chassis No.:	KNAE351AMJ6038670
Maximum Power Output:	182.0 kW (244 bhp)
Open Market Value:	\$32,716.00
Original Registration Date:	02 Jul 2018
First Registration Date:	02 Jul 2018
Transfer Count:	0
Actual ARF Paid:	\$37,803.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	01 Jul 2028
PARF Rebate Amount:	\$28,352.00
Intended COE Rebate Details	
COE Expiry Date:	01 Jul 2028
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$37,330.00
COE Rebate Amount:	\$33,887.00
Total Rebate Amount:	\$62,239.00

The information contained herein is correct as at 03 Jun 2019

OK

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	08/03/2019 09:55
Date Of Accident	05/03/2019 19:45
Exact Location Of Accident	50 JALAN LENGKOK SEMBAWANG
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJG6126B
<b>Insured/Policyholder</b>	
Name Of Registered Owner	YONG ZHI YONG
NRIC No	S8314076C
Email Address	YONGZHIYONG@GMAIL.COM
Mobile Phone No	(LOCAL) +65-98507700
Alternative Phone No	OFFICE-98507700

### Vehicle Particulars

Manufacturer	KIA
Model	STINGER-2.0 2WD SUNROOF (A)
Exact Purpose for which vehicle was being used at time of accident	HAVING DINNER
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

### Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	1800073680
Cover Note Number	

### Driver

Name of Driver	YONG ZHI YONG
NRIC No	S8314076C
Date Of Birth	17/05/1983
Occupation	INDOOR
Date Of Driving Pass	27/02/2004
Driving Experience	15 YEARS AND 0 MONTHS
Gender	MALE
Mobile Number	+65-98507700
Fax Number	
Contact Number	OFFICE-98507700
Email Address	YONGZHIYONG@GMAIL.COM



Address	61 BRIGHT HILL DRIVE #15-04
Postcode	579853
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLIDED INTO PARKED VEHICLE
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	0

#### Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

REFER TO POLICE REPORT T/20190308/2031

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBD7134G
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	



## Sketch Plan

### SKETCH PLAN

#### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

Date & Time:

08/03/2019

0930

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Transit:

NRIC/FIN No.:

### Sketch Plan #2

### SKETCH PLAN

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

REFER TO POLICE REPORT T/2019 0308/2031

## DECLARATION

I/We declare the foregoing particulars are true in every respect.



Policyholder's Signature: \_\_\_\_\_  
Date & Time: 08/03/2019  
09:30



Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

2

Reporting Centre Personnel's Signature  
Name: B. J. J.  
NRIC/FIN No.:

## POLICE REPORT Pg. 1



**SINGAPORE  
POLICE FORCE**



T/20190308/2031

Police Station Of Origin:  
Bishan N.P.C  
20 Bishan Street 23 SINGAPORE 579757  
Tel No: 1800-5529999

1 of 3

Report No. T/20190308/2031

## REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 08/03/2019 09:05		Vide Report No.:		Station Diary No.: 33	
<b>Informant's Particulars</b>					
Name of Informant: YONG ZHI YONG			Address: 61 BRIGHT HILL DRIVE #15-04 SINGAPORE 579653		
ID Type / ID No.: NRIC NO / S8314076C			Contact No.: Home/Office: Mobile: 98507700		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 35	Date of Birth: 17/05/1983	Type of Informant: Vehicle Owner		
Race: Chinese			Language:		Institution / School Name:
Occupation: Doctor			Driving Licence Information: Class: 3		Date of Expiry:

## General Information of the Accident

Type of Accident:	Non-Injury Hit and Run	Drink Drive: No	Date/Time of Accident: 05/03/2019 19:45	Type of Location:
Location: Along Road 1 JALAN LENGKOK SEMBAWANG 50 Jln Lengkok Sembawang				
Weather:		Road Surface:		Road Speed Limit:
Traffic Flow:		Traffic Control:		Traffic Volume:
Type of Collision:				Anyone conveyed by ambulance: No

## Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
GBD7134G	Van					0
SJG6126B	Car	KIA	Stinger	Grey	Slightly Damaged	0

## Details of Person Involved

Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA



**SINGAPORE  
POLICE FORCE**



T/20190308/2031

Police Station Of Origin:  
Bishan N.P.C  
20 Bishan Street 23 SINGAPORE 579757  
Tel No: 1800-5529999

2 of 3

Report No. T/20190308/2031

**CONTINUATION OF REPORT**

Vehicle Owner			
Name	YONG ZHI YONG	ID No.	S8314076C
Related Vehicle	NIL	Contact No.	98507700
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

**Brief Details.**

On the 05/03/2019 at about 1900hrs I parked my car(SJG6126B) along 50 Jln Lengkok Sembawang and left for dinner and subsequently returned my vehicle at about 2100hrs and drove off. On the 07/03/2019 I noticed a dent on the front number plate of my car. As such I viewed my In-car cam and noticed that at about 1944hrs on 05/03/19 a Silver van (GBD7134) had reversed into my car and drove off. I also wish to state that there was not any note with contact information left behind. No one was injured and no government property was damaged. I am lodging this report for insurance claims purposes.

POLICE REPORT Pg. 1



SINGAPORE  
POLICE FORCE



T/20190308/2031

Police Station Of Origin:  
Bishan N.P.C  
20 Bishan Street 23 SINGAPORE 579757  
Tel No: 1800-5529999

3 of 3

Report No. T/20190308/2031

CONTINUATION OF REPORT

**Sketch Plan**

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

E /  
K MANOJ KUMAR

Signature Of Informant:

Signature Of Interpreter:  
Not applicable

Date/Time:  
08/03/2019 09:05

Officer In Charge Of Case:  
TP / HRT /  
Sr Staff Sgt ESTHER CHONG  
Contact No.: 65476368



Classification Of Case:

SN 061

Authentication Stamp  
NP168



CYCLE &amp; CARRIAGE

# CYCLE & CARRIAGE KIA PTE LTD PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684567 Fax: 65651240



Co Reg No : 199405410K

## ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
YONG ZHI YONG (YANG ZHIYONG)	Cust No/Name LCV06051/YONG ZHI YONG (YANG ZHIYONG)
61 BRIGHT HILL DRIVE	Reg No/Reg Date SJG6126B / 02/07/201
#15-04	Date In/Mileage / 0
SINGAPORE 579653	Chassis No KNAE351AMJ6038670
Contact No	Engine No G4KLJH016676
	Make/Model KIA/STINGER 2.0 A834RED LEATHER
	Colour/Trim P2M PANTHERA METAL / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
LCV06051	CRDVCH	11/03/2019/ 12:47	QUA	265 / AndreChow	46194

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M SUNDRY				60.00
SUPPLY FRONT NUMBER PLATE WITH FRAME				
E PNT88000				550.00
REPAIR FRONT BUMPER				
E PNT98000				420.00
RESpray FRONT BUMPER				
E PNT88000				100.00
REMOVE AND INSTALL FRONT PARKING SENSORS				
A 10028901				200.00
TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST				
USING HI-SCAN PRO TEST				
A 54900099				100.00
CHECK WIRING AND CHASSIS ELECTRICAL SYSTEM				
M SUNDRY				150.00
SUPPLY ZERTONA PAINT PROTECTION				
M MOULDING-FRT BPR LICENSE PLATE	1.00	35.00	00.00	35.00
M ABSORBER-FRONT BUMPER ENERGY	1.00	105.00	00.00	105.00
M EXTN WIRING ASSY-SPAS	1.00	194.00	00.00	194.00

SURVEYOR NAME: Steve (83228813)

SURVEYOR SIGNATURE: 

DATE: 3/6/19, 12.00pm

REMARKS: P/P, Reg before spray

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey

Confirm &amp; accepted by

- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Authorized signatory and company stamp

	Nett	1,914.00
7% GST on	1914.00	133.98
Total Payable		2,047.98

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE &amp; CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD  
PANDAN GARDENS CUSTOMER SERVICE CENTRE  
209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



## PRO-FORMA INVOICE

Co Reg No : 199405410K

**THIS IS NOT AN OFFICIAL TAX INVOICE**

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
CHINA TAIPING INSURANCE (S) PTE LTD MOTOR CLAIM DEPARTMENT 3 ANSON ROAD #16-00 SPRINGLEAF TOWER SINGAPORE 079909 Contact No	Cust No/Name LCVO6051/YONG ZHI YONG (YANG ZHIYONG) Reg No/Reg Date SJG6126B / 02/07/2018 Date In/Mileage 03/06/2019/ 13822 Chassis/Package KNAE351AMJ603867C /1F17 Engine No G4KLJH016676 Make/Model KIA/STINGER 2.0 A834RED LEATHER Colour/Trim P2M PANTHERA METAL / WK SATURN BLACK
03/06/	

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CTP00080	Cash	26/06/2019/ 11:55	TLA	881 / Jojo Cheng	46194

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
E PNT88000 REPAIR FRONT BUMPER				✓550.00
E PNT98000 RESPRAY FRONT BUMPER				✓420.00
E PNT88000 REMOVE AND INSTALL FRONT PARKING SENSORS				✓100.00
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST				✓200.00
A 54900099 CHECK WIRING AND CHASSIS ELECTRICAL SYSTEM				✓100.00
S SPECIALISTJOB TO SUPPLY FRONT LICENSE PLATE(RECTANGULAR & BLACK)				✓60.00
S SPECIALISTJOB SUPPLY ZERTONA PAINT PROTECTION				✓150.00
X MOULDING-FRT BPR LICENSE PLATE	1.00	35.00	00.00	✓35.00
Z TEXT CHINA TAIPING TP CLAIM GBD7134G DOA: 05/03/2019 SURVEYOR: STEVE LKK 03/06/2019				
<p><i>Cycle &amp; Carriage celebrates 120 years.</i> Visit <a href="http://www.cyclecarriage.com/120">www.cyclecarriage.com/120</a> for more info!</p>				

Parts	35.00	Nett	1,615.00
Labour	1,370.00	7% GST on	1615.00
Standard Menu	0.00		113.05
Specialist Job	210.00	Total Payable	1,728.05
Diagnostics Job	0.00		
Sundry/Others	0.00		
Total(w/o GST)	1,615.00		

This is not an official tax invoice.

This is a computer generated document, no signature is required.



Surveyor : Steve - LKK  
 Company : China Taiping  
 DOA : 05/03/2019  
 CSE : Andre  
 Date of Survey : 03/06/2019

VEHICLE NO : SJG6126B  
 MODEL : KIA/ STINGER 2.0 A834RED LEATHER  
 WIP : 46194

Material	:	\$	35.00
Labour	:	\$	1,580.00
Sub-Total	:	\$	1,615.00
Less Excess	:	\$	-
Total	:	\$	1,615.00
GST 7%	:	\$	113.05
Grand Total	:	\$	1,728.05
Finalise By/Date	:	JoJo dtd	26/06/2019

Email :

*Shiau Chan - File*

☒ REVERT BACK WITHIN 7 DAYS,  
 OTHERWISE WILL PROCEED WITH INVOICING

☐ SURVEYOR'S REPORT REQUIRED

REPAIR TOOK 3 WORKING DAYS +        Days (        ) Weekends  
 +        Days (        ) Public Holiday  
 + 1 Survey - 03/06/2019 - Mon  
 TOTAL DAYS REPAIR TOOK = 4

☒ TP Claim China Taiping - GBD7134G

☒ Claim GIA / LTA fee \$ 2.00

☒ Claim Loss ☐ Use ☒ Rental

☐ Claim Medical Fee / Others                     

☐ Third Party Report

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT119004981/EQD3N2

Date: 02/07/2019

## REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSN30183718011
Claimant Vehicle No :	SJG6126B	Insured Vehicle No :	GBD7134G
Date of Loss:	05/03/2019	Nature of Claim:	TP
		Claim No:	SNM19D201231C02

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No:	SJG6126B	Engine No:	G4KLJH016676
Make & Model:	KIA STINGER, 2.0 2WD SUNROOF (A)	Chassis No:	KNAE351AMJ6038670
Reg. Date:	02/07/2018 (Man. Year: 2018)	Odometer:	13822 km
Colour:	Grey		
Engine Capacity:	1998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size:	225/45R18	Rear Tyre Size:	225/45R18
Front Left Side:	Continental 7 mm	Rear Left Side:	Continental 7 mm
Front Right Side:	Continental 7 mm	Rear Right Side:	Continental 7 mm

The above values represent the remaining tyre treads depth

## COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	334.00	35.00	299.00	89.52
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,580.00	1,580.00	0.00	0.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>1,914.00</b>	<b>1,615.00</b>	<b>299.00</b>	<b>15.62</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>133.98</b>	<b>113.05</b>	<b>20.93</b>	<b>15.62</b>
<b>Nett Amount (S\$)</b>	<b>2,047.98</b>	<b>1,728.05</b>	<b>319.93</b>	<b>15.62</b>

## INSPECTION

Date of Assignment:	27/06/2019	
Date Inspected:	03/06/2019 Inspected At:	Cycle & Carriage Automotive Pte Ltd (Pandan Gardens) 209 Pandan Gardens Singapore 609339

Estimated Period of Repair: 3.0 days

Adjuster: CHEN TSUE YEE

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

## REPAIR DETAILS

### Reference

<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 02 Jul 2019)
<b>Parts:</b> M1-SUV	KIA STINGER 2.0 2WD SUNROOF (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SJG6126B)
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*ABSORBER-FRONT BUMPER ENERGY	Not Necessary	105.00 FS	*- FS
2	1		*EXTN WIRING ASSY-SPAS	Not Necessary	194.00 FS	*- FS
3	1		*MOULDING-FRT BPR LICENSE PLATE	Crushed	35.00 FS	*35.00 FS
				<b>Total Parts (\$\$)</b>	<b>334.00</b>	<b>35.00</b>

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	REPAIR FRONT BUMPER	New	550.00	550.00
2	SUPPLY FRONT NUMBER PLATE WITH FRAME	New	60.00	60.00
3	RESPRAY FRONT BUMPER	New	420.00	420.00
4	REMOVE AND INSTALL FRONT PARKING SENSORS	New	100.00	100.00
5	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST	New	200.00	200.00
6	CHECK WIRING AND CHASSIS ELECTRICAL SYSTEM	New	100.00	100.00
7	SUPPLY ZERTONA PAINT PROTECTION	New	150.00	150.00
<b>Gross Labour Cost (\$\$)</b>			<b>1,580.00</b>	<b>1,580.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >