

NATIONAL Assessment Centre Services. (wef 1 Jan'05) MHA 119036626

Date In: 14/3/19 - 17:25	Job description	Date & Time Completed	Done by
Ref No: NA/INC 1904985 / 24.	SAS e-filing		
Veh No: SUP5613	E-mail (within Shrs, AIC 2hrs)		
D.O.A: 15/3/19 - 10:30	i-Motor Claim Form	MT/11036607-001	19/3/19 17:25
☒ OD TP: Reporting Only	i-Motor W/O (Within: OD 2hrs, TP 4hrs)		
	i-Photo Uploaded		
TP Insurer:	Assessment/Survey Report		
	Ass't Report by Fax / Hand to Owner/Wksp		

Preferred Wksp / INC Assign Wksp / QW: (	Tel: (	Fax: (
TP Particulars:	Veh No: 4429067	INC () / Non-INC ()
Owner / Driver: (	Tel: (	
Policy No: (	Period: (	Cover Type: (
Confirmed by: (	Date: (	Time: (
Insured/Driver Liability: (	% [Note-Est Status (WO): N: 0-20%; P: 21-79% P: 80-100%]	
Year of Registration: (	Warranty: YES () / NO ()	
Excess: (\$	Loading: \$1,000 () / \$2,000 ()	

General Remarks:

() Walk-In Customer: Customer's information strictly Confidential & Strictly NO refer of repairer.

() Total Loss Case: to e-mail Insurer URGENTLY.

Drive-In () / Towed-In (); Invoice: YES () / NO (); Towing Co: ()

Remarks: (INC hotline: 6788 6616)	Date & Time Completed	Done by
1) Apply for Transport Allowance () / Courtesy Car ()		
2) QC Check / Post Repair Inspection ()		
3) Upload Resurvey Photo [Repair Cost > \$3000] ()		

Injury: _____

Date/Time	Actions

NA1903166	Invoice Preparation Checklist	Am't (\$) In Bill	Am't (\$) Add Bill
Claimant's Particulars:-	1) AR: Accident Reporting (\$30);		
Driver/Owner:	2) DA: Damage Assessment (\$100); INC (\$80)		
Contact No:	3) TF: Towing Fee \$40/\$45		
Damaged Portion:	4) FT: Follow-Through Survey \$120		
	5) FT: Follow-Through Survey (Resurvey) \$30		
	For claiming against INC Only (wef 10 Jan 2005)		
	6) TR: Re-inspection \$75		
	7) N1: Idac DA + SMRT Survey \$160		
	8) NTUC Additional Services:-		
QC Checked by (Engr-In-Charge):	QD*		
	*N5: Courtesy Car / Tpt Allowance \$5		
	*N6: Repair Co-ordination \$10		
	*N7: Post Repair Inspection \$25		
	*N8: DV / Collect Excess Coordination \$5		
Auditors' Comments:-	TP (N11): TP (Non INC) against INC \$20		
Pat 1:	9) N12: Idac Mobile 30		
Pat 2 / 3:	Invoice dated	Fee Charged	
	Invoice dated	Fee Charged	

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	19/03/2019 17:05
Date Of Accident	15/03/2019 00:30
Exact Location Of Accident	AMK ST 54
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLF5361B
-----------------------------	----------

Insured/Policyholder

Name Of Registered Owner	SEBASTIAN POH YONG SHENG
NRIC No	S8943339H
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-97851280
Alternative Phone No	OFFICE-97851280

Vehicle Particulars

Manufacturer	HONDA
Model	HRV 1.5 LX CVT
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5104188959
Cover Note Number	

Driver

Name of Driver	LEE SOON TEE
NRIC No	S1541314Z
Date Of Birth	15/08/1962
Occupation	OUTDOOR
Date Of Driving Pass	17/03/1981
Driving Experience	37 YEARS AND 11 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-92722239
Fax Number	
Contact Number	OFFICE-92722239
EMail Address	NOEMAIL

Address	BLK 547 ANG MO KIO AVENUE 10 #02-2242
Postcode	560547
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	PARENT
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO STATEMENT.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	YN2906D
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

The diagram shows a road layout on a grid background. At the top, a horizontal line is labeled "SCHOOL". Below this line, a vertical dashed line represents a road junction. To the left of the junction, two vehicles are shown: vehicle A is a rectangle with the letter "A" inside, and vehicle B is a rectangle with the letter "B" inside. Both vehicles have arrows pointing to the right, indicating they are moving towards the junction. To the right of the junction, the road continues horizontally. There are arrows on this section of the road: one pointing right above the road and one pointing left below the road, indicating two-way traffic. The entire diagram is drawn with black lines and text on a white grid background.

At 11.30PM, I was going to pick my daughter from AMK Hub. It was dark and I was tired, I did not notice the vehicle parked by the Road. When I noticed, it was already too late and I bang the side of the lorry.

I/We declare the foregoing particulars are true in every respect.

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

JACKSON CAR WILL LOW ON MONDAY -
THE WORKSHOP GUY KNOW YOU THANK
ROSLI

ACCIDENT STATEMENT

ACCIDENT DATE: (14 / 03 / 2019) (DD/MM/YYYY), TIME: (11 : 35) (HH:MM)

LOCATION: Ang Mo Kio Ave 10, street 54

1. DETAILS OF VEHICLE

a) VEHICLE NUMBER: SLF5361B

b) INSURANCE COMPANY: NTUC

c) POLICY NUMBER: 5104182959

d) POLICY TYPE: (COMPREHENSIVE / THIRD PARTY / THIRD PARTY FIRE & THEFT)

e) MAKE & MODEL: Honda HRV

f) TYPE: (SALOON / COUPE / MPV / VAN / LORRY / MOTORCYCLE / OTHERS)

g) VEHICLE CATEGORY: (PRIVATE / COMMERCIAL / MOTORCYCLE)

h) PURPOSE OF USING AT ACCIDENT TIME: On the way to pick my daughter

i) ARE YOU CLAIMING UNDER YOUR OWN INSURANCE (YES/NO)

IF NO, PLEASE STATE (THIRD PARTY CLAIM / REPORTING ONLY)

2. INSURED / POLICY HOLDER

A) NAME: Sebastian Poh Yong Sheng (MALE / FEMALE)

B) NRIC/FIN/PASSPORT: S8943339H CONTACT: 97851280

C) ADDRESS: 547 Ang Mo Kio Ave 10, #02-2242

* CONTINUE TO 3.d IF DRIVER ALSO POLICY HOLDER

DRIVER

a) NAME: Lee Soon TEH (MALE / FEMALE)

b) NRIC/FIN/PASSPORT: S1541314Z CONTACT: 12722239

c) ADDRESS: 547 Ang Mo Kio Ave 10, #02-2242

* d) DATE OF BIRTH: (15 / 08 / 1962) (DD/MM/YYYY)

e) OCCUPATION: (INDOOR / OUTDOOR)

f) DATE OF DRIVING PASS: 17 March 1981

4. WAS DRIVER AN EMPLOYEE OF THE INSURED'S COMPANY? (YES / NO)

IF NO, RELATIONSHIP OF THE DRIVER WITH INSURED: Mother

5. a) WEATHER CONDITION: (CLEAR / RAINING / OTHERS) Dark, at night

b) ROAD SURFACE: (DRY / WET / OTHERS)

6. WAS ANYBODY INJURED (YES / NO)

7. a) REPORTED TO POLICE (YES / NO)

IF YES, PLEASE STATE WHICH POLICE STATION:

8. THIRD PARTY VEHICLE

a) VEHICLE NUMBER: YN2906D

b) DRIVER'S NAME:

c) NRIC/FIN/PASSPORT:

MODEL:

CONTACT:

9. THIRD PARTY VEHICLE

d) VEHICLE NUMBER:

e) DRIVER'S NAME:

f) NRIC/FIN/PASSPORT:

MODEL:

CONTACT:

Email = seraphina.poh@hotmail.com

VIDEO

Pre-arranged workshop

Eng. Anto He Ltd.

92313123

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S1541314Z



Name
LEE SOON TEE
李 顺 治

Race
CHINESE

Date of birth
15-08-1962

Country/Place of Birth
SINGAPORE

Sex
F



REPUBLIC OF SINGAPORE DRIVING LICENCE



Licence Number **S1541314Z**
Name
LEE SOON TEE

Exp. Date **15 Aug 1962**
Issue Date **18 Feb 2003**

000210180K



5785419



NRIC No. **S1541314Z**



Date of Issue
16-08-2017

Address
**APT BLK 547 ANG MO KIO AVENUE 10
#02-2242
SINGAPORE 560547**


YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(S)

CLASS DATE
17 Mar 1961

Class 3 **Motor Cars and Motor Tractors the weight of which unladen does not exceed 2500 kilograms**

NP 429A

Licence No: S1541314Z



eBaoTech

GeneralClaim

Hello, NAC_PAYA_UBI_800601

[Change Language](#)[Change Password](#)[Log Out](#)[My Desktop](#)[Notice of Loss](#)

Policy Query

Policy No. Date of Accident

Vehicle No. (For Motor) Certificate Number

Select	Policy No.	Certificate Number	Policyholder Name	Policyholder NRIC	Product	Cover Type	Vehicle No.	Insured Object	Commence Date	Expiry Date
☐	5104188959		SEBASTIAN POH YONG SHENG	S8943339H	GPC	drive CLASSIC	SLF5361B	SLF5361B	01/10/2018	30/09/2019

 Policy Information

Policy No.	5104188959	Policyholder Name	SEBASTIAN POH YONG SHENG	Policyholder NRIC	S8943339H
Certificate No.					
Address	BLK 547 #02-2242 ANG MO KIO AVENUE 10 SINGAPORE 560547				
Product Name	PRIVATE CAR INSURANCE	Plan		Group Policy Flag	N
Policy Issue Date	28/09/2018	Effective Date	01/10/2018 00:00	Expiry Date	30/09/2019 23:59
Excess Type		All Claims Excess			
Third Party Excess	0	Own damage Excess	600	Windscreen Excess	100
Additional Excess	0	OS Premium	0		
Outside Singapore OD Excess	600	Outside Singapore TP Excess	0	Young/Inexperience Driver Excess	
Agent	CH INSURANCE AGENCY PTE. L ^T	Agent Tel.	98781682	GST Flag	Y
Co-insurance Flag	No				
Open Policy Info					
Certificate Info					

 Policyholder Mailing Address

Address 1	BLK 547 #02-2242	Address 2	ANG MO KIO AVENUE 10	Address 3	SINGAPORE 560547
Address 4		Address Type	Singapore address	Post Code	560547
Unit No.		Related Policy Number	5104188959		

 Insured Object: SLF5361B

 Endorsements

Sequence	Date of Endorsement	Endorsement Type	Endorsement Status	Endorsement Content
----------	---------------------	------------------	--------------------	---------------------

Continue

Cancel

Claim Handling

Accident HT/1036603

- EXIT

Policy No.	S104188959	Vehicle No.	SLF53618	GST Registration No.	
Certificate No.					
Policyholder Name	SEBASTIAN POH YONG SHENG			Policyholder NRIC	S8943239H
Product Code	PRIVATE CAR INSURANCE	Cover Type	drive CLASSIC	Loading	0
Contact No.(Mobile)	97861280	Contact No.(Office)	0	Contact No.(Home)	0
Email Address		Special Remark		eCode	T1
KFK	☒ No ☐ Yes	TCA	☒ No ☐ Yes	eCode Reason	
NCD Protection	No	NCD Entitlement(%)	0	Private Hire	No
🔍 Accident Details					
Report Date	19/03/2019 17:23	Accident Report Within 24 hrs	Yes	Accident Type	Collision - Head to Rear
Date of Accident	15/03/2019	Time of Accident hh:mm	00:30	Country of Accident	Singapore
Reporting Centre		Orange Force		ICM No.	
Accident Location	AMK ST 54				
🔍 Excess					
Own Damage Excess	600.00	Additional Excess	0	Windscreen Excess	100.00
Unnamed Driver Excess	0.00	Outside Singapore OD Excess	600.00		
Third Party Excess	0.00	Outside Singapore TP Excess	0.00		
🔍 Benefits					
🔍 GST Registered Information					
GST Registered	No	GST Registration Date			
GST Registration No.		GST Status Verified	Yes		
Modification History					
🔍 Policyholder Mailing Address					
Address 1	BLK 547 #02-2242	Address 2	ANG MO KIO AVENUE 10	Address 3	SINGAPORE S60547
Address 4		Address Type	Singapore address	Post Code	S60547
Unit No.		Related Policy Number	S104188959		
🔍 OT Driver Info					
Driver Name	LEE SOON TEE	Driver Type	Main Driver		
Unnamed driver Name		Driver NRIC	S1541314Z	Driver DOB	15/08/1962
Register Date of Driver License	17/03/1981	Driver Age	36	Driving Experience	37
Contact No.(Mobile)	92722239	Contact No.(Office)	0	Contact No.(Home)	0
Address 1	BLK 547	Address 2	ANG MO KIO AVENUE 10	Address 3	CHENG SAN GREEN
Address 4	SINGAPORE S60547	Address Type	Singapore address	Post Code	S60547
Unit No.	02-2242				
Does he own a Singapore Registered car?	☐ Yes ☒ No	Driver Vehicle No.		Driver Insurer Company	
Declaration					
Breathalyser or Blood Test Reading?	0 mg	Any Injury?	☐ Yes ☒ No		
Modification History					

Claim 001 New

Claim Type *	OD-MD	Insured Name	SEBASTIAN POH YONG SHENG	Insured NRJC	SB943339H
Contact No.(Mobile)	97851280	Contact No.(Home)	64527667	Contact No.(Office)	
Email Address		OI Vehicle Number	SLF5361B	TP Vehicle Number	YN2906D
Claimant Type Claimant Type *	Please Select	Type of Benefit *	Please Select		
Claimant Name *		Claimant NRJC *			
Claimant Address					
Claim Description	SLF5361B / YN2906D ON 15 Mar 2019				Name of Preferred Workshop
Preferred Workshop Contact No.	92313123	Insured Liability *	Fully at Fault		QING AUTO PTE LTD
Require Finalisation	Yes	Preferred Repair Option	Preferred Workshop (refer below)	GIA report	Received
Date Registered	19/03/2019 17:25	Claim Close Date		Date Received	19/03/2019 00:00
Report Taken By	Jackson			OD Excess Collected by Workshop	
☒ Print AK letter					

Attachment

Accident No.:	MT/1036603	Claim No.:	001
Last Doc. Received	☒ Yes ☐ No	Upload Date	19/03/2019 17:27

Path *	Category *	Confidential	Urgency *	Description *
Browse... Clear	Please Select	NO	Normal	
Browse... Clear	Please Select	NO	Normal	
Browse... Clear	Please Select	NO	Normal	
Browse... Clear	Please Select	NO	Normal	

Browse...		Clear	Please Select	NO	Normal	
Browse...		Clear	Please Select	NO	Normal	

☐ Send Message

Attachment List

Attachment	Uploaded By/Date	Category	Urgency	Description	Msg Sent? (CO)	Action
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERV) CES) on 19 Mar 2019 17:27	NRIC/ Driving License	Normal	NRIC/ Driving License 2019-3-19		Edit
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERV) CES) on 19 Mar 2019 17:27	SAS	Normal	SAS 2019-3-19		Edit
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERV) CES) on 19 Mar 2019 17:26	Photos	Normal	Photos 2019-3-19		Edit
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERV) CES) on 19 Mar 2019 17:26	Photos	Normal	Photos 2019-3-19		Edit
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERV) CES) on 19 Mar 2019 17:26	Photos	Normal	Photos 2019-3-19		Edit
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERV) CES) on 19 Mar 2019 17:26	Photos	Normal	Photos 2019-3-19		Edit
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERV) CES) on 19 Mar 2019 17:26	Photos	Normal	Photos 2019-3-19		Edit
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERV) CES) on 19 Mar 2019 17:26	Photos	Normal	Photos 2019-3-19		Edit
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERV) CES) on 19 Mar 2019 17:26	Photos	Normal	Photos 2019-3-19		Edit
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERV) CES) on 19 Mar 2019 17:26	Photos	Normal	Photos 2019-3-19		Edit
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERV) CES) on 19 Mar 2019 17:26	Photos	Normal	Photos 2019-3-19		Edit
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERV) CES) on 19 Mar 2019 17:26	Photos	Normal	Photos 2019-3-19		Edit
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERV) CES) on 19 Mar 2019 17:26	Photos	Normal	Photos 2019-3-19		Edit
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERV) CES) on 19 Mar 2019 17:26	Photos	Normal	Photos 2019-3-19		Edit
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERV) CES) on 19 Mar 2019 17:26	Photos	Normal	Photos 2019-3-19		Edit
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERV) CES) on 19 Mar 2019 17:26	Photos	Normal	Photos 2019-3-19		Edit
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERV) CES) on 19 Mar 2019 17:26	Photos	Normal	Photos 2019-3-19		Edit
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERV) CES) on 19 Mar 2019 17:26	Photos	Normal	Photos 2019-3-19		Edit
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERV) CES) on 19 Mar 2019 17:26	Photos	Normal	Photos 2019-3-19		Edit
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERV) CES) on 19 Mar 2019 17:26	Photos	Normal	Photos 2019-3-19		Edit
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERV) CES) on 19 Mar 2019 17:26	Photos	Normal	Photos 2019-3-19		Edit

Video List

Uploaded By/Date	Folder Date	File Name	Source	Action
Display in New Window Scan and uploading				

ASSIGNMENT (IDAC)

By CSO: Nature of Accident:

- 1) Vehicle hit Vehicle:
 - a) Pedestrian ()
 - b) Animal ()
 - c) Bicycle ()
- 2) Vehicle hit:
 - a) Pedestrian ()
 - b) Animal ()
 - c) Bicycle ()
- 3) Vehicle hit Road Side Objects:
 - a) Govn Property ()
 - b) Road Work Object ()
 - c) Private Property ()
- 4) Vehicle drop into drain ()
- 5) Damage due to Act of God:
 - a) Fallen Object ()
 - b) Flood ()
 - c) Other ()
- 6) Parked & Found Damaged:
 - a) Vandalism ()
 - b) Hit by Moving Object ()
- 7) Theft Case:
 - a) Stolen ()
 - b) Damage found when recovered ()
- 8) Fire:
 - a) Whilst driving ()
 - b) Parked ()
- 9) Accident date more than 24hrs: ()

Remarks for internal information

Remarks to appear in Works Order & Assessment report

- 1) Potential Total Loss ()
- 2) SRS Light on ()
- 3) ABS Light on ()

By Assessor- 1) Vehicle Information

Vch No: **SLF5361B** Rega: **30 Aug 2016**
 Type: **MC** / MCycle / Bus / Van / Lorry / Taxi / Prime Mover /
 / Truck / Trailer or
 Make & Model: **Honda HRV 1.5 LX CVT 1496**
 Colour: **Black** Transmission Type: **Auto** / Manual
 Eng/Flt: **No Display**
 C/Mo: **JHMRU1830G X 200172**
 Gen. Cond: **Good** / Fair / Poor / Burnt or
 Steering: **Good** / Jammed / Leaked / Burnt or
 Brake: **Good** / Jammed / Leaked / Burnt or
 Mod: **NH** / S/Rim / STD A/Rim or
 Tyre Size: F: **215 / 60 R16**
 R: **215 / 60 R16**
 BS: **DUN** / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or
 Front: R/Bal: **7** mm L/Bal: **7** mm
 Rear: R/Bal: **6** mm L/Bal: **6** mm
 Parallel Import: Yes **No** Towed-In: **Yes** / No
 Repair Type: LS / I.B.I Towing Required: **Yes** / No
 No of Repair Days: **10** Vehicle in Idac: **Yes** / No
 D.O.I: **20/3/2019** Time: **10.10 am**

By Assessor- 2) Comments

- 1) Damages not due to recent accident.
- 2) Damages do not seem hit onto:
 - a) Vehicle () b) Motorcycle () c) Bicycle () d) Pedestrian ()
 - e) Animal () f) Govn Object () g) Road Work Object ()
 - h) Private Property () i) Drain () j) Road Kerb/Grass Verge ()
- 3) Vehicle does not seem damaged as a result of:
 - a) Fallen Object () b) Flood () c) Vandalism () d) Fire ()
 - e) Moving Object () f) Stolen () g) Stolen & Recovered ()

Time Started

Time completed

D/CSO

S/ASS

3) Entire Operation Completed Time:

(1)Bent (2)Bent (3)Bent (4)Bent (5)Cut (6)Scratched (7)Distorted
(8)Shaded (9)Dented (10)Broken (11)Missing (12)Missing (13)Tom
(14)Unidentified (15)Not Working

MOTOR CAR (Frt)

ACTUAL (AC)
(1)Replace (✓) (2)Part CO (3)Check
(4)For Constant (5)C

1063

Front Portion

NAC	INC	Item	CON	AC	Qty
1001	991886	Frt Number Plate			
1002	991887	Frt Number Plate Base			
1003	991889	Frt Number Plate Garnish			
1004	991300	Frt Bumper	DD		
1005	992341	Frt Bumper Clips	NEC		6
1006	991325	Frt Bumper Bracket			
1007	991462	Frt Bumper Side Retainer	DIS		2
1008	991433	Frt Bumper Reinforcement			
1009	991318	Frt Bumper Beam			
1010	991468	Frt Bumper Sponge			
1011	991427	Frt Bumper Protector			
1012	991420	Frt Bumper Pad			
1013	991363	Frt Bumper Grille			
1014	991301	Frt Bumper Moulding			
1015	991407	Frt Bumper Lower Spoiler			
1016	991438	Frt Bumper Sensor			
1017	995100	Frt LH Bumper Fog Lamp Cover			
1018	991355	Frt RH Bumper Fog Lamp Cover			
1019	995079	Frt LH Bumper Fog Lamp			
1020	995080	Frt RH Bumper Fog Lamp			
1021	991793	Frt Grille			
1022	991328	Frt Grille Emblem			
1023	991799	Frt Grille Chrome Moulding			
1024	991222	Frt Apron Panel			
1025	992013	Frt Support Panel	BT		
1026	992025	Frt Support Panel Top Garnish Cover	CRA		
1027	992416	Horn			
1028	991277	Frt Brace Panel			
1029	995153	Frt LH Headlamp Assy	BR		
1030	991821	Frt RH Headlamp Assy			
1031	995088	Frt LH Side Lamp			
1032	995089	Frt RH Side Lamp			
1033	990248	Bonnet	BUC		
1034	991328	Bonnet Emblem			
1035	990287	Bonnet Lock	BT		
1036	990285	Bonnet Insulator	TN		
1037	990273	Bonnet Hinge	BT		2
1038	990261	Bonnet Damper			
1039	990305	Bonnet Rubber			
1040	990252	Bonnet Cable	DD		
1041	990311	Bonnet Stand			
1042	990119	Air Con Condenser			
1043	990122	Air Con Fan Cowling			
1044	990134	Air Con Suction Pipe (Low Pressure)			
1045	990118	Air Con Suction Hose			
1046	990133	Air Con Discharge Pipe (High Pressure)			
1047	990114	Air Con Discharge Hose			
1048	990149	Air Con Liquid Pipe			
1049	995066	Air Con Receiver Drier			
1050	990111	Air Con Compressor Assy			
1051	995294	Air Con Belt			
1052	995074	Radiator			
1053	992738	Radiator Cowling			
1054	992742	Radiator Fan Assy			
1055	992745	Radiator Fan Clutch			
1056	992758	Radiator Hose Top			
1057	992757	Radiator Hose Bottom	DD		
1058	992741	Radiator Expansion Tank			
1059	990151	Air Duct			
1060	990070	Air Cleaner Assy			
1061	990056	Air Cleaner Hose	CUT		
1062	990089	Air Cleaner Resonator			
1063	991712	Frt Int Manifold			
1064	991713	Frt Manifold Cover			
1065	991054	Frt Exhaust Manifold Sensor (Oxygen)			
1066	991714	Front Exhaust Pipe			
1067	990219	Battery			
1068	990224	Battery Cover	CRA		
1069	990223	Battery Bracket	BT		
1070	990229	Battery Tray			

Vehicle No: SLF 53618

NAC	INC	Item	CON	AC	Qty
1071	992205	Fuse Box			
1072	994011	Relay Box	BR		
1073	995053	Wiper Washer Tank	BR		
1074	995052	Wiper Washer Tank Motor			
1075	990159	Alternator Assy			
1076	990160	Alternator Belt			
1077	992688	Power Steering Pump			
1078	992669	Power Steering Belt			
1079	994431	Power Steering Cooler Pipe			
1080	992692	Power Steering Hose			
1081	990010	ABS Pump Control Unit			
1082	990427	Brake Master Pump Assy			
1083	990403	Brake Booster Pump Assy			
1084	991005	Engine Top Cover			
1085	991011	Engine Under Cover			
1086	990946	Engine Control Unit	CRA		
1087	990949	Engine Throttle Body			
1088	990950	Engine			
1089	990952	Engine Mounting RH			
1090	990951	Engine Mounting Rear			
1091	992234	Gear Box Mounting			
1092	991520	Frt LH Chassis Member			
1093	991520	Frt RH Chassis Member			
1094	990728	Frt Vertical Cross Member			
1095	991863	Frt Lower Cross Member			
1096	995070	Frt LH Fender	BUC		
1097	995072	Frt LH Fender Wheel Housing	BUC		
1098	995147	Frt LH Fender Wheel Arch			
1099	995148	Frt LH Fender Wheel Arch			
1100	991740	Frt LH Fender Inner Shield	TN		
1101	995179	Frt LH Mudflap			
1102	995170	Frt LH Wheel Rim			
1103	994025	Frt LH Rim Cover			
1104	995065	Frt LH Tyre			
1105	995071	Frt RH Fender	BT		
1106	991739	Frt RH Fender Inner Panel			
1107	991744	Frt RH Fender Wheel Arch			
1108	991752	Frt RH Fender			
1109	991740	Frt RH Fender Inner Shield			
1110	991884	Frt RH Mudflap			
1111	992087	Frt RH Wheel Rim			
1112	994025	Frt RH Rim Cover			
1113	995065	Frt RH Tyre			
1114	992093	Frt Windscreen Glass	BR		
1115	992117	Frt Windscreen Rubber			
1116	992108	Frt Windscreen Moulding	NEC		
1117	992098	Frt Windscreen Sealant	NEC		
1118	991019	ERP Bracket	NEC		
1119	991020	ERP Unit			
1120	992140	Frt Wiper Arm LH			
1121	992142	Frt Wiper Blade			
1122	995045	Wiper Panel Garnish	CUT		
1123	991126	Firewall Panel	DD		
1124	990753	Dashboard Assy			
1125	992282	Glove Box Cover			
1126	992281	Glove Box Compartment			
1127	994483	Steering Wheel Airbag			
1128	994483	Steering Wheel Airbag Sensor			
1129	990749	Dashboard Airbag			
1130	990750	Dashboard Airbag Sensor			
1131	990029	Airbag Control Unit			
1132	990864	Frt Driver Seat			
1133	991922	Frt RH Seat Belt Assy			
1134	991899	Frt Passenger Seat			
1135	995182	Frt LH Seat Belt Assy			
1136	990247	Sticker			
		Front Wire Harness			
		Frt LH Door	BUC		

No of Items:

Agg 45801

30(7) 123128-70

531512-70

Condition (C019)

(01) Bent (2) Dented (3) Distorted (4) Cracked (5) Curved (6) Scratched
 (07) Deformed (08) Stained (09) Buckled (10) Broken (11) Necessary (12) Missing
 (13) Torn (14) Unconfirmed (15) Not Working

MOTOR CAR (LH)

ACTION (AC)

(1) Replace (✓) (2) Repair (C) (3) Change (T)
 (4) Not Consistent (HC)

283

Left Portion

Vehicle No: SLF5361B

NAC	INC	Item	CON	AC	Qty
1255	995326	Frt LH Door			
1256	995140	Frt LH Door Protector			
1257	995104	Frt LH Door Hinge			
1258	995142	Frt LH Door Wing Mirror	CUT		
1259	995102	Frt LH Door Garnish			
1260	991593	Frt LH Door Glass Outer Moulding			
1261	991588	Frt LH Door Glass Inner Moulding			
1262	995103	Frt LH Door Glass			
1263	991595	Frt LH Door Glass Regulator			
1264	991596	Frt LH Door Glass Regulator Motor			
1265	991662	Frt LH Door Rubber			
1266	991636	Frt LH Door Outer Handle			
1267	991607	Frt LH Door Inner Handle			
1268	991625	Frt LH Door Lock w/Key			
1269	991624	Frt LH Door Lock			
1270	991562	Frt LH Door Central Lock			
1271	991675	Frt LH Door Switch			
1272	991617	Frt LH Door Inner Trim Board			
1273	991568	Frt LH Door Checker			
1274	991575	Frt LH Door Felt			
1275	991688	Frt LH Door Wire Harness			
1276	991683	Frt LH Door Window Glass Pillar			
1277	991640	Frt LH Door Outer Pillar			
1278	991613	Frt LH Door Inner Pillar			
1279	991646	Frt LH Door Pillar Inner Garnish			
1280	990554	Centre Pillar LH			
1281	990542	Centre Inner Pillar LH			
1282	990517	Centre Pillar Upper Garnish LH			
1283	990564	Centre Pillar Lower Garnish LH			
1284	991670	Frt LH Door Step Garnish			
1285	994052	Rocker Panel LH			
1286	994049	Rocker Panel Inner Panel LH			
1287	994046	Rocker Panel Garnish LH			
1288	994055	Rocker Panel Outer Side Skirt LH			
1004	991300	Frt Bumper			
1006	991325	Frt Bumper Bracket			
1007	991462	Frt Bumper Side Retainer			
1008	991433	Frt Bumper Reinforcement			
1010	991468	Frt Bumper Sponge			
1011	991427	Frt Bumper Protector			
1014	991301	Frt Bumper Moulding			
1015	991407	Frt Bumper Lower Spoiler			
1029	995153	Frt LH Headlamp Assy			
1031	995088	Frt LH Side Lamp			
1096	995070	Frt LH Fender			
1098	995147	Frt LH Fender Lamp			
1099	995148	Frt LH Fender Protector			

NAC	INC	Item	CON	AC	Qty
1289	995156	Rear LH Door			
1290	993282	Rear LH Door Protector			
1291	995194	Rear LH Door Hinge			
1292	993228	Rear LH Door Garnish			
1293	993278	Rear LH Door Glass Outer Moulding			
1294	993231	Rear LH Door Glass Inner Moulding			
1295	995190	Rear LH Door Glass			
1296	993238	Rear LH Door Glass Regulator			
1297	995192	Rear LH Door Glass Regulator Motor			
1298	993294	Rear LH Door Rubber			
1299	993275	Rear LH Door Outer Handle			
1300	993250	Rear LH Door Inner Handle			
1301	993261	Rear LH Door Lock			
1302	993256	Rear LH Door Inner Trim Board			
1303	993218	Rear LH Door Checker			
1304	993230	Rear LH Door Glass Channel			
1305	993242	Rear LH Door Glass Triangle Garnish			
1306	993285	Rear LH Door 1/4 Glass			
1307	993288	Rear LH Door 1/4 Glass Rubber			
1308	993287	Rear LH Door 1/4 Glass Pillar			
1309	993305	Rear LH Door Step Garnish			
1310	993309	Rear LH Door Switch			
1311	994070	Roof Top Panel			
1312	994098	Roof Top Moulding			
1313	994085	Roof Top Air-bag			
1314	994084	Roof Top Air-bag Sensor			
1315	994083	Roof Top Air-bag Control Unit			
1141	992958	Rear Bumper			
1147	992976	Rear Bumper Bracket			
1148	993068	Rear Bumper Side Retainer			
1149	993045	Rear Bumper Reinforcement			
1151	993077	Rear Bumper Sponge			
1153	993040	Rear Bumper Protector			
1155	993026	Rear Bumper Moulding			
1157	993023	Rear Bumper Lower Spoiler			
1163	993851	Rear LH Taillamp			
1218	993436	Rear LH Fender			
1219	993449	Rear LH Fender Protector			
1136	990247	Sticker			

No of Items: _____ Assessor: _____

(01)Bent (2)Dented (3)Distorted (4)Cracked (5)Cut (6)Scratched
(07)Deformed (08)Shifted (09)Buckled (10)Broken (11)Necessary
(12)Missing (13)Torn (14)Unconfirmed (15)Not Working

(1) Replace (✓) (2) Repair (X) (3) Check (?)
(4) Not Consistent (NC)

Aug 2005

Aug 2005
3563

NAC	INC	Item	CON	AC	Qty
1372	995163	Frt LH Shock Absorber	BR	/	
1373	991944	Frt LH Shock Absorber Mounting		?	
1374	990632	Frt LH Coil Spring			
1375	995198	Frt LH Knuckle Arm		?	
1376	995199	Frt LH Knuckle Arm Bearing		?	
1377	995178	Frt LH Lower Arm		?	
1378	995169	Frt LH Upper Arm			
1379	995183	Frt LH Tie Rod			
1380	995143	Frt LH Drive Shaft		?	
1381	990661	Frt LH Control Arm			
1382	992062	Frt LH Trailing Arm			
1383	991848	Frt LH Leaf Spring			
1384	991293	Frt LH Brake Disc Rotor			
1385	991281	Frt LH Brake Caliper			
1386	991292	Frt LH Brake Pipe		?	
1387	991287	Frt LH Brake Hose		?	
1388	991295	Frt LH Brake Sensor Wire			
1389	991989	Frt Stay Bar Bracket			
1390	994455	Steering Rack & Pinion			
1391	994435	Steering Cross Member			
1392	994519	Frt Sub Frame			
1393	992003	Frt Sub Frame Mounting			
1394	991217	Frt Anti Roll Bar			
1395	991219	Frt Anti Roll Bar Linkage			
1396	990887	Engine Block			
1397	990890	Engine Block Gasket			
1398	990972	Engine Oil Sump			
1399	990960	Engine Oil			
1400	992224	Gear Box Assy			
1401	992229	Gear Box Gasket			
1402	992241	Gear Box Oil Sump			
1403	992257	Gear Oil			
1210	990534	Centre Exhaust Pipe Assy			
1211	990532	Centre Exhaust Mounting			
1404	991134	Floor Panel			
1405	993719	Rear LH Shock Absorber			
1406	993723	Rear LH Shock Absorber Mounting			
1407	993170	Rear LH Coil Spring			
1408	993550	Rear LH Knuckle Arm			
1409	993551	Rear LH Knuckle Arm Bearing			
1410	993597	Rear LH Lower Arm			
1411	993884	Rear LH Upper Arm			
1412	995161	Rear LH Drive Shaft			
1413	995216	Rear LH Control Arm			
1414	993881	Rear LH Trailing Arm			
1415	993573	Rear LH Leaf Spring			
1416	992941	Rear LH Brake Disc Rotor			
1417	992937	Rear LH Brake Caliper Assy			
1418	990434	Rear LH Brake Pipe			
1419	992946	Rear LH Brake Hose			
1420	993819	Rear Sub Frame			
1421	993820	Rear Sub Frame Mounting			
1422	992813	Rear Anti Roll Bar			
1423	990168	Rear Anti Roll Bar Linkage			
1424	990202	Axle Beam			
1425	990170	Rear Axle Panhard Rod			
1426	990810	Differential Assy			
1427	992706	Propeller Shaft			

[illegible]

Original copy

Claim Handling

Task Transfer Exit

Accident MT/1036603

LOGS TAB SUB

Policy No.	5104188959	Vehicle No.	SLF5361B	GST Registration No.	
Certificate No.					
Policyholder Name	SEBASTIAN POH YONG SHENG	Cover Type	drive CLASSIC	Policyholder NRIC	S8943339H
Product Code	PRIVATE CAR INSURANCE	Contact No.(Office)	0	Leading	0
Contact No.(Mobile)	97851280	Special Remark		Contact No.(Home)	0
Email Address		TCA	☒ No ☐ Yes	eCode	
KPK	☒ No ☐ Yes	NCD Entitlement(%)	0	eCode Reason	
NCD Protection	No			Private Hire	No

Accident Details

Report Date	19/03/2019 17:23	Accident Report Within 24 hrs	No	Accident Type	Collision - Head to Rear
Date of Accident	15/03/2019	Time of Accident hh:mm	00:30	Country of Accident	Singapore
Reporting Centre	NATIONAL ASSESSMENT CENTR	Orange Force	No	ICM No.	
Accident Location	ANK ST 54				

Excess

Own damage Excess	600.00	Additional Excess	0	Windscreen Excess	100.00
Unnamed Driver Excess	0.00	Outside Singapore OD Excess	600.00		
Third Party Excess	0.00	Outside Singapore TP Excess	0.00		

Benefits

GST Registered Information

GST Registered	No	GST Registration Date	
GST Registration No.		GST Status Verified	Yes
Modification History			

Policyholder Mailing Address

Address 1	BLK 547 #02-2242	Address 2	ANG MO KIO AVENUE 10	Address 3	SINGAPORE S60547
Address 4		Address Type	Singapore address	Post Code	S60547
Unit No.		Related Policy Number	5104188959		

OI Driver Info

Driver Name	LEE SOON TEE	Driver Type	Main Driver	Driver DOB	15/06/1962
Unnamed driver Name		Driver NRIC	S1541314Z	Driving Experience	37
Register Date of Driver License	17/03/1981	Driver Age	56	Contact No.(Home)	0
Contact No.(Mobile)	92722239	Contact No.(Office)	0	Address 3	CHENG SAN GREEN
Address 1	BLK 547	Address 2	ANG MO KIO AVENUE 10	Post Code	S60547
Address 4	SINGAPORE S60547	Address Type	Singapore address		
Unit No.	02-2242				
Does he own a Singapore Registered car?	☐ Yes ☒ No	Driver Vehicle No.		Driver Insurer Company	

Declaration

Breathalyser or Blood Test Reading?	0 mg	Any Injury?	☐ Yes ☒ No
Modification History	20/03/2019 15:13 s018940 Modify Accident Report Within 24 hrs(Yes->No)		

Investigation

Claim 001 OD-MD

Claim Case Officer Tan Siew Choo

LOGS TAB SUB

Claim Type	OD-MD	Insured Name	SEBASTIAN POH YONG SHENG	Insured NRIC	S8943339H
Contact No.(Mobile)	97851280	Contact No.(Home)	64527667	Contact No.(Office)	
Email Address		OI Vehicle Number	SLF5361B	TP Vehicle Number	YN2906D
Claimant Type		Type of Benefit			
Claimant Name		Claimant NRIC			
Claimant Address					
Claim Description	SLF5361B / YN2906D ON 15 Mar 2019	Name of Preferred Workshop	DING AUTO PTE LTD		
Preferred Workshop Contact No.	92313123	Insured Liability	Fully at Fault		
Require Finalisation	Yes	Preferred Repair Option	Preferred Workshop (refer below)		
Date Registered	19/03/2019 17:28	Claim Close Date			
Report Taken By	Jackson	Workshop Repairer			
☒ Print AK letter					
Modification History					

Special Claim Creation Approval

Approval	Reason
Remarks	

damage assessment Activity Handling Attachment

Vehicle Info

Vehicle Make	HONDA	Vehicle Model	HRV	Engine Capacity	
Date of Registration	30/06/2016	Class No.	JHMRU1830GX200172		
Towing Required *	☒ Yes ☐ No	Vehicle in IDAC *	☒ Yes ☐ No	Parallel Import *	☐ Yes ☒ No

Type of Tender * Assessor Name * Survey Current Status

IDAC/Workshop Name: NATIONAL ASSESSMENT CENTR IDAC/Workshop Location: 51 UBI AVENUE 1 #01-25 PAYA

Windscreen Parts & Labour Cost Total Loss * ☐ Yes ☒ No

Market Value(\$) Scrap Value(\$) Economical Repair Value(\$)

Remark: REMARK: NO OF REPAIR DAY: 10 DAYS: 1 X FRT SUPPORT PANEL TOP GARNISH COVER - REPLACE. 1 X AIR DUCT - UNCONFIRM. 1 X AIR CLEANER ASSY - UNCONFIRM. 1 X RELAY BOX - REPLACE. 1 X ENGINE CONTROL UNIT - REPLACE. 1 X ENGINE THROTTLE BODY - UNCONFIRM. 1 X FRT LH FENDER WHEEL HOUSING - REPLACE. 1 X FRT WINDSCREEN MOULDING - REPLACE. 1 X FRT WIPER BLADE - UNCONFIRM. 1 X FRT LH DOOR WING MIRROR - REPLACE. 1 X FRT LH BRAKE PIPE - UNCONFIRM. 1 X FRT LH BRAKE HOSE - UNCONFIRM.

Remark for Supplementary

Damage Listing

Find a Part	No.	Part No.	Description	Qty *	Repair Code *	
Not Applicable	1	26600102	FUSE BOX (CENTRE)	1	Replace	☒
ABS	2	243014	ENGINE LOWER COVER	1	Unconfirm	☒
ACCELERATOR	3	25400102	FENDER (FRONT LEFT)	1	Replace	☒
ACTUATOR	4	25401601	FENDER WHEEL ARCH GARNISH (FRONT LEFT)	1	Replace	☒
ADVERTISEMENT STICKER	5	25400901	FENDER INNER SHIELD (FRONT LEFT)	1	Replace	☒
AIR BAG	6	16000101	BUMPER (FRONT)	1	Replace	☒
AIR BLOWER	7	16002401	BUMPER CLIPS (FRONT)	6	Replace	☒
AIR BOX	8	16005101	BUMPER RETAINER (FRONT LEFT)	1	Replace	☒
AIR CHAMBER BOX	9	16005102	BUMPER RETAINER (FRONT RIGHT)	1	Replace	☒
AIR CLEANER	10	16005001	BUMPER REINFORCEMENT (FRONT)	1	Unconfirm	☒
AIR COMPRESSOR	11	16005901	BUMPER SPONGE (FRONT)	1	Unconfirm	☒
AIR CON	12	16003201	BUMPER GRILLE (FRONT)	1	Unconfirm	☒
AIR CON (VAN)	13	16004101	BUMPER LOWER SPOILER (FRONT)	1	Unconfirm	☒
AIR COOLER	14	16005501	BUMPER SENSOR (FRONT)	1	Unconfirm	☒
AIR DISTRIBUTOR	15	41300101	SUPPORT PANEL (FRONT)	1	Replace	☒
AIR FILTER	16	27700101	HEAD LAMP (LEFT)	1	Replace	☒
AIR FLOW	17	27700102	HEAD LAMP (RIGHT)	1	Unconfirm	☒
AIR GRILLE	18	149001	BONNET	1	Replace	☒
AIR HORN	19	14903401	BONNET LOCK (LOWER)	1	Replace	☒
AIR INTAKE	20	149029	BONNET INSULATOR	1	Replace	☒
AIR RESONATOR BOX	21	14902201	BONNET HINGE (LEFT)	1	Replace	☒
AIR THROTTLE BODY AND SENSOR	22	14902202	BONNET HINGE (RIGHT)	1	Replace	☒
ALARM	23	149041	BONNET RUBBER (CENTRE)	1	Replace	☒
ALTERNATOR	24	149007	BONNET CABLE	1	Unconfirm	☒
ALUMINIUM PANEL - SIDE	25	112023	AIR CON CONDENSER	1	Unconfirm	☒
AMPLIFIER	26	112064	AIR CON FAN COWLING	1	Unconfirm	☒
ANTENNA	27	344001	RADIATOR	1	Unconfirm	☒
ANTI ROLL	28	344005	RADIATOR COWLING	1	Unconfirm	☒
APRON	29	34402802	RADIATOR HOSE (TOP)	1	Replace	☒
ARCH	30	11001302	AIR CLEANER HOSE (CENTRE)	1	Replace	☒
ARM REST	31	2900	INLET MANIFOLD	1	Unconfirm	☒
ASH TRAY	32	141001	BATTERY	1	Unconfirm	☒
AUTO CLUTCH	33	141005	BATTERY COVER	1	Replace	☒
AUTO COOLER PIPE	34	141002	BATTERY BRACKET	1	Replace	☒
AUTO CRUISE MOTOR	35	25400103	FENDER (FRONT RIGHT)	1	Replace	☒
AUTO TRANSMISSION	36	25401602	FENDER WHEEL ARCH GARNISH (FRONT RIGHT)	1	Unconfirm	☒
AXLE	37	25400902	FENDER INNER SHIELD (FRONT RIGHT)	1	Unconfirm	☒
BACK REST (MC)	38	45100401	WINDSCREEN GLASS (FRONT)	1	Replace	☒
BACK SEAT	39	451020	WINDSCREEN SEALANT	1	Replace	☒
BALANCER	40	245001	ERP BRACKET	1	Replace	☒
BATTERY	41	45400101	WIPER ARM (FRONT LEFT)	1	Unconfirm	☒
BEADING (MC)	42	454009	WIPER PANEL GARNISH	1	Replace	☒
BELT COVER (MC)	43	2550	FIREWALL PANEL	1	Repair	☒
BELT TENSIONER	44	22600102	DASHBOARD (TOP)	1	Unconfirm	☒
BODY	45	455001	WIRE HARNESS	1	Unconfirm	☒
BODY (MC)	46	23300201	DOOR (FRONT LEFT)	1	Replace	☒
BOLT CAP (MC)	47	23302001	DOOR GLASS (FRONT LEFT)	1	Unconfirm	☒
BOLT HEAD COVER (MC)	48	36600101	SHOCK ABSORBER (FRONT LEFT)	1	Replace	☒
BONNET	49	36600601	SHOCK ABSORBER MOUNTING (FRONT LEFT)	1	Unconfirm	☒
BOT	50	30000101	KNUCKLE ARM (FRONT LEFT)	1	Unconfirm	☒
BOX (MC)	51	30000201	KNUCKLE ARM BEARING (FRONT LEFT)	1	Unconfirm	☒
BOX BRACKET (MC)	52	30500101	LOWER ARM (FRONT LEFT)	1	Unconfirm	☒
BOX CARRIER (MC)	53	23600101	DRIVE SHAFT (FRONT LEFT)	1	Unconfirm	☒
BOX DOOR						
BOX STICKER (MC)						
BRACE PANEL						
BRAKE						
BRAKE - ABS						
BRAKE (MC)						
BUMPER						
CABIN						
CAMBER						
CAMSHAFT						
CAR AUDIO SYSTEM						
CAR JACK						
CARBURATOR						
CARGO						
CARRIAGE						
CARRIER MOUNTING						
CASTOR						
CATALYTIC CONVERTOR						
CD CHANGER						
CD PLAYER						
CDI UNIT (MC)						
CENTRE BOTTOM						
CENTRE BRACKET						
CENTRE CONSOLE						
CENTRE COWLING (MC)						

Save Submit

LKK Paya Ubi

From: Yap Chee Ling <CheeLing.Yap@income.com.sg>
Sent: Monday, 25 March 2019 10:13 AM
To: LKK Paya Ubi
Subject: SLF5361B | MT/1036603 (Awarding Letter to Ding Auto)

Importance: High

Hi IDAC,

Please release the vehicle to Ding Auto.

Thank you.

Yap Chee Ling (Ms)
Executive
Motor Insurance
T +65 6430 7893
www.income.com.sg



At Income, we are 'In with You' on Performance, Growth, Innovation and Impact. These attributes reflect what we promise as an employer and what we want our people to exemplify. Find out more at income.com.sg/careers



Our Ref: MT/CA/OD/051/1036603-001/TSC/YCL

25 Mar 2019

DING AUTO PTE LTD
BLK 10 #01-20
SIN MING INDUSTRIAL EST SECTOR C
SIN MING INDUSTRIAL ESTATE
SINGAPORE 575645

Dear Sir

CLAIM NUMBER: MT/1036603-001
REPAIR OF VEHICLE NUMBER: SLF5361B

We are pleased to inform you that you are successful in your tender to repair the vehicle. The details are as follows:

Award Date: 25 Mar 2019
Make: HONDA
Model: HRV
Estimated Repair Days: 10
Location: NATIONAL ASSESSMENT CENTRE SERVICES

Address: 51 UBI AVENUE 1 #01-25 PAYA UBI INDUSTRIAL PARK SINGAPORE 408933

Benefits: Not applicable

Excess Applicable: 600

Please note that supplementary items will not be allowed.

If you have any queries, please contact Tan Siew Choo at 6430-7882 or email us at motor@income.com.sg.

Yours sincerely

Jenny Pe
Deputy Vice President
Motor Insurance

Disclaimer

This e-mail contains privileged or confidential information which is intended only for the use of the recipient(s) named above. If you have received this message in error, please notify the sender immediately and delete all copies of it. Thank you.



NATIONAL ASSESSMENT CENTRE SERVICES
(LKK GROUP)

51 Ubi Ave 1, #01-25, Paya Ubi Industrial Park,
Singapore 408933, TEL: 6841 0055 FAX: 6841 6315



Vehicle Movement Form

Vehicle Check-In

Vehicle No: SGF5361B Date In: _____ Time In: _____ with Keys: Yes / No

For Office use

Attended by: _____

Workshop Collection of Vehicle

Workshop: Ding Auto

Collection Date: 25/03/19 Time: 16.47 with Keys: Yes / ~~No~~

Tow Truck No: GBH 3735C Tow Man: Sebastian Chua NRIC: S8417572/B

Signature: [Signature]

For office use

Attended by: Jackson.

Approved by: _____

Workshop Return of Vehicle

Workshop: _____

Returned Date: _____ Time: _____ with Key: Yes / No

* Tow In / Drive In

Tow Man / Workshop Representative: _____ NRIC: _____

Signature: _____

For office use

Attended by: _____

Owner Collection of Vehicle

Collection Date: _____ Time: _____ with Key: Yes / No

Owner: _____ NRIC: _____

Signature: _____

For office use

Attended by: _____

Approved by: _____