

2/09/2007

ASS. REC. BY:

REF: CS3/CT1 19004987/RICd3

Special Instruction:

Surveyor

Razli

ASSIGNMENT (Office)

From (Person):

Ong Chin Kiat

of

CT1

Date/Time:

19.3.2019 3.28pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJD 1780K

Insured:

XD95902

at Workshop m/s:

Ah Koon Motor (1960)

Tel:

of BIK 1001 Bukit Merah Lane 3, # 01-69

Policy No:

DMCVSN16702318022

Claim No:

8NM19D201224C02

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

13.3.2019

20.3.2019

CA / REV / REP. / REV 24 HRS

"wp"

H.O.D. Endorsement:

Date/Time:

19.3.19 5.37pm

Person Contacted:

Anthony

Vehicle (IN) OUT

Date/Time

Action/Instruction (X) Estimate

SJD 1780K - NBA / INC 19004681 / Y

D.O.A - 06/03/2019.

XD95902 - NBA / INC 19004681 / Y

D.O.A - 06/03/2019

After repair: 1/4/2019.

Dismantle: 27/3/2019.

Prema

REF:

ASST. CLERK

97279
Cob X4M4: 2023/P6B

From: Date:
Estimated cost:
OD / TP / WS / TP RES / OD RLS / EVA / INV / MV
To inspect Vehicle No: SJO 1780K
at Workshop on: AH Koon Motor
of: 1001, BUKIT MERTAH LN 3 #01-69
Insured: CTI
Policy No:
Claim No:
Sum Insured: Excess:
(Client's Record)
Make of Veh:



(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Est. or Market Value:

28K \$25K.

IRAC Accident Report

Consistent? Yes or No

GA / PR / Green

Consistent? Yes or No

Est. Repairs:

5

days

Res? Yes or No

Est. Cost:

%

3Val? Yes or No

GA / REV / REP / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted

Veh No: SJO 1780K
Type: Car / Motorcycle / Bus / Van / Lorry / Taxi / Private Motor /
Truck / Trailer or
Make: TOYOTA COROLLA 410 1.5XA 1496
Colour: GOLD
Sp Reading: 161802
Eng No:
Chassis: P2E1416057433
Gen. Cond: Good / Fair / Poor / Burnt
Steering: In order / Jammed / Leaked / Burnt or
Brake: In order / Jammed / Leaked / Burnt or
Mod: M / R / STD A/Rim or
Tyre Size: F: 195/60R15
R: --

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OH / SU / PIR / SUMU /
TOYO / YOKO or FALKEN

Front

Rear

R/Wal

5

mm

R/Wal

5

mm

L/Wal

5

mm

L/Wal

5

mm

D.O.A.

13/03/19

D.O.A.

20/03/19

Survey held at

AH Koon Motor

Des. of Damages: Frt / Rear / O/S / H/S / U/C / Rooftop or

o/s Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Estimated repair range \$4,000 - \$5,000

15/5/2019

Date/Time File/Case No:



Preli. Report

Final Report

Days Of Repair:

5

Restruvy No. of Trip:

2

Survey Fee

Transportation

190

Date/Time File/Return No:

Add Fee:



Subs. Imp. CB

Interp. CB

Test. Fees CB

Wheel and CB

Subs. Imp. CB

Interp. CB

Test. Fees CB

Wheel and CB

Report Format

PRE.

Lump Sum / LBA / CB

190

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	19 Mar 2019		19 Mar 2019 15:28 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

Show All

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	KASZON PTE LTD, Co. Reg. No.: 200007153D		
Main Claimant:	VEMALATHVEI D/O ARANASALAM, ID: S1449727G		
Vehicle Reg. No.:	SJD1780K	Date of Loss:	13/03/2019 17:00 - :59 [132 Months and 1 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / SNM19D201224C02	Policy/Cover Note No.:	DMCVSN16702318022 (Comprehensive) Coverage: 15/10/2018 - 14/10/2019
Vehicle Reg. No. (Insured):	XD9590Z	Policy No. (Claimant):	
		Excess:	S\$0.00
Repairer:	Ah Koon Motor (1960) Pte Ltd (HQ) BLK 1001 BUKIT MERAH LANE 3, #01-69, 159718 Bukit Merah - Tel: 62707113		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Ong Chin Kiat]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 28/03/2019]		

ASSOCIATED MAIL RECEIVED

View All

Compose Case Mail

There are no mail for this case.



ALL ASSOCIATED TASKS

View All

Search Tasks

Create New Task

Complete

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

P: Anthony
T: 5.37pm
V: in
E: ✓

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	9727G
Vehicle Details	
Vehicle No.:	SJD1780K
Vehicle to be Exported:	No
Intended Deregistration Date:	20 Mar 2019
Vehicle Make:	TOYOTA
Vehicle Model:	COROLLA AXIO 1.5X A
Primary Colour:	Gold
Manufacturing Year:	2007
Engine No.:	1NZC805663
Chassis No.:	NZE1416057433
Maximum Power Output:	81.0 kW (108 bhp)
Open Market Value:	\$11,394.00
Original Registration Date:	12 Mar 2008
First Registration Date:	12 Mar 2008
Transfer Count:	1
Actual ARF Paid:	\$11,394.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	28 Feb 2023
COE Category:	A - Car (1600cc & below)
COE Period(Years):	5
PQP Paid:	\$21,061.00
COE Rebate Amount:	\$16,598.00
Total Rebate Amount:	\$16,598.00
Message	
Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 20 Mar 2019

OK

28,000
16,598
11,402

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S1449727G



VEMALATHVEI D/O
ARANASALAM

அ. வீமலாதேவி

SRI LANKAN

Date of Birth: 17-11-1940 Sex: F

PERAK

0892860



Identity No: S1449727G

Blood Group: O+ Date of Issue: 14-04-1993

50A FABER HEIGHTS #01-02
SINGAPORE 129195

NRIC No: S1449727G

Date: 11-05-2002 (R)

No: 1298153



Licence Number: S 1449727 G

NAME
VEMALATHVEI D/O
ARANASALAM

Exp. Date: 17 Nov 1940

Issue Date: 12 Jun 2004



YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASSES:

Class 3 Motor Cars of unladen weight not exceeding 2500 kg, with not more than 7 passengers, exclusive of the driver; and Motor Tractors and other Motor Vehicles of unladen weight not exceeding 2500 kg

PASS DATE

23 May 1969

NP 426A



Certificate of Insurance

MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189)
MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) RULES, 1960
ROAD TRANSPORT ACT, 1987 (MALAYSIA)
MOTOR VEHICLES (THIRD PARTY RISKS) RULES, 1959 (MALAYSIA)

Certificate Number: 5070104410-04

Cover : drive CLASSIC

1. Index mark and Registration Number of Vehicle : **SJD1780K**
Chassis Number : **NZE1416057433**
2. Name of Policyholder : **VEMALATHVEI D/O ARANASALAM**
3. Effective Date of Insurance : **12 Mar 2019**
4. Expiry Date of Insurance : **11 Mar 2020**
5. Persons or Classes of Persons entitled to drive#
(a) The Policyholder.
(b) Any other person who is driving on the Policyholder's order or with his/her permission.
Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.
6. Limitations as to Use#
(a) Use for social domestic and pleasure purposes and in connection with the Policyholder's business or profession.

This Policy does not cover

- (a) Use for hire or reward.
- (b) Use for racing, pace-making, reliability trial or speed-testing.
- (c) Use for the carriage of goods (other than samples) in connection with any trade or business.
- (d) Use for any purpose in connection with the Motor Trade.

Limitations rendered inoperative by Section 8 of the Motor Vehicle (Third Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS (SECTION 1)	: S\$600
EXCESS (SECTION 2)	: N/A
WINDSCREEN EXCESS	: S\$100
ADDITIONAL EXCESS	: N/A
UNNAMED DRIVER EXCESS	: PLEASE REFER OVERLEAF
REPAIR AT OWNER'S PREFERRED WORKSHOP	: NO
INSURE WITH COE	: YES
NCD PROTECTION	: YES (FREE)
TRANSPORT ALLOWANCE	: NO
EXCESS WAIVER	: NO
PRIMARY DRIVER	: VEMALATHVEI D/O ARANASALAM
NAMED DRIVER (1)	: N/A
NAMED DRIVER (2)	: N/A
HIRE PURCHASE COMPANY	: N/A
SUM INSURED	: MARKET VALUE OF INSURED VEHICLE AT TIME OF LOSS

I/We hereby Certify that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia)

Agency : LQ INSURANCE AGENCY PTE LTD (00000613125)
Date of Issue : 19 Feb 2019 17:01 hrs
Reprint : 19 Feb 2019 17:01 hrs



For NTUC INCOME INSURANCE CO-OPERATIVE LIMITED



Countersigned By:

Authorised Officer



Chief Executive

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 14/03/2019 15:56
 Date Of Accident 13/03/2019 17:55
 Exact Location Of Accident ALONG BRADDELL ROAD TOWARDS LORNIE HIGHWAY
 Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number SJD1780K

Insured/Policyholder

Name Of Registered Owner VEMALATHVEI D/O ARANASALAM
 NRIC No S1449727G
 Email Address VEMALAARANASALAM@GMAIL.COM
 Mobile Phone No (LOCAL) +65-98323917
 Alternative Phone No OTHERS-98323917

Vehicle Particulars

Manufacturer TOYOTA
 Model COROLLA AXIO-1.5 X (A)
 Exact Purpose for which vehicle was being used at time of accident GOING HOME

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company NTUC INCOME INSURANCE CO-OPERATIVE LTD
 Type Of Coverage COMPREHENSIVE
 Fleet Policy NO
 Policy Number 5070104410-04
 Cover Note Number

Driver

Name of Driver VEMALATHVEI D/O ARANASALAM
 NRIC No S1449727G
 Date Of Birth 17/11/1940
 Occupation INDOOR
 Date Of Driving Pass 23/05/1969
 Driving Experience 49 YEARS AND 9 MONTHS
 Gender FEMALE
 Mobile Number (LOCAL) +65-98323917
 Fax Number
 Contact Number OTHERS-98323917
 EMail Address VEMALAARANASALAM@GMAIL.COM

Address	50A FABER HEIGHTS #1-02
Postcode	129195
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	- - -
Insurance Company of Driver's Own Vehicle	- - -

General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : HUSBAND GENDER: : MALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE REFER TO SKETCH PLAN

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	XD9590Z
Vehicle Make/Model/Colour	TRUCK
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

No. Of Passenger (Including Driver)

2

Passenger 1

NAME:

GENDER:

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Yam Kah 14/3/2019

Policyholder's Signature

Date & Time: 12:25 pm

Yam Kah

Driver's Signature

(If driver is not the policyholder)

Date & Time:

grr 14/03/2019

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

Rishi

SKETCH PLAN

A) SJD 1780K

B) XD 9590Z

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was driving my car, SJD 1780K, along Braddell Road towards Horne Road (to go home) on 13/3/2019 at about 1755 hrs.

I was on the 3rd lane of Braddell Road when suddenly, a big truck XD 9590Z (Kaszen Pte Ltd) hit onto the rear right fender and rear bumper of my car.

He pulled over to the side of the road just before exit to Teo Puah Lor 6 (at the bus stop). I asked for his personal particulars but he refused to give them to me.

I am filing a third party claim against his company truck insurance company.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Vimala 14/3/2019

Policyholder's Signature

Date & Time: 12:38 pm

Vimala

Driver's Signature

(If driver is not the policyholder)

Date & Time:

14/03/2019

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

Pandi Karthi






































...CLAIM SUBFOLDER...(Pending for Survey Report)












CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	19 Mar 2019		19 Mar 2019 15:28 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	KASZON PTE LTD , Co. Reg. No.: 200007153D								
Main Claimant:	VEMALATHVEI D/O ARANASALAM , ID: S1449727G								
Vehicle Reg. No.:	SJD1780K	Date of Loss:	13/03/2019 17:00 - :59 [132 Months and 1 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / SNM19D201224C02	Policy/Cover Note No.:	DMCVSN16702318022 (Comprehensive) Coverage: 15/10/2018 - 14/10/2019						
Vehicle Reg. No. (Insured):	XD9590Z	Policy No. (Claimant):							
		Excess:	S\$0.00						
Repairer:	Ah Koon Motor (1960) Pte Ltd (HQ) BLK 1001 BUKIT MERAH LANE 3, #01-69, 159718 Bukit Merah - Tel: 62707113								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Ong Chin Kiat]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 28/03/2019]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SJD1780K (SNM19D201224C02)
[XD9590Z]
TP
VEMALATHVEI D/O ARANASALAM
Mar 13 2019 5:00PM
[KASZON PTE LTD]
Ah Koon Motor (1960) Pte Ltd

Upload Documents			Upload Photos		Compose New Letter		View		View in Browser		
Photos/Images							3 per page		<input checked="" type="checkbox"/>		
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print						
1	15/05/19 16:13	General View		Load JPG	<input checked="" type="checkbox"/>						
2	15/05/19 16:13	General View		Load JPG	<input checked="" type="checkbox"/>						
3	15/05/19 16:13	General View		Load JPG	<input checked="" type="checkbox"/>						
4	15/05/19 16:13	General View		Load JPG	<input checked="" type="checkbox"/>						
5	15/05/19 16:13	General View		Load JPG	<input checked="" type="checkbox"/>						
6	15/05/19 16:13	General View		Load JPG	<input checked="" type="checkbox"/>						
7	15/05/19 16:13	General View		Load JPG	<input checked="" type="checkbox"/>						
8	15/05/19 16:13	General View		Load JPG	<input checked="" type="checkbox"/>						
9	15/05/19 16:13	General View		Load JPG	<input checked="" type="checkbox"/>						
10	15/05/19 16:13	General View		Load JPG	<input checked="" type="checkbox"/>						
11	15/05/19 16:13	General View		Load JPG	<input checked="" type="checkbox"/>						
12	15/05/19 16:13	General View		Load JPG	<input checked="" type="checkbox"/>						
13	15/05/19 16:13	General View		Load JPG	<input checked="" type="checkbox"/>						
14	15/05/19 16:13	General View		Load JPG	<input checked="" type="checkbox"/>						
15	15/05/19 16:13	General View		Load JPG	<input checked="" type="checkbox"/>						
16	15/05/19 16:13	General View		Load JPG	<input checked="" type="checkbox"/>						
17	15/05/19 16:13	General View		Load JPG	<input checked="" type="checkbox"/>						
18	15/05/19 16:13	General View		Load JPG	<input checked="" type="checkbox"/>						
19	15/05/19 16:13	General View		Load JPG	<input checked="" type="checkbox"/>						
20	15/05/19 16:13	General View		Load JPG	<input checked="" type="checkbox"/>						
21	15/05/19 16:19	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>						
22	15/05/19 16:19	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>						
23	15/05/19 16:19	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>						
24	15/05/19 16:19	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>						
25	15/05/19 16:19	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>						
26	15/05/19 16:19	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>						
27	15/05/19 16:19	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>						
28	15/05/19 16:19	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>						
29	15/05/19 16:19	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>						
30	15/05/19 16:19	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>						
31	15/05/19 16:19	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>						
32	15/05/19 16:20	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>						
33	15/05/19 16:20	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>						
34	15/05/19 16:20	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>						
35	15/05/19 16:20	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>						
36	15/05/19 16:20	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>						
37	15/05/19 16:20	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>						

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	15/05/19 16:20	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
39	15/05/19 16:20	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
40	15/05/19 16:20	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
41	15/05/19 16:20	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
42	15/05/19 16:20	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
43	15/05/19 16:20	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
44	15/05/19 16:20	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
45	15/05/19 16:20	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
46	15/05/19 16:20	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	19/03/19 15:27	PRS EMAIL	 Load PDF	
2	19/03/19 15:27	TP SJD1780K GIA REPORT	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>				
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>				

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/CTI19004987/R1CD3E2

Date: 15/05/2019

REFERENCE

Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMCVSN16702318022

Claimant Vehicle
No : SJD1780KInsured Vehicle
No : XD9590Z

Date of Loss: 13/03/2019

Nature of Claim: TP

Claim
No: SNM19D201224C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SJD1780K

Make & Model: TOYOTA COROLLA, 1.5 X AXIO (A)

Engine No: 1NZC805663

Reg. Date: 12/03/2008 (Man. Year: 2007)

Chassis No: NZE1416057433

Colour: Gold

Odometer: 161802 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/60 R15	Rear Tyre Size:	195/60 R15
Front Left Side:	Falken 5 mm	Rear Left Side:	Falken 5 mm
Front Right Side:	Falken 5 mm	Rear Right Side:	Falken 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 19/03/2019

Date Inspected: 20/03/2019 Inspected At:

Ah Koon Motor (1960) Pte Ltd (HQ)
BLK 1001 BUKIT MERAH LANE 3, #01-69
Singapore 159718

Estimated Period of Repair: 5.0 days

Adjuster: MOHD RASUL

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$4,000.00 - \$5,000.00

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 15 May 2019)
Parts:	143	TOYOTA COROLLA 1.5 X AXIO (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJD1780K)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >