



Your Ref: AEMD/105/009/2018/156

Date: 22<sup>nd</sup> March 2019

Our Ref: CS1/SPF19005000/K1qd3s2

**M/s Automotive Engineering & MGT Division**  
Accident Claim Section (Singapore Police Force)  
1 Mount Pleasant Road  
Blk 8 Old Police Academy  
Singapore 298333

Attn: Hafizul Farhan

Dear Sir / Madam,

**EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: SHC 6824P  
INSURED VEHICLE: TP 67L ACCIDENT DATE: 04/11/2018**

We thank you for your instruction on 19/03/2019.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SHC 6824P from M/s KM Auto Assessors Pte. Ltd.
- b) Final Repair Bill of SHC 6824P from M/s Premier Automotive Services Pte Ltd.
- c) Singapore Accident Statement of Vehicles SHC 6824P.
- d) Colour damaged vehicle photographs of SHC 6824P.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number	: SHC 6824P
Make & Model	: Kia Optima 1.7 Taxi Auto
Year of Registration	: 2015
Chassis Number	: KNAGM414MF5593816
Engine Capacity	: 1685 cc
2. We recommend that the repairs of the entire damage require about 5 (Five) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.