

2/10/2019

ASS. REC. BY:

REF: CS/CTI 19005002/JS d3ⁿ²

Special Instruction:

Surveyor: Hwee Jie

ASSIGNMENT (Office)

From (Person): Ong chin Kiat

of CTI

Date/Time: 19.3.2019 17.15p.m

Estimated Cost:

Bill to:

OD / IT / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLB 253J

Insured: GBB 4842B

at Workshop n/a: Toh Ah Swee Spray Painting Co.

Tel: 6366 0115 / 6366 ~~0286~~ 0286

at BLK 2 Kranji Loop, # 01-02

Policy No: DMCVSN 12074818000

Claim No: SNM19D 201232C02

Sum Insured:

Excess:

Make of Vch:
(Client's Record)

D.O.A. 9.3.2019

CA / REV / REP. / REV 24 HRS

"wp"

Sally

21/3/19 @ 10-12am

Date/Time: 20.3.19 9.25am

Person Contacted:

Eileen

H.O.D. Endorsement:

Vehicle: JBL / OUTD

Date/Time	Action/Instruction (✓) Estimate
	SLB 253J - X
	GBB 4842B - CS / TP 15019289 / 09km2
	D.O.A. - 11/11/2015
05/07/19	@ 16:13 pm checked with Sally (repairer), vehicle has not out in for repair

08/07/19

REF:

CTI

Surveyor Hwee Jie

ASSIGNMENT

From: _____ Date: 21/3/19

Estimated Cost: _____

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLB 253J

at Workshop m/s Toh Ah Swee

of BLK 2 Krunji loop #01-02

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: 10am-12pm

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS 1 up

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SLB 253J Yr Regn: 24 mar 2016

Type: ☒ M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota wlsb C.C. 1797

Colour: white A/C: Insured / Std / NI / NA

Sp. Reading: 21897 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: ZGE 20602710

Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ Inorder / Jammed / Leaked / Burnt orBrake: ☒ Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/55 R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA ☒ MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. 9/3/19 D.O.I. 21/3/19

Survey held at Toh ah Swee

Des. of Damages: Frt / Rear / ☒ N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

RECEIVED 08 JUL 2019

Date/Time, File Pass to?

08/07/19

1) Type: SP

Date/Time, File Return to?

2)

☒ : Preli. Report☐ : Final Report

Days Of Repair: 2

Resurvey No. of Trip: 1

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

Report Format: Preli

Lump Sum / I.B.I. (\$))

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

220

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	19 Mar 2019		19 Mar 2019 17:15 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS				[Created by insurer]					
Insured:	SWIFFOX PTE LTD, Co. Reg. No.: 201728360R								
Main Claimant:	LOH CHEE KHIANG STEVEN, ID: S7419335H								
Vehicle Reg. No.:	SLB253J	Date of Loss:	09/03/2019 14:00 - :59 [35 Months and 13 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / SNM19D201232C02	Policy/Cover Note No.:	DMCVSN18074818000 (Comprehensive) Coverage: 06/03/2018 - 03/05/2019						
Vehicle Reg. No. (Insured):	GBB4842B	Policy No. (Claimant):							
		Excess:	S\$0.00						
Repairer:	Toh Ah Swee Spray Painting Co. (HQ) Blk 2 Kranji Loop, #01-02, 739538 Kranji - Tel: 63660115, 63660286								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Ong Chin Kiat]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 28/03/2019]								
ASSOCIATED MAIL RECEIVED				View All Compose Case Mail					
There are no mail for this case.									
<input type="checkbox"/> ALL ASSOCIATED TASKS									
View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	9335H
Vehicle Details	
Vehicle No.:	SLB253J
Vehicle to be Exported:	No
Intended Deregistration Date:	22 Mar 2019
Vehicle Make:	TOYOTA
Vehicle Model:	WISH 1.8X A
Primary Colour:	White
Manufacturing Year:	2015
Engine No.:	2ZR1681061
Chassis No.:	ZGE206027710
Maximum Power Output:	105.0 kW (140 bhp)
Open Market Value:	\$18,268.00
Original Registration Date:	24 Mar 2016
First Registration Date:	24 Mar 2016
Transfer Count:	0
Actual ARF Paid:	\$18,268.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	23 Mar 2026
PARF Rebate Amount:	\$13,701.00
Intended COE Rebate Details	
COE Expiry Date:	23 Mar 2026
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$46,502.00
COE Rebate Amount:	\$32,563.00
Total Rebate Amount:	\$46,264.00

The information contained herein is correct as at 22 Mar 2019

OK

Enquire Transfer Fee

Enquire Transfer Fee

Vehicle Details			
Vehicle No. :	SLB253J		
Vehicle Type :	P11 - Passenger Station Wagon/Jeep/Land Rover		
Vehicle Attachment 1 :	No Attachment		
Vehicle Scheme :	Normal		
Vehicle Make :	TOYOTA		
Vehicle Model :	WISH 1.8X A		
Chassis No. :	ZGE206027710		
Propellant :	Petrol		
Engine No. :	2ZR1681061		
Engine Capacity :	1797 cc		
Maximum Power Output :	105.0 kW (140 bhp)		
Maximum Laden Weight :	1735 kg		
Unladen Weight :	1350 kg		
Year Of Manufacture :	2015		
Original Registration Date :	24 Mar 2016		
Lifespan Expiry Date :	-		
COE Category :	B - Car above 1600cc or 97kW (130bhp)		
Quota Premium :	\$46,502.00		
COE Expiry Date :	23 Mar 2026		
Road Tax Expiry Date :	23 Mar 2019		
PARF Eligibility Expiry Date :	23 Mar 2026		
Inspection Due Date :	23 Mar 2019		
Intended Transfer Date :	15 Mar 2019		
CO2 Emission :	159.00 (g/km)		
CEV/VES Rebate Utilised Amount :	-		
CO Emission :	-		
HC Emission :	-		
NOx Emission :	-		
PM Emission :	-		
The current road tax expiry is 23 Mar 2019. You may renew the road tax from 24 Dec 2018 with all pre-requisite(s) fulfilled. If the road tax is renewed after 23 Mar 2019, late renewal fee(s) will be imposed. Please use Enquire Road Tax Payable to check on the late fee(s) payable.			
Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.			
Amount Payable (From 24 Mar 2019 to 23 Sep 2019)			
	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee :	25.00	-	25.00
Sub Total :			25.00
Nett Road Tax Amount (After Offsetting Over Payment) :	487.00	-	487.00
Total Amount Payable :			512.00
Amount Payable (From 24 Mar 2019 to 23 Mar 2020)			
	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee :	25.00	-	25.00
Sub Total :			25.00
Nett Road Tax Amount (After Offsetting Over Payment) :	974.00	-	974.00
Total Amount Payable :			999.00

You may print this page for reference.

OK

Print

卓亚水喷漆公司
TOH AH SWEE SPRAY PAINTING CO.

BLK 2, KRANJI LOOP #01-02 (OFF KRANJI ROAD), SINGAPORE 739538.

TEL: 63660115 (WORKSHOP), 63660286 (OFFICE) FAX: 63685943

EMAIL: claims@tohahswee.com.sg

BUSINESS REG. NO: 09935300L

GST REG. NO: 09-935300-L

15/03/2019

CHINA TAIPING INSURANCE COMPANY LIMITED

3 ANSON ROAD

#16-00 SPRINGLEAF TOWER

SINGAPORE 079909

ATTN: MOTOR CLAIMS DEPT

ESTIMATED REPAIR BILL

YOUR REF : GBB4842B
TYPE OF CLAIM : THIRD PARTY CLAIMS
CLAIMANT : LOH CHEE KHIANG STEVEN
VEHICLE NO. : SLB253J
MAKE/ MODEL : **TOYOTA WISH 1.8**
ACCIDENT DATE : 09/03/2019

MATERIAL COST

IPC SIDE MIRROR SIGNAL LAMP	SCR ✓	\$	125.00
LESS : DISCOUNT 25%		\$	31.25
		\$	93.75

LABOUR CHARGE :

TO REMOVE DAMAGED PARTS, TO KNOCK OUT DENTS, TO STRAIGHTEN, ADJUST, CHECK, RESHAPE INCLUDING CUTTING AND WELDING WHERE NECESSARY, TO REMOVE AND REINSTALL NECESSARY FITTINGS TO FACILITATE REPAIRS, TO REPLACE AND ALIGN THE ABOVE PARTS,

\$ 100.00 ✓

PUTTY AND SPRAY PAINTING ON ABOVE NEW AND REPAIRED PARTS INCLUDING SUPPLY OF PAINT MATERIALS

\$ 150.00 ✓

COATING (PAINT PROTECTION)

\$ 280.00 ?

\$ 623.75

\$ 43.66

\$ 667.41

ADD : GST 7%

TOTAL :

SINGAPORE DOLLARS : SIX HUNDRED SIXTY SEVEN AND CENTS FORTY ONE ONLY.

NOTE: THE ESTIMATED PERIOD OF REPAIRS IS THREE (3) DAYS

TOH AH SWEE SPRAY PAINTING CO.

SALLY ANG

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Page 1

Handwritten notes:
26/3/19
Hwee Jia - LKK
21/3/19
P/P 2 days.
[Signature]

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT119005002/JSD3N2

Date: 12/07/2019

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSN18074818000	
Claimant Vehicle No :	SLB253J	Insured Vehicle No :	GBB4842B	
Date of Loss:	09/03/2019	Nature of Claim:	TP	Claim No: SNM19D201232C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLB253J	Engine No:	2ZR1681061
Make & Model:	TOYOTA WISH, 1.8 X (A)	Chassis No:	ZGE206027710
Reg. Date:	24/03/2016 (Man. Year: 2015)	Odometer:	21897 km
Colour:	White		
Engine Capacity:	1797 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55R16	Rear Tyre Size:	205/55R16
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	93.75	93.75	0.00	0.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	530.00	250.00	280.00	52.83
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	623.75	343.75	280.00	44.89
+ GST 7.00/7.00% (\$\$)	43.66	24.06	19.60	44.89
Nett Amount (\$\$)	667.41	367.81	299.60	44.89

INSPECTION

Date of Assignment:	19/03/2019	
Date Inspected:	21/03/2019	Inspected At:
		BLK 2, KRANJI LOOP OFF KRANJI ROAD #01-02 SINGAPORE 739538 REPAIRER: TOH AH SWEE SPRAY PAINTING CO.
Estimated Period of Repair:	2.0 days	

Adjuster: ONG HWEE JIE

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

THE VEHICLE HAS NOT SEND IN FOR REPAIRS.

(REPAIR COST NOT CONCLUDE)

(EXCLUDE CHECK ITEMS S\$280.00 NETT)

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 12 Jul 2019)
Parts:	M1-MPV	TOYOTA WISH 1.8 X (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLB253J)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SIDE MIRROR SIGNAL LAMP	Scratched	125.00 FL	*125.00 FL
				Sub Total (\$\$)	125.00	125.00
				- List Item Discount on L Items 25.00/25.00% (\$\$)	31.25	31.25
				Total Parts (\$\$)	93.75	93.75

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE DAMAGED PARTS,TO KNOCK OUT DENTS,TO STRAIGHTEN.AJUST,CHECK,RESHAPE INCLUDING CUTTING AND WELDING WHERE NECESSARY.TO REMOVE AND REINSTALL NECESSARY FITTINGS TO FACILITATE REPAIRS.TO REPLACE AND ALIGN THE ABOVE PARTS	New	100.00	100.00
2	PUTTY AND SPRAY PAINTING ON ABOVE NEW AND REPAIRED PARTS INCLUDING SUPPLY OF PAINT MATERIALS	New	150.00	150.00
3	COATING (PAINT PROTECTION) (*CHECK)	New	280.00	0.00
Gross Labour Cost (\$\$)			530.00	250.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >