

ASS. REC. BY:

REF: CS3/MXG 1900 S007/ Gcd352 Special Instruction.

SUNWAY G.A.

ASSIGNMENT (Office)

From (Person): Jowyn Tay Mui Ling of MSI A

Date/Time: 19.3.19 18:16 p.m.

Estimated Cost: Bill to:

OD / TP WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No. SLE 3941X

Insured: SDV 5331 D

at Workshop m/s Hiap Lek Automobile Trading

of 160 Sin Ming Drive # 05-17

Tel:

Policy No. 29092678 & MX

Claim No:

Sum Insured:

Excess:

Make of Vch:

(Client's Record)

D.O.A. 17.3.19

CA / REV / REP. / REV 24 HRS

"W"

Date/Time: 20.3.19

Person Contacted: Mr Wong

H.O.D. Endorsement:

Vehicle (IN) OUT

Date/Time	Action/Instruction (X) Estimate
	SLE 3941X - X
	SDV 5331 D - X
	After repair: 27/3/2019
	Dismantle: 21/3/2019

Surveys

PRS
602

REF:

MSG

3959E

(-2026)

ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No:

Claims No:


Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 5 days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SLE3941X Yr Regn: 20 Jul 2016

Type: M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda Vezel C.C. 1496

Colour: white A/C: Insured / Std / NI / NA

Sp. Reading: 89403 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: RU11117530

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / SiRim / STD A/Rim or

Tyre Size: F: 215/60 R16

R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front Rear

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. D.O.I. 20-03-19

Survey held at w/s 1 pm

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	\$ 3000 - \$ 4000

Date/Time, File Pass to?

☐ : Preli. Report
☐ : Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair: 5

Resurvey No. of Trip: 2

Survey Fee:

Transportation:

\$ + RS, \$

Photos

Others

TOTAL

Report Format: PRS

Lump Sum / I.B.I: (\$)

Add Fee: ☐ : Site Insp (\$)

☐ : Interview (\$)

☐ : Tech. Invs (\$)

☐ : Weekend (\$)

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	18 Mar 2019		19 Mar 2019 18:16 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	PHUA YEN PENG, ID: S1595292Z, Tel: +6598255318, Email: NGJENNIFER25@GMAIL.COM								
Main Claimant:	LAU KOK KEONG (LIU GUOQIANG), ID: S7813959E								
Vehicle Reg. No.:	SLE3941X	Date of Loss:	17/03/2019 10:00 - :59 [31 Months and 25 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP	Policy/Cover Note No.:	29092678QMX (Comprehensive) Coverage: 22/08/2018 - 21/08/2019						
Vehicle Reg. No. (Insured):	SDU5331D	Policy No. (Claimant):							
		Excess:	S\$700.00						
Repairer:	Hiap Lek Automobile Trading (HQ) 160 Sin Ming Drive, #05-17 Sin Ming Autocity, 575722 Sin Ming - Tel: 64531743								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Jowyn Tay Mei Ling - 6643 1307]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 20/03/2019]								
Driver/Custodian (Insured):	PHUA YEN PENG (55 / Male) , NRIC: S1595292Z, Tel: +6598255318 Email: NGJENNIFER25@GMAIL.COM								
Adj Asg. Remarks:	SJE : DISAGREED / LIABILITY 100%. On WP. Please contact us if can't attend. Kindly contact MR HAN WEI @ 9660 1347 to arrange for survey								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GiA Records Management Centre established by the General Insurance Association of Singapore (GiA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	18/03/2019 14:57
Date Of Accident	17/03/2019 10:20
Exact Location Of Accident	JALAN MEMBINA
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLE3941X
Insured/Policyholder	
Name Of Registered Owner	LAU KOK KEONG (LIU GUOQIANG)
NRIC No	S7813959E
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-98712354
Alternative Phone No	OFFICE-98712354

Vehicle Particulars

Manufacturer	HONDA
Model	VEZEL
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5098684135-01
Cover Note Number	

Driver

Name of Driver	LAU KOK KEONG (LIU GUOQIANG)
NRIC No	S7813959E
Date Of Birth	23/05/1978
Occupation	OUTDOOR
Date Of Driving Pass	14/11/2008
Driving Experience	10 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98712354
Fax Number	
Contact Number	OFFICE-98712354
Email Address	NOEMAIL

Address	BLK 128 #15-119 KIM TIAN ROAD
Postcode	160128
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : WIFE GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	THOMSON NEIGHBOURHOOD POLICE POST
Police Station Address	ROAD: BLK 25 SIN MING ROAD , POSTCODE: 570025 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-4529999 - FAX NO: 6 5535740
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER POLICE REPORT (ATTENDED BY: JAMES NG)

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SDU5331D
Vehicle Make/Model/Colour	TOYOTA
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	PHUA YEN PENG
NRIC/Passport Number	S1595292Z
Contact Number	98255318
Address	

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name	LAU KOK KEONG (LIU GUOQIANG)
Approximate Age	40
Injuries Sustain	PAIN IN NECK, SHOULDER AND BACK
Injured person in which vehicle?	SLE3941X
Were seat belts worn?	
Was this injured conveyed to hospital by ambulance?	NO
Address	BLK 128 #15-119 KIM TIAN ROAD
Postcode	160128

DETAILS OF INJURED PERSON 2

Name	YICK KIT NGOH
Approximate Age	40
Injuries Sustain	PAIN IN NECK, SHOULDER AND BACK
Injured person in which vehicle?	SLE3941X
Were seat belts worn?	
Was this injured conveyed to hospital by ambulance?	NO
Address	BLK 128 #15-119 KIM TIAN ROAD
Postcode	160128

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

18 MAR 2019

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name: NG WING KIN JAMES
NRIC/FIN No.: S7927881E



SKETCH PLAN

(A) SLK 3941X

⑦ Say 5331 p.

-Jalan membina

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

AS per police report

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature _____

Date & Time:

18 MAR 2019

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN NO.:

NG WING KIN JAMES

S7927881E





**SINGAPORE
POLICE FORCE**



T/20190318/2070

1 of 4

Police Station Of Origin:
Thomson NPP
25 Sin Ming Road #01-180 SINGAPORE
570025
Tel No: 1800-4529999

Report No. T/20190318/2070

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 18/03/2019 12:43	Vide Report No.:	Station Diary No.: 16
--	------------------	--------------------------

Informant's Particulars

Name of Informant: LAU KOK KEONG			Address: APT BLK 128 KIM TIAN ROAD #15-119 SINGAPORE 160128		
ID Type / ID No.: NRIC NO / S7813959E			Contact No.: Home/Office: Mobile: 98712354		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 40	Date of Birth: 23/05/1978	Type of Informant: Driver		
Race: Chinese			Language:		Institution / School Name:
Occupation: GRAB DRIVER			Driving Licence Information: Class: 3 Date of Expiry:		

General Information of the Accident

Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 17/03/2019 10:20	Type of Location: T-Junction
Location: Along Road 1 Traveling Toward Road 2 JALAN MEMBINA KIM TIAN ROAD Along Jalan Membina towards Kim Tian Road opposite Blk 118 Jalan Membina.				
Weather: Sunny		Road Surface: Dry		Road Speed Limit:
Traffic Flow: Dual Carriage Way		Traffic Control: Not Controlled		Traffic Volume: Light
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SDU5331D	Car	TOYOTA	CAMRY 2.0 AUTO ABS AIRBAG	Black		1
SLE3941X	Car	HONDA	VEZEL 1.5X CVT	White		1

Details of Vehicle Insurance

Vehicle No.	Insurance Company	Insurance No.	Effective	Expiry Date
SLE3941X	NTUC Income Insurance Co-Operative Limited	5098684135-01	10/03/2019	19/01/2020



**SINGAPORE
POLICE FORCE**



T/20190318/2070

2 of 4

Police Station Of Origin:
Thomson NPP
25 Sin Ming Road #01-180 SINGAPORE
570025
Tel No: 1800-4529999

Report No. T/20190318/2070

CONTINUATION OF REPORT

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Driver			
Name	PHUA YEN PENG	ID No.	S1595292Z
Related Vehicle	SDU5331D (Car)	Contact No.	98255318
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Driver			
Name	LAU KOK KEONG	ID No.	S7813959E
Related Vehicle	SLE3941X (Car)	Contact No.	98712354
Hospital/Clinic	SIN MIN CLINIC	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	18/03/2019	Date Discharge	18/03/2019
No. of Days granted Medical Leave	07	Degree of Injury	Slight
Passenger			
Name	YICK KIT NGOH	ID No.	S7930061F
Related Vehicle	SLE3941X (Car)	Contact No.	97439354
Hospital/Clinic	SIN MIN CLINIC	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	18/03/2019	Date Discharge	18/03/2019
No. of Days granted Medical Leave	07	Degree of Injury	Slight

Brief Details.

On 17/03/2019 at about 1019hrs, I was driving my car bearing SLE3941X along Jalan Membina towards Kim Tian Road. I was travelling along a one lane road. As I was approaching the T-Junction before Kim Tian Road, I wanted to turn right into Blk 118 Jalan Membina. As such, I slowed down and signalled right. I then stopped at the junction to check on the oncoming traffic before making the right turn.

All of a sudden, I felt an impact coming from the rear of my car. I alighted from my car and discovered that a car bearing SDU5331D had collided into the rear of my car. The driver claimed that he was distracted and did not notice my car. Thus, he collided into my car. We then exchanged particulars and at



**SINGAPORE
POLICE FORCE**



T/20190318/2070

Police Station Of Origin:
Thomson NPP
25 Sin Ming Road #01-180 SINGAPORE
570025
Tel No: 1800-4529999

3 of 4

Report No. T/20190318/2070

CONTINUATION OF REPORT

that point of time nobody was injured. My wife was in my car as well.

Due to the accident the rear portion of my car were damaged. I have an in-built camera installed at the front and back of my car.

On 18/03/2019, my wife and I felt pain on our neck, shoulder and back area. We went to Sin Min Clinic and both of us were given 7 days of MC.



**SINGAPORE
POLICE FORCE**



T/20190318/2070

4 of 4

Report No. T/20190318/2070



Police Station Of Origin:
Thomson NPP
25 Sin Ming Road #01-180 SINGAPORE
570025
Tel No: 1800-4529999

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report: E / Sgt 2 MUHAMMAD ZULHILMI BIN ABU HASSAN	Signature Of Informant: 
Signature Of Interpreter: Not applicable	Date/Time: 18/03/2019 12:43
Officer In Charge Of Case: TP / AEIT / Sgt 2 SHARIFAH NOR FARIZAN BINTE SYED MOHD SAID Contact No.: 65476172	Classification Of Case: CN 070
Authentication Stamp NP168	 SIGNATURE

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	3959E
Vehicle Details	
Vehicle No.:	SLE3941X
Vehicle to be Exported:	No
Intended Deregistration Date:	21 Mar 2019
Vehicle Make:	HONDA
Vehicle Model:	VEZEL 1.5X CVT
Primary Colour:	White
Manufacturing Year:	2016
Engine No.:	L15B4037537
Chassis No.:	RU11117530
Maximum Power Output:	96.0 kW (128 bhp)
Open Market Value:	\$20,662.00
Original Registration Date:	20 Jul 2016
First Registration Date:	20 Jul 2016
Transfer Count:	2
Actual ARF Paid:	\$10,927.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	19 Jul 2026
PARF Rebate Amount:	\$8,195.00
Intended COE Rebate Details	
COE Expiry Date:	19 Jul 2026
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$55,200.00
COE Rebate Amount:	\$40,439.00
Total Rebate Amount:	\$48,634.00

The information contained herein is correct as at 21 Mar 2019

OK

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	18 Mar 2019		19 Mar 2019 18:16 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	PHUA YEN PENG, ID: S1595292Z, Tel: +6598255318, Email: NGJENNIFER25@GMAIL.COM		
Main Claimant:	LAU KOK KEONG (LIU GUOQIANG), ID: S7813959E		
Vehicle Reg. No.:	SLE3941X	Date of Loss:	17/03/2019 10:00 - :59 [31 Months and 25 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 588025	Policy/Cover Note No.:	29092678 (Comprehensive) Coverage: 22/08/2018 - 21/08/2019
Vehicle Reg. No. (Insured):	SDU5331D	Policy No. (Claimant):	
		Excess:	S\$700.00
Repairer:	Hiap Lek Automobile Trading (HQ) 160 Sin Ming Drive, #05-17 Sin Ming Autocity, 575722 Sin Ming - Tel: 64531743		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Jowyn Tay Mei Ling - 6643 1307]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Imm.Advice due 20/03/2019]		
Driver/Custodian (Insured):	PHUA YEN PENG (55 / Male), NRIC: S1595292Z, Tel: +6598255318 Email: NGJENNIFER25@GMAIL.COM		
Adj Asg. Remarks:	SJE : DISAGREED / LIABILITY 100%. On WP. Please contact us if can't attend. Kindly contact MR HAN WEI @ 9660 1347 to arrange for survey		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLE3941X (588025)

[SDU5331D]























TP

LAU KOK KEONG (LIU GUOQIANG)

Mar 17 2019 10:00AM

[PHUA YEN PENG]

Hiap Lek Automobile Trading

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	25/03/19 15:24	General View	 Load JPG	<input checked="" type="checkbox"/>
2	25/03/19 15:24	General View	 Load JPG	<input checked="" type="checkbox"/>
3	25/03/19 15:24	General View	 Load JPG	<input checked="" type="checkbox"/>
4	25/03/19 15:24	General View	 Load JPG	<input checked="" type="checkbox"/>
5	25/03/19 15:24	General View	 Load JPG	<input checked="" type="checkbox"/>
6	25/03/19 15:24	General View	 Load JPG	<input checked="" type="checkbox"/>
7	25/03/19 15:24	General View	 Load JPG	<input checked="" type="checkbox"/>
8	25/03/19 15:24	General View	 Load JPG	<input checked="" type="checkbox"/>
9	25/03/19 15:24	General View	 Load JPG	<input checked="" type="checkbox"/>
10	25/03/19 15:24	General View	 Load JPG	<input checked="" type="checkbox"/>
11	25/03/19 15:24	General View	 Load JPG	<input checked="" type="checkbox"/>
12	25/03/19 15:24	General View	 Load JPG	<input checked="" type="checkbox"/>
13	25/03/19 15:24	General View	 Load JPG	<input checked="" type="checkbox"/>
14	25/03/19 15:24	General View	 Load JPG	<input checked="" type="checkbox"/>
15	25/03/19 15:24	General View	 Load JPG	<input checked="" type="checkbox"/>
16	25/03/19 15:24	General View	 Load JPG	<input checked="" type="checkbox"/>
17	25/03/19 15:24	General View	 Load JPG	<input checked="" type="checkbox"/>
18	25/03/19 15:24	General View	 Load JPG	<input checked="" type="checkbox"/>
19	25/03/19 15:24	General View	 Load JPG	<input checked="" type="checkbox"/>
20	25/03/19 15:24	General View	 Load JPG	<input checked="" type="checkbox"/>
21	25/03/19 15:24	General View	 Load JPG	<input checked="" type="checkbox"/>
22	25/03/19 15:24	General View	 Load JPG	<input checked="" type="checkbox"/>
23	25/03/19 15:24	General View	 Load JPG	<input checked="" type="checkbox"/>
24	25/03/19 15:24	General View	 Load JPG	<input checked="" type="checkbox"/>
25	25/03/19 15:24	General View	 Load JPG	<input checked="" type="checkbox"/>
26	25/03/19 15:24	General View	 Load JPG	<input checked="" type="checkbox"/>
27	25/03/19 15:24	General View	 Load JPG	<input checked="" type="checkbox"/>
28	25/03/19 15:24	General View	 Load JPG	<input checked="" type="checkbox"/>
29	25/03/19 15:24	General View	 Load JPG	<input checked="" type="checkbox"/>
30	25/03/19 15:24	General View	 Load JPG	<input checked="" type="checkbox"/>
31	25/03/19 15:24	General View	 Load JPG	<input checked="" type="checkbox"/>
32	25/03/19 15:24	General View	 Load JPG	<input checked="" type="checkbox"/>
33	25/03/19 15:24	General View	 Load JPG	<input checked="" type="checkbox"/>
34	02/04/19 11:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
35	02/04/19 11:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page ▼	✓
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
36	02/04/19 11:15	Photographs of Damaged Parts	 Load JPG	✓
37	02/04/19 11:15	Photographs of Damaged Parts	 Load JPG	✓
38	02/04/19 11:15	Photographs of Damaged Parts	 Load JPG	✓
39	02/04/19 11:15	Photographs of Damaged Parts	 Load JPG	✓
40	02/04/19 11:15	Photographs of Damaged Parts	 Load JPG	✓
41	02/04/19 11:15	Photographs of Damaged Parts	 Load JPG	✓
42	02/04/19 11:15	Photographs of Damaged Parts	 Load JPG	✓
43	02/04/19 11:15	Photographs of Damaged Parts	 Load JPG	✓
44	02/04/19 11:15	Photographs of Damaged Parts	 Load JPG	✓
45	02/04/19 11:15	Photographs of Damaged Parts	 Load JPG	✓
46	02/04/19 11:15	Photographs of Damaged Parts	 Load JPG	✓
47	02/04/19 11:15	Photographs of Damaged Parts	 Load JPG	✓
48	02/04/19 11:15	Photographs of Damaged Parts	 Load JPG	✓
49	02/04/19 11:15	Photographs of Damaged Parts	 Load JPG	✓
50	02/04/19 11:15	Photographs of Damaged Parts	 Load JPG	✓
51	02/04/19 11:15	Photographs of Damaged Parts	 Load JPG	✓
52	02/04/19 11:15	Photographs of Damaged Parts	 Load JPG	✓
53	02/04/19 11:15	Photographs of Damaged Parts	 Load JPG	✓
54	02/04/19 11:15	Photographs of Damaged Parts	 Load JPG	✓
55	02/04/19 11:15	Photographs of Damaged Parts	 Load JPG	✓
56	02/04/19 11:15	Photographs of Damaged Parts	 Load JPG	✓
57	02/04/19 11:15	Photographs of Damaged Parts	 Load JPG	✓
58	02/04/19 11:15	Photographs of Damaged Parts	 Load JPG	✓
59	02/04/19 11:15	Photographs of Damaged Parts	 Load JPG	✓
60	02/04/19 11:15	Photographs of Damaged Parts	 Load JPG	✓
61	02/04/19 11:15	Photographs of Damaged Parts	 Load JPG	✓
62	02/04/19 11:15	Photographs of Damaged Parts	 Load JPG	✓
63	02/04/19 11:15	Photographs of Damaged Parts	 Load JPG	✓
64	02/04/19 11:15	Photographs of Damaged Parts	 Load JPG	✓
65	02/04/19 11:15	Photographs of Damaged Parts	 Load JPG	✓
66	02/04/19 11:15	Photographs of Damaged Parts	 Load JPG	✓
67	02/04/19 11:15	Photographs of Damaged Parts	 Load JPG	✓
68	02/04/19 11:15	Photographs of Damaged Parts	 Load JPG	✓
69	02/04/19 11:15	Photographs of Damaged Parts	 Load JPG	✓
70	02/04/19 11:15	Photographs of Damaged Parts	 Load JPG	✓
71	02/04/19 11:15	Photographs of Damaged Parts	 Load JPG	✓
72	02/04/19 11:16	Photo After Spray	 Load JPG	✓
73	02/04/19 11:16	Photo After Spray	 Load JPG	✓
74	02/04/19 11:16	Photo After Spray	 Load JPG	✓
75	02/04/19 11:16	Photo After Spray	 Load JPG	✓
76	02/04/19 11:16	Photo After Spray	 Load JPG	✓
77	02/04/19 11:16	Photo After Spray	 Load JPG	✓
78	02/04/19 11:16	Photo After Spray	 Load JPG	✓
79	02/04/19 11:16	Photo After Spray	 Load JPG	✓
80	02/04/19 11:16	Photo After Spray	 Load JPG	✓
81	02/04/19 11:16	Photo After Spray	 Load JPG	✓
82	02/04/19 11:16	Photo After Spray	 Load JPG	✓
83	02/04/19 11:16	Photo After Spray	Load JPG	✓

Photos/Images			3 per page ▼	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
Documentation			1 per page ▼	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	19/03/19 09:16	TPD SLE3941X GIA REPORT	 Load PDF	
2	19/03/19 09:16	OI SDU5331D GIA REPORT	 Load PDF	
3	19/03/19 09:16	TPD SLE3941X - PRI	 Load PDF	
4	19/03/19 09:16	Reply email from TP Lawyer & appoint LKK AUTO	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG19005007/GCD3S2

Date: 03/04/2019

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 29092678

Claimant Vehicle No: SLE3941X

Insured Vehicle No: SDU5331D

Date of Loss: 17/03/2019

Nature of Claim: TP

Claim No: 588025

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLE3941X

Make & Model: HONDA VEZEL, 1.5 X CVT (A)

Engine No: L15B4037537

Reg. Date: 20/07/2016 (Man. Year: 2016)

Chassis No: RU11117530

Colour: White

Odometer: 89403 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good

Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60R16

Rear Tyre Size:

215/60R16

Front Left Side: Dunlop 6 mm

Rear Left Side:

Dunlop 6 mm

Front Right Side: Dunlop 6 mm

Rear Right Side:

Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 19/03/2019

Date Inspected: 20/03/2019

Inspected At:

160 SIN MING DRIVE #05-17

Repairer: Hiap Lek Automobile Trading

Estimated Period of Repair: 5.0 days

Adjuster: XING GUO QIANG

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,000.00 - \$4,000.00

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 03 Apr 2019)

Parts: M1-SUV HONDA VEZEL 1.5 X CVT (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SLE3941X)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >