

22/03/2002

ASS. REC. BY:

REF: CS3 / CTI 19005009 / JCD302

Special Instruction:

Survivor: Hwe Jie

ASSIGNMENT (Office)

MURFAN

From (Person): Irene Tay Hui

of CTI

Date/Time: 19.3.2019 16.05p.m

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: PZ 1036P

Insured: PC 434JT

at Workshop m/s Sincere Lead Automotive

Tel: 9815 8858 (Raymond chua)

Policy No: DMBISN30152818000

Claim No: SNM19D201226(02)

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 22.2.2019

CA / REV / REP. / REV 24 HRS

"WP"

H.O.D. Endorsement:

Date/Time: 20.3.19 9.00a.m

Person Contacted: Raymond chua

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

PZ 1036P - X

PC 434JT - MA / CTI 19004626 / 14

D.O.A. - 14/3/2019

25/3/19 @ 8.57am Hwe Jie informed that the repairer will not provide us estimate.

Dismantle: 21/3/2019

REF: CTI

Sincere Hwe Jia

## ASSIGNMENT

From:

Date: 20.3.2019

Veh No: PZ 1036 P

Yr Regn: 19 May 2003

Estimated Cost:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

OD TP / WS / TP RES / OD RES / EVA / INV / MV

Truck / Trailer or

To Inspect Vehicle No:

PZ 1036 P

Make:

Toyota Hince

C.C 2982

at Workshop m/s

Sincere Lead Auto Motive

Colour

white

A/C: Insured / Std / NI / NA

of

38 Woodlands Ind Part E1 #0513

Sp. Reading

422801

T/Radio: Insured / Std / NI / NA

Insured:

Eng/No:

Policy No.

C/No:

LH1726112511

Claims No.

Gen. Cond: Good / Fair / Poor / Burnt

Sum Insured:

Excess:

Steering: Inorder / Jammed / Leaked / Burnt or

(Client's Record)

Brake: Inorder / Jammed / Leaked / Burnt or

Make of Veh:

Modi: Nil / S/Rim / STD A/Rim or


(Policy Condition)

Tyre Size:

F: 195R15

R: -

Remark: The veh had commenced its repair at the time of inspection.



BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Condor

Bal. or Market Value:

Front

Rear

IDAC Accident Rpt:

Consistent? : Yes or No

R/Bal.

7

mm

R/Bal.

7

mm

GIA / PR Seen:

Consistent? : Yes or No

L/Bal.

7

mm

L/Bal.

7

mm

Est. Repairs:

days

Res.: Yes or No

D.O.A.

22/2/19

D.O.I.

20/3/19

Lum Sum:

%

3 Val.: Yes or No

Survey held at

Sincere Lead

CA / REV / REP. / 24 HRS "WP"

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Date:

Person Contacted:

Vehicle: IN / OUT

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

20/3/19 Waiting for repairs to email estimate

PRS - no estimate

Range: \$4000 - \$5000  
5 days.

RECEIVED 03 APR 2019

2/4/2019

Date/Time, File Pass to?

☐

Preli. Report

Days Of Repair:

5

1)

☐

Final Report

Resurvey No. of Trip:

1

Survey Fee:

150

Date/Time, File Return to?

Transportation:

2)

Add Fee:

☐

Site Insp (\$

) S + RS. SI

☐

Interview (\$

) Photos

☐

Tech. Invs (\$

) Others

☐

Weekend (\$

)

Report Format:

PR2

Lump Sum / I.B.I: (\$

TOTAL

150

## ...CLAIM SUBFOLDER...(New Assignment)

## CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	19 Mar 2019		19 Mar 2019 16:05 Assign				<b>New Assignment</b> Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

## CLAIM SUBFOLDER DETAILS

Insured:		DYN00 TRANSPORT SERVICES, Co. Reg. No.: 53378134E		[Created by insurer]
Main Claimant:		SUNWAY TRANSPORTATION SERVICE, Co. Reg. No.: 53251719M		
Vehicle Reg. No.:	PZ1036P	Date of Loss:	22/02/2019 06:00 - :59 [189 Months and 3 Days From LTA Reg Date (Man Yr)]	
Claim Type:	TP / SNM19D201226C02	Policy/Cover Note No.:	DMB1SN30152818000 (Comprehensive) Coverage: 28/03/2018 - 27/03/2019	
Vehicle Reg. No. (Insured):	PC4347T	Policy No. (Claimant):		
		Excess:	S\$1,500.00	
Repairer:	Sincere Lead Automotive (Woodlands 3) 38 Woodlands Ind. Park E1 #05-13, 757710 Woodlands - Tel:			
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]			
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 28/03/2019]			
Adj Asg. Remarks:	to conduct PRS at Sincere Lead Automotive 38 woodlands industrial Park E1 #05-16 Singapore 757700. Contact Raymond chua 9815 8858 to arrange. thank you.			

## ASSOCIATED MAIL RECEIVED

There are no mail for this case.

View All

Compose Case Mail



## ALL ASSOCIATED TASKS

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type: Business

Owner ID: 1719M

**Vehicle Details**

Vehicle No.: PZ1036P

Vehicle to be Exported: No

Intended Deregistration Date: 22 Mar 2019

Vehicle Make: TOYOTA

Vehicle Model: HIACE

Primary Colour: White

Manufacturing Year: 2003

Engine No.: 5L5299691

Chassis No.: LH1726112511

Maximum Power Output: -

Open Market Value: \$24,449.00

Original Registration Date: 19 May 2003

First Registration Date: 19 May 2003

Transfer Count: 1

Actual ARF Paid: \$1,223.00

**Intended PARF Rebate Details**

PARF Eligibility: No

PARF Eligibility Expiry Date: -

PARF Rebate Amount: \$0.00

**Intended COE Rebate Details**

COE Expiry Date: 18 May 2023

COE Category: C - Goods Vehicle &amp; Bus

COE Period(Years): 5

PQP Paid: \$17,865.00

COE Rebate Amount: \$14,842.00

**Total Rebate Amount: \$14,842.00****Message**

Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 22 Mar 2019

OK

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	25/02/2019 12:47
Date Of Accident	22/02/2019 06:50
Exact Location Of Accident	5 ANG MO KIO AVE 10
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE	
Vehicle Registration Number	PZ1036P
<b>Insured/Policyholder</b>	
Name Of Registered Owner	SUNWAY TRANSPORTATION SERVICE
Co Reg No	53251719M
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-83806578
Alternative Phone No	OFFICE-83806578

<b>Vehicle Particulars</b>	
Manufacturer	TOYOTA
Model	HIACE
Exact Purpose for which vehicle was being used at time of accident	WORK USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	BUS

<b>Insurance Company</b>	
Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	NO
Policy Number	5088844745-01

<b>Driver</b>	
Name of Driver	TOH HOCK CHYE (ZHUO FUCAI)
NRIC No	S7212585A
Date Of Birth	17/04/1972
Occupation	OUTDOOR
Date Of Driving Pass	19/10/1993
Driving Experience	25 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-83806578
Fax Number	
Contact Number	
EEmail Address	NOEMAIL

Address BLK 13 MARSILING LANE #07-05  
 Postcode 730013  
 Was driver an employee of the Insured's Company YES  
 If No, Relationship of the Driver with the Insured  
 Vehicle Registration Number of Driver's Own Vehicle -  
 -  
 -  
 Insurance Company of Driver's Own Vehicle -  
 -  
 -

#### General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR  
 Weather Conditions CLEAR  
 Road Surface DRY

#### Other Information

Was any foreign vehicle involved in this accident? NO  
 Number of vehicles (including own vehicle) involved in the accident 2  
 Was any body injured in the Accident? YES  
 Was any injured conveyed to hospital by ambulance? NO  
 Was any other material or property damaged? YES  
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO  
 Number of Passengers (Including Driver) 11

#### Details of Police Action

Was the accident reported to the police? NO  
 If Yes, Please state which Police Station  
 Was notice of intended Prosecution given? NO  
 If Yes, against whom?

#### Circumstances of Accident

REFER TO ATTACHMENT

#### Attachment(s)

Are accident photos available for attachment? YES  
 Was there any video captured by Car Camera? NO  
 Was there any audio recorded? NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number PC4347T  
 Vehicle Make/Model/Colour  
 Details Of Properties  
 Vehicle Category BUS  
 Name of Driver DINIE HAZIQ BIN NORDIN  
 NRIC/Passport Number S9429454A  
 Contact Number 87763945  
 Address BLK 227 YISHUN ST 21 #02-504  
 Postcode 760227  
 Insurance Company Name  
 Nature Of Damage  
 No. Of Passenger (Including Driver)

#### DETAILS OF INJURED PERSON 1

Name TOH HOCK CHYE (ZHUO FUCAI)

Approximate Age

Injuries Sustain

Injured person in which vehicle?

PZ1036P

Were seat belts worn?

YES

Was this injured conveyed to hospital by ambulance?

NO

Address

Postcode

## Sketch Plan

### SKETCH PLAN

#### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow Insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by Insurance companies is not an admission of policy liability on the part of the Insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My Insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims, (collectively the "Purposes")
- (b) all Insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:


Reporting Centre Personnel's Signature  
Name:  
NRUC/FIN No.:



# Sketch Plan #2

## SKETCH PLAN

A) PZ 1036 P  
B) PC 4347 T



## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

ON THE STATED TIME & DATE, WHILE WAITING TO ENTER PATHLIGHT SCHOOL, SUDDENLY I FELT A GREAT IMPACT COMING FROM MY REAR. THEN I REALISED A VAN BEARING REGISTRATION NO. PC 4347 T HAD COLLIDED ONTO THE REAR OF MY VEHICLE.

I SUSTAINED SOME INJURIES DUE TO THE IMPACT. HENCE I PROCEED TO SEEK FOR MEDICAL TREATMENT AT PUBLIC MEDICAL CLINIC SURGERY. I WAS GIVEN 1 DAY OF MC. THAT IS ALL.

DECLARATION: I/we declare the above particulars are true in every respect.

Policyholder's Signature  
Date & Time:

Driver's Signature  
(if driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FBN No.:

### ...CLAIM SUBFOLDER...(Pending for Survey Report)






































CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	19 Mar 2019		19 Mar 2019 16:05 <a href="#">Edit Adj Rpt</a>	<b>S\$0.00</b> <a href="#">Edit Estimates</a>	<b>S\$0.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>











  

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by insurer]</span>									
Insured:	<b>DYNOO TRANSPORT SERVICES</b> , Co. Reg. No.: 53378134E								
Main Claimant:	<b>SUNWAY TRANSPORTATION SERVICE</b> , Co. Reg. No.: 53251719M								
Vehicle Reg. No.:	<b>PZ1036P</b>	Date of Loss:	22/02/2019 06:00 - :59 [189 Months and 3 Days From LTA Reg Date (Man Yr)]						
Claim Type:	<b>TP / SNM19D201226C02</b>	Policy/Cover Note No.:	DMB1SN30152818000 (Comprehensive) Coverage: 28/03/2018 - 27/03/2019						
Vehicle Reg. No. (Insured):	<b>PC4347T</b>	Policy No. (Claimant):							
		Excess:	S\$1,500.00						
Repairer:	<b>Sincere Lead Automotive (Woodlands 3)</b> 38 Woodlands Ind. Park E1 #05-13, 757710 Woodlands - Tel:								
Handling Insurer:	<b>China Taiping Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: 6389 6111 ... [Handled by <b>Irene Tay Hui Ping</b> - 638986192]								
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>ONG HWEE JIE</b> ] ... [Final Rpt due 28/03/2019]								
Adj Asg. Remarks:	to conduct PRS at Sincere Lead Automotive 38 woodlands industrial Park E1 #05-16 Singapore 757700. Contact Raymond chua 9815 8858 to arrange. thank you.								
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

\*PZ1036P (SNM19D201226C02)  
[PC4347T]  
TP  
SUNWAY TRANSPORTATION SERVICE  
Feb 22 2019 6:00AM  
[DYN00 TRANSPORT SERVICES]  
Sincere Lead Automotive

Upload Documents			Upload Photos		Compose New Letter		View		View in Browser	
Photos/Images								3 per page		<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print	
1	22/03/19 10:31	General View						 Load JPG	<input checked="" type="checkbox"/>	
2	22/03/19 10:31	General View						 Load JPG	<input checked="" type="checkbox"/>	
3	22/03/19 10:31	General View						 Load JPG	<input checked="" type="checkbox"/>	
4	22/03/19 10:31	General View						 Load JPG	<input checked="" type="checkbox"/>	
5	22/03/19 10:31	General View						 Load JPG	<input checked="" type="checkbox"/>	
6	22/03/19 10:31	General View						 Load JPG	<input checked="" type="checkbox"/>	
7	22/03/19 10:31	General View						 Load JPG	<input checked="" type="checkbox"/>	
8	22/03/19 10:31	General View						 Load JPG	<input checked="" type="checkbox"/>	
9	22/03/19 10:31	General View						 Load JPG	<input checked="" type="checkbox"/>	
10	22/03/19 10:31	General View						 Load JPG	<input checked="" type="checkbox"/>	
11	22/03/19 10:31	General View						 Load JPG	<input checked="" type="checkbox"/>	
12	22/03/19 10:31	General View						 Load JPG	<input checked="" type="checkbox"/>	
13	22/03/19 10:31	General View						 Load JPG	<input checked="" type="checkbox"/>	
14	22/03/19 10:31	General View						 Load JPG	<input checked="" type="checkbox"/>	
15	22/03/19 10:31	General View						 Load JPG	<input checked="" type="checkbox"/>	
16	22/03/19 10:31	General View						 Load JPG	<input checked="" type="checkbox"/>	
17	22/03/19 10:31	General View						 Load JPG	<input checked="" type="checkbox"/>	
18	22/03/19 10:31	General View						 Load JPG	<input checked="" type="checkbox"/>	
19	22/03/19 10:31	General View						 Load JPG	<input checked="" type="checkbox"/>	
20	22/03/19 10:31	General View						 Load JPG	<input checked="" type="checkbox"/>	
21	22/03/19 10:31	General View						 Load JPG	<input checked="" type="checkbox"/>	
22	22/03/19 10:31	General View						 Load JPG	<input checked="" type="checkbox"/>	
23	22/03/19 10:32	Dismantled Parts						 Load JPG	<input checked="" type="checkbox"/>	
24	22/03/19 10:32	Dismantled Parts						 Load JPG	<input checked="" type="checkbox"/>	
25	22/03/19 10:32	Dismantled Parts						 Load JPG	<input checked="" type="checkbox"/>	
26	22/03/19 10:32	Dismantled Parts						 Load JPG	<input checked="" type="checkbox"/>	
27	22/03/19 10:32	Dismantled Parts						 Load JPG	<input checked="" type="checkbox"/>	
28	22/03/19 10:32	Dismantled Parts						 Load JPG	<input checked="" type="checkbox"/>	
29	22/03/19 10:32	Dismantled Parts						 Load JPG	<input checked="" type="checkbox"/>	
30	22/03/19 10:32	Dismantled Parts						 Load JPG	<input checked="" type="checkbox"/>	
31	22/03/19 10:32	Dismantled Parts						 Load JPG	<input checked="" type="checkbox"/>	
32	22/03/19 10:32	Dismantled Parts						 Load JPG	<input checked="" type="checkbox"/>	
33	22/03/19 10:32	Dismantled Parts						 Load JPG	<input checked="" type="checkbox"/>	
34	22/03/19 10:32	Dismantled Parts						 Load JPG	<input checked="" type="checkbox"/>	
35	22/03/19 10:32	Dismantled Parts						 Load JPG	<input checked="" type="checkbox"/>	
36	22/03/19 10:32	Dismantled Parts						 Load JPG	<input checked="" type="checkbox"/>	
37	22/03/19 10:32	Dismantled Parts						 Load JPG	<input checked="" type="checkbox"/>	

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	22/03/19 10:32	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
39	22/03/19 10:32	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
40	22/03/19 10:32	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
41	22/03/19 10:32	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
42	22/03/19 10:32	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
43	22/03/19 10:32	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
44	22/03/19 10:32	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
45	22/03/19 10:32	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
46	22/03/19 10:32	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
47	22/03/19 10:32	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
48	22/03/19 10:32	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
49	22/03/19 10:32	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
50	22/03/19 10:32	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	19/03/19 16:02	PRS email	 Load PDF	
2	19/03/19 16:02	TP GIA Report	 Load PDF	
3	26/03/19 17:10	Singapore Accident Statement	 Load PDF	

## Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div style="border: 1px solid black; height: 100px; margin-top: 5px;"></div>				
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>				

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/CTI19005009/JCD3E2

Date: 04/04/2019

### REFERENCE

Handling Insurer: China Taiping Insurance  
(Singapore) Pte. Ltd.

Policy No: DMB1SN30152818000

Claimant Vehicle  
No : PZ1036PInsured Vehicle  
No : PC4347T

Date of Loss: 22/02/2019

Nature of Claim: TP

Claim  
No: SNM19D201226C02

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **PZ1036P**

Make &amp; Model: TOYOTA HIACE, 3.0 (A)

Reg. Date: 19/05/2003 (Man. Year: 2003)

Colour: White

Engine Capacity: 2985 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

Engine No: 5L5299691

Chassis No: LH1726112511

Odometer: 422801 km

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	195 R15	Rear Tyre Size:	195 R15
Front Left Side:	Condor 7 mm	Rear Left Side:	Condor 7 mm
Front Right Side:	Condor 7 mm	Rear Right Side:	Condor 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

### INSPECTION

Date of Assignment: 19/03/2019

Date Inspected: 20/03/2019 Inspected At:

Sincere Lead Automotive (Woodlands 3)  
38 Woodlands Ind. Park E1 #05-13  
Singapore 757710

Estimated Period of Repair: 5.0 days

Adjuster: ONG HWEE JIE

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.



- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.  
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$4,000.00 -\$5,000.00

## REPAIR DETAILS

<b>Reference</b>		
<b>Part Source:</b>	(Last Synchronised: 03 Apr 2019)	
<b>Parts:</b>	N/A	TOYOTA HIACE 3.0 (A) (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for PZ1036P)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.



## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.
---

< END OF ESTIMATES >