

ASS. REC. BY:

REF: CS 3 / A16 / 900507 / Gcd307 Special Instruction:

Surveyor:

GQ

ASSIGNMENT (Office)

From (Person):

Chin lee ying

of

AIG

Date/Time:

20/3/19 @ 12:09pm

Estimated Cost:

Bill to:

OD ATP / AWS / TP RES / OD RES / EVA / INV / MY / CS

To Inspect Vehicle No:

SMH 78084

Insured:

SKU 9449P

at Workshop m/s

Apex Motoring

Tel:

9169 0825

of

25 Kaki Bkt Rd # 61-55

Policy No:

1900011665

Claim No:

SMH 69237386

Sum Insured:

Excess:

Make of Vch:

(Client's Record)

D.O.A.

18/3/19

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

12:21pm @ 20/3/19

Person Contacted:

pei juen

Vehicle IN/OUT

Date/Time

Action/Instruction (X) Estimate

SMH 7808 H - X

SKU 9449 P - X

Dismantle: 21/3/2019

After repair: 25/3/2019

Surveysor: 1/K> 602REF: Alb.

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s Apex Motoring

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_

Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt.: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: \_\_\_\_\_ days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: SMH7808U Yr Regn: Jan / 19Type: M.Cas / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Noah C.C. 1797Colour: white

A/C: Insured / Std / NI / NA

Sp. Reading: 12263

T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: ZWR 80034 8845Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 155 / 65 R15R: u

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 8 mmR/Bal. 8 mmL/Bal. 8 mmL/Bal. 8 mm

D.O.A. \_\_\_\_\_

D.O.I. 20-03-19Survey held at w/s4:30pm

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Int n/s

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

\$2000 - \$2000

RECEIVED 02 APR 2019

Date/Time, File Pass to?

☐

: Preli. Report

☐

: Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair: 4Resurvey No. of Trip: 2Survey Fee: 180

Transportation: \_\_\_\_\_

S + RS, SI

Photos

Others

TOTAL

Report Format : DAR

Lump Sum / I.B.I.: (\$ \_\_\_\_\_)

Add Fee:

☐

: Site Insp (\$ \_\_\_\_\_)

☐

: Interview (\$ \_\_\_\_\_)

☐

: Tech. Invs (\$ \_\_\_\_\_)

☐

: Weekend (\$ \_\_\_\_\_)

10190

**- PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURE...**

From: Chin, Lee-Ying  
To: assignments@lkkauto.com, admin-a@lkkauto.com  
Cc: Fong, Andy-SY  
Sent: 20/3/2019 12:09:25 PM  
Attachments:  SMH7808U vs SKU9449P.PDF

---

Hi LKK,

Kindly assist to survey, vehicle in workshop.

Thanks.

Best Regards  
Lee Ying, Chin  
AIG  
Claims | AIG Asia Pacific Insurance Pte. Ltd.  
78 Shenton Way #08-16 Singapore 079120  
Tel +(65) 6419 1947  
[Lee-Ying.Chin@aig.com](mailto:Lee-Ying.Chin@aig.com) | [www.aig.sg](http://www.aig.sg)

**IMPORTANT NOTICE:**

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.



19/03/2019

**AIG Asia Pacific Insurance Pte Ltd**

AIG Building

78 Shenton Way #07-16

Singapore 079120

Fax : 6415 3727

Dear Sirs

**ACCIDENT BETWEEN VEHICLE NO. SMH 7808 U AND VEHICLE NO. SKU 9449 P ON 18/03/2019 @ 2230 Hrs**

We are the appointed repair workshop of vehicle no. **SMH 7808 U**.

We understand that you are the insurer of vehicle no. **SKU 9449 P**.

The owner of vehicle number **SMH 7808 U** has authorised us to carry out the repairs to his vehicle which was damaged by your insured's vehicle. The owner intends to make a claim against your insured and/or insured's authorised driver for the accident which is caused wholly and/or contributed by your insured and/or your insured's authorised driver's negligence.

We hereby give you notice of the accident and an opportunity to inspect the damaged to the vehicle prior to the commencement of the repairs.

The vehicle is now at our workshop awaiting for your inspection at the following address: 25 Kaki Bukit Road 4 #01-55 Synergy@KB Singapore 417800  
Mobile No. 91690825 / peijie@expresscar.com.sg. Ms Lim

Yours faithfully

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	6882D
Vehicle Details	
Vehicle No.:	SMH7808U
Vehicle to be Exported:	No
Intended Deregistration Date:	02 Apr 2019
Vehicle Make:	TOYOTA
Vehicle Model:	NOAH HYBRID 7-SEATER 1.8X CVT
Primary Colour:	White
Manufacturing Year:	2018
Engine No.:	2ZROC48330
Chassis No.:	ZWR800348845
Maximum Power Output:	100.0 kW (134 bhp)
Open Market Value:	\$33,549.00
Original Registration Date:	31 Jan 2019
First Registration Date:	31 Jan 2019
Transfer Count:	0
Actual ARF Paid:	\$28,969.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	30 Jan 2029
PARF Rebate Amount:	\$21,726.00
Intended COE Rebate Details	
COE Expiry Date:	30 Jan 2029
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$33,989.00
COE Rebate Amount:	\$33,395.00
<b>Total Rebate Amount:</b>	<b>\$55,121.00</b>

The information contained herein is correct as at 02 Apr 2019

OK

### SINGAPORE ACCIDENT STATEMENT

#### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	20/03/2019 12:09
Date Of Accident	18/03/2019 10:30
Exact Location Of Accident	CHANGI AIRPORT TERMINAL 4 CARPARK
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SMH7808U
<b>Insured/Policyholder</b>	
Name Of Registered Owner	ASIA EXPRESS CAR RENTAL PTE LTD
Co Reg No	201116882D
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-93690018
Alternative Phone No	OFFICE-93690018
<b>Vehicle Particulars</b>	
Manufacturer	TOYOTA
Model	NOAH
Exact Purpose for which vehicle was being used at time of accident	HIRER USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE
<b>Insurance Company</b>	
Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5089067751-01
Cover Note Number	
<b>Driver</b>	
Name of Driver	KOH CHENG HWEE JOSEPH
NRIC No	S8020319E
Date Of Birth	11/07/1980
Occupation	INDOOR
Date Of Driving Pass	16/12/2010
Driving Experience	8 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-93690018
Fax Number	
Contact Number	
EEmail Address	NOEMAIL

Address	BLK 209 JURONG EAST ST 21 # 10-345
Postcode	600209
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - CROSS JUNCTION
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	JURONG EAST NEIGHBOURHOOD POLICE CENTRE
Police Station Address	<b>ROAD:</b> NO. 92 BOON LAY WAY , <b>POSTCODE:</b> 609962 , <b>COUNTRY:</b> SINGAPORE
Police Station Contact	<b>TEL NO:</b> 1800-8999999 - <b>FAX NO:</b> 66655791
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

REFER TO ATTACHED

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKU9449P
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	KOO LILY
NRIC/Passport Number	S7017649A
Contact Number	91380378
Address	39H WEST COAST PARK #11-27
Postcode	
Insurance Company Name	
Nature Of Damage	

• No. Of Passenger (Including Driver)



## Sketch Plan

### SKETCH PLAN

#### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My Insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my Insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all Insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

Date & Time: 19-03-19

11:48am

Driver's Signature

(If driver is not the policyholder)

Date & Time: 19-03-19


11:48am

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to police report.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time: 19-03-19

11-48am

Driver's Signature

(If driver is not the policyholder)

Date & Time: 19-03-19

11-48am

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

POLICE REPORT



**SINGAPORE  
POLICE FORCE**



T/20190319/2086

Police Station Of Origin:  
Jurong East N.P.C  
92 Boon Lay Way SINGAPORE 609962  
Tel No: 1800-8999999

1 of 4

Report No. T/20190319/2086

**REPORT OF A TRAFFIC ACCIDENT**

Date/Time Report Made: 19/03/2019 15:37	Vide Report No.:	Station Diary No.: 86
--	------------------	--------------------------

**Informant's Particulars**

Name of Informant: KOH CHENG HWEE JOSEPH			Address: APT BLK 209 JURONG EAST STREET 21 #10-345 SINGAPORE 600209		
ID Type / ID No.: NRIC NO / S8020319E			Contact No.: Home/Office: Mobile: 93690018		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 38	Date of Birth: 11/07/1980	Type of Informant: Driver		
Race: Chinese			Language: English		Institution / School Name:
Occupation: GRAB DRIVER			Driving Licence Information: Class: 3 Date of Expiry:		

**General Information of the Accident**

Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 18/03/2019 22:30	Type of Location: Car Park
Location: Along Road 1 AIRPORT BOULEVARD  Carpark of Terminal 4				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow: One Way		Traffic Control: Not Controlled		Traffic Volume: Light
Type of Collision: Between Moving Vehicles - Head To Side				Anyone conveyed by ambulance: No

**Details of Vehicle Involved**

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SKU9449P	Car				Slightly Damaged	2
SMH7808U	Car				Slightly Damaged	0

**Details of Person Involved**

Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA

POLICE REPORT



**SINGAPORE  
POLICE FORCE**



T/20190319/2086

Police Station Of Origin:  
Jurong East N.P.C  
92 Boon Lay Way SINGAPORE 609962  
Tel No: 1800-8999999

2 of 4

Report No. T/20190319/2086

**CONTINUATION OF REPORT**

<b>Driver</b>			
Name	KOO LILY	ID No.	S7017649A
Related Vehicle	SKU9449P (Car)	Contact No.	91380378
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
<b>Driver</b>			
Name	KOH CHENG HWEE JOSEPH	ID No.	S8020319E
Related Vehicle	SMH7808U (Car)	Contact No.	93690018
Hospital/Clinic	RAFFLESMEDICAL	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	19/03/2019	Date Discharge	NIL
No. of Days granted Medical Leave	03	Degree of Injury	Slight

**Brief Details.**

On 18/03/2019 at about 2230hrs, I was driving my vehicle SMH7808U going out from Terminal 4 Carpark Level 1. When I was driving along the drive way near to the exit, I saw a car from the minor lane beside the slope travelling towards my lane, at high speed. I then made an emergency brake to avoid collision however it was too late, the car's front-right part hit onto the front-left part of my car.

We then alighted our vehicles to check on the damages as well as if anyone injured. The female driver informed that she was not injured and did not need medical attention at the point of time, she also informed that the two children on board was ok as well. We then exchanged particulars and left the location.

The damages to my car as follows:

- Front-left bumper dented;
- Front-left grill out of place;
- Front bonnet cover shifted;
- Front-left head light shifted.

I as unsure about the cost of the damages. I wish to inform that there was stopping line at the minor lane, the female driver supposed to stop and made a check before she proceed however she did not do so.

On 19/03/2019 in the morning, I informed the car leasing company (Favordrive Car Rental) as my car is a rented car, the other driver's particulars were also forwarded to them.



**SINGAPORE  
POLICE FORCE**



T/20190319/2086

Police Station Of Origin:  
Jurong East N.P.C  
92 Boon Lay Way SINGAPORE 609962  
Tel No: 1800-8999999

3 of 4

Report No. T/20190319/2086

**CONTINUATION OF REPORT**

On 19/03/2019 around noon, I went to seek medical treatment as I can feel strain at my neck area due to the impact. I was given three days MC from Raffles Medical.



**SINGAPORE  
POLICE FORCE**



T/20190319/2086

Police Station Of Origin:  
Jurong East N.P.C  
92 Boon Lay Way SINGAPORE 609962  
Tel No: 1800-8999999

4 of 4





Report No. T/20190319/2086

**CONTINUATION OF REPORT**

**Sketch Plan**

Informant is not able to provide sketch plan

**IMPORTANT:** Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report: D/ Sgt 3 MIAO TIAN 	Signature Of Informant: 
Signature Of Interpreter: Not applicable	Date/Time: 19/03/2019 15:37
Officer In Charge Of Case: TP / AEIT / Staff Sgt WONG SIEU LUI Contact No.: 65476151	Classification Of Case:
Authentication Stamp NP168   SIGNATURE	SN 34

**POLICE REPORT**



## Front Portion

AIG

Vehicle No:

SMH 7808N

NAC	INC	Item	CON	AC	Qty
1001	991886	Frt Number Plate			
1002	991887	Frt Number Plate Base			
1003	991889	Frt Number Plate Garnish			
1004	991300	Frt Bumper			
1005	992341	Frt Bumper Clips			
1006	991325	Frt Bumper Bracket			
1007	991462	Frt Bumper Side Retainer			
1008	991433	Frt Bumper Reinforcement			
1009	991318	Frt Bumper Beam			
1010	991468	Frt Bumper Sponge			
1011	991427	Frt Bumper Protector			
1012	991420	Frt Bumper Pad			
1013	991363	Frt Bumper Grille			
1014	991301	Frt Bumper Moulding			
1015	991407	Frt Bumper Lower Spoiler			
1016	991438	Frt Bumper Sensor			
1017	995100	Frt LH Bumper Fog Lamp Cover			
1018	991355	Frt RH Bumper Fog Lamp Cover			
1019	995079	Frt LH Bumper Fog Lamp			
1020	995080	Frt RH Bumper Fog Lamp			
1021	991793	Frt Grille			
1022	991328	Frt Grille Emblem			
1023	991799	Frt Grille Chrome Moulding			
1024	991222	Frt Apron Panel			
1025	992013	Frt Support Panel			
1026	992025	Frt Support Panel Top Garnish Cover			
1027	992416	Horn			
1028	991277	Frt Brace Panel			
1029	995153	Frt LH Headlamp Assy			
1030	991821	Frt RH Headlamp Assy			
1031	995088	Frt LH Side Lamp			
1032	995089	Frt RH Side Lamp			
1033	990248	Bonnet			
1034	991328	Bonnet Emblem			
1035	990287	Bonnet Lock			
1036	990285	Bonnet Insulator			
1037	990273	Bonnet Hinge			
1038	990261	Bonnet Damper			
1039	990305	Bonnet Rubber			
1040	990252	Bonnet Cable			
1041	990311	Bonnet Stand			
1042	990119	Air Con Condenser			
1043	990122	Air Con Fan Assy			
1044	990134	Air Con Suction Pipe (Low Pressure)			
1045	990118	Air Con Suction Hose			
1046	990133	Air Con Discharge Pipe (High Pressure)			
1047	990114	Air Con Discharge Hose			
1048	990149	Air Con Liquid Pipe			
1049	995066	Air Con Receiver Drier			
1050	990111	Air Con Compressor Assy			
1051	995294	Air Con Belt			
1052	995074	Radiator			
1053	992738	Radiator Cowling			
1054	992742	Radiator Fan Assy			
1055	992745	Radiator Fan Clutch			
1056	992758	Radiator Hose Top			
1057	992757	Radiator Hose Bottom			
1058	992741	Radiator Expansion Tank			
1059	990151	Air Duct			
1060	990070	Air Cleaner Assy			
1061	990056	Air Cleaner Hose			
1062	990089	Air Cleaner Resonator			
1063	991712	Frt Exhaust Manifold			
1064	991713	Frt Exhaust Manifold Cover			
1065	991054	Frt Exhaust Manifold Sensor (Oxygen)			
1066	991714	Front Exhaust Pipe			
1067	990219	Battery			
1068	990224	Battery Cover			
1069	990223	Battery Bracket			
1070	990229	Battery Tray			

NAC	INC	Item	CON	AC	Qty
1071	992205	Fuse Box			
1072	994011	Relay Box			
1073	995053	Wiper Washer Tank			
1074	995052	Wiper Washer Tank Motor			
1075	990159	Alternator Assy			
1076	990160	Alternator Belt			
1077	992688	Power Steering Pump			
1078	992669	Power Steering Belt			
1079	994431	Power Steering Cooler Pipe			
1080	992692	Power Steering Hose			
1081	990010	ABS Pump Control Unit			
1082	990427	Brake Master Pump Assy			
1083	990403	Brake Booster Pump Assy			
1084	991005	Engine Top Cover			
1085	991011	Engine Under Cover			
1086	990946	Engine Mounting			
1087	990949	Engine Mounting Frt			
1088	990950	Engine Mounting LH			
1089	990952	Engine Mounting RH			
1090	990951	Engine Mounting Rear			
1091	992234	Gear Box Mounting			
1092	991520	Frt LH Chassis Member			
1093	991520	Frt RH Chassis Member			
1094	990728	Frt Vertical Cross Member			
1095	991863	Frt Lower Cross Member			
1096	995070	Frt LH Fender			
1097	995072	Frt LH Fender Inner Panel			
1098	995147	Frt LH Fender Lamp			
1099	995148	Frt LH Fender Protector			
1100	991740	Frt LH Fender Inner Shield			
1101	995179	Frt LH Mudflap			
1102	995170	Frt LH Wheel Rim			
1103	994025	Frt LH Rim Cover			
1104	995065	Frt LH Tyre			
1105	995071	Frt RH Fender			
1106	991739	Frt RH Fender Inner Panel			
1107	991744	Frt RH Fender Lamp			
1108	991752	Frt RH Fender Protector			
1109	991740	Frt RH Fender Inner Shield			
1110	991884	Frt RH Mudflap			
1111	992087	Frt RH Wheel Rim			
1112	994025	Frt RH Rim Cover			
1113	995065	Frt RH Tyre			
1114	992093	Frt Windscreen Glass			
1115	992117	Frt Windscreen Rubber			
1116	992108	Frt Windscreen Moulding			
1117	992098	Frt Windscreen Sealant			
1118	991019	ERP Bracket			
1119	991020	ERP Unit			
1120	992140	Frt Wiper Arm			
1121	992142	Frt Wiper Blade			
1122	995045	Wiper Panel Garnish			
1123	991126	Firewall Panel			
1124	990753	Dashboard Assy			
1125	992282	Glove Box Cover			
1126	992281	Glove Box Compartment			
1127	994483	Steering Wheel Airbag			
1128	994485	Steering Wheel Airbag Sensor			
1129	990749	Dashboard Airbag			
1130	990750	Dashboard Airbag Sensor			
1131	990029	Airbag Control Unit			
1132	990864	Frt Driver Seat			
1133	991922	Frt RH Seat Belt Assy			
1134	991899	Frt Passenger Seat			
1135	995182	Frt LH Seat Belt Assy			
1136	990247	Sticker			

4 Days

### ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	19 Mar 2019 <a href="#">Edit Reg</a>		20 Mar 2019 00:00 <a href="#">Edit Adj Rpt</a>	<b>S\$0.00</b> <a href="#">Edit Estimates</a>	<b>S\$0.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> [Created by adjuster]									
Insured: <b>Foo Chee Juey</b> , ID: S7473107D									
Main Claimant: -									
Vehicle Reg. No.: <b>SMH7808U</b>		Date of Loss: 18/03/2019 00:00 - :59 [1 Months and 18 Days From LTA Reg Date (Man Yr)]							
Claim Type: <b>TP / 5474692373SG</b>		Policy/Cover Note No.: 1900011665 (Comprehensive)							
Vehicle Reg. No. (Insured): <b>SKU9449P</b>		Policy No. (Claimant):							
		Excess:							
Repairer: <b>Apex Motoring ( )</b> 25 Kaki Bukit Road 4, #01-55 Synergy @ KB, 417800 Kaki Bukit - Tel:									
Handling Insurer: <b>AIG Asia Pacific Insurance Pte. Ltd. (Express)</b> - Tel: 65-6419-3000 ... [Handled by <b>Loh, Chee-Heng</b> ] Chee-Heng.Loh@aig.com									
Adjuster: <b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>XING GUO QIANG</b> ] ... [Final Rpt due 29/03/2019]									
<b>ASSOCIATED MAIL RECEIVED</b> <a href="#">View All</a> <a href="#">Compose Case Mail</a>									
<ul style="list-style-type: none"> <li>AIG_SG (21/03/2019): Request To Upload TP GIA Report</li> </ul>									
<b>ALL ASSOCIATED TASKS</b> <a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									































## Claim Documents

**\*SMH7808U (5474692373SG)**  
**[SKU9449P]**  
**TP**

**Mar 18 2019 12:00AM**  
**[Foo Chee Juey]**  
**Apex Motoring**

Upload Documents		Upload Photos		Compose New Letter		Upload Video		Upload Audio		View <span style="border: 1px solid black; padding: 2px;">View in Browser</span>	
<b>Assessment Reports</b> <span style="float: right;">1 per page <span style="border: 1px solid black; padding: 2px;">v</span> <input checked="" type="checkbox"/></span>											
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)						Thumbnail		Print	
1	21/03/19 13:28	<b>Accident Statement</b> From: SC - Reg. No: SKU9449P, Claimant: FOO CHEE JUEY						Load HTM			
<b>Photos/Images</b> <span style="float: right;">3 per page <span style="border: 1px solid black; padding: 2px;">v</span> <input checked="" type="checkbox"/></span>											
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail		Print	
1	21/03/19 09:57	General View						Load JPG		<input checked="" type="checkbox"/>	
2	21/03/19 09:57	General View						Load JPG		<input checked="" type="checkbox"/>	
3	21/03/19 09:57	General View						Load JPG		<input checked="" type="checkbox"/>	
4	21/03/19 09:57	General View						Load JPG		<input checked="" type="checkbox"/>	
5	21/03/19 09:57	General View						Load JPG		<input checked="" type="checkbox"/>	
6	21/03/19 09:57	General View						Load JPG		<input checked="" type="checkbox"/>	
7	21/03/19 09:57	General View						Load JPG		<input checked="" type="checkbox"/>	
8	21/03/19 09:57	General View						Load JPG		<input checked="" type="checkbox"/>	
9	21/03/19 09:57	General View						Load JPG		<input checked="" type="checkbox"/>	
10	21/03/19 09:57	General View						Load JPG		<input checked="" type="checkbox"/>	
11	21/03/19 09:57	General View						Load JPG		<input checked="" type="checkbox"/>	
12	21/03/19 09:57	General View						Load JPG		<input checked="" type="checkbox"/>	
13	21/03/19 09:57	General View						Load JPG		<input checked="" type="checkbox"/>	
14	21/03/19 09:57	General View						Load JPG		<input checked="" type="checkbox"/>	
15	21/03/19 09:57	General View						Load JPG		<input checked="" type="checkbox"/>	
16	21/03/19 09:57	General View						Load JPG		<input checked="" type="checkbox"/>	
17	21/03/19 09:57	General View						Load JPG		<input checked="" type="checkbox"/>	
18	21/03/19 09:57	General View						Load JPG		<input checked="" type="checkbox"/>	
19	21/03/19 09:57	General View						Load JPG		<input checked="" type="checkbox"/>	
20	21/03/19 09:57	General View						Load JPG		<input checked="" type="checkbox"/>	
21	21/03/19 09:57	General View						Load JPG		<input checked="" type="checkbox"/>	
22	21/03/19 09:57	General View						Load JPG		<input checked="" type="checkbox"/>	
23	21/03/19 09:57	General View						Load JPG		<input checked="" type="checkbox"/>	
24	21/03/19 09:58	Odometer Reading						Load JPG		<input checked="" type="checkbox"/>	
25	21/03/19 09:58	Chassis Number						Load JPG		<input checked="" type="checkbox"/>	
26	02/04/19 09:01	Photographs of Damaged Parts						Load JPG		<input checked="" type="checkbox"/>	
27	02/04/19 09:01	Photographs of Damaged Parts						Load JPG		<input checked="" type="checkbox"/>	
28	02/04/19 09:01	Photographs of Damaged Parts						Load JPG		<input checked="" type="checkbox"/>	
29	02/04/19 09:01	Photographs of Damaged Parts						Load JPG		<input checked="" type="checkbox"/>	
30	02/04/19 09:01	Photographs of Damaged Parts						Load JPG		<input checked="" type="checkbox"/>	
31	02/04/19 09:01	Photographs of Damaged Parts						Load JPG		<input checked="" type="checkbox"/>	
32	02/04/19 09:01	Photographs of Damaged Parts						Load JPG		<input checked="" type="checkbox"/>	
33	02/04/19 09:01	Photographs of Damaged Parts						Load JPG		<input checked="" type="checkbox"/>	

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
34	02/04/19 09:01	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
35	02/04/19 09:01	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
36	02/04/19 09:01	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
37	02/04/19 09:01	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
38	02/04/19 09:01	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
39	02/04/19 09:01	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
40	02/04/19 09:01	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
41	02/04/19 09:01	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
42	02/04/19 09:01	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
43	02/04/19 09:01	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
44	02/04/19 09:02	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
45	02/04/19 09:02	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
46	02/04/19 09:02	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
47	02/04/19 09:02	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
48	02/04/19 09:02	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
49	02/04/19 09:02	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
50	02/04/19 09:02	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
51	02/04/19 09:02	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
52	02/04/19 09:02	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
53	02/04/19 09:02	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
54	02/04/19 09:02	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
55	02/04/19 09:02	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
56	02/04/19 09:02	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
57	02/04/19 09:02	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
58	02/04/19 09:02	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
59	02/04/19 09:02	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
60	02/04/19 09:02	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	26/03/19 11:58	TP GIA	 Load PDF	

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div style="border: 1px solid black; height: 100px; width: 100%;"></div>			
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG19005027/GCD3E2

Date: 04/04/2019

## REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1900011665  
**Claimant Vehicle No :** SMH7808U **Insured Vehicle No :** SKU9449P  
 Date of Loss: 18/03/2019 Nature of Claim: TP Claim No: 5474692373SG

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: **SMH7808U**  
 Make & Model: TOYOTA NOAH, 1.8 (A) Engine No: 2ZR0C48330  
 Reg. Date: 31/01/2019 (Man. Year: 2018) Chassis No: ZWR800348845  
 Colour: White Odometer: 12263 km  
 Engine Capacity: 1797 cc  
 Market Value/New Car Price: N/A  
 Sum Insured (S\$): **Market Value/New Car Price**

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

## CONDITION OF TYRES

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15  
 Front Left Side: Yokohama 8 mm Rear Left Side: Yokohama 8 mm  
 Front Right Side: Yokohama 8 mm Rear Right Side: Yokohama 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

## INSPECTION

Date of Assignment: 20/03/2019  
 Date Inspected: 20/03/2019 Inspected At: Apex Motoring  
 25 Kaki Bukit Road 4, #01-55 Synergy @  
 KB  
 Singapore 417800  
 Estimated Period of Repair: 4.0 days

Adjuster: XING GUO QIANG

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT BUMPER	Cut	0.00 F	*- F
2	1		*FRT BUMPER CLIPS	Necessary	0.00 F	*- F
3	1		*FRT GRILLE	Cracked	0.00 F	*- F
4	1		*FRT GRILLE EMBLEM	Necessary	0.00 F	*- F
5	1		*FRT SUPPORT PANEL	Repair	0.00 F	*- F
6	1		*FRT LH HEADLAMP ASSY	Cracked	0.00 F	*- F
7	1		*FRT LH FENDER	Repair	0.00 F	*- F
				<b>Total Parts (S\$)</b>	<b>0.00</b>	<b>0.00</b>

F=Franchise part.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.
---

< END OF ESTIMATES >