



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM19005097/Jga3q2

8 SHENTON WAY #24-01
AXA TOWERSINGAPORE 068811

Date : 17-04-2020



ATTN:RICHARD ANG

Code : ASM

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	XD 1959Y	Veh. Inspected	SG 5582S
Policy No.	GA420734/1	Coverage (\$)	0.00
Claim No.	S9M01HFS	Excess (\$)	0.00
Assign From		Assign Date	20/03/2019

2. Vehicle Particulars & Condition

Make & Model	VOLVO 9TL	c.c	9364
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	YV3S4P929GA179848	Colour	MULTI COLOUR
Odometer	126827	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	275/70 R22.5	CONTINENTAL	7 mm
L/H Front Tyre	275/70 R22.5	CONTINENTAL	7 mm
R/H Rear Tyre	275/70 R22.5	CONTINENTAL	7 mm
L/H Rear Tyre	275/70 R22.5	CONTINENTAL	7 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	18/03/2019	Inspection Date	21/03/2019
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	3 Working Days
-------------------------------------	----------------