



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672


Date Generated : 20/03/2019

User ID : GohKK2

Section A - Accident Details

Registration Number	SG5582S
Case Reference Number	BUS/03/19/7018
Registration Date	24/11/2016
Company Type	SMRT Buses Ltd
Make	VOLVO B9TL DD
Model	VOLVO
Name of Driver	Cao Guang
Type of Accident	Side Swipe
Accident Date and Time	18/3/2019 11:57 PM
Accident Reported Date and Time	19/3/2019 12:45 AM
Is Surveyor Required?	No
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	
Special Instruction to ARC, if any	SG5582S - REAR PORTION XD1959T (TP) - INSURED WITH AXA.
Prepared Date and Time	20/3/2019 12:47 PM
Chassis Number	YV3S4P929GA179848
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$1,590.00	\$0.00
Total Spray Cost	\$528.00	\$0.00
Total Spare Part Cost	\$979.12	\$0.00
Total Other Cost	\$0.00	\$0.00
TOTAL COST	\$3,097.12	\$0.00
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	4.0	
Prepared / Adjusted By	Kok Khoon Goh	
ARC / Surveyor Sign Off Date	20/03/2019 1:02 PM	
Signature		
Remarks		

Section C - Quotation and Accident Invoice Details

Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 20/03/2019

User ID : GohKK2

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS	\$1,590.00 1325	
Total Labour	\$1,590.00	

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS	\$528.00 446	
Total Spray Painting & Panel Beating	\$528.00	

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Other Costs		

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
6008191	VE		REFLECTOR, REAR: SCR EW-ON	1.00	\$5.14	10.00	\$4.63	Replace	CRA /
6009375			TYPE, MBOC500, MBG	1.00	\$54.24	10.00	\$48.82	Replace	Jam /
			RATAINER MALE & FEMALE	1.00	\$75.00	0.00	\$75.00	Replace	nn x
			STICKER SG LOVE	1.00	\$861.86	10.00	\$775.67	Replace	CRA /
6011099	VE	7612002L21	LIGHT, REVERSE LED, F OR ADL E500 DD BUS	1.00	\$75.00	0.00	\$75.00	Replace	nc /
			STICKER SMRT	1.00			\$979.12		
Total					\$1,071.24				

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Hue Jie-LKK

21/3/19

P/P 3days.

[Signature]