



SMRT Accident Vehicle Repair Estimates

Pole kin

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63885592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 08/04/2019

User ID : CatherineLee

Section A - Accident Details

Registration Number	SG5582S
Case Reference Number	BUS/03/19/7018
Registration Date	24/11/2016
Company Type	SMRT Buses Ltd
Make	VOLVO B9TL DD
Model	VOLVO
Name of Driver	Cao Guang
Type of Accident	Side Swipe
Accident Date and Time	18/3/2019 11:57 PM
Accident Reported Date and Time	19/3/2019 12:45 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle Issued?	No
Job Card Number	24100696
Special Instruction to ARC, if any	SG5582S - REAR PORTION XD1959T (TP) - INSURED WITH AXA
Prepared Date and Time	20/3/2019 12:47 PM
Chassis Number	YV3S4P929GA179848
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$1,590.00	\$1,325.00
Total Spray Cost	\$528.00	\$446.00
Total Spare Part Cost	\$979.12	\$904.12
Total Other Cost	\$0.00	\$0.00
TOTAL COST	\$3,097.12	\$2,675.12
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	4.0	3.0
Prepared / Adjusted By	Kok Khoo Goh	Hwee Jie
ARC / Surveyor Sign Off Date	20/03/2019 1:02 PM	21/03/2019 12:58 PM
Signature		
Remarks		

Section C - Quotation and Accident Invoice Details

Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 08/04/2019

User ID : CatherineLee

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS.	\$1,590.00	\$1,325.00
Total Labour	\$1,590.00	\$1,325.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS	\$528.00	\$446.00
Total Spray Painting & Panel Beating	\$528.00	\$446.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Other Costs		

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
			STICKER SMRT	1.00	\$75.00	0.00	\$75.00	Replace	Replace
6011099	VE	7612002L21	LIGHT, REVERSE LED, F OR ADL E500 DD BUS	1.00	\$861.86	10.00	\$775.67	Replace	Replace
6008191	VE		REFLECTOR, REAR, SCR EW-ON TYPE, MB0C500, MBG	1.00	\$5.14	10.00	\$4.63	Replace	Replace
6009375			RATAINER MALE & FEMALE	1.00	\$54.24	10.00	\$48.82	Replace	Replace
			STICKER SG LOVE	0.00	\$75.00	0.00	\$0.00	Replace	Not Given
Total					\$1,071.24		\$904.12		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

p/p \$2675 12/- 3days.