

Customer

ASS. REF. NO.

Surveyor

REF CS3/ALG/9005130/Gcd3br

ed Instruction

ASSIGNMENT (Office)

From (Person)

Chin Lee Ying

ed

ALG

Date/Time

20/3/19 @ 3:56am

Estimated Cost

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MYTC

To Inspect Vehicle No

SJU 1536K

Insured

SGV 2447H

at Workshop m/

Wee Hwee Auto
19 Kim Chuan Terrace

Tel

68880019

of

Policy No

Claim No

9015245727SG

Sum Insured

Excess

Make of Veh

(Client's Record)

D.O.A

19/3/19

CA / REV / REP. / REV 24 HRS

Date/Time

9:55am 21/3/19

Person Contacted

Mr. Kiat

H.O.D. Endorsement

Vehicle IN/OUT

Date/Time

Action/Instruction (X) Estimate

SJU 1536K - NBA/ALG/9005046/Y

D.O.A: 19/3/19

SGV 2447H - NBA/ALG/9005046/Y

D.O.A: 19/3/19

After repair: 26/3/2019.

Dismantle: 22/3/2019

PRS
GA

REF: AIG

C4281H

ASSIGNMENT

C-2019)

From: Date: 21/3/19

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SJU1536K
at Workshop m/s: Wee Hee Auto
of: 19 Kim chuan Terrace

Insured:

Policy No.

Claims No.


Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Report: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 9 days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted:

Vehicle: IN / OUT

Veh No: SJU1536K Yr Regn: 2e Nov 2009

Type: M/Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Prius C.C. 1798

Colour: Black A/C: Insured / Std / NI / NA

Sp.Reading: 228304 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: JTDKN36U 0011 06321

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195/65 R15

R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or NEXEN

Front

Rear

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. D.O.I. 21-03-19

Survey held at IDAC UB; NAC 10:20

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: 4

Resurvey No. of Trip: 2

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

Add Fee: ☐ : Site Insp (\$)

☐ : Interview (\$)

☐ : Tech. Invs (\$)




☐ : Weekend (\$)

Report Format : DAR

Lump Sum / I.B.I. (\$)

180
10
190

- PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURE...

From: Chin, Lee-Ying
To: assignments@lkkauto.com, admin-a@lkkauto.com
Cc: Fong, Andy-SY
Sent: 20/3/2019 3:56:25 PM
Attachments:  tmpB744.tif  4757_001.pdf  3113_001.pdf

Hi LKK,

Kindly assist to survey.

Thanks.

Best Regards
Lee Ying, Chin
AIG
Claims | AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way #08-16 Singapore 079120
Tel +(65) 6419 1947
Lee-Ying.Chin@aig.com | www.aig.sg

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

VISION LAW LLC

Advocates & Solicitors - Notary Public - Commissioner for Oaths
Agents for Trade Marks
(Incorporated with limited liability)

ERIC NG CHING HOON
WONG KENG LEONG RAYNEY
AUDREY WONG SU-HSIEN
PAUL YAP TAI SAN
ANJALI D/O MUNIANDY
ANG KIM NOI DIANE
RAVENDRA KRISHNASAMY
TAN YINGXIAN, SELWYN
CHEONG YUNHUI, CLARISSA
EDISON TAM CHYI EU
SONIA LIM WEI LEI

Company Registration No. 200721148H



Head Office:

133 New Bridge Road
#18-01/02 Chinatown Point
Singapore 059413

Branch:

490 Toa Payoh Lorong 6
#03-11 HDB Hub
Singapore 310490

HEAD OFFICE:

TEL : 65342811 (Hunting)
FAX : 65356802 (General)



E-MAIL: annatan@visionlawllc.com

BRANCH

TEL : 63580703
FAX : 63580448(conveyancing)

WHEN REPLYING PLEASE QUOTE OUR REFERENCE - Please reply to **HEAD OFFICE** for this matter

OUR REF: AW1-atv-INS-W30-SJU1536K-2019 - please reply to: annatan@visionlawllc.com
YOUR REF: SGV 2447 H

20 March 2019

AIG ASIA PACIFIC INSURANCE PTE LTD

CHARTIS Building
78 Shenton Way #07-16
Singapore 079120

Attn: Motor Claims Department

BY FAX 6835-7416 ONLY

AIGSGP_ClaimsSurvey@aig.com

Dear Sirs

NAME OF CLAIMANT: QUALITY PTE LTD

VEHICLE NUMBER: SJU 1536 K

YOUR INSURED VEHICLE NUMBER: SGV 2447 H

ACCIDENT ALONG GUILLEMARD ROAD TURN TO GEYLANG LOR 22 ON 19 march 2019 AT ABOUT 1910HOURS

We refer to your email dated 20 march 2019 wherein there is no agreement to the appointment of Single Joint Expert for this matter.

Please be informed that the said vehicle can be inspected at :

WEE HOE AUTO SERVICE

19 KIM CHUAN TERRACE
SINGAPORE 537041

Contact Person:

TEL: 6858-0019 (KIAT)

If you fail to conduct the pre-repair inspection within the next 2 working days excluding any intervening Saturday, Sunday or Public Holiday, the said workshop will commence repairs thereafter without further reference to you.

Yours faithfully

(Head Office)

cc. **SJU 1536 K**- By fax 6858-0195 only

FOR SURVEYOR

Please initial here after completion of pre-repair inspection. Thank you.

Appointed surveyor :
(Name & Signature) :

Date & Time of Inspection :

CONFIDENTIALITY

THE INFORMATION CONTAINED IN THESE DOCUMENTS MAY BE PRIVILEGED AND CONFIDENTIAL AND IS INTENDED FOR THE EXCLUSIVE USE OF THE ADDRESSEE DESIGNATED ABOVE. If you are not the addressee, any disclosure, reproduction, distribution or other dissemination or use of this communication is strictly prohibited. If you have received this transmission in error please contact us immediately by telephone so that we can arrange for its return.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	4281H
Vehicle Details	
Vehicle No.:	SJU1536K
Vehicle to be Exported:	No
Intended Deregistration Date:	22 Mar 2019
Vehicle Make:	TOYOTA
Vehicle Model:	PRIUS AUTO
Primary Colour:	Black
Manufacturing Year:	2009
Engine No.:	2ZR4485265
Chassis No.:	JTDKN36U001106321
Maximum Power Output:	73.0 kW (97 bhp)
Open Market Value:	\$35,505.00
Original Registration Date:	20 Nov 2009
First Registration Date:	20 Nov 2009
Transfer Count:	1
Actual ARF Paid:	\$21,303.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	19 Nov 2019
PARF Rebate Amount:	\$10,651.00
Intended COE Rebate Details	
COE Expiry Date:	19 Nov 2019
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
QP Paid:	\$18,890.00
COE Rebate Amount:	\$1,247.00
Total Rebate Amount:	\$11,898.00

The information contained herein is correct as at 22 Mar 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	20/03/2019 10:46
Date Of Accident	19/03/2019 19:10
Exact Location Of Accident	GUILLEMARD RD TURN TO GEYLANG LOR 22
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SJU1536K
Insured/Policyholder	
Name Of Registered Owner	QUALITY PTE. LTD.
Co Reg No	201624281H
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-90088701
Vehicle Particulars	
Manufacturer	TOYOTA
Model	PRIUS
Exact Purpose for which vehicle was being used at time of accident	COMMERCIAL
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE
Insurance Company	
Name of Insurance Company	TOKIO MARINE INSURANCE SINGAPORE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	NO
Policy Number	18-MJ001405-R00
Cover Note Number	-
Driver	
Name of Driver	NG CHENG HAN
NRIC No	S1789870A
Date Of Birth	24/10/1967
Occupation	OUTDOOR
Date Of Driving Pass	30/01/1988
Driving Experience	31 YEARS AND 1 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-98801140
Fax Number	
Contact Number	
EEmail Address	NOEMAIL

Address	BLK 98 ALJUNIED CRESCENT #08-417
Postcode	380098
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - CROSS JUNCTION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

I WAS TRAVELLING ALONG GUILLEMARD RD ON THE SECOND LANE, WHILE APPROACHING JUNC WITH LOR 22 GEYLANG, MY LANE WAS A TURN LEFT AND GO STRAIGHT LANE. VEH B WAS ON THE EXTREME LEFT LANE, EXTREME LEFT LANE ONLY FOR TURN LEFT. WHILE I TURNING LEFT INTO LOR 22 GEYLANG, VEH B GOING STRAIGHT AND HIT ONTO MY VEH LEFT HAND SIDE.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	WITH DRIVER
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SGV2447H
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	RAMESH S/O ELANGO VAN
NRIC/Passport Number	S8942051B
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

No. Of Passenger (Including Driver)

Accident Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all Insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Accident Sketch Plan

SKETCH PLAN

Acc 22 Geylang

A = SJU 1536K
B = SGV 2447H

← ↑ ↑

Quintessence Rd

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Please Refer to Statement

[The remaining lines of the section are crossed out with a diagonal line.]

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Other

7.20 PM
RAMESH
90253045

This accident
was caused
by me.

R.

CONDITIONS

(1) Item (2) Bent (3) Distorted (4) Cracked (5) Cut (6) Scratched
 (7) Disconnected (8) Stuffed (9) Buckled (10) Broken (11) Necessary (12) Missing
 (13) Torn (14) Unfinished (15) Not Working

MOTOR CAR (LH)

ACTION (AC)

(1) Replace (✓) (2) Repair (X) (3) Check (7)
 (4) Not Consistent (NC)

Aug

Vehicle No:

STU15361C

Left Portion

NAC	INC	Item	CON	AC	Qty
1255	995326	Frt LH Door	Repl		
1256	995140	Frt LH Door Protector			
1257	995104	Frt LH Door Hinge			
1258	995142	Frt LH Door Wing Mirror	Repl		
1259	995102	Frt LH Door Garnish			
1260	991593	Frt LH Door Glass Outer Moulding			
1261	991588	Frt LH Door Glass Inner Moulding			
1262	995103	Frt LH Door Glass			
1263	991595	Frt LH Door Glass Regulator			
1264	991596	Frt LH Door Glass Regulator Motor			
1265	991662	Frt LH Door Rubber			
1266	991636	Frt LH Door Outer Handle			
1267	991607	Frt LH Door Inner Handle			
1268	991625	Frt LH Door Lock w/Key			
1269	991624	Frt LH Door Lock			
1270	991562	Frt LH Door Central Lock			
1271	991675	Frt LH Door Switch			
1272	991617	Frt LH Door Inner Trim Board			
1273	991568	Frt LH Door Checker			
1274	991575	Frt LH Door Felt			
1275	991688	Frt LH Door Wire Harness			
1276	991683	Frt LH Door Window Glass Pillar			
1277	991640	Frt LH Door Outer Pillar			
1278	991613	Frt LH Door Inner Pillar			
1279	991646	Frt LH Door Pillar Inner Garnish			
1280	990554	Centre Pillar LH			
1281	990542	Centre Inner Pillar LH			
1282	990517	Centre Pillar Upper Garnish LH			
1283	990564	Centre Pillar Lower Garnish LH			
1284	991670	Frt LH Door Step Garnish			
1285	994052	Rocker Panel LH	Repair		
1286	994049	Rocker Panel Inner Panel LH			
1287	994046	Rocker Panel Garnish LH			
1288	994055	Rocker Panel Outer Side Skirt LH			
1004	991300	Frt Bumper			
1006	991325	Frt Bumper Bracket			
1007	991462	Frt Bumper Side Retainer			
1008	991433	Frt Bumper Reinforcement			
1010	991468	Frt Bumper Sponge			
1011	991427	Frt Bumper Protector			
1014	991301	Frt Bumper Moulding			
1015	991407	Frt Bumper Lower Spoiler			
1029	995153	Frt LH Headlamp Assy			
1031	995088	Frt LH Side Lamp			
1096	995070	Frt LH Fender	Repair		
1098	995147	Frt LH Fender <i>Lamp Emblem</i>	Repl		
1099	995148	Frt LH Fender Protector			

NAC	INC	Item	CON	AC
1289	995156	Rear LH Door		
1290	993282	Rear LH Door Protector		
1291	995194	Rear LH Door Hinge		
1292	993228	Rear LH Door Garnish		
1293	993278	Rear LH Door Glass Outer Moulding		
1294	993231	Rear LH Door Glass Inner Moulding		
1295	995190	Rear LH Door Glass		
1296	993238	Rear LH Door Glass Regulator		
1297	995192	Rear LH Door Glass Regulator Motor		
1298	993294	Rear LH Door Rubber		
1299	993275	Rear LH Door Outer Handle		
1300	993250	Rear LH Door Inner Handle		
1301	993261	Rear LH Door Lock		
1302	993256	Rear LH Door Inner Trim Board		
1303	993218	Rear LH Door Checker		
1304	993230	Rear LH Door Glass Channel		
1305	993242	Rear LH Door Glass Triangle Garnish		
1306	993285	Rear LH Door 1/4 Glass		
1307	993288	Rear LH Door 1/4 Glass Rubber		
1308	993287	Rear LH Door 1/4 Glass Pillar		
1309	993305	Rear LH Door Step Garnish		
1310	993309	Rear LH Door Switch		
1311	994070	Roof Top Panel		
1312	994098	Roof Top Moulding		
1313	994085	Roof Top Air-bag		
1314	994084	Roof Top Air-bag Sensor		
1315	994083	Roof Top Air-bag Control Unit		
1141	992958	Rear Bumper		
1147	992976	Rear Bumper Bracket		
1148	993068	Rear Bumper Side Retainer		
1149	993045	Rear Bumper Reinforcement		
1151	993077	Rear Bumper Sponge		
1153	993040	Rear Bumper Protector		
1155	993026	Rear Bumper Moulding		
1157	993023	Rear Bumper Lower Spoiler		
1163	993851	Rear LH Taillamp		
1218	993436	Rear LH Fender		
1219	993449	Rear LH Fender Protector		
1136	990247	Sticker		

No of Items: _____

Assessor: _____



































...CLAIM SUBFOLDER...(Pending for Survey Report)



CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	20 Mar 2019 Edit Reg		20 Mar 2019 00:00 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	ASSET LIMO , Co. Reg. No.: NA								
Main Claimant:	QUALITY PTE LTD , Co. Reg. No.: 201624281H								
Vehicle Reg. No.:	SJU1536K	Date of Loss:	19/03/2019 19:00 - :59 [111 Months and 27 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 9015245727SG	Policy/Cover Note No.:	(Third Party Only)						
Vehicle Reg. No. (Insured):	SGV2447H	Policy No. (Claimant):							
		Excess:							
Repairer:	Wee Hoe Auto Service (HQ) 19 Kim Chuan Terrace, Singapore 537041, 537041 Kaki Bukit - Tel: 68580019								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Foo, Chit Yan] Chityan.Foo@aig.com								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 10/04/2019]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
<ul style="list-style-type: none"> AIG_SG (02/04/2019): Request To Upload TP GIA Report 									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SJU1536K (9015245727SG)
[SGV2447H]
TP
QUALITY PTE LTD
Mar 19 2019 7:00PM
[ASSET LIMO]
Wee Hoe Auto Service

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View			View in Browser		
Photos/Images															3 per page		<input checked="" type="checkbox"/>			
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)													Thumbnail	Print				
1	01/04/19 14:00	General View													Load JPG	<input checked="" type="checkbox"/>				
2	01/04/19 14:00	General View													Load JPG	<input checked="" type="checkbox"/>				
3	01/04/19 14:00	General View													Load JPG	<input checked="" type="checkbox"/>				
4	01/04/19 14:00	General View													Load JPG	<input checked="" type="checkbox"/>				
5	01/04/19 14:00	General View													Load JPG	<input checked="" type="checkbox"/>				
6	01/04/19 14:00	General View													Load JPG	<input checked="" type="checkbox"/>				
7	01/04/19 14:00	General View													Load JPG	<input checked="" type="checkbox"/>				
8	01/04/19 14:00	General View													Load JPG	<input checked="" type="checkbox"/>				
9	01/04/19 14:00	General View													Load JPG	<input checked="" type="checkbox"/>				
10	01/04/19 14:00	General View													Load JPG	<input checked="" type="checkbox"/>				
11	01/04/19 14:00	General View													Load JPG	<input checked="" type="checkbox"/>				
12	01/04/19 14:00	General View													Load JPG	<input checked="" type="checkbox"/>				
13	01/04/19 14:00	General View													Load JPG	<input checked="" type="checkbox"/>				
14	01/04/19 14:00	General View													Load JPG	<input checked="" type="checkbox"/>				
15	01/04/19 14:00	General View													Load JPG	<input checked="" type="checkbox"/>				
16	01/04/19 14:00	General View													Load JPG	<input checked="" type="checkbox"/>				
17	01/04/19 14:00	General View													Load JPG	<input checked="" type="checkbox"/>				
18	01/04/19 14:00	General View													Load JPG	<input checked="" type="checkbox"/>				
19	01/04/19 14:00	General View													Load JPG	<input checked="" type="checkbox"/>				
20	01/04/19 14:04	Photographs of Damaged Parts													Load JPG	<input checked="" type="checkbox"/>				
21	01/04/19 14:04	Photographs of Damaged Parts													Load JPG	<input checked="" type="checkbox"/>				
22	01/04/19 14:04	Photographs of Damaged Parts													Load JPG	<input checked="" type="checkbox"/>				
23	01/04/19 14:04	Photographs of Damaged Parts													Load JPG	<input checked="" type="checkbox"/>				
24	01/04/19 14:04	Photographs of Damaged Parts													Load JPG	<input checked="" type="checkbox"/>				
25	01/04/19 14:04	Photographs of Damaged Parts													Load JPG	<input checked="" type="checkbox"/>				
26	01/04/19 14:04	Photographs of Damaged Parts													Load JPG	<input checked="" type="checkbox"/>				
27	01/04/19 14:05	Photo After Spray													Load JPG	<input checked="" type="checkbox"/>				
28	01/04/19 14:05	Photo After Spray													Load JPG	<input checked="" type="checkbox"/>				
29	01/04/19 14:05	Photo After Spray													Load JPG	<input checked="" type="checkbox"/>				
30	01/04/19 14:05	Photo After Spray													Load JPG	<input checked="" type="checkbox"/>				
31	01/04/19 14:05	Photo After Spray													Load JPG	<input checked="" type="checkbox"/>				
32	01/04/19 14:05	Photo After Spray													Load JPG	<input checked="" type="checkbox"/>				
33	01/04/19 14:05	Photo After Spray													Load JPG	<input checked="" type="checkbox"/>				
34	01/04/19 14:05	Photo After Spray													Load JPG	<input checked="" type="checkbox"/>				
															1 per page		<input checked="" type="checkbox"/>			
Documentation															1 per page		<input checked="" type="checkbox"/>			
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)													Thumbnail	Print				

Photos/Images			3 per page	<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	03/04/19 09:31	TP GIA		Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail	Print
1	02/04/19 13:38	OI GIA REPORT		Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)
<div></div>
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG19005130/GCD3E2

Date: 04/04/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

Claimant Vehicle No : SJU1536K

Insured Vehicle No : SGV2447H

Date of Loss: 19/03/2019

Nature of Claim: TP

Claim No: 9015245727SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SJU1536K

Make & Model: TOYOTA PRIUS, 1.5 (A)

Engine No: 2ZR4485265

Reg. Date: 20/11/2009 (Man. Year: 2009)

Chassis No: JTDKN36U001106321

Colour: Black

Odometer: 228304 km

Engine Capacity: 1798 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15

Front Left Side: Nexen 6 mm Rear Left Side: Nexen 6 mm

Front Right Side: Nexen 6 mm Rear Right Side: Nexen 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 20/03/2019

Date Inspected: 21/03/2019 Inspected At:

Wee Hoe Auto Service (HQ)
19 Kim Chuan Terrace, Singapore 537041
Singapore 537041

Estimated Period of Repair: 4.0 days

Adjuster: XING GUO QIANG

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT LH DOOR	Buckled	0.00 F	*- F
2	1		*FRT LH DOOR WING MIRROR	Cracked	0.00 F	*- F
3	1		*ROCKER PANEL LH	Repair	0.00 F	*- F
4	1		*FRT LH FENDER	Repair	0.00 F	*- F
5	1		*FRT LH FENDER EMBLEM	Necessary	0.00 F	*- F
Total Parts (S\$)					0.00	0.00

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >