

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD			Ref : CC4/ASM19005138/Eps3q2	
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:KIAN CHUAN		Date: 12-05-2020 Code: ASM		
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SGY 265M	Veh. Inspected	FJ 7379M
	Policy No.	GA260212	Coverage (\$)	0.00
	Claim No.	S8M00WLW	Excess (\$)	0.00
	Assign From		Assign Date	21/03/2019
2. Vehicle Particulars & Condition				
	Make & Model	YAMAHA RXZ	c.c	133
	Engine No.	HIDDEN	Year of Reg.	1991
	Chassis No.	2UX005906	Colour	BLUE
	Odometer	6279	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	FAIR		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	70/80-18	METZELER	6 mm
	L/H Front Tyre			mm
	R/H Rear Tyre	80-90-18	METZELER	6 mm
	L/H Rear Tyre			mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION & O/S AND N/S BODY.			
	DAMAGES SEE DETAILS.			
5.	General Information			
	Accident Date	22/09/2018	Inspection Date	25/03/2019
	Survey held at	eld at SYN MAGDACO INTERNATIONAL		
	20, SHAW ROAD, #01-03, CHING SHINE INDUSTRIAL BUILDING, SINGAPORE 367956			
5a.	Remarks			
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b.	Estimate Days of Repair			
	ESTIMATED NORMAL PERIOD FOR REPAIR: 5 Working Days			