

Consumer

ASSIGNMENT

SALES

023/CTI19005150/Gcd302

ASSIGNMENT (Office)

From Person: **Chong Boon Sen**

of **CTI**

Date/Time: **21/3/19 @ 2:44pm**

Estimated Cost

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MY / CS

To Inspect Vehicle No.

**SLG 6953G**

Insured

**GBC 1851P**

at Workshop m/s

**Euro Success**

Tel

**9828 9277**

of

**1 Kaki Blk Ave 6 #02-03**

Policy No.

**DMCVSN30490518000**

Claim No.

**SNM11D201267C02**

Sum Insured

Excess

Make of Veh

(Client's Record)

D.O.A

**20/3/2019**

CA / REV / REP. / REV 24 HRS

**22/3/2019**

H.O.D. Enforcement

Date/Time:

**3:37pm @ 21/3/19**

Person Contacted:

**Ah Hwat**

Vehicle

**IN / OUT**

Date/Time	Action/Instruction (X) Estimate
	<b>GBC 1851P - NA / INC / 5003/24 / 14</b>
	<b>SLG 6953G - NA / EQ / 18016400 / 13</b>
	<b>Dismantle: 30/4/2019</b>
	<b>20A: 17/2/15</b>
	<b>DOA: 17/3/18</b>
	<b>F1 2884</b>
	<b>FBE 5/19</b>

REF: CTI

C58288

## ASSIGNMENT

PRS

From:

Date:

22/3/2019

Veh No:

SLG6953G

Yr Regn:

11 oct 2016

Estimated Cost:

Type: ☒ M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /OD / ☒ TP / WS / TP RES / OD RES / EVA / INV / MV

Truck / Trailer or

To Inspect Vehicle No:

~~ABC1851P~~

Make:

Mazda 3

C.C.

1496

at Workshop m/s

Euro Success

Colour

white

A/C: Insured / Std / NI / NA

of

11 Kaki Bukit Ave 6 # 02-03

Sp. Reading

160090

T/Radio: Insured / Std / NI / NA

Insured:

Eng/No:

Policy No.

C/No:

JM6BM 42A8G0349672

Claims No.

Gen. Cond: ☒ Good / Fair / Poor / Burnt

Sum Insured:

Excess:

Steering: ☒ In order / Jammed / Leaked / Burnt or

(Client's Record)

Brake: ☒ In order / Jammed / Leaked / Burnt or

Make of Veh:

Ah Huat @ 9828 9277

Modi: Nil / S/Rim / STD / A/Rim or

(Policy Condition)

Tyre Size:

F:

205/60 R16

R:

11

Remark: The veh had commenced its  
repair at the time of inspection.

<input checked="" type="checkbox"/>	
N/S	O/S

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

CST

Bal. or Market Value:

Front

Rear

IDAC Accident Rpt:

Consistent? : Yes or No

R/Bal.

6

mm

R/Bal.

6

mm

GIA / PR Seen:

Consistent? : Yes or No

L/Bal.

6

mm

L/Bal.

6

mm

Est. Repairs:

12

days

Res.: Yes or No

D.O.A.

D.O.I.

22/3/2019

Lum Sum:

%

3 Val.: Yes or No

Survey held at

CA / REV / REP. / 24 HRS

1up

Vehicle: IN / OUT

Date:

Person Contacted:

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

\$10k - \$12k

Date/Time, File Pass to?

☐

Preli. Report

Days Of Repair:

10

1)

☐

Final Report

Resurvey No. of Trip:

1

Date/Time, File Return to?

2)

Add Fee:

☐

Site Insp (\$)

☐

Interview (\$)

☐

Tech. Invs (\$)

☐

Weekend (\$)

Survey Fee:

150

Transportation:

S + RS, SI

Photos

Others

TOTAL

150

Report Format :

PRS

Lump Sum / I.B.I: (\$)

**Nivitha (LKK Auto)**

---

**From:** Chong Boon Sen <boonsen.chong@sg.cntaiping.com>  
**Sent:** Thursday, 21 March 2019 2:49 PM  
**To:** Ruby Ong  
**Cc:** assignments  
**Subject:** RE: OUR REF: SNM19D201267-GBC1851P -REQUEST FOR PRE-REPAIR SURVEY  
PROTOCOL FOR SLG 6953G [OUR REF. TCL.GCN.RO.50168.19.ESS]

**WITHOUT PREJUDICE**  
**SAVE AS TO COSTS**

Dear Ruby,

We refer to your email below.

We regret to inform that we are not agreeable to your list of proposed surveyors and will be assigning our panel surveyor, M/s LKK Auto Consultants to conduct the Pre-repair survey.

Please contact our surveyor to conduct the post repair inspection before returning the repaired vehicle to the claimant.

Aside to LKK,

Please refer to the email below and liaise with third party workshop accordingly.

Thank you.

Regards,  
**Chong Boon Sen**  
Claims Executive  
Claims

**China Taiping Insurance (Singapore) Pte. Ltd.**  
3 Anson Road #16-00 Springleaf Tower  
Singapore 079909  
Co. Reg. No. 200208384E  
DID: 63896171  
Fax: 62247175  
Email: boonsen.chong@sg.cntaiping.com  
Website: www.sg.cntaiping.com

*Disclaimer :*

*This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.*

---

**From:** Ruby Ong [mailto:ruby@htapartners.com.sg]  
**Sent:** Thursday, 21 March, 2019 2:47 PM  
**To:** Chong Boon Sen <boonsen.chong@sg.cntaiping.com>  
**Subject:** RE: OUR REF: SNM19D201267-GBC1851P -REQUEST FOR PRE-REPAIR SURVEY PROTOCOL FOR SLG 6953G  
[OUR REF. TCL.GCN.RO.50168.19.ESS]  
**Importance:** High

Without Prejudice

Save As To Cost

Dear Sirs

We refer to your email of even date.

Our client regrets to reject your list of surveyors and append below our client's list of surveyors for your consideration.

1. Mr Bok
2. Mike

If your end is not agreeable with the above list of surveyors, kindly contact the person-in-charge to arrange for the inspection of the vehicle. Please be informed that the said vehicle can be inspected at: -

Venue : **EURO SUCCESS SERVICES PTE LTD**  
1 Kaki Bukit Avenue 6  
#02-03 Autobay  
Singapore 417883

Contact Person : Ah Huat (Tel. 9828 9277 / 6742 6231)

If you fail to conduct the pre-repair survey within the next 2 working days excluding any intervening Saturday, Sunday or Public Holiday, the said workshop will commence repairs thereafter without further reference

Best regards,  
Ruby Ong  
Secretary  
M/s Hin Tat Augustine & Partners  
20 Upper Circular Road  
#02-10/12 The Riverwalk  
Singapore 058416  
**Tel : 6533 0212 ext 278**  
**Fax : 6338 3536 / 6533 0313**  
[www.htapartners.com.sg](http://www.htapartners.com.sg)

Privileged/Confidential information is contained in this message. If you are not the addressee indicated in this message (or responsible for delivery of the message to such person), you may not copy or deliver this message to anyone. In such case, you should destroy this message and kindly notify the sender by reply email.

---

**From:** Chong Boon Sen <[boonsen.chong@sg.cntaiping.com](mailto:boonsen.chong@sg.cntaiping.com)>

**Sent:** Thursday, March 21, 2019 1:57 PM

**To:** Ruby Ong <[ruby@htapartners.com.sg](mailto:ruby@htapartners.com.sg)>

**Subject:** RE: OUR REF: SNM19D201267-GBC1851P -REQUEST FOR PRE-REPAIR SURVEY PROTOCOL FOR SLG 6953G  
[OUR REF. TCL.GCN.RO.50168.19.ESS]

Without Prejudice

Dear Sir,

We intend to conduct a pre-repair survey of the damage to your client's vehicle jointly with your client/your motor workshop. We propose to use one of the following motor surveyors to conduct the joint pre-repair survey as a single joint expert.

ADRIAN LING
Kelvin Ang
SEE CHEW SENG
MOHD FADHILAH BIN OSMAN
XING QUO QIANG
KENNETH KONG
SIMON HO
CHUA WEIJIE
MARCUS CHUA
HENRY NG

Please let us know within two(2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.

You may select one of the listed motor surveyors and we will bear the cost of the pre-repair survey carried out by the single joint expert.

Regards,

**Chong Boon Sen**

Claims Executive

Claims

**China Taiping Insurance (Singapore) Pte. Ltd.**

3 Anson Road #16-00 Springleaf Tower

Singapore 079909

Co. Reg. No. 200208384E

DID: 63896171

Fax: 62247175

Email: [boonsen.chong@sg.cntaiping.com](mailto:boonsen.chong@sg.cntaiping.com)

Website: [www.sg.cntaiping.com](http://www.sg.cntaiping.com)

*Disclaimer :*

*This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.*

---

**From:** Ruby Ong [<mailto:ruby@htapartners.com.sg>]

**Sent:** Thursday, 21 March 2019 12:01 PM

**To:** Claims Dept of CTI <[claimsdept@sg.cntaiping.com](mailto:claimsdept@sg.cntaiping.com)>

**Subject:** REQUEST FOR PRE-REPAIR SURVEY PROTOCOL FOR SLG 6953G [OUR REF. TCL.GCN.RO.50168.19.ESS]

**Importance:** High

Your ref : GBC 1851P

**WITHOUT PREJUDICE**

Our ref : TCL.GCN.ro.50168.19.ess

21 March 2019

**China Taiping Insurance Co (Singapore) Pte Ltd**  
Motor Claims Department  
3 Anson Road  
#16-00 Springleaf Tower  
Singapore 079909

By Email Only

## VERY URGENT

Dear Sirs,

**CLAIMANT: AMV PTE LTD**

**ACCIDENT INVOLVING SLG 6953G & GBC 1851P ALONG CORPORATION ROAD TOWARDS JURONG PORT ROAD ON 20 MARCH 2019 @ 0715 HRS**

We are instructed by AMV Pte Ltd to notify you of a road traffic accident on 20 March 2019 at about 0715 hrs along Corporation Road towards Jurong Port Road involving our clients' vehicle registration number SLG 6953G and vehicle registration number GBC 1851P driven by your insured/insured's driver at the material time.

As a result of the accident, our client's vehicle has been damaged. Before our client proceed to repair the damaged vehicle, please let us know within 2 working days of your receipt of this notice whether you or your insurers would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without reference to you.

Best regards,

Ruby Ong

Secretary

M/s Hin Tat Augustine & Partners

20 Upper Circular Road

#02-10/12 The Riverwalk

Singapore 058416

**Tel : 6533 0212 ext 278**

**Fax : 6338 3536 / 6533 0313**

[www.htapartners.com.sg](http://www.htapartners.com.sg)

Privileged/Confidential information is contained in this message. If you are not the addressee indicated in this message (or responsible for delivery of the message to such person), you may not copy or deliver this message to anyone. In such case, you should destroy this message and kindly notify the sender by reply email.

---

This email has been scanned by the Symantec Email Security.cloud service.

For more information please visit <http://www.symanteccloud.com>

---

---

This email has been scanned by the Symantec Email Security.cloud service.

For more information please visit <http://www.symanteccloud.com>

---

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

Owner ID Type:	Company
Owner ID:	5825Z
Vehicle No.:	SLG6953G
Vehicle to be Exported:	No
Intended Deregistration Date:	24 Mar 2019
Vehicle Make:	MAZDA
Vehicle Model:	MAZDA3 4-DOOR SEDAN 1.5L SP6EAT
Primary Colour:	White
Manufacturing Year:	2016
Engine No.:	P520369712
Chassis No.:	JM6BM42A8G0343672
Maximum Power Output:	88.0 kW (118 bhp)
Open Market Value:	\$17,428.00
Original Registration Date:	11 Oct 2016
First Registration Date:	11 Oct 2016
Transfer Count:	2
Actual ARF Paid:	\$12,428.00
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	10 Oct 2026
PARF Rebate Amount:	\$9,321.00
COE Expiry Date:	10 Oct 2026
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$50,000.00
COE Rebate Amount:	\$37,717.00
<b>Total Rebate Amount:</b>	<b>\$47,038.00</b>

The information contained herein is correct as at 24 Mar 2019

OK

## Certificate of Insurance

MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189)  
MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) RULES, 1960  
ROAD TRANSPORT ACT, 1987 (MALAYSIA)  
MOTOR VEHICLES (THIRD PARTY RISKS) RULES, 1959 (MALAYSIA)

Certificate Number: 5095368867-01

Cover : drive CLASSIC

1. Index mark and Registration Number of Vehicle : SLG6953G  
Chassis Number : JM6BM42A8G0343672
2. Name of Policyholder : AMV PTE. LTD.
3. Effective Date of Insurance : 27 Oct 2018
4. Expiry Date of Insurance : 26 Oct 2019
5. Persons or Classes of Persons entitled to drive#  
(a) The Policyholder.  
(b) Any other person who is driving on the Policyholder's order or with his/her permission.  
Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.
6. Limitations as to Use#  
(a) Use for social domestic and pleasure purposes and in connection with the Policyholder's or Hirer's business.

**This Policy does not cover**

- (a) Use for racing, pace-making, reliability trial or speed-testing.
  - (b) Use for the carriage of goods (other than samples) in connection with any trade or business.
  - (c) Use for any purpose in connection with the Motor Trade.
- # Limitations rendered inoperative by Section 8 of the Motor Vehicle (Third Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS (SECTION 1)	: S\$2,000
EXCESS (SECTION 2)	: S\$1,500
WINDSCREEN EXCESS	: S\$100
ADDITIONAL EXCESS	: N/A
UNNAMED DRIVER EXCESS	: PLEASE REFER OVERLEAF
REPAIR AT OWNER'S PREFERRED WORKSHOP	: NO
INSURE WITH COE	: YES
NCD PROTECTION	: NO
TRANSPORT ALLOWANCE	: NO
EXCESS WAIVER	: NO
PRIMARY DRIVER	: N/A
NAMED DRIVER (1)	: N/A
NAMED DRIVER (2)	: N/A
HIRE PURCHASE COMPANY	: SWEE SENG CREDIT PTE LTD
SUM INSURED	: MARKET VALUE OF INSURED VEHICLE AT TIME OF LOSS

I/We hereby Certify that the Policy to which this Certificate relates is Issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia)

Agency : SININS AGENCY PTE. LTD. (00000615123)  
Date of Issue : 23 Oct 2018 13:20 hrs

For NTUC INCOME INSURANCE CO-OPERATIVE LIMITED

Countersigned By:

Authorised Officer

Chief Executive



REPUBLIC OF SINGAPORE DRIVING LICENCE



Licence Number: **S8515434F**  
Name: **CHEN YUTONG**  
Birth Date: **14 May 1985**  
Issue Date: **03 Nov 2003**



000972187D


REPUBLIC OF SINGAPORE  
IDENTITY CARD NO. **S8515434F**




Name: **CHEN YUTONG**  
**陳煜童**  
Race: **CHINESE**  
Date of birth: **14-05-1985**  
Country/Place of birth: **SINGAPORE**  
Sex: **M**



Land Transport Authority



**VOCATIONAL LICE**  
Licence No: **S8515434F**  
Name: **CHEN YUTONG**  
Card Issue Date: **15/03/2018**  
Please visit [www.lta.gov.sg](http://www.lta.gov.sg) to check the status of this vocational licence



PDVL/TDVL  
33 888 88888  
261168

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

Class 2B Motorcycles <= 200 CC  
 Class 3 Motor cars <= 3500 kg with <= 7 passengers, exclusive of the driver; and motor tractors/vehicles <= 2500 kg

PASS DATE

22 Jan 2012  
 03 Nov 2003

S8515434F

S / No. 9000160676

NP 428A



Licence No. S8515434F

5525290



S8515434F



Date of issue

07-09-2015

Address

APT BLK 317 JURONG EAST STREET 31  
 #13-30  
 SINGAPORE 600317

This card is not transferable and is the property of the Land Transport Authority (LTA). It must be surrendered to LTA on request. If found, please return to LTA, 10 Sin Ming Drive, Singapore 575701.

Type	Description	Issue Date
13	PRIVATE HIRE CAR VL	15/03/2018



## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	20/03/2019 15:25
Date Of Accident	20/03/2019 07:15
Exact Location Of Accident	CORPORATION RD BEFORE JURONG PORT ROAD
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SLG6953G
Insured/Policyholder	
Name Of Registered Owner	AMV PTE. LTD.
Co Reg No	201505825Z
Email Address	INFO@AMV-SINGAPORE.COM
Mobile Phone No	(LOCAL) +65-98583956
Alternative Phone No	OFFICE-98583956
Vehicle Particulars	
Manufacturer	MAZDA
Model	MAZDA3 4-DOOR SEDAN 1.5L SP.6EAT
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE
Insurance Company	
Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5095368867-01
Cover Note Number	
Driver	
Name of Driver	CHEN YUTONG
NRIC No	S8515434F
Date Of Birth	14/05/1985
Occupation	OUTDOOR
Date Of Driving Pass	03/11/2003
Driving Experience	15 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-93264941
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	BLK 317 JURONG EAST STREET 31 #13-30
Postcode	600317
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - HEAD ON COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : GRAB PASSENGER GENDER: : MALE

#### Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	TRAFFIC POLICE DIVISION HQ
Police Station Address	ROAD: 10 UBI AVENUE 3 , POSTCODE: 408865 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 65470000 - FAX NO:
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

AS PER POLICE REPORT No.T/20190320/2066;

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBC1851P
Vehicle Make/Model/Colour	MITSUBISHI FB70BB1SRDEA
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	ZHANG XING
NRIC/Passport Number	G3283509R
Contact Number	
Address	

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodging of this report to the insurer, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore (GIA) are/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurers who have insured vehicle(s) involved in this accident (all insurers who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Roadside Authority, Singapore and any relevant government agency/authority (such as the police) for the purposes of:
  - (i) processing, handling and/or dealing with my claim including the settlement of the claim and any necessary investigations relating to my claim;
  - (ii) investigating the accident and/or this claim;
  - (iii) carrying out and/or dealing with any investigation or responding to any enquiry from;
  - (iv) administering my claim, including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as the external cover of envelopes/mail packages; and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claim(s) collectively the "Purposes".
- (b) all insurers who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may be permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may be disclosed by any of the insurers and/or GIA to their third party agent or agent or agent(s) holding their insurance policy, which may be used outside of Singapore for the purposes of the above Purposes;
- (d) my Personal Information may be disclosed and/or used by the insurers and/or GIA to their third party agent or agent or agent(s) holding their insurance policy for the purposes of the above Purposes;
- (e) my Personal Information collected under this Form may be shared with:
  - (i) to all insurers and/or any third party (that exist in evaluating, investigating, controlling or managing their regulators, law enforcement and government agencies is reasonably required for the purposes herein);
  - (ii) for complying with requirements under any regulations, and reports orders



Policyholder's Signature  
Date & Time:

Driver's Signature  
(if driver is not the policyholder)  
Date & Time:


20 JAN 2019

**IDAC KAKI BUKIT, VSCB**  
23 KAKI BUKIT AVENUE

Reporting Centre: Singapore 410906  
Name: Tel: 67416697  
NRIC/FIN No.: Fax: 67492305  
Email: vscb@singnet.com.sg

1. SIGNATURE OF THE POLICYHOLDER

# Accident Sketch Plan Pg. 1



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to police report.

## DECLARATION

I/We declare the foregoing particulars are true in every respect.



Police Officer's Signature  
Date & Time:

SPRAC (Revised) Form 1001\_V3

Driver's Signature  
(if driver is not the policyholder)  
Date & Time:

20 MAR 2019  
IDAC KAKI BUKIT (VAC)

23 KAKI BUKIT AVE 4  
Singapore 415933  
Reporting Centre Phone: 67492305  
Name: Fax: 67492305  
NRIC/FIN Email: vackb@singnet.com.sg

# Accident Sketch Plan Pg. 1



**SINGAPORE  
POLICE FORCE**



T/20190320/2066

Police Station Of Origin:  
Traffic Police  
10 Ubi Avenue 3 SINGAPORE 408865  
Tel No: 65470000

1 of 3

Report No. T/20190320/2066

## REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 20/03/2019 12:43		Vide Report No.:		Station Diary No.:	
<b>Informant's Particulars</b>					
Name of Informant: CHEN YU TONG			Address: APT BLK 317 JURONG EAST STREET 31 #13-30 SINGAPORE 600317		
ID Type / ID No.: NRIC NO / S8515434F			Contact No.: Home/Office: Mobile: 93264941		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 33	Date of Birth: 14/05/1985	Type of Informant: Driver		
Race: Chinese			Language: English		Institution / School Name:
Occupation: GRAB DRIVER			Driving Licence Information: Class: 2B,3		Date of Expiry:

<b>General Information of the Accident</b>				
Type of Accident:	Injury Attended by Police	Drink Drive: No	Date/Time of Accident: 20/03/2019 07:15	Type of Location:
Location: Along Road 1 CORPORATION ROAD  CORPORATION ROAD > JURONG PORT ROAD				
Weather:		Road Surface:	Road Speed Limit:	
Traffic Flow:		Traffic Control:	Traffic Volume:	
Type of Collision:			Anyone conveyed by ambulance: Yes	

<b>Details of Vehicle Involved</b>						
Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
GBC1851P	Lorry					0
SLG6953G	Car					1





SINGAPORE  
POLICE FORCE



T/20190320/2066

Police Station Of Origin:  
Traffic Police  
10 Ubi Avenue 3 SINGAPORE 408865  
Tel No: 65470000

2 of 3

Report No. T/20190320/2066

CONTINUATION OF REPORT

**Brief Details.**

ON THE ABOVE MENTION DATE TIME AND LOCATION,

ON 20/03/2019 AT ABOUT 0715HRS, I WAS TRAVELLING ALONG CORPORATION ROAD > JURONG PORT ROAD CENTER OF 3 LANE ROAD. WHILE TRAVELLING ALONG MENTIONED LOCATION THE TRAFFIC WAS GREEN AND I PROCEEDED FORWARD TO CROSS THE JUNCTION. SUDDENLY A LORRY FROM OPPOSITE SIDE MAKE A RIGHT TURN AND COLLIDED ONTO FRONT RIGHT PORTION OF MY VEHICLE WITH FRONT LEFT PORTION OF HIS VEHICLE. AFTER THAT, POLICE AND AMBULANCE CAME ME AND MY PASSENGER CONVEYED BY AMBULANCE.

Accident Sketch Plan Pg. 1



**SINGAPORE  
POLICE FORCE**



T/20190320/2066

Police Station Of Origin:  
Traffic Police  
10 Ubi Avenue 3 SINGAPORE 408865  
Tel No: 65470000

3 of 3

Report No. T/20190320/2066

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report: TP / TAN KOK RAY	Signature Of Informant: 
Signature Of Interpreter: Not applicable	Date/Time: 20/03/2019 12:43
Officer In Charge Of Case: TP / GIT / Sgt 3 MARIAH BINTE ZAKARIA Contact No.: 65476433	Classification Of Case:  SINGAPORE POLICE FORCE
Authentication Stamp NP168	

Date of Accident : 20-03-2019 Accident Time: 0715 (24-HR-Format)

Accident Place : Corporation road before Jurong port road

Vehicle No. (Car Plate No.) : SL6 6753 G Make/Model: Mazda

Insurance Company : NTUC Policy No: 5095368867-01

Owner or Company Name / IC No. : AMV PTE LTD 2015058252

Owner or Company Contact No. : 98583956 Owner's Hp Company Tel

DRIVER'S Name / IC No. : Chen Yutong (S8515434F)

DRIVER'S Date Of Birth : 14-05-1985 DRIVER'S License Pass Date : 03-11-2003

Relationship of Owner & Driver : Spouse Parents Children Sibling Employee Others:

DRIVER'S Address : B1K 317 Jurong East Street 31, #13-30, (S) 600 317

DRIVER'S Contact No. / Alt No. : 9326 4941 21

DRIVER'S Occupation : INDOOR OUTDOOR (e.g. working inside or outside office)

Email Address : xdetox32@gmail.com

Weather & Road Surface : CLEAR & DRY RAINING & WET AFTER RAIN & WET

Reporting Type : Reporting Only Claim Other Party Claim Own Insurance

Number of Passengers (Including Driver): 02

Was there any video Captured by car camera: YES \ NO

Exact purpose for which vehicle was being used at the time of accident: Private use \ Work purpose

Any Injury (If YES, Pls state):

Other Party Driver's Particular (if any)

Vehicle No: ABC 1851P

Vehicle No: \_\_\_\_\_

Vehicle Make/Model: MITSUBISHI FUSO

Vehicle Make/Model: \_\_\_\_\_

Name Driver: Zhang Xing

Name Driver: \_\_\_\_\_

IC No. Driver/Contact: G 328 3509 R

IC No. Driver/Contact: \_\_\_\_\_

\* NEW - Passenger's name & gender:

黃雨新 : 8678 4520, (M)



Police Station Of Origin:  
Traffic Police  
10 Ubi Avenue 3 SINGAPORE 408865  
Tel No: 65470000

**REPORT OF A TRAFFIC ACCIDENT**

Date/Time Report Made: 20/03/2019 12:43	Vide Report No.:	Station Diary No.:
--	------------------	--------------------

**Informant's Particulars**

Name of Informant: CHEN YU TONG			Address: APT BLK 317 JURONG EAST STREET 31 #13-30 SINGAPORE 600317		
ID Type / ID No.: NRIC NO / S8515434F			Contact No.: Home/Office: Mobile: 93264941		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 33	Date of Birth: 14/05/1985	Type of Informant: Driver		
Race: Chinese			Language: English		Institution / School Name:
Occupation: GRAB DRIVER			Driving Licence Information: Class: 2B,3 Date of Expiry:		

**General Information of the Accident**

Type of Accident:	Injury Attended by Police	Drink Drive: No	Date/Time of Accident: 20/03/2019 07:15	Type of Location:
Location: Along Road 1 CORPORATION ROAD  CORPORATION ROAD > JURONG PORT ROAD				
Weather:		Road Surface:	Road Speed Limit:	
Traffic Flow:		Traffic Control:	Traffic Volume:	
Type of Collision:			Anyone conveyed by ambulance: Yes	

**Details of Vehicle Involved**

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
GBC1851P	Lorry					0
SLG6953G	Car					1



**SINGAPORE  
POLICE FORCE**



T/20190320/2066

2 of 3

Police Station Of Origin:  
Traffic Police  
10 Ubi Avenue 3 SINGAPORE 408865  
Tel No: 65470000

Report No. T/20190320/2066

**CONTINUATION OF REPORT**

**Brief Details.**

ON THE ABOVE MENTION DATE TIME AND LOCATION,

ON 20/03/2019 AT ABOUT 0715HRS, I WAS TRAVELLING ALONG CORPORATION ROAD > JURONG PORT ROAD CENTER OF 3 LANE ROAD. WHILE TRAVELLING ALONG MENTIONED LOCATION THE TRAFFIC WAS GREEN AND I PROCEEDED FORWARD TO CROSS THE JUNCTION. SUDDENLY A LORRY FROM OPPOSITE SIDE MAKE A RIGHT TURN AND COLLIDED ONTO FRONT RIGHT PORTION OF MY VEHICLE WITH FRONT LEFT PORTION OF HIS VEHICLE. AFTER THAT, POLICE AND AMBULANCE CAME ME AND MY PASSENGER CONVEYED BY AMBULANCE.



**SINGAPORE  
POLICE FORCE**



T/20190320/2066

Police Station Of Origin:  
Traffic Police  
10 Ubi Avenue 3 SINGAPORE 408865  
Tel No: 65470000

3 of 3

Report No. T/20190320/2066

**CONTINUATION OF REPORT**

**Sketch Plan**

Informant is not able to provide sketch plan

**IMPORTANT:** Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the **report number** as reference.

Signature Of Officer Recording The Report:  
TP /  
TAN KOK RAY

Signature Of Interpreter:  
Not applicable

Officer In Charge Of Case:  
TP / GIT /  
Sgt 3 MARIAH BINTE ZAKARIA  
Contact No.: 65476433

Authentication Stamp  
NP168

Signature Of Informant:

Date/Time:  
20/03/2019 12:43

Classification Of Case:

SINGAPORE  
POLICE FORCE

### ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	02 Apr 2019		02 Apr 2019 15:34 <a href="#">Edit Adj Rpt</a>	<b>S\$0.00</b> <a href="#">Edit Estimates</a>	<b>S\$0.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>



















































Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by insurer]</span>									
Insured:	-, Co. Reg. No.: -								
Main Claimant:	<b>AMV PTE. LTD.,</b> Co. Reg. No.: 201505825Z								
Vehicle Reg. No.:	<b>SLG6953G</b>	Date of Loss:	20/03/2019 07:00 - :59 [29 Months and 9 Days From LTA Reg Date (Man Yr)]						
Claim Type:	<b>TP / SNM19D201267C02</b>	Policy/Cover Note No.:	DMCVSN30490518000						
Vehicle Reg. No. (Insured):	<b>GBC1851P</b>	Policy No. (Claimant):	5095368867-01						
		Excess:	S\$0.00						
Repairer:	<b>Euro Success Services Pte Ltd (HQ)</b> 1 KAKI BUKIT AVENUE 6 #02-03 AUTOBAY, 417883 Kaki Bukit - Tel:								
Handling Insurer:	<b>China Taiping Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: 6389 6111 ... [Handled by <b>Chong Boon Sen</b> ]								
Claimant's Insurer:	<b>NTUC Income Insurance Co-operative Ltd (HQ)</b> - Tel:								
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>XING GUO QIANG</b> ] ... <b>[Final Rpt due 11/04/2019]</b>								
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									



















































## Claim Documents

\*SLG6953G (SNM19D201267C02)  
 [GBC1851P]  
 TP  
 AMV PTE. LTD.  
 Mar 20 2019 7:00AM  
 [-]  
 Euro Success Services Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			View <div>View In Browser</div>		
Assessment Reports									1 per page		<input checked="" type="checkbox"/>
No	Finalized On	VAC (Kaki Bukit)								Thumbnail	Print
1	21/03/19 11:04	Accident Statement								Load HTM	
Photos/Images									3 per page		<input checked="" type="checkbox"/>
No	Finalized On	VAC (Kaki Bukit)								Thumbnail	Print
1	21/03/19 11:03	Accident Photo [Linked Accident Report Documents]								Load JPG	<input checked="" type="checkbox"/>
2	21/03/19 11:03	Accident Photo [Linked Accident Report Documents]								Load JPG	<input checked="" type="checkbox"/>
3	21/03/19 11:03	Accident Photo [Linked Accident Report Documents]								Load JPG	<input checked="" type="checkbox"/>
4	21/03/19 11:03	Accident Photo [Linked Accident Report Documents]								Load JPG	<input checked="" type="checkbox"/>
5	21/03/19 11:03	Accident Photo [Linked Accident Report Documents]								Load JPG	<input checked="" type="checkbox"/>
6	21/03/19 11:03	Accident Photo [Linked Accident Report Documents]								Load JPG	<input checked="" type="checkbox"/>
7	21/03/19 11:03	Accident Photo [Linked Accident Report Documents]								Load JPG	<input checked="" type="checkbox"/>
8	21/03/19 11:03	Accident Photo [Linked Accident Report Documents]								Load JPG	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)								Thumbnail	Print
1	06/05/19 18:14	General View								Load JPG	<input checked="" type="checkbox"/>
2	06/05/19 18:14	General View								Load JPG	<input checked="" type="checkbox"/>
3	06/05/19 18:14	General View								Load JPG	<input checked="" type="checkbox"/>
4	06/05/19 18:14	General View								Load JPG	<input checked="" type="checkbox"/>
5	06/05/19 18:14	General View								Load JPG	<input checked="" type="checkbox"/>
6	06/05/19 18:14	General View								Load JPG	<input checked="" type="checkbox"/>
7	06/05/19 18:14	General View								Load JPG	<input checked="" type="checkbox"/>
8	06/05/19 18:14	General View								Load JPG	<input checked="" type="checkbox"/>
9	06/05/19 18:14	General View								Load JPG	<input checked="" type="checkbox"/>
10	06/05/19 18:14	General View								Load JPG	<input checked="" type="checkbox"/>
11	06/05/19 18:14	General View								Load JPG	<input checked="" type="checkbox"/>
12	06/05/19 18:14	General View								Load JPG	<input checked="" type="checkbox"/>
13	06/05/19 18:14	General View								Load JPG	<input checked="" type="checkbox"/>
14	06/05/19 18:14	General View								Load JPG	<input checked="" type="checkbox"/>
15	06/05/19 18:14	General View								Load JPG	<input checked="" type="checkbox"/>
16	06/05/19 18:14	General View								Load JPG	<input checked="" type="checkbox"/>
17	06/05/19 18:14	General View								Load JPG	<input checked="" type="checkbox"/>
18	06/05/19 18:14	General View								Load JPG	<input checked="" type="checkbox"/>
19	06/05/19 18:14	General View								Load JPG	<input checked="" type="checkbox"/>
20	06/05/19 18:14	General View								Load JPG	<input checked="" type="checkbox"/>
21	06/05/19 18:14	General View								Load JPG	<input checked="" type="checkbox"/>
22	06/05/19 18:14	General View								Load JPG	<input checked="" type="checkbox"/>

















Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	VAC (Kaki Bukit)	Thumbnail	Print
23	06/05/19 18:14	General View	 Load JPG	<input checked="" type="checkbox"/>
24	06/05/19 18:14	General View	 Load JPG	<input checked="" type="checkbox"/>
25	06/05/19 18:14	General View	 Load JPG	<input checked="" type="checkbox"/>
26	06/05/19 18:14	General View	 Load JPG	<input checked="" type="checkbox"/>
27	06/05/19 18:14	General View	 Load JPG	<input checked="" type="checkbox"/>
28	06/05/19 18:14	General View	 Load JPG	<input checked="" type="checkbox"/>
29	06/05/19 18:14	General View	 Load JPG	<input checked="" type="checkbox"/>
30	06/05/19 18:14	General View	 Load JPG	<input checked="" type="checkbox"/>
31	06/05/19 18:14	General View	 Load JPG	<input checked="" type="checkbox"/>
32	06/05/19 18:14	General View	 Load JPG	<input checked="" type="checkbox"/>
33	06/05/19 18:14	General View	 Load JPG	<input checked="" type="checkbox"/>
34	06/05/19 18:14	General View	 Load JPG	<input checked="" type="checkbox"/>
35	06/05/19 18:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
36	06/05/19 18:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
37	06/05/19 18:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
38	06/05/19 18:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
39	06/05/19 18:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
40	06/05/19 18:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
41	06/05/19 18:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
42	06/05/19 18:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
43	06/05/19 18:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
44	06/05/19 18:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
45	06/05/19 18:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
46	06/05/19 18:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
47	06/05/19 18:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
48	06/05/19 18:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
49	06/05/19 18:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
50	06/05/19 18:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
51	06/05/19 18:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
52	06/05/19 18:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
53	06/05/19 18:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
54	06/05/19 18:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
55	06/05/19 18:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
56	06/05/19 18:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
57	06/05/19 18:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
58	06/05/19 18:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
59	06/05/19 18:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
60	06/05/19 18:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
61	06/05/19 18:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
62	06/05/19 18:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
63	06/05/19 18:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
64	06/05/19 18:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
65	06/05/19 18:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
66	06/05/19 18:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
67	06/05/19 18:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
68	06/05/19 18:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
69	06/05/19 18:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
70	06/05/19 18:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
71	06/05/19 18:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
72	06/05/19 18:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	VAC (Kaki Bukit)	Thumbnail	Print
73	06/05/19 18:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
74	06/05/19 18:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
75	06/05/19 18:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
76	06/05/19 18:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
77	06/05/19 18:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
78	06/05/19 18:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
79	06/05/19 18:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
80	06/05/19 18:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
81	06/05/19 18:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
82	06/05/19 18:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
83	06/05/19 18:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
84	06/05/19 18:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
85	06/05/19 18:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
86	06/05/19 18:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
87	06/05/19 18:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
88	06/05/19 18:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
89	06/05/19 18:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
90	06/05/19 18:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
91	06/05/19 18:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
92	06/05/19 18:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
93	06/05/19 18:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
94	06/05/19 18:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
95	06/05/19 18:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
96	06/05/19 18:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
97	06/05/19 18:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
98	06/05/19 18:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
99	06/05/19 18:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
100	06/05/19 18:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
101	06/05/19 18:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
102	06/05/19 18:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
103	06/05/19 18:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
104	06/05/19 18:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
105	06/05/19 18:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
106	06/05/19 18:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
107	06/05/19 18:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
108	06/05/19 18:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
109	06/05/19 18:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
110	06/05/19 18:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
111	06/05/19 18:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
112	06/05/19 18:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
113	06/05/19 18:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
114	06/05/19 18:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
115	06/05/19 18:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
116	06/05/19 18:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
117	06/05/19 18:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
118	06/05/19 18:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
119	06/05/19 18:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
120	06/05/19 18:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
121	06/05/19 18:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
122	06/05/19 18:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	VAC (Kaki Bukit)	Thumbnail	Print
123	06/05/19 18:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
124	06/05/19 18:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
125	06/05/19 18:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
126	06/05/19 18:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
127	06/05/19 18:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
128	06/05/19 18:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
129	06/05/19 18:15	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	02/04/19 15:35	pri contact	 Load PDF	<input checked="" type="checkbox"/>
No	Finalized On	VAC (Kaki Bukit)	Thumbnail	Print
1	20/03/19 15:42	Accident Sketch Plan [Linked Accident Report Documents]	 Load TIF	<input type="checkbox"/>
2	20/03/19 15:42	Accident Sketch Plan [Linked Accident Report Documents]	 Load TIF	<input type="checkbox"/>
3	20/03/19 15:42	Accident Sketch Plan [Linked Accident Report Documents]	 Load TIF	<input type="checkbox"/>
4	20/03/19 15:42	Accident Sketch Plan [Linked Accident Report Documents]	 Load TIF	<input type="checkbox"/>
5	20/03/19 15:42	Accident Sketch Plan [Linked Accident Report Documents]	 Load TIF	<input type="checkbox"/>

## Linked Accident Report Documents

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	VAC (Kaki Bukit)	Thumbnail	Print
1	21/03/19 11:04	Accident Statement	 Load HTM	<input type="checkbox"/>
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	VAC (Kaki Bukit)	Thumbnail	Print
1	21/03/19 11:03	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
2	21/03/19 11:03	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
3	21/03/19 11:03	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
4	21/03/19 11:03	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
5	21/03/19 11:03	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
6	21/03/19 11:03	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
7	21/03/19 11:03	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
8	21/03/19 11:03	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	VAC (Kaki Bukit)	Thumbnail	Print
1	20/03/19 15:42	Accident Sketch Plan	 Load TIF	<input type="checkbox"/>
2	20/03/19 15:42	Accident Sketch Plan	 Load TIF	<input type="checkbox"/>
3	20/03/19 15:42	Accident Sketch Plan	 Load TIF	<input type="checkbox"/>
4	20/03/19 15:42	Accident Sketch Plan	 Load TIF	<input type="checkbox"/>
5	20/03/19 15:42	Accident Sketch Plan	 Load TIF	<input type="checkbox"/>

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

**Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)****Show Remarks To:** ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/CT119005150/GCD3E2

Date: 07/06/2019

## REFERENCE

Handling Insurer: China Taiping Insurance  
(Singapore) Pte. Ltd.

Policy No: DMCVSN30490518000

Claimant Vehicle  
No : SLG6953GInsured Vehicle  
No : GBC1851P

Date of Loss: 20/03/2019

Nature of Claim: TP

Claim  
No: SNM19D201267C02

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: SLG6953G

Make &amp; Model: MAZDA 3, 1.5 L 4-DOOR SEDAN SP.6EAT (A)

Engine No: P520369712

Reg. Date: 11/10/2016 (Man. Year: 2016)

Chassis No: JM6BM42A8G0343672

Colour: White

Odometer: 160090 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	CST 6 mm	Rear Left Side:	CST 6 mm
Front Right Side:	CST 6 mm	Rear Right Side:	CST 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

## INSPECTION

Date of Assignment: 02/04/2019

Date Inspected: 22/03/2019 Inspected At:

Euro Success Services Pte Ltd (HQ)  
1 KAKI BUKIT AVENUE 6 #02-03  
AUTOBAY  
Singapore 417883

Estimated Period of Repair: 12.0 days

Adjuster: XING GUO QIANG

Manager: CELINE FONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.  
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$10,000.00 - \$12,000.00

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 06 Jun 2019)
<b>Parts:</b>	143	MAZDA 3 1.5 L 4-DOOR SEDAN SP.6EAT (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SLG6953G)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.



Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.
---

< END OF ESTIMATES >