

AGS REC BY: CS3/AIG19005153/9cd302

ASSIGNMENT (Office)

From Person: Chin lee Yng of AIG Date/Time: 21/3/19 @ 2.36pm

Estimate/Coat: TP WS / TP RES / OD RES / EVA / INV / MYTC5

To Inspect Vehicle No: SJM1113P Insured: SJW 6773Z

at Workshop no.: EM solution Tel: 6456 0226

of 160 Sin Ming Drive #03-18/19

Policy No: 2100873210-04 Claim No: 373227507586

Sum Insured: _____ Excess: _____
Make of Veh: _____ D.O.A: 16/03/2019

(Client's Record) _____
CA / REV / REP. / REV 241185 H.O.D. Endorsement: 22/03/2019 @ Mominer

Date/Time: 3.37pm @ 21/3/19 Person Contacted: Josephine Vehicle IN / OUT

Date/Time	Action/Instruction (*) Estimate
	<u>SJM1113P-X</u>
	<u>SJW 6773Z - CS3/AIG14017290/Agba2</u> <u>D.O.A: 4/9/14</u>
	<u>Dismantle: 22/3/2019</u>
	<u>After repair: 25/3/2019.</u>

...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	22 Mar 2019 Edit Reg		21 Mar 2019 00:00 Edit Adj Rpt				Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	KHOO BOON WEI, DAMIEN (QIU WENWEI, DAMIEN) , ID: S73412571								
Main Claimant:	-								
Vehicle Reg. No.:	SJM1113P	Date of Loss:	16/03/2019 18:00 - :59						
Claim Type:	TP / 3732275075SG	Policy/Cover Note No.:	2100373210-04 (Comprehensive)						
Vehicle Reg. No. (Insured):	SJW6773Z	Policy No. (Claimant):							
		Excess:							
Repairer:	Em Solution Pte Ltd - Sin Ming (HQ) BLK 17 #01-59 SIN MING INDUSTRIAL ESTATE SECTOR A, 575675 Sin Ming - Tel: 6456 0556								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Tan, Bennie-WZ - 6419 1718] Bennie-WZ.Tan@aig.com								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 01/04/2019]								
ASSOCIATED MAIL RECEIVED				View All	Compose Case Mail				
<ul style="list-style-type: none"> AIG_SG (22/03/2019): Request To Upload TP GIA Report AIG_SG (22/03/2019): No OI GIA Report 									
ALL ASSOCIATED TASKS [View All] [Search Tasks] [Create New Task] [Complete]									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

- PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SJW6773Z AND SJM1113P ON 16/03/...

From: Chin, Lee-Ying
To: assignments@lkkauto.com, admin-a@lkkauto.com
Cc: Fong, Andy-SY
Sent: 21/3/2019 2:36:27 PM

Hi LKK,

Kindly assist to survey, vehicle in workshop.

Thanks.

Best Regards
Lee Ying, Chin
AIG
Claims | AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way #08-16 Singapore 079120
Tel +(65) 6419 1947
Lee-Ying.Chin@aig.com | www.aig.sg

From: Sally Chong [mailto:sallychong@visionlawllc.com]
Sent: Tuesday, March 19, 2019 4:44 AM
To: Hor, Yinrul; Azlan, Syazairdina; Chin, Lee-Ying; AIG SGP, Claims-Survey; Lim, Sheng Yang
Cc: EM Solution Pte Ltd; 'Judy Soh'
Subject: OUR REF.: E21-109918.19 (SJM 1113P @ 16.03.2019) // AIG REF.: SJW 6773Z
Importance: High

VERY URGENT

Dear Yinrul,

NOTICE TO INSURERS TO CONDUCT PRE-REPAIR SURVEY WITHIN 2 WORKING DAYS PURSUANT TO PARAGRAPH 2 OF PRE-ACTION PROTOCOL FOR NIMA CASES

CLAIMANT: ROBERT LOH CHEE SENG

ACCIDENT INVOLVING SJM 1113P & SJW6773Z ON 16 MARCH 2019 ALONG YISHUN AVE 5 AT ABOUT 18:50 HRS

We refer to your email of 18 March 2019 and your list of surveyors.

TAKE NOTICE that we object to your surveyor stated in your said List, for appointment as the Single Joint Expert.

Pursuant to Pre-Action Protocol for NIMA cases, we now propose for appointment as Single Joint Expert the following List of Motor Surveyors for your consideration:-

Name of Surveyor	Company Name
Dennis Yap	Pal's Appraiser Pte Ltd
Michael Yap	Mc-coy Appraiser Pte Ltd
Andy Yap	LCW Appraiser Pte Ltd
B J Loi	Par Automotive Consultancy
Sebastian Lim	Constant Appraiser Services
Lee Yew Hok	Constant Appraiser Services
Alan Cheong	CL Appraiser Pte Ltd

Please be informed that the said vehicle can be inspected at:-

Venue : E M SOLUTION PTE LTD
160, Sin Ming Drive, #03-18/19, Sin Ming
Autocity,
Singapore 575722
Contact : Mr. Bernard (Tel.: 6456-0226 / 9101-8302)

If you fail to conduct the pre-repair inspection within the next 2 working days, the said workshop will commence repairs thereafter without further reference to you.

Thank you.

Sally Chong
(Secretary)
VISION LAW LLC
133 NEW BRIDGE ROAD,
#18-01/02, CHINATOWN POINT,
SINGAPORE 059413
TEL.: 6534-2811 (ext 115)
FAX : 6535-6802

From: Hor, Yinrul
Sent: Mon, 18 Mar 2019 08:17:57 +0000
To: 'sallychong@visionlawllc.com'
Cc: Fong, Andy-SY, Chin, Lee-Ying, Kaur, Baljit, Abu Kassim, Noor Mariesa, Azlan, Syazairdina, Chan, Yoke Shi, Lim, Sheng Yang, Mithoosingh, Aashweenjeetkaur
Subject: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SJW6773Z AND SJM1113P ON 16/03/2019

Without Prejudice

Your Reference : E21-MISC.19

Our Reference : SJW6773Z

Dear Sir/Madam,

We refer to your Notice of Accident of even date.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert:

Name of Surveyor	Company Name
AIG In House Surveyor	AIG Asia Pacific Insurance Pte Ltd
Lawrence Ng Chun Kee	Priority Services
Jeffrey Ong Leng Kiat	Priority Services
Jimmy Lee	Priority Services
EC Looi	Automobile Inspection Services Pte Ltd
Pang Kiah Keen (Frankie)	Formteam Adjusters Pte Ltd
Ng You Han	Formteam Adjusters Pte Ltd
Soon HanXin (Gary)	Formteam Adjusters Pte Ltd
Chow Bo Xiong	Formteam Adjusters Pte Ltd
Chua Soo Teck (Benjamin)	Formteam Adjusters Pte Ltd
Kalvin Ang	LKK Auto Consultants Pte Ltd
Xing Guo Qiang	LKK Auto Consultants Pte Ltd
Marcus Chua	LKK Auto Consultants Pte Ltd
Mohamad Taufikh	LKK Auto Consultants Pte Ltd
Adrian Ling	LKK Auto Consultants Pte Ltd
Mohammed Rasul	LKK Auto Consultants Pte Ltd
Kenneth Kong	LKK Auto Consultants Pte Ltd

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select one or more of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Thanks & Regards,

Yin Rul, Hor (Viviane)

AIG

Claims Adjuster II, Singapore FNOL, Claims Operations – Auto

Shared Services – Malaysia | Global Business Services

Yinrul.Hor@aig.com | www.aig.sg

From: Sally Chong [<mailto:sallychong@visionlawllc.com>]
Sent: Monday, 18 March, 2019 4:01 PM
To: Yinrul.Hor@aig.com; 'Azlan, Syazairdina'; Lee-Ying.Chin@aig.com; AIGSGP_ClaimsSurvey@aig.com; 'Lim, Sheng Yang'
Cc: 'EM Solution Pte Ltd'; 'Leong, Kah Yin'; 'Hassim, Mohd Fitri'; 'Abu Kassim, Noor Mariesa'; 'Md Ishak, Mohd Imran'; judysoh@visionlawllc.com
Subject: RE: OUR REF.: E21-MISC.19 (SJM 1113P @ 16.03.2019) // AIG REF.: SJW 6773Z
Importance: High

VERY URGENT

Dear Sir,

NOTICE TO INSURERS TO CONDUCT PRE-REPAIR SURVEY WITHIN 2 WORKING DAYS PURSUANT TO PARAGRAPH 2 OF PRE-ACTION PROTOCOL FOR NIMA CASES

CLAIMANT: ROBERT LOH CHEE SENG

ACCIDENT INVOLVING SJM 1113P & SJW6773Z ON 16 MARCH 2019 ALONG YISHUN AVE 5 AT ABOUT 18:50 HRS

We are instructed by **ROBERT LOH CHEE SENG** to notify you of a road traffic accident **ON 16 MARCH 2019 ALONG YISHUN AVE 5 AT ABOUT 18:50 HRS** involving our client's vehicle registration number **SJM 1113P** and vehicle registration number **SJW 6773Z** driven by you/your insured at the material time.

As a result of the accident, our client's vehicle has been damaged. Before our client proceed to repair the damaged vehicle, please let us know within 2 working days of your receipt of this notice whether you or your insurers would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without reference to you.

Thank you.

Sally Chong

(Secretary)
VISION LAW LLC
133 NEW BRIDGE ROAD,
#18-01/02, CHINATOWN POINT,
SINGAPORE 059413
TEL: 6534-2811 (ext 115)
FAX : 6535-6802

C.c.: VEHICLE OWNER OF SJW 6773Z
KHOO BOON WEI DAMIEN
503, Canberra Drive,
#03-10,
Singapore 768125

VISION LAW LLC
Advocates & Solicitors
(Incorporated with limited liability)
Unique Entity No. 200721148H
Head Office: 133 New Bridge Road #18-01/02 Chinatown Point, Singapore 059413
Branch: 490 Lorong 6 Toa Payoh #03-11 HDB Hub (Biz 3 Lobby 1), Singapore 310490

DISCLAIMER:

The contents of this email (including any attachments) are confidential and privileged and only intended for the recipient(s) addressed above. If you received this email by error, please notify the sender immediately and destroy it (and all attachments) without reading, storing and/or disseminating any of its contents (in any form) to any person. Email communication is not secure. Vision Law LLC is not liable for any losses arising out of any errors or omissions in the contents resulting from email transmission or any illegal or unauthorised usage or tampering of its email system.

VISION LAW LLC
Advocates & Solicitors
(Incorporated with limited liability)
Unique Entity No. 200721148H
Head Office: 133 New Bridge Road #18-01/02 Chinatown Point, Singapore 059413
Branch: 490 Lorong 6 Toa Payoh #03-11 HDB Hub (Biz 3 Lobby 1), Singapore 310490

DISCLAIMER:

The contents of this email (including any attachments) are confidential and privileged and only intended for the recipient(s) addressed above. If you received this email by error, please notify the sender immediately and destroy it (and all attachments) without reading, storing and/or disseminating any of its contents (in any form) to any person. Email communication is not secure. Vision Law LLC is not liable for any losses arising out of any errors or omissions in the contents resulting from email transmission or any illegal or unauthorised usage or tampering of its email system.

VISION LAW LLC
Advocates & Solicitors
(Incorporated with limited liability)
Unique Entity No. 200721148H
Head Office: 133 New Bridge Road #18-01/02 Chinatown Point, Singapore 059413
Branch: 490 Lorong 6 Toa Payoh #03-11 HDB Hub (Biz 3 Lobby 1), Singapore 310490

DISCLAIMER:

The contents of this email (including any attachments) are confidential and privileged and only intended for the recipient(s) addressed above. If you received this email by error, please notify the sender immediately and destroy it (and all attachments) without reading, storing and/or disseminating any of its contents (in any form) to any person. Email communication is not secure. Vision Law LLC is not liable for any losses arising out of any errors or omissions in the contents resulting from email transmission or any illegal or unauthorised usage or tampering of its email system.

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

> [Back to OneMotoring](#)

Enquire Transfer Fee

Vehicle Details			
Vehicle No. :	SJM1113P		
Vehicle Type :	Z11 - Private Hire (Chauffeur) Station Wagon/Jeep/Land Rover		
Vehicle Attachment 1 :	No Attachment		
Vehicle Scheme :	Normal		
Vehicle Make :	HONDA		
Vehicle Model :	SHUTTLE HYBRID 1.5X AUTO		
Chassis No. :	GP71117796		
Propellant :	Petrol-Electric		
Engine No. :	LEB6321917		
Motor No. :	H13622186		
Engine Capacity :	1496 cc		
Power Rating :	22.0 kW		
Maximum Power Output :	101.0 kW (135 bhp)		
Maximum Laden Weight :	1465 kg		
Unladen Weight :	1190 kg		
Year Of Manufacture :	2017		
Original Registration Date :	13 Nov 2017		
Lifespan Expiry Date :	-		
COE Category :	B - Car above 1600cc or 97kW (130bhp)		
Quota Premium :	\$49,996.00		
COE Expiry Date :	12 Nov 2027		
Road Tax Expiry Date :	12 Nov 2019		
PARF Eligibility Expiry Date :	12 Nov 2027		
Inspection Due Date :	12 Nov 2020		
Intended Transfer Date :	02 Apr 2019		
CO2 Emission :	86.00 (g/km)		
CEV/VES Rebate Utilised Amount :	\$18,783.00		
CO Emission :	-		
HC Emission :	-		
NOx Emission :	-		
PM Emission :	-		
Late renewal fee(s) will be imposed if road tax / lay up has expired. Please use Enquire Road Tax Payable for fee(s) payable.			
Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.			
Amount Payable			
	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee :	25.00	-	25.00
Total Amount Payable :			25.00

You may print this page for reference.

OK

Print

> [Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	1740D
Vehicle Details	
Vehicle No.:	SJM1113P
Vehicle to be Exported:	No
Intended Deregistration Date:	02 Apr 2019
Vehicle Make:	HONDA
Vehicle Model:	SHUTTLE HYBRID 1.5X AUTO
Primary Colour:	White
Manufacturing Year:	2017
Engine No.:	LEB6321917
Chassis No.:	GP71117796
Maximum Power Output:	101.0 kW (135 bhp)
Open Market Value:	\$22,702.00
Original Registration Date:	13 Nov 2017
First Registration Date:	13 Nov 2017
Transfer Count:	0
Actual ARF Paid:	\$5,000.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	12 Nov 2027
PARF Rebate Amount:	\$3,750.00
Intended COE Rebate Details	
COE Expiry Date:	12 Nov 2027
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$49,996.00
COE Rebate Amount:	\$43,052.00
Total Rebate Amount:	\$46,802.00

The information contained herein is correct as at 02 Apr 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	18/03/2019 17:19
Date Of Accident	16/03/2019 18:50
Exact Location Of Accident	YISHUN AVE 5
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJM1113P
Insured/Policyholder	
Name Of Registered Owner	LOH CHEE SENG ROBERT
NRIC No	S1471740D
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-93808218
Alternative Phone No	OFFICE-93808218

Vehicle Particulars

Manufacturer	HONDA
Model	SHUTTLE
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

Insurance Company

Name of Insurance Company	GREAT EASTERN GENERAL INSURANCE LIMITED
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	2018-V0102704-VDP-R001
Cover Note Number	

Driver

Name of Driver	LOH CHEE SENG ROBERT
NRIC No	S1471740D
Date Of Birth	18/07/1967
Occupation	INDOOR
Date Of Driving Pass	16/07/1983
Driving Experience	35 YEARS AND 8 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-93808218
Fax Number	
Contact Number	OFFICE-93808218
EEmail Address	NOEMAIL

Address	BLK 108 GERALD DRIVE #01-18
Postcode	799035
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : JUNAINAH BINTE JASMIN
	GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE REFER TO SKETCH PLAN.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJW6773Z
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	KHOO BOON WEI DAMIEN
NRIC/Passport Number	S7341257I
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My Insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my Insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.




Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.: 143034

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer Attachment

Report at when work stop -

DECLARATION

I/We declare the foregoing particulars are true in every respect.



Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:



Reporting Centre Personnel's Signature

Name:
NRIC/FIN No.: 1813032

Accident along Yishun Ave 5 and Yishun Ring Road (16 March 2019 - 1850 Hrs)



I stopped along Yishun Ave 5 at the traffic light, waiting to turn right onto Yishun Ring Road and was waiting for the lights to turn green.

SJW 6773Z driven by Mr Khoo Boon Wei Damien, S7341257I, suddenly hit into the back of my car, SJM1113P driven by myself, Robert Loh Chee Seng, S1471740D. This cause the back and bumper of SJM1113P to be dented.

Mr Khoo then insisted to claim against his insurance. The whole incident was witness by Miss Junainah Binte Jasmin who was my passenger in my car at the moment of impact. She has also agreed to be my witness if needed.

Also attached a thumb drive of the whole accident for your perusal.

Driver of SJW6773Z



Driver of SJM1113P



Witness (Passenger in my car)



Cars Pixs



(01) Bent (2) Dented (3) Distorted (4) Cracked (5) Cut (6) Scratched
 (07) Deformed (08) Shifted (09) Buckled (10) Broken (11) Necessary
 (12) Missing (13) Torn (14) Unconfirmed (15) Not Working

MOTORCAR (Rear)

(1) Replace (✓) (2) Repair (0) (3) Check (0)
 (4) Not Consistent (NC)

Vehicle No: **SJM 113P**

Rear Portion

NAC	INC	Item	CON	AC	Qty
1137	993626	Rear Number Plate			
1138	993627	Rear Number Plate Base			
1139	993630	Rear Number Plate Garnish			
1140	993632	Rear Number Plate Lamp			
1141	992958	Rear Bumper	re	/	
1142	993085	Rear Bumper Upper			
1143	993017	Rear Bumper Lower			
1144	993054	Rear Bumper Side			
1145	993103	Rear Bumper Tow Cover			
1146	992341	Rear Bumper Clips	re	/	
1147	992976	Rear Bumper Bracket			
1148	993068	Rear Bumper Side Retainer			
1149	993045	Rear Bumper Reinforcement			
1150	992970	Rear Bumper Beam			
1151	993077	Rear Bumper Sponge			
1152	992999	Rear Bumper Damper			
1153	993040	Rear Bumper Protector			
1154	993036	Rear Bumper Pad			
1155	993026	Rear Bumper Moulding			
1156	993044	Rear Bumper Reflector			
1157	993023	Rear Bumper Lower Spoiler			
1158	994023	Reverse Sensor	short	Repair	
1159	993327	Rear End Panel			
1160	993339	Rear End Panel Top Garnish			
1161	993333	Rear End Panel Inner Trim			
1162	990333	Boot Compartment Inner Trim			
1163	993851	Rear LH Taillamp			
1164	993853	Rear LH Taillamp Garnish			
1165	993859	Rear LH Taillamp Panel			
1166	995116	Rear RH Taillamp			
1167	993853	Rear RH Taillamp Garnish			
1168	993859	Rear RH Taillamp Panel			
1169	993554	Rear Apron Panel			
1170	992895	Bootlid			
1171	991328	Bootlid Emblem			
1172	990356	Bootlid Handle			
1173	995250	Bootlid Moulding			
1174	990376	Bootlid Reflector			
1175	995222	Bootlid Lamp LH			
1176	992899	Bootlid Lamp RH			
1177	995243	Bootlid Lock			
1178	990377	Bootlid Rubber			
1179	990382	Bootlid Hinge			
1180	993877	Bootlid Spoiler			
1181	994543	Tailgate	buc	/	
1182	991328	Tailgate Emblem	re	/	3
1183	994643	Tailgate Outer Handle			
1184	994640	Tailgate Moulding			
1185	994545	Tailgate Garnish			
1186	994648	Tailgate Reflector			
1187	994549	Tailgate Lamp			
1188	994646	Tailgate Protector			
1189	994676	Tailgate Wiper Arm			
1190	994677	Tailgate Wiper Blade			
1191	994679	Tailgate Wiper Nozzle			
1192	994555	Tailgate Wiper Motor			
1193	994602	Tailgate Glass			
1194	994606	Tailgate Glass Rubber			
1195	994604	Tailgate Glass Moulding	re	/	
1196	994607	Tailgate Glass Sealant	re	/	
1197	994629	Tailgate Lock			
1198	994651	Tailgate Rubber			
1199	994611	Tailgate Hinge			
1200	994594	Tailgate Damper			
1201	994613	Tailgate inner Board			

NAC	INC	Item	CON	AC	Qty
1202	993784	Spare Tyre Board			
1203	994328	Spare Tyre Panel			
1204	995065	Spare Tyre			
1205	994326	Spare Tyre Lock Screw			
1206	993787	Spare Tyre Cover			
1207	995323	Triangle Breakdown Sign			
1208	990507	CD Changer Assy			
1209	990164	Antenna			
1210	990534	Centre Exhaust Pipe Assy			
1211	990532	Centre Exhaust Mounting			
1212	993364	Rear Exhaust Pipe			
1213	993357	Rear Exhaust Chrome Pipe			
1214	993361	Rear Exhaust Mounting			
1215	993358	Rear Exhaust Heat Shield			
1216	995223	Rear LH Chassis Member			
1217	993165	Rear RH Chassis Member			
1218	993436	Rear LH Fender			
1219	993449	Rear LH Fender Protector			
1220	993420	Rear LH Fender Inner Panel			
1221	993431	Rear LH Fender Inner Trim			
1222	993415	Rear LH Fender Inner Garnish			
1223	993425	Rear LH Fender Inner Shield			
1224	993621	Rear LH Mudflap			
1225	993933	Rear LH Wheel Rim			
1226	994025	Rear LH Rim Cover			
1227	995065	Rear LH Tyre			
1228	993456	Rear RH Fender			
1229	993450	Rear RH Fender Protector			
1230	993420	Rear RH Fender Inner Panel			
1231	993431	Rear RH Fender Inner Trim			
1232	993415	Rear RH Fender Inner Garnish			
1233	993425	Rear RH Fender Inner Shield			
1234	993622	Rear RH Mudflap			
1235	993934	Rear RH Wheel Rim			
1236	994025	Rear RH Rim Cover			
1237	995065	Rear RH Tyre			
1238	995162	Rear Fender Extension Panel LH			
1239	993401	Rear Fender Extension Panel RH			
1240	993430	Rear Fender Inner Top Garnish			
1241	993673	Rear Fender 1/4 Glass			
1242	993452	Rear Fender 1/4 Glass Rubber			
1243	993453	Rear Fender 1/4 Glass Sealant			
1244	993949	Rear Windscreen Glass			
1245	993976	Rear Windscreen Rubber			
1246	993961	Rear Windscreen Moulding			
1247	993955	Rear Windscreen Sealant			
1248	994729	Third Brake Light			
1249	993385	Rear Fender Air Grille			
1250	992167	Fuel Lid			
1251	992168	Fuel Neck			
1252	992179	Fuel Tank			
1253	992184	Fuel Tank Bracket			
1254	992191	Fuel Tank Float			
1136	990247	Sticker			

[Handwritten signature]
 4 Days
 2/7/2019

No of Items: _____ Assessor: _____

original copy

...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	22 Mar 2019 Edit Reg		21 Mar 2019 00:00 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	KHOO BOON WEI, DAMIEN (QIU WENWEI, DAMIEN), ID: S73412571								
Main Claimant:	-								
Vehicle Reg. No.:	SJM1113P	Date of Loss:	16/03/2019 18:00 - :59 [16 Months and 3 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 3732275075SG	Policy/Cover Note No.:	2100373210-04 (Comprehensive)						
Vehicle Reg. No. (Insured):	SJW6773Z	Policy No. (Claimant):							
		Excess:							
Repairer:	Em Solution Pte Ltd - Sin Ming (HQ) BLK 17 #01-59 SIN MING INDUSTRIAL ESTATE SECTOR A, 575675 Sin Ming - Tel: 6456 0556								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Tan, Bennie-WZ - 6419 1718] Bennie-WZ.Tan@aig.com								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 01/04/2019]								
ASSOCIATED MAIL RECEIVED				View All	Compose Case Mail				
<ul style="list-style-type: none"> AIG_SG (22/03/2019): Request To Upload TP GIA Report AIG_SG (22/03/2019): No OI GIA Report 									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SJM1113P (3732275075SG)**
[SJW6773Z]
TP

Mar 16 2019 6:55PM
[KHOO BOON WEI, DAMIEN (QIU WENWEI, DAMIEN)]
Em Solution Pte Ltd - Sin Ming

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View		View in Browser	
Video															1 per page		<input checked="" type="checkbox"/>	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)										Thumbnail		Print				
1	01/07/19 11:25	TP Video - Accident										Load MP4						
Photos/Images															3 per page		<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)										Thumbnail		Print				
1	25/03/19 14:32	General View										Load JPG		<input checked="" type="checkbox"/>				
2	25/03/19 14:32	General View										Load JPG		<input checked="" type="checkbox"/>				
3	25/03/19 14:32	General View										Load JPG		<input checked="" type="checkbox"/>				
4	25/03/19 14:32	General View										Load JPG		<input checked="" type="checkbox"/>				
5	25/03/19 14:32	General View										Load JPG		<input checked="" type="checkbox"/>				
6	25/03/19 14:32	General View										Load JPG		<input checked="" type="checkbox"/>				
7	25/03/19 14:32	General View										Load JPG		<input checked="" type="checkbox"/>				
8	25/03/19 14:32	General View										Load JPG		<input checked="" type="checkbox"/>				
9	25/03/19 14:32	General View										Load JPG		<input checked="" type="checkbox"/>				
10	25/03/19 14:32	General View										Load JPG		<input checked="" type="checkbox"/>				
11	25/03/19 14:32	General View										Load JPG		<input checked="" type="checkbox"/>				
12	25/03/19 14:32	General View										Load JPG		<input checked="" type="checkbox"/>				
13	25/03/19 14:32	General View										Load JPG		<input checked="" type="checkbox"/>				
14	25/03/19 14:32	General View										Load JPG		<input checked="" type="checkbox"/>				
15	25/03/19 14:32	General View										Load JPG		<input checked="" type="checkbox"/>				
16	25/03/19 14:32	General View										Load JPG		<input checked="" type="checkbox"/>				
17	25/03/19 14:32	General View										Load JPG		<input checked="" type="checkbox"/>				
18	25/03/19 14:32	General View										Load JPG		<input checked="" type="checkbox"/>				
19	25/03/19 14:32	General View										Load JPG		<input checked="" type="checkbox"/>				
20	25/03/19 14:32	General View										Load JPG		<input checked="" type="checkbox"/>				
21	25/03/19 14:32	General View										Load JPG		<input checked="" type="checkbox"/>				
22	25/03/19 14:32	General View										Load JPG		<input checked="" type="checkbox"/>				
23	25/03/19 14:32	General View										Load JPG		<input checked="" type="checkbox"/>				
24	25/03/19 14:32	General View										Load JPG		<input checked="" type="checkbox"/>				
25	25/03/19 14:32	General View										Load JPG		<input checked="" type="checkbox"/>				
26	25/03/19 14:32	General View										Load JPG		<input checked="" type="checkbox"/>				
27	25/03/19 14:32	General View										Load JPG		<input checked="" type="checkbox"/>				
28	25/03/19 14:32	General View										Load JPG		<input checked="" type="checkbox"/>				
29	25/03/19 14:32	General View										Load JPG		<input checked="" type="checkbox"/>				
30	25/03/19 14:32	General View										Load JPG		<input checked="" type="checkbox"/>				
31	25/03/19 14:32	General View										Load JPG		<input checked="" type="checkbox"/>				
32	25/03/19 14:32	General View										Load JPG		<input checked="" type="checkbox"/>				
33	25/03/19 14:32	General View										Load JPG		<input checked="" type="checkbox"/>				
34	25/03/19 14:32	General View										Load JPG		<input checked="" type="checkbox"/>				

Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
				<input checked="" type="checkbox"/>
35	25/03/19 14:32	General View	Load JPG	<input checked="" type="checkbox"/>
36	25/03/19 14:33	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
37	25/03/19 14:33	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
38	25/03/19 14:33	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
39	25/03/19 14:33	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
40	25/03/19 14:33	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
41	25/03/19 14:33	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
42	02/07/19 15:07	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
43	02/07/19 15:07	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
44	02/07/19 15:07	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
45	02/07/19 15:07	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
46	02/07/19 15:07	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
47	02/07/19 15:07	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
48	02/07/19 15:07	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
49	02/07/19 15:07	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
50	02/07/19 15:07	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
51	02/07/19 15:07	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
52	02/07/19 15:07	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
53	02/07/19 15:07	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
54	02/07/19 15:07	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
55	02/07/19 15:07	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
56	02/07/19 15:07	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
57	02/07/19 15:07	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
58	02/07/19 15:07	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
59	02/07/19 15:07	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
60	02/07/19 15:07	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
61	02/07/19 15:07	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
62	02/07/19 15:07	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
63	02/07/19 15:07	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
64	02/07/19 15:07	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
65	02/07/19 15:07	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
66	02/07/19 15:07	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
67	02/07/19 15:07	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
68	02/07/19 15:07	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
69	02/07/19 15:07	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	02/04/19 12:31	E-filed GIA report	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			

Show Remarks To: Handling Insurer
Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG19005153/GCD3E2

Date: 02/07/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100373210-04
Claimant Vehicle No : SJM1113P **Insured Vehicle No :** SJW6773Z
 Date of Loss: 16/03/2019 Nature of Claim: TP Claim No: 3732275075SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJM1113P**
 Make & Model: HONDA SHUTTLE HYBRID, 1.5 (A) Engine No: LEB6321917
 Reg. Date: 13/11/2017 (Man. Year: 2017) Chassis No: GP71117796
 Colour: White Odometer: 87371 km
 Engine Capacity: 1496 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/50Z R16 Rear Tyre Size: 205/50Z R16
 Front Left Side: APLUS 6 mm Rear Left Side: APLUS 6 mm
 Front Right Side: APLUS 6 mm Rear Right Side: APLUS 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 21/03/2019
 Date Inspected: 22/03/2019 Inspected At: Em Solution Pte Ltd - Sin Ming (HQ)
 160 SIN MING DRIVE #03-18/19
 SIN MING AUTOCITY
 SINGAPORE 575722
 Estimated Period of Repair: 4.0 days

Adjuster: XING GUO QIANG

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*REAR BUMPER	Deformed	0.00 F	*- F	
2	1		*REAR BUMPER CLIPS	Necessary	0.00 F	*- F	
3	1		*REVERSE SENSOR	Shorted	0.00 F	*- F	
4	1		*REAR END PANEL	Repair	0.00 F	*- F	
5	1		*TAILGATE	Buckled	0.00 F	*- F	
6	3		*TAILGATE EMBLEM	Necessary	0.00 F	*- F	
7	1		*TAILGATE GLASS MOULDING	Necessary	0.00 F	*- F	
8	1		*TAILGATE GLASS SEALANT	Necessary	0.00 F	*- F	
					Total Parts (S\$)	0.00	0.00

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >