



ComfortDelGro Engineering

320 UBI ROAD 3 SINGAPORE 408649

ACCIDENT REPAIR ESTIMATESTP A16.
Khanchai.

Our Ref:

Type of Claim : 3RD PARTYVehicle No. : FZ856AMake & Model : HONDA CB400M

Year of Manufacture : _____

Chassis No. : _____

Engine No. : _____

Policy No. : _____

Time of Accident : _____

Ins Company : _____

Excess : _____

Date of Accident : _____

Suggested Days of Repair : _____

In-house Vehicle Assessor**Repair Estimates**

Case Owner : _____

Signature : _____

Contact No

68438723 - SAHARAN

68438736-SAHARAN / JASMINE CHNG

Parts (a) Cost / List Price Items \$-

Plus/Less \$-

Total of Cost / List \$-

(b) Nett Price Items \$-

Less

Total of Nett Item

(c) Special Nett Items \$2,380.00

Total Parts Cost (Appendix A) \$2,380.00

Labour (Appendix B) \$260.00

Total Repair Cost \$2,640.00

The above total will be subjected to 7% G.S.T.

Name of Surveyor : AdrianCompany : LICKSurvey conducted on : 27/03/19at 5:30pm**Remarks By Surveyor**(a) The repair of this vehicle is authorized / is not authorized until further notice.(b) Recommended Days of Repair : 03 day(s)(c) Resurvey : Required / Not Required

(d) Excess : \$

(e) Signature of surveyor : [Signature]

Date:

Spark Car Care

ComfortDelGro Engineering Pte Ltd
320 UBI ROAD 3 SINGAPORE 408649
TEL : 68438723/68438736 Fax: 67436072

Spare Parts

Vehicle No : FZ666A Case Owner : 0
Make & Model : HONDA CB400M Year Manufacture : 0
Chassis No : 0 Engine No : 0
Sales Order : _____ Supplier : _____
Order By : _____ Type of Claim : 3RD PARTY

S/No	Part Description	QTY	Cost Price	List Price	Nett Price	S/N	Disposition By Surveyor
1	CUSTOMISED CRASH BAR <i>Bent</i>	1				\$850.00	700
2	CUSTOMISED REAR CRASH BAR - LEFT <i>Bent</i>	1				\$320.00	250
3	REAR SADDLE BAG - LEFT <i>New</i>	1				\$720.00	*
4	SADDLE BAG COVER - LEFT <i>Del</i>	1				\$370.00	✓
5	3M REFLECTIVE STICKER <i>New</i>	2				\$120.00	✓
6	0	0					
7	0	0					
8	0	0					
9	0	0				1440 (S/N)	
10	0	0					
11	0	0					
12	0	0					
13	0	0					
14	0	0					
15	0	0					
16	0	0					
17	0	0					
18	0	0					
19	0	0					
20	0	0					
21	0	0					
22	0	0					
23	0	0					
24	0	0					
25	0	0					
26	0	0					
27	0	0					
28	0	0					
29	0	0					
30	0	0					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

ComfortDelGro Engineering Pte Ltd
320 UBI ROAD 3 SINGAPORE 408649
Tel: 68438723/68438736 FAX : 67436072

Vehicle No. : FZ656A Case Owner : 0
Make & Model : HONDA CB400M Year of Manufacture : 0

[illegible]

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.