

<< Service Request Details

Claim	S9M01HOK
Reference	CC4/ASM19005156/Kpa3q2 
Loss Date	19 March 2019
Report Date	21 Mar 2019 10:28:10 AM
Request Date	21 March 2019
Due Date	
Vendor Name	LKK AUTO CONSULTANTS PTE LTD (TP)
Type of Loss	Third Party Vehicle Damage
Services	Pending verification - Direct Settlement

Actions

Next Step Wait for: Approve invoice

Add Invoice

Vehicle Information

Incident Vehicle YN7166P
Registration #

Make TPVD

Model MITSUBISHI

Service Address

...

Primary Contact/Insured

TOP-MIX CONCRETE PTE LTD
29 INTERNATIONAL BUSINESS PARK, #08-05/06,
ACER BUILDING TOWER B, 609923, Singapore
63380083

Claim Handler

TAN Jas
6568804844
jas.tan@axa.com.sg

Additional Instructions K KIM HIN VIRTUAL ACC Please do not finalise repair

Messages Invoices History Documents Assessment Metrics Notes

Document Type Document SubType

Upload Documents

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
 ASM-LKKInvoice1 (1)-AC2004800.pdf	Invoice	Surveyor/ Assessor expense	LKK AUTO CONSULTANTS PTE LTD (TP)	15 July 2020

NAME	TYPE	SUB-TYPE	AMOUNT	DATE
 LKKInspection.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	15 July 2020
 LKKAdjustment1a (1).pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	15 July 2020
 Email to TP.pdf	Letters and Correspondence	Third Party	LKK AUTO CONSULTANTS PTE LTD (TP)	17 June 2020
 LKK Survey Photos.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	17 June 2020
 TP ESTIMATE-MARKED.pdf	Reports & Statement	Estimate / Quotation	LKK AUTO CONSULTANTS PTE LTD (TP)	1 April 2019
 TP KKIM HIN-PRI FROM WORKSHOP WITH TP GIA YN7166P.msg	Letters and Correspondence	Workshop	KUMAR Shailendra	21 March 2019
 WC8141K INS.PDF	Reports & Statement	GIA Report	KUMAR Shailendra	21 March 2019
 GBC7216J TP.PDF	Reports & Statement	GIA Report	KUMAR Shailendra	21 March 2019
 TP KKIM HIN-EMAIL FROM WORKSHOP.msg	Letters and Correspondence	Workshop	DHIWAR Namrata	21 March 2019