

22/03/2012

ASS. REC. BY:

REF: CS3/MSG19005167/Ecd3/2

Special Instruction:

Surveyor: SteveASSIGNMENT (Office)From (Person): Monica Chung Pei Zhen of MSIG Date/Time: 21.3.19 16.50 p.m

Estimated Cost: _____ Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SKR 7014P Insured: SLE 8828Hat Workshop m/s Jementah motor works Tel: 92996636of 14 Dafu Lane 10 #01-406Policy No: A28770069 MCX Claim No: 587841

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 16.3.2019
(Client's Record)CA / REV / REP. / REV 24 HRS "Wp" H.O.D. Endorsement: _____Date/Time: 22.3.19 9.15 a.m Person Contacted: AN chuan Vehicle (IN) OUT

Date/Time	Action/Instruction	Estimate (X)
	SKR 7014P - X	
	SLE 8828H - X	
	Dismantle: 28/3/2019	

Steve

REF:

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop n/s: _____
 of: _____
 Insured: _____
 Policy No: _____
 Claims No: _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S
X	X

Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lump Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: **SKR 7014P** Yr Regn: **15/08/19**
 Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: **Nissan Qashqai** CC: **1997**
 Colour: **White** A/C: _____ Insured / Std / NI / NA
 Sp. Reading: **79730** T/Radin: Insured / Std / NI / NA
 Eng/No: _____
 C/No: **MR707841 7A** KJ **90705743**
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Order / Jammed / Leaked / Burnt or
 Brake: Order / Jammed / Leaked / Burnt or
 Mod: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: **215/60R17**
 R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or

Front: _____ Rear: _____
 R/Bal. **7** mm R/Bal. **7** mm
 L/Bal. **7** mm L/Bal. **7** mm
 D.O.A. **16/3/19** D.O.I. **22/3/19**

Survey held at **Jemilah Mdn**
 Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

PRS

Repair charge 6K - 7K, 7 days

27/3/2019

Date/Time, File Pass to?

☐

: Prel. Report

4)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: **7**

Resurvey No. of Trip: **1**

Survey Fee:

Transportation

) S + R: \$

) Photos

) Other

130

Report Format: **PRS**

Lump Sum / I.B.L. (\$) _____

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

120
10
130

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	18 Mar 2019		21 Mar 2019 16:50 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS									
Insured:		AUTOMATE GEUNINE PARTS PTE LTD , Co. Reg. No.: 200815448D, Tel: +6596610227 [Created by insurer]							
Main Claimant:		TREGOLD JAMIE PAUL , ID: S8287461E							
Vehicle Reg. No.:		SKR7014P	Date of Loss:	16/03/2019 13:00 - :59 [115 Months and 1 Days From LTA Reg Date (Man Yr)]					
Claim Type:		TP / 587841	Policy/Cover Note No.:	A28770069MCX (Comprehensive) Coverage: 15/06/2018 - 14/06/2019					
Vehicle Reg. No. (Insured):		SLE8828H	Policy No. (Claimant):						
		Excess:	S\$1,000.00						
Repairer:		Jementah Motor Works (HQ) 14 Defu Lane 10, #01-406, 539195 Defu Lane - Tel: 92996636							
Handling Insurer:		MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Monica Chung Pei Zhen - 6594 2552]							
Adjuster:		LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 22/03/2019]							
Driver/Custodian (Insured):		PALLANIAPPAN CHANDRAN (), NRIC: S7018828G Email:							
Adj Asg. Remarks:		LIAB 100% SJE DISAGREE APPOINT LKK. PLS CONTACT MR AH CHUAN @ 9299 6636							
ASSOCIATED MAIL RECEIVED									
			View All	Compose Case Mail					
There are no mail for this case.									
ALL ASSOCIATED TASKS									
		View All	Search Tasks	Create New Task	Complete				
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	7461E
Vehicle Details	
Vehicle No.:	SKR7014P
Vehicle to be Exported:	No
Intended Deregistration Date:	25 Mar 2019
Vehicle Make:	NISSAN
Vehicle Model:	QASHQAI PREMIUM 2.0L SMT ABS D/AB HID SR
Primary Colour:	White
Manufacturing Year:	2008
Engine No.:	MR20730417A
Chassis No.:	KJ10205743
Maximum Power Output:	101.0 kW (135 bhp)
Open Market Value:	\$29,951.00
Original Registration Date:	15 Aug 2009
First Registration Date:	15 Aug 2009
Transfer Count:	1
Actual ARF Paid:	\$29,951.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	14 Aug 2019
PARF Rebate Amount:	\$14,975.00
Intended COE Rebate Details	
COE Expiry Date:	14 Aug 2019
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$18,189.00
COE Rebate Amount:	\$704.00
Total Rebate Amount:	\$15,679.00

The information contained herein is correct as at 25 Mar 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 18/03/2019 09:49
Date Of Accident 16/03/2019 13:20
Exact Location Of Accident GRANGE ROAD
Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number SKR7014P

Insured/Policyholder

Name Of Registered Owner TREGOLD JAMIE PAUL
NRIC No S8287461E
Email Address JAMIETREDGOLD@HOTMAIL.COM
Mobile Phone No (LOCAL) +65-96752504
Alternative Phone No OTHERS-97235551

Vehicle Particulars

Manufacturer NISSAN
Model QASHQAI PREMIUM 2.0L SMT ABS D/AB HID SR
Exact Purpose for which vehicle was being used at time of accident
Are you claiming under your own insurance policy for repair to your vehicle? NO
If No, Please state action to be taken THIRD PARTY
Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company AXA INSURANCE PTE LTD
Type Of Coverage COMPREHENSIVE
Fleet Policy NO
Policy Number GA252197/1
Cover Note Number

Driver

Name of Driver EMILIA RUTH LAW
NRIC No S8368459C
Date Of Birth 20/04/1983
Occupation INDOOR
Date Of Driving Pass 04/08/2015
Driving Experience 3 YEARS AND 7 MONTHS
Gender FEMALE
Mobile Number (LOCAL) +65-97235551
Fax Number
Contact Number
Email Address EMILIATREGOLD@GMAIL.COM

Address	261 RIVER VALLEY ROAD #06-08
Postcode	238309
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	SPOUSE
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : CAMILLA ALICE TREDGOLD GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE REFER TO ATTACHED.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLE8828H
Vehicle Make/Model/Colour	TOYOTA / ESTIMA
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	CHANDRAN PALLANIAPPAN
NRIC/Passport Number	S7018828G
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN


IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


 Policyholder's Signature
 Date & Time:


 Driver's Signature
 (If driver is not the policyholder)
 Date & Time:


 Reporting Centre Personnel's Signature
 Name:
 NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

REFER TO ATTACHMENTS

EMILIA LAW WAS REQUIRED TO TRAVEL TO EUROPE FOR BUSINESS ON 17 MARCH 2019. AS SUCH, HER HUSBAND (JAMIE TREDGOLD) REPORTED THE ACCIDENT IN HER ABSENCE.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time:

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

Incident report:

Date: 16 March 2019

Time: circa 1.20pm

Location: Grange Road - near junction of Grange Road and Rochalie Drive (next to construction site on Grange Road).

I was stationery at a red light on Grange Road (approaching Tanglin Mall on my right). After the lights turned green, I started to move away and was hit by another car from behind.

The driver of the other vehicle apologised and said he was not concentrating. He admitted that it was his fault and repsonsibimity and that his insurance company would cover the cost of all repairs.

We exchanged details and information and he requested to leave the scene. I agreed and he left.

JAMIE TREDGOLD

58287461E








































...CLAIM SUBFOLDER...(Pending for Survey Report)









































CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	18 Mar 2019		21 Mar 2019 16:50 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	AUTOMATE GEUNINE PARTS PTE LTD , Co. Reg. No.: 200815448D, Tel: +6596610227								
Main Claimant:	TREGOLD JAMIE PAUL , ID: S8287461E								
Vehicle Reg. No.:	SKR7014P	Date of Loss:	16/03/2019 13:00 - :59 [115 Months and 1 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 587841	Policy/Cover Note No.:	A28770069MCX (Comprehensive) Coverage: 15/06/2018 - 14/06/2019						
Vehicle Reg. No. (Insured):	SLE8828H	Policy No. (Claimant):							
		Excess:	S\$1,000.00						
Repairer:	Jementah Motor Works (HQ) 14 Defu Lane 10, #01-406, 539195 Defu Lane - Tel: 92996636								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Monica Chung Pei Zhen - 6594 2552]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by CHEN TSUE YEE] ... [Imm.Advice due 22/03/2019]								
Driver/Custodian (Insured):	PALLANIAPPAN CHANDRAN (), NRIC: S7018828G Email:								
Adj Asg. Remarks:	LIAB 100% SJE DISAGREE APPOINT LKK. PLS CONTACT MR AH CHUAN @ 9299 6636								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SKR7014P (587841)**
[SLE8828H]
TP
TREGOLD JAMIE PAUL
Mar 16 2019 1:00PM
[AUTOMATE GEUNINE PARTS PTE LTD]
Jementah Motor Works

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	25/03/19 09:20	General View	 Load JPG	<input checked="" type="checkbox"/>
2	25/03/19 09:20	General View	 Load JPG	<input checked="" type="checkbox"/>
3	25/03/19 09:20	General View	 Load JPG	<input checked="" type="checkbox"/>
4	25/03/19 09:20	General View	 Load JPG	<input checked="" type="checkbox"/>
5	25/03/19 09:20	General View	 Load JPG	<input checked="" type="checkbox"/>
6	25/03/19 09:20	General View	 Load JPG	<input checked="" type="checkbox"/>
7	25/03/19 09:20	General View	 Load JPG	<input checked="" type="checkbox"/>
8	25/03/19 09:20	General View	 Load JPG	<input checked="" type="checkbox"/>
9	25/03/19 09:20	General View	 Load JPG	<input checked="" type="checkbox"/>
10	25/03/19 09:20	General View	 Load JPG	<input checked="" type="checkbox"/>
11	25/03/19 09:20	General View	 Load JPG	<input checked="" type="checkbox"/>
12	25/03/19 09:20	General View	 Load JPG	<input checked="" type="checkbox"/>
13	25/03/19 09:20	General View	 Load JPG	<input checked="" type="checkbox"/>
14	25/03/19 09:20	General View	 Load JPG	<input checked="" type="checkbox"/>
15	25/03/19 09:20	General View	 Load JPG	<input checked="" type="checkbox"/>
16	25/03/19 09:20	General View	 Load JPG	<input checked="" type="checkbox"/>
17	25/03/19 09:20	General View	 Load JPG	<input checked="" type="checkbox"/>
18	25/03/19 09:20	General View	 Load JPG	<input checked="" type="checkbox"/>
19	25/03/19 09:20	General View	 Load JPG	<input checked="" type="checkbox"/>
20	25/03/19 09:20	General View	 Load JPG	<input checked="" type="checkbox"/>
21	25/03/19 09:20	General View	 Load JPG	<input checked="" type="checkbox"/>
22	25/03/19 09:20	General View	 Load JPG	<input checked="" type="checkbox"/>
23	25/03/19 09:20	General View	 Load JPG	<input checked="" type="checkbox"/>
24	25/03/19 09:20	General View	 Load JPG	<input checked="" type="checkbox"/>
25	25/03/19 09:20	General View	 Load JPG	<input checked="" type="checkbox"/>
26	25/03/19 09:20	General View	 Load JPG	<input checked="" type="checkbox"/>
27	25/03/19 09:20	General View	 Load JPG	<input checked="" type="checkbox"/>
28	25/03/19 09:20	General View	 Load JPG	<input checked="" type="checkbox"/>
29	25/03/19 09:20	General View	 Load JPG	<input checked="" type="checkbox"/>
30	25/03/19 09:20	General View	 Load JPG	<input checked="" type="checkbox"/>
31	25/03/19 09:20	General View	 Load JPG	<input checked="" type="checkbox"/>
32	25/03/19 09:20	General View	 Load JPG	<input checked="" type="checkbox"/>
33	25/03/19 09:20	General View	 Load JPG	<input checked="" type="checkbox"/>
34	25/03/19 09:20	Odometer Reading	 Load JPG	<input checked="" type="checkbox"/>
35	25/03/19 09:20	General View	 Load JPG	<input checked="" type="checkbox"/>
36	25/03/19 09:20	General View	 Load JPG	<input checked="" type="checkbox"/>
37	25/03/19 09:20	Chassis Number	 Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	25/03/19 09:20	Chassis Number	 Load JPG	<input checked="" type="checkbox"/>
39	28/03/19 14:08	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
40	28/03/19 14:08	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
41	28/03/19 14:08	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
42	28/03/19 14:08	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
43	28/03/19 14:08	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
44	28/03/19 14:08	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
45	28/03/19 14:08	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
46	28/03/19 14:08	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
47	28/03/19 14:08	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
48	28/03/19 14:08	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
49	28/03/19 14:08	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
50	28/03/19 14:08	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
51	28/03/19 14:08	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
52	28/03/19 14:08	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
53	28/03/19 14:08	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
54	28/03/19 14:08	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
55	28/03/19 14:08	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
56	28/03/19 14:08	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
57	28/03/19 14:08	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
58	28/03/19 14:08	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
59	28/03/19 14:08	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
60	28/03/19 14:08	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
61	28/03/19 14:08	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
62	28/03/19 14:08	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
63	28/03/19 14:08	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
64	28/03/19 14:08	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
65	28/03/19 14:08	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
66	28/03/19 14:08	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
67	28/03/19 14:08	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
68	28/03/19 14:08	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
69	28/03/19 14:08	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
70	28/03/19 14:08	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
71	28/03/19 14:08	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
72	28/03/19 14:08	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
73	28/03/19 14:08	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
74	28/03/19 14:08	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
75	28/03/19 14:08	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
76	28/03/19 14:08	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
77	28/03/19 14:08	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
78	28/03/19 14:08	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
79	28/03/19 14:08	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
80	28/03/19 14:08	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
81	28/03/19 14:08	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
82	28/03/19 14:08	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
83	28/03/19 14:08	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
84	28/03/19 14:08	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
85	28/03/19 14:08	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
86	28/03/19 14:08	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
87	28/03/19 14:08	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>

Photos/Images				3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
88	28/03/19 14:08	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
89	28/03/19 14:08	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
90	28/03/19 14:08	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
91	28/03/19 14:08	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
92	28/03/19 14:08	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
93	28/03/19 14:08	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
94	28/03/19 14:08	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
Documentation				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	20/03/19 17:11	OI GIA Report From:OD - Reg. No: SLE8828H, Claimant: AUTOMATE GEUNINE PARTS PTE LTD		Load PDF	
2	20/03/19 17:11	TP GIA Report - SKR7014P From:OD - Reg. No: SLE8828H, Claimant: AUTOMATE GEUNINE PARTS PTE LTD		Load PDF	
3	20/03/19 17:12	PRI		Load PDF	
4	21/03/19 10:22	fax to lawyer - SJE DISAGREE APPOINT LKK		Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG19005167/ECD3E2

Date: 29/03/2019

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: A28770069MCX

Claimant Vehicle No : SKR7014P

Insured Vehicle No : SLE8828H

Date of Loss: 16/03/2019

Nature of Claim: TP

Claim No: 587841

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKR7014P**

Make & Model: NISSAN QASHQAI, 2.0 PREMIUM (J10) (A)

Engine No: MR20730417A

Reg. Date: 15/08/2009 (Man. Year: 2008)

Chassis No: KJ10205743

Colour: White

Odometer: 79730 km

Engine Capacity: 1997 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60 R17

Rear Tyre Size: 215/60 R17

Front Left Side: Yokohama 7 mm

Rear Left Side: Yokohama 7 mm

Front Right Side: Yokohama 7 mm

Rear Right Side: Yokohama 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 21/03/2019

Date Inspected: 22/03/2019 Inspected At:

Jementah Motor Works (HQ)
14 Defu Lane 10, #01-406
Singapore 539195

Estimated Period of Repair: 7.0 days

Adjuster: CHEN TSUE YEE

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$6,000.00 - \$7,000.00

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 29 Mar 2019)
Parts:	M1-SUV	NISSAN QASHQAI 2.0 PREMIUM (J10) (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKR7014P)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >